

ASS. REC. BY:

REF: 08/FCT/19018530/K/d3n2 Special Instruction:Surveyor: KennethASSIGNMENT (Office)

CWS

From (Person): Jason Tean

of

ref

Date/Time:

18/10/14 @ 6:24pm

Estimated Cost:

Bill to:

OD ① / FWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIC 5991X

Insured:

SHC8338M

at Workshop m/s

Transcub Auto

Tel:

6287 6666

of

NO. 2 AMK St. 63

Policy No:

Claim No:

D19006647MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/10/2011

(Client's Record)

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time: 9:32am @ 21/10/14

Person Contacted:

CandyVehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	<u>SIC 5991X-CC3/114/190/10682/1cha 3.2</u>	<u>D.O.A: 13/6/2011</u>
	<u>SHC8338M-CS/FCT/190/14007/R/190382</u>	<u>DIA: 19/8/2014</u>

REF: FCI

ADJ. REC. BY:

ASSIGNMENT

From:

Date:

21/10/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SHC 5991X

at Workshop m/s

Thursclub

of

No. 2 AMK St. 63

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SHC 5991X

Yr Regn:

12 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour:

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

601414

T/Radin:

Insured / Std / NI / NA

Eng/No:

C/No:

VIF1ABL15AUG 280996

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Sailen 215/60R16

R: Giti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

7

mm

L/Bal.

9

mm

L/Bal.

7

mm

D.O.A.

13/10/19

D.O.I.

21/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/1 Long 824001 (Red: 22516.23, 90%)

RECEIVED 22 OCT 2019

Date/Time, File Pass to?



Preli. Report



Final Report

Date/Time, File Return to?

3)

Days Of Repair:

2

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Week end (\$

Survey Fee:

Transportation:

S + RS \$

Travel

Other

TOTAL

350

Report Format:

TP

Lump (\$m / L.P.): (\$

24001

MOTOR SURVEY ASSIGNMENT

Date	17-10-2019	Our Ref No. D19006647MFSH
Accident Date	15-10-2019	Claim Type. Third Party
Insured Vehicle	SHC8338M	Third Party Vehicle. SHC5991X
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62877764
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JASON TEA CHEE KIAT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Tuesday, 22 October 2019 2:00 PM
To: Denise Tay (LKKAUTO)
Subject: FW: SHC 5991X / TP / FIRST CAPITAL / DOA: 21/10/2019 -- AAD1910-125
Attachments: SHC 5991X.pdf

Hi Denise

Amount confirmed \$ 2,400 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Tuesday, 22 October, 2019 11:16 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Subject: SHC 5991X / TP / FIRST CAPITAL / DOA: 21/10/2019

Dear Wai Yin,

Please check and confirm

Lump sum \$2400

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[➤ Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHC5991X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 Oct 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002434
Chassis No.:	VF1ABL15AUC280996
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	18 Dec 2014
First Registration Date:	18 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	17 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$20,469.00
Total Rebate Amount:	\$29,842.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 Oct 2019

OK

Trans-cab Auto Services Pte Ltd**AAD1910-125**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5991X

VF1ABL15AUC280996

RENAULT

LATITUDE

15.10.19

FCIL

18/12/2014

		PART			LIST
1	1	BUMPER COVER REAR	\$		561.70
2	1	BUMPER LOWER REAR	\$		411.90
3	1	BUMPER BRACKET CTR REAR	\$		98.10
4	1	BUMPER BRACKET SIDE RH REAR	\$		82.10
5	1	BUMPER RETAINER RH REAR	\$		59.80
6	1	BUMPER REFLECTOR RH	\$		16.60
7	1	BUMPER BRACKET SIDE LH REAR	\$		80.80
8	1	BUMPER RETAINER LH REAR	\$		54.20
9	1	BUMPER REFLECTOR LH	\$		16.60
10	1	BUMPER BEAM REAR	\$		547.80
11	1	BUMPER BEAM BRACKET LH REAR	\$		114.50
12	1	BUMPER BEAM BRACKET RH REAR	\$		100.90
13	1	OUTER PANEL REAR (End Panel)	\$		745.80
14	1	OUTER PANEL REAR (End Panel) TRIM	\$		404.56
15	1	TAILLAMP RH	\$		313.10
16	1	TAILLAMP PANEL RH	\$		401.40
17	1	TAILLAMP LH	\$		401.40
18	1	TAILLAMP PANEL LH	\$		401.40
19	1	BOOT REAR	\$		1,677.20
20	1	BOOT FINISHER	\$		344.70
21	1	BOOT WHEATERSTRIP	\$		178.20
22	1	BOOT REFLECTOR LAMP LH	\$		277.70
23	1	BOOT REFLECTOR LAMP RH	\$		277.70
24	1	BOOT BADGE 'RENAULT'	\$		82.40
25	1	BOOT BADGE	\$		95.80
26	1	BOOT STRUT LH	\$		145.10
27	1	BOOT STRUT RH	\$		145.10

Trans-cab Auto Services Pte Ltd**AAD1910-125**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X

28	1	BOOT HINGE LH	\$	254.20
29	1	BOOT HINGE RH	\$	253.80
30	1	BOOT INNER TRIM BOARD	\$	611.00
31	1	BOOT SWITCH	\$	113.00
32	1	BOOT LOCK	\$	246.60
33	1	BOOT LOCK CATCH	\$	41.70
34	1	EXHAUST CAP REAR	\$	125.40
TOTAL			\$	9,682.26
10%			\$	968.23
			\$	8,714.03

Special Nett

1	1SET	PARKING AID	\$	700.00
2	1SET	REAR BUMPER CLIP	\$	66.00
3	1SET	BUMPER BRACKET CTR CLIP	\$	33.00
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	10.00
5	1SET	BUMPER RETAINER RH CLIP RR	\$	20.00
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	10.00
7	1SET	BUMPER RETAINER CLIP LH RR	\$	20.00
8	1SET	BUMPER LOWER REAR RIVET	\$	22.00
9	1SET	BUMPER LOWER REAR CLIP	\$	66.00
10	1	BOOT STICKER "Trans-cab"	\$	30.00
11	1	BOOT STICKER "6555-3333"	\$	30.00
12	1	EXHAUST MOUNTING REAR	\$	16.00
13	2	REAR WINDSCREEN SEALANT	\$	80.00
14	1	WINDSCREEN MOULDING	\$	100.00
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00
16	1	BOOT INNER TRIM CLIP	\$	45.00
17	1SET	BOOT FINISHER CLIP	\$	24.20
18	1	TAILLAMP CLIP LH	\$	5.00
19	1	TAILLAMP CLIP RH	\$	5.00
20	1	Rear Bumper Protector	\$	100.00
TOTAL			\$	1,482.20

TOTAL PARTS \$ 10,196.23**LABOUR**

Trans-cab Auto Services Pte Ltd**AAD1910-125**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00
To Rust-Proofing Of The Affected Areas.	\$	170.00
To Check Electrical Lighting Concerned.	\$	170.00
To transfer of tire, rim and on wheel balancing.	\$	170.00
To reinstall rear bumper parking sensor.	\$	170.00
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00
To check steering geometry and computer wheel alignment	\$	220.00
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	380.00
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00
Putty and spray painting of the affected portion.	\$	6,000.00
To repair and realign rear exhaust pipe.	\$	170.00

TOTAL \$ 14,720.00**Over All Total \$ 24,916.23****LUMP SUM (REPAIR DAY) 20 DAYS**

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X**AAD1910-125***Not Authorized
L1 Smp & 2400*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

21 OCT 2019

SHC 5991X

VF1ABL15AUC280996

RENAULT

LATITUDE

15.10.19

FCIL

18/12/2014

PART

1	1	BUMPER COVER REAR
2	1	BUMPER LOWER REAR
3	1	BUMPER BRACKET CTR REAR
4	1	BUMPER BRACKET SIDE RH REAR
5	1	BUMPER RETAINER RH REAR
6	1	BUMPER REFLECTOR RH
7	1	BUMPER BRACKET SIDE LH REAR
8	1	BUMPER RETAINER LH REAR
9	1	BUMPER REFLECTOR LH
10	1	BUMPER BEAM REAR
11	1	BUMPER BEAM BRACKET LH REAR
12	1	BUMPER BEAM BRACKET RH REAR
13	1	OUTER PANEL REAR (End Panel)
14	1	OUTER PANEL REAR (End Panel) TRIM
15	1	TAILLAMP RH
16	1	TAILLAMP PANEL RH
17	1	TAILLAMP LH
18	1	TAILLAMP PANEL LH
19	1	BOOT REAR
20	1	BOOT FINISHER
21	1	BOOT WHEATERSTRIP
22	1	BOOT REFLECTOR LAMP LH
23	1	BOOT REFLECTOR LAMP RH
24	1	BOOT BADGE 'RENAULT'
25	1	BOOT BADGE
26	1	BOOT STRUT LH
27	1	BOOT STRUT RH

LIST

\$	<i>Buc / cm</i>	561.70	✓
\$	<i>nc</i>	411.90	✓
\$	<i>SL</i>	98.10	X
\$	<i>SL</i>	82.10	X
\$	<i>SL</i>	59.80	X
\$	<i>SL</i>	16.60	X
\$	<i>SL</i>	80.80	X
\$	<i>SL</i>	54.20	X
\$	<i>CM</i>	16.60	✓
\$	<i>B</i>	547.80	✓
\$	<i>n</i>	114.50	} X
\$	<i>n</i>	100.90	
\$	<i>n</i>	745.80	
\$	<i>SL</i>	404.56	
\$	<i>SL</i>	313.10	
\$	<i>n</i>	401.40	
\$	<i>SL</i>	401.40	
\$	<i>n</i>	401.40	
\$	<i>n</i>	1,677.20	
\$	<i>SL</i>	344.70	
\$	<i>SL</i>	178.20	
\$	<i>SL</i>	277.70	
\$	<i>SL</i>	277.70	
\$	<i>n</i>	82.40	✓
\$	<i>n</i>	95.80	✓
\$	<i>SL</i>	145.10	X
\$	<i>SL</i>	145.10	X

Trans-cab Auto Services Pte Ltd

AAD1910-125

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X

28	1	BOOT HINGE LH
29	1	BOOT HINGE RH
30	1	BOOT INNER TRIM BOARD
31	1	BOOT SWITCH
32	1	BOOT LOCK
33	1	BOOT LOCK CATCH
34	1	EXHAUST CAP REAR

\$	254.20	
\$	253.80	
\$	611.00	
\$	113.00	
\$	246.60	
\$	41.70	
\$	125.40	
TOTAL \$	9,682.26	
10% \$	968.23	
\$	8,714.03	

Special Nett

1	1SET	PARKING AID
2	1SET	REAR BUMPER CLIP
3	1SET	BUMPER BRACKET CTR CLIP
4	1SET	BUMPER BRACKET SIDE CLIP RH RR
5	1SET	BUMPER RETAINER RH CLIP RR
6	1SET	BUMPER BRACKET SIDE CLIP LH RR
7	1SET	BUMPER RETAINER CLIP LH RR
8	1SET	BUMPER LOWER REAR RIVET
9	1SET	BUMPER LOWER REAR CLIP
10	1	BOOT STICKER "Trans-cab"
11	1	BOOT STICKER "6555-3333"
12	1	EXHAUST MOUNTING REAR
13	2	REAR WINDSCREEN SEALANT
14	1	WINDSCREEN MOULDING
15	1	REAR WINDSCREEN INNER SPONGE SEAL
16	1	BOOT INNER TRIM CLIP
17	1SET	BOOT FINISHER CLIP
18	1	TAILLAMP CLIP LH
19	1	TAILLAMP CLIP RH
20	1	Rear Bumper Protector

\$	700.00	Shan 400.00
\$	66.00	na ✓
\$	33.00	na ✓
\$	10.00	na X
\$	20.00	na X
\$	10.00	na X
\$	20.00	na X
\$	22.00	na X
\$	66.00	na ✓
\$	30.00	na —
\$	30.00	na —
\$	16.00	na } X
\$	80.00	na }
\$	100.00	na }
\$	100.00	na }
\$	45.00	na }
\$	24.20	na }
\$	5.00	na }
\$	5.00	na }
\$	100.00	na 40.00
TOTAL \$	1,482.20	
TOTAL PARTS \$	10,196.23	

LABOUR

Trans-cab Auto Services Pte Ltd

AAD1910-125

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5991X

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~ 170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	~ 380.00 X
To Rust-Proofing Of The Affected Areas.	\$	~ 170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 15/
To transfer of tire, rim and on wheel balancing.	\$	~ 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 60/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 300/
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	~ 170.00 X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	~ 170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	~ 380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	~ 380.00 X
Putty and spray painting of the affected portion.	\$	6,000.00 440/
To repair and realign rear exhaust pipe.	\$	~ 170.00 X

TOTAL \$ **14,720.00**
Over All Total \$ **24,916.23**

LUMP SUM (REPAIR DAY)**20 DAYS****2 days**

LXX Auto Consultants hence notify the Repairs of the following:

- To remove & refit interior garnish
- To replace damaged paint during
- Panel beating & straightening
- To check steering geometry & computer wheel alignment
- To transfer of rear bumper fittings, attachment and perform water seepage test
- To transfer of rear windscreen glass to facilitate bodywork repair
- To transfer of rear end panel fittings, attachment and perform water seepage test
- To transfer of rear bumper fittings, attachment and perform water seepage test
- To transfer of rear bumper fittings, attachment and perform water seepage test

Authorised Signature: _____
 Name: _____
 Designation: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19018530/Kld3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 25-10-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8338M	Veh. Inspected	SHC 5991X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006647MFSH	Excess (\$)	0.00	
Assign From	JASON TEA	Assign Date	18/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC280996	Colour	METALLIC WHITE / RED	
Odometer	601414	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	SAILUN	9 mm	
L/H Front Tyre	215/60 R16	SAILUN	9 mm	
R/H Rear Tyre	215/60 R16	GITI	7 mm	
L/H Rear Tyre	215/60 R16	GITI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/10/2019	Inspection Date	21/10/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5991X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BUCKLED / CRACKED	561.70	561.70
1	BUMPER LOWER REAR	DENTED	411.90	411.90
1	BUMPER BRACKET CTR REAR	SERVICEABLE	98.10	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	82.10	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	59.80	-
1	BUMPER REFLECTOR RH	SERVICEABLE	16.60	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	80.80	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	54.20	-
1	BUMPER REFLECTOR LH	CRACKED	16.60	16.60
1	BUMPER BEAM REAR	BENT	547.80	547.80
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	114.50	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	100.90	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	745.80	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	TAILLAMP RH	SERVICEABLE	313.10	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	401.40	-
1	TAILLAMP LH	SERVICEABLE	401.40	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	401.40	-
1	BOOT REAR	TO REPAIR SEE LABOUR	1,677.20	-
1	BOOT FINISHER	SERVICEABLE	344.70	-
1	BOOT WEATHERSTRIP	SERVICEABLE	178.20	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	277.70	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	277.70	-
1	BOOT BADGE "RENAULT"	NECESSARY	82.40	82.40
1	BOOT BADGE	NECESSARY	95.80	95.80
1	BOOT STRUT LH	SERVICEABLE	145.10	-

Report Ref No. CS/FCI19018530/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOT STRUT RH	SERVICEABLE	145.10	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	254.20	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	253.80	-
1	BOOT INNER TRIM BOARD	SERVICEABLE	611.00	-
1	BOOT SWITCH	SERVICEABLE	113.00	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	246.60	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	41.70	-
1	EXHAUST CAP REAR	SERVICEABLE	125.40	-
	LESS 10% DISCOUNT		-968.23	-171.62
			8,714.03	1,544.58
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SHORTED	700.00	400.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	EXHAUST MOUNTING REAR (SN)	NOT NECESSARY	16.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-

Report Ref No. CS/FCI19018530/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	100.00	40.00
			1,482.20	665.00
	LABOUR			
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	15.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, OUTER PANEL REAR (END PANEL), TAILLAMP PANEL RH, TAILLAMP PANEL LH, BOOT REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK AND BOOT LOCK CATCH.		6,000.00	300.00
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	440.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
			14,720.00	815.00
GRAND TOTAL			24,916.23	3,024.58

Report Ref No. CS/FCI19018530/Ktd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00
---	--	--	----------

Report Ref No. CS/FCI19018530/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.