

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 21 October 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799

VEHICLE NO : FBC 8525K
ACCIDENT DATE: 10 October 2019

Suzuki DRZ400

Description	Qty	Quotation \$
1 Front LH Side Cover <i>HN</i>	1	305.00 X
2 Front Fender <i>Dented</i>	1	550.00 ✓
3 Handle Bar <i>HN</i>	1	645.00 X
4 Front Fork Tube <i>repaired</i>	1 set	1,650.00 X
5 RH Fork Guard <i>Cut</i>	1	228.00 ✓
6 Front RH Fork Assy <i>distorted</i>	1	1,650.00 ✓
7 Front Wheel Slider <i>Cut o/s</i>	1 set	450.00 225/-
8 Hand Guard <i>Cut o/s</i>	1 set	450.00 225/-
9 Rear Centre Cover LH <i>HN</i>	1	395.00 X
10 Rear Wheel Slider <i>HN</i>	1	250.00 X
Sub-Total		6,573.00
Less 10%		657.30
Sub-Total		5,915.70

2878.00

2590.20

VEHICLE NO : FBC 8525K

Suzuki DRZ400

Nett Items

- 1 Towing fee ~~RM~~
- 2 Remove & replace necessary parts, align & etc
- 3 Remove & replace front fork, top up fork oil & check front rim - repress & front brake disc
- 4 Respray paint & touch up

330.00

60.00 X
250.00 150/-

~~280.00~~ 80/-

~~300.00~~ 100/-

Sub-Total

890.00

Nett Total

6,805.70

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

2920.20

4/s 2300/-

Kindly revert upon completion.

Thank you

S9 MOTOR TRADING PTE LTD

21/10/2019 @ 1030am

NA Antmal

4/Sum 3 days.

yan

LKK Anto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: