

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jeannie Cheng Jin Rong

Date: 22 Oct 2019

Preliminary Advice

Vehicle No	: SLC3663J	Accident Date	: 08/10/2019
Make	: MERCEDES-BENZ C180	Policy No.	: 29123465
Assignment Date	: 21/10/2019	Excess	: S\$500.00
Date of Inspection	: 22/10/2019	Est. Duration of Repair	: 10 days
Inspection At	: Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,832.98
Revised Amount	:S\$	17,985.77
Check Items (Estimated)	:S\$	6,244.12
Total	:S\$	24,229.89

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	107,000.00
COE / PARF Rebate	:S\$	63,315.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,685.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.