

ASS. REC. BY:

REF:

CS/MG/19018535/ RLS0327

Special Instruction:

Junior: Rasul

ASSIGNMENT (Office)

Miner

From (Person): Jeannie cheng

of

MSIG

Date/Time:

21/10/2019 @ 1:37pm

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 3663J

Insured:

at Workshop m/s

Cycle & Carriage Ltd.

Tel:

8332 0062

of

188 punden loop

Policy No:

29123165

Claim No:

608425

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A.

08/11/10/2019

CA / (REV) /

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:27am @ 21/10/19

Person Contacted:

Vincent

Vehicle IN/OUT

Date/Time

Action/Instruction

Follow up

SLC 3663J-X

21/10/19

Notified Rasul the excess is \$500.00. He is aware of it.

22/10/19

@ 14:21 pm revised PA to Jeannie cheng via miner

22/10/19

@ 14:22 pm mandate requested authorize repair to Jeannie cheng via miner

22/10/19

@ 15:55 pm mandate approval by Jocelyn Ng Shin Ban

22/10/19

@ 12:44 pm mandate approval by Jeannie cheng via miner

ASS. REL. BY:

REP: MS16

CSMSQ-1018 0007/1305

9386

ASSIGNMENT

From:

Date:

22/10/2019

Veh No:

SLC 3663J

Yr Regn:

2016 / APR

Estimated Cost:

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No:

SLC 3663J

at Workshop m/s

Cycle & Camridge Industries

of

188 Fenden loop

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

TBA

(Client's Record)


Make of Veh:

9-300m-100m (waiting)

Vincent @ 8332 0062

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

107K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Make:

Mercedes Benz C180 Avantgarde c.c. 1595

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

55367

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WSD 205040 2R154602

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod:

Nil / ☒ R/Rim / ☐ STD A/Rim or

Tyre Size:

F:

225/50 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CONTINENTAL

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

08/10/19

D.O.I.

22/10/19

Survey held at

CBC (PL)

Des. of Damages: ☒ Fd / ☒ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

21/11/19

Confirmed P/P & 19,769.23 @ 10 days
(\$ 9,977.44 Red - 34 %)

RECEIVED 23 NOV 2019

21/11/2019

Date/Time, File Page to?

25/11/19

1)

Type: st

Date/Time, File Return to?

2)

Report Format:

Lump Sum / H/L:

19,769.23 P/P

Days Of Repair:

10

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp

(\$

☐

Interview

(\$

☐

Tech. Insp

(\$

☐

Weekend

(\$

Survey Fee:

300

Transportation

(\$ + RS. \$)

Parked

Other

TOTAL

11

211

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Oct 2019		21 Oct 2019 13:37 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	Seah Ngee Boon, ID: S1508938E, Tel: +6594877332								
Vehicle Reg. No.:	SLC3663J	Date of Loss:	08/10/2019 21:00 - :59 [41 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 608425	Policy/Cover Note No.:	29123465 (Comprehensive) Coverage: 28/04/2019 - 27/04/2020						
		Excess:	S\$500.00						
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jeannie Cheng Jin Rong - 6594 2537]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/10/2019]								
Driver/Custodian:	Neo Bee Lian (55 / Female), NRIC: S1573647Z, Tel: +6591287662 Email: snbseah@gmail.com								
Adj Asg. Remarks:	Survey appt 22/10/19, 10am. Owner waiting. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Manual assigned to LKK via email on 21/10/19. LKK Auto Consultants will be attending survey. Please revert.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Monday, 21 October 2019 11:11 AM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned
Attachments: img-X21073704-0001.pdf; SLC3663J_08102019 ADD.pdf

SLC3663J- OD CLAIM SURVEY DOA: 19/10/19 (Survey appt 22/10/19, 10am. Owner waiting)

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We will assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A member of **MS&AD** INSURANCE GROUP

From: Motor Survey

Sent: Monday, 21 October, 2019 9:59 AM

To: Jeannie Cheng <jeannie_cheng@sg.msig-asia.com>

Cc: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>;
vincent.seah@cyclecarriage.com.sg

Subject: FW: SLC3663J- OD CLAIM SURVEY DOA: 19/10/19 Kindly arrange survey tomorrow morning 22.10.19
(outsource) Estimate: \$30k

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A 15% stake in **MS&AD** INSURANCE GROUP

From: Crystal Lee

Sent: Monday, 21 October 2019 9:41 AM

To: Vincent Seah <vincent.seah@cyclecarriage.com.sg>; Motor Survey <motorsurvey@sg.msia-asia.com>

Subject: FW: SLC3663J- OD CLAIM SURVEY

**We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Moving forward, please email your survey request to motorsurvey@sg.msia-asia.com*

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msia-asia.com

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

-----Original Message-----

From: Vincent Seah [<mailto:vincent.seah@cyclecarriage.com.sg>]

Sent: Monday, 21 October, 2019 7:45 AM

To: Claims <claims@sg.msia-asia.com>

Cc: Crystal Lee <crystal_lee@sg.msia-asia.com>

Subject: SLC3663J- OD CLAIM SURVEY

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Morning

Kindly arrange survey tomorrow morning 22.10.19

OD CLAIM

Tks

Vincent Seah

Cycle & Carriage Ind. Pte Limited

Body Care & Repair - Pandan Loop Service Center

188 Pandan Loop Singapore 128378

Tel : 83320062 (H/P) DID: 6771 4401

Fax : 6872 1272

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	938E
Vehicle Details	
Vehicle No.:	SLC3663J
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Oct 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180 AVANTGARDE (R17 LED)
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	27491030529699
Chassis No.:	WDD2050402R154602
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$35,465.00
Original Registration Date:	28 Apr 2016
First Registration Date:	28 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$36,651.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Apr 2026
PARF Rebate Amount:	\$27,488.00
Intended COE Rebate Details	
COE Expiry Date:	27 Apr 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,001.00
COE Rebate Amount:	\$35,827.00
Total Rebate Amount:	\$63,315.00

The information contained herein is correct as at 22 Oct 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 25 November 2019 8:56 am
To: Vincent Seah
Subject: RE: SLC3663J- FINALIZE

Dear Vincent,

Supplementary approved by MSIG.

Confirmed P/P \$ 19,769.23 @ 10 days of repairs before excess \$ 500/- & GST.

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Vincent Seah <vincent.seah@cyclecarriage.com.sg>

Sent: Wednesday, 13 November 2019 9:08 am

To: Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: SLC3663J- FINALIZE

Importance: High

Hi

Kindy finalize

Urgent

Tks

Vincent Seah

Cycle & Carriage Ind. Pte Limited

Body Care & Repair - Pandan Loop Service Center

188 Pandan Loop Singapore 128378

Tel : 83320062 (H/P) DID: 6771 4401

Fax.: 6872 1272

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Tuesday, 22 October 2019 5:04 pm
To: vincent.seah@cyclecarriage.com.sg
Cc: SUR
Subject: SLC 3663J OD (MSIG) DOA - 08/10/2019

Hi Vincent,

As instructed by our client, please proceed to repair the insured vehicle **SLC 3663J (Excess S 500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLC3663J (608425)**

OD

Oct 8 2019 9:00PM

[Seah Ngee Boon]

Cycle & Carriage Industries Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 22/11/2019 19:27 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$19769.23) - SLC3663J - Claim Handler: Jeannie Cheng Jin Rong

Approved:19769.23:a lf c

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

*SLC3663J (608425)

OD

Oct 8 2019 9:00PM

[Seah Ngee Boon]

Cycle & Carriage Industries Pte Ltd

Reply	Reply All	Mark as Unread	Print Message	Delete Message	Forward
-------	-----------	----------------	---------------	----------------	---------

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 19/11/2019 13:09 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (\$25143.58) - SLC3663J - Claim Handler: Jeannie Cheng Jin Rong

Approved:25143.58:a if c

DOCUMENTS SUMMARY
There are no documents.

View Received Message

This mail is associated with :

***SLC3663J (608425)**

OD

Oct 8 2019 9:00PM

[Seah Ngee Boon]

Cycle & Carriage Industries Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 22/10/2019 15:55 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$17985.77) - SLC3663J - Claim Handler: Jeannie Cheng Jin Rong

Approved:17985.77:a if c

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jeannie Cheng Jin Rong

Date: 21 Nov 2019

Preliminary Advice

Vehicle No	: SLC3663J	Accident Date	: 08/10/2019
Make	: MERCEDES-BENZ C180	Policy No.	: 29123465
Assignment Date	: 21/10/2019	Excess	: S\$500.00
Date of Inspection	: 22/10/2019	Est. Duration of Repair	: 10 days
Inspection At	: Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,746.67
Revised Amount	:S\$	19,769.23
Check Items (Estimated)	:S\$	0.00
Total	:S\$	19,769.23
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	107,000.00
COE / PARF Rebate	:S\$	63,315.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,685.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jeannie Cheng Jin Rong

Date: 18 Nov 2019

Preliminary Advice

Vehicle No	: SLC3663J	Accident Date	: 08/10/2019
Make	: MERCEDES-BENZ C180	Policy No.	: 29123465
Assignment Date	: 21/10/2019	Excess	: S\$500.00
Date of Inspection	: 22/10/2019	Est. Duration of Repair	: 10 days
Inspection At	: Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,746.67 (inclusive supp)
Revised Amount	:S\$	18,899.46 (inclusive supp)
Check Items (Estimated)	:S\$	6,244.12
Total	:S\$	25,143.58
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	107,000.00
COE / PARF Rebate	:S\$	63,315.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,685.00

Remarks

(X) The vehicle is economical for repair. Supplementary amount is \$ 913.69.

() The above survey was conducted on a 'without prejudice' basis.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jeannie Cheng Jin Rong

Date: 22 Oct 2019

Preliminary Advice

Vehicle No	: SLC3663J	Accident Date	: 08/10/2019
Make	: MERCEDES-BENZ C180	Policy No.	: 29123465
Assignment Date	: 21/10/2019	Excess	: S\$500.00
Date of Inspection	: 22/10/2019	Est. Duration of Repair	: 10 days
Inspection At	: Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,832.98
Revised Amount	:S\$	17,985.77
Check Items (Estimated)	:S\$	6,244.12
Total	:S\$	24,229.89

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	107,000.00
COE / PARF Rebate	:S\$	63,315.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,685.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/10/2019 16:19
Date Of Accident	08/10/2019 21:20
Exact Location Of Accident	UPPER SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC3663J
Insured/Policyholder	
Name Of Registered Owner	SEAH NGEE BOON
NRIC No	S1508938E
Email Address	SNBSEAH@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91287662
Alternative Phone No	OFFICE-91287662

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 29123465 QMY
Cover Note Number	

Driver

Name of Driver	NEO BEE LIAN
NRIC No	S1573647Z
Date Of Birth	12/11/1963
Occupation	INDOOR
Date Of Driving Pass	15/09/2003
Driving Experience	16 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91287662
Fax Number	
Contact Number	OFFICE-91287662
Email Address	SNBSEAH@GMAIL.COM

Address	APT BLK 187B RIVERVALE DRIVE #06-868 SINGAPORE
Postcode	542187
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : SEAH NGEE BOON GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	SENGKANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 2 SENGKANG SQUARE #01-02 SINGAPORE , POSTCODE: 545025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800 - 3438999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKQ5168Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG SOON HENG
NRIC/Passport Number	57801645J



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 - 17:00
UEN: S665300200 / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MSI 119135087 Vehicle Registration No: SLC 3663J
Name (as shown in NRIC): Leo Bee Lian NRIC/FIN/Passport No: S1573647Z
[*Vehicle Driver / ~~Vehicle Owner~~] [*] Please delete as appropriate
Address: APT BLK 187B RIVERVALE DR #06-868 Singapore (542187)
Contact (Tel): 90577773 Mobile No.: 91287662
Email Address: SubSeah@gmail.com
Date of Accident: 8-10-19 Time of Accident: 2120hrs
Place of Accident: Upper Serangoon Road
Insurance Company: MSIG

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

① I want to amend my third party claims to own damage claim

② I want to add in additional statement.

When vehicle B hit the rear side of my vehicle, my vehicle was pushed forward and hit the cyclist.

Policyholder / Driver's Signature
Date:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:
Date:

Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number
Vehicle Make/Model/Colour BICYCLE
Details Of Properties
Vehicle Category NA/UNKNOWN
Name of Driver NA (CYCLIST)
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 08/12/2019 at about 2119hrs. I was driving my vehicle bearing plate number SLC 3663J along Upper Serangoon Road towards Angkor East drive. I was travelling along line 2 and when I was approaching the traffic light junction there was cyclist (Chinese/60 yrs) who suddenly cross the road when the traffic light was in my favour. Upon seeing him, I stopped my vehicle however the car behind me bearing plate no. SKG 5168Y was unable to stop in time and hit onto the rear side of my vehicle. Traffic police and ambulance was at scene, nobody was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
NRIC/FIN No:



SINGAPORE POLICE FORCE



T/20191008/2183

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

1 of 3

Report No. T/20191008/2183

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/10/2019 23:36	Vide Report No.: F/20191008/0188	Station Diary No.: 196
--	-------------------------------------	---------------------------

Informant's Particulars

Name of Informant: NEO BEE LIAN			Address: APT BLK 187B RIVERVALE DRIVE #06-868 SINGAPORE 542187		
ID Type / ID No.: NRIC NO / S1573647Z			Contact No.: Home/Office: Mobile: 91287662		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 55	Date of Birth: 12/11/1963	Type of Informant: Driver		
Race: Chinese			Language: English	Institution / School Name:	
Occupation: ADMIN.			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 08/10/2019 21:20	Type of Location: Straight Road
Location: Along Road 1 UPPER SERANGOON ROAD UPPER SERANGOON ROAD TOWARDS SENGKANG EAST DRIVE				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Pedestrian				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKQ5168Y	Car					1
SLC3663J	Car				Slightly Damaged	1
	Bicycle			Bicycle		0



**SINGAPORE
POLICE FORCE**



T/20191008/2183

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

2 of 3

Report No. T/20191008/2183

CONTINUATION OF REPORT

Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	NG SOON HENG	ID No.	S7801645J
Related Vehicle	SKQ5168Y (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	NEO BEE LIAN	ID No.	S1573647Z
Related Vehicle	SLC3663J (Car)	Contact No.	91287662
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 08/10/2019 at about 2118hrs, I was driving my vehicle bearing plate number SLC3663J along Upper Serangoon Road towards Sengkang East Drive. I was travelling alone lane 2 and when I was approaching the traffic light junction, there was cyclist (Chinese/ 60yrs) who suddenly cross the road when the traffic light was in my favor. Upon seeing him, i stopped my vehicle however the car behind me bearing plate number SKQ5168Y was unable to stop in time and hit onto the rear side of my vehicle.

Traffic police and ambulance was at scene however nobody was injured and conveyed to the hospital.

I was advised by traffic police to make traffic accident report under IO Jerry contact: 65476213



**SINGAPORE
POLICE FORCE**



T/20191008/2183

Police Station Of Origin:
Sengkang N.P.C
2 Sengkang Square #01-02 SINGAPORE
545025
Tel No: 1800-343 8999

3 of 3

Report No. T/20191008/2183

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
F /
Sr Staff Sgt MUHAMMAD YASSER BIN OSMAN

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
08/10/2019 23:36

Officer In Charge Of Case:
TP / GIT /
SI YEO CHUN JIAN
Contact No.: 65476213

Classification Of Case:

SN 085

Authentication Stamp
NP168



Signature:

Singapore Police Force

MSIG

Insurance (Singapore) Pte. Ltd.

100, Raffles Place, # 21-01, SGX Centre 2, Singapore 068807

+65 6827 7888, Fax +65 6827 7800

Reg. No. 200412212G GST Reg. No. 20-0412212G

MOTOR MAX PLUS

THE SCHEDULE

Policy Number	Period of Insurance	Place of Issue
A 29123465 QMY	28/04/2019 to 27/04/2020	SINGAPORE
Name and Address of Insured		Date of Issue
Seah Ngee Boon 187B Rivervale Drive #06-868 Singapore 542187		02/05/2019
		Account Number
		1A0319
Premium	GST	Total Due
SGD894.54	SGD62.62	SGD957.16

RISK NUMBER 1

MOTORMAX PLUS

OCCUPATION

Executive

FINANCIAL INTEREST

Standard Chartered Bank (Singapore) Limited
as Hire Purchase Owners

SCOPE OF COVER Comprehensive

INTEREST INSURED

REGISTRATION NO.	SLC3663J	SUM INSURED	MARKET VALUE
MAKE/MODEL	Mercedes Benz C180 Avantgarde	INCL. COE/PARF	YES
ENGINE NUMBER	27491030529699	OFF-PEAK CAR	NO
CHASSIS NUMBER	WDD2050402R154602	NO CLAIM DISCOUNT	50.00% (or F/D)
YEAR OF MFG	2016	GOOD DRIVER'S	
CAPACITY	1595 C.C.	DISCOUNT	SGD47.08
SEATING CAPACITY	5 (INCL. DRIVER)	NCD PROTECTOR	COVERED
WINDSCREEN	UNLIMITED	EXCESS	SGD500
		ANNUAL PREMIUM	SGD894.54

ACCESSORIES Aircon, radio/cassette/compact disc player, in-vehicle unit, rust-proofing and other accessories that are factory fitted.

AUTHORISED DRIVERS

Seah Ngee Boon



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-6500111-X

ESTIMATE FOR SLC3663J

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information

WIP No 37659
Reg No/Reg Date SLC3663J / 28/04/2016
Date In/Mileage / 0
Chassis No WDD2050402R154602
Engine No 27491030529699
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 027 792 Palladium S/ 041 118 Alpaca grey

Account No	Terms	Date/Time Printed	CSE	Operator
WI000558	Credit	22/10/2019/ 10:48	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :A29123465QMY // 08.10.19 DRIVE IN/EXCESS : 18.10.19 // DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB "USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT"			0.10	380.00 ✓
A BPILAB REMOVE REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NET				120.00 ✓
S BPNSUB SUPPLY 1 PC NUMBER PLATE WITH HOUSING.NETT				60.00 ✓
A BPILAB "REMOVE & INSTALL INTERIOR GARNISH,SEAT AND UPHOLSTERY FOR NECESSARY REPAIR."				480 960.00 ✓
A BPILAB REMOVE & REPLACE ON FRONT BUMPER, BONNET,REAR BUMPER, END PANEL				5280 6720.00 ✓
A BPIRES RESPRAY ON FRONT BUMPER, BONNET, REAR BUMPER, END PANE,BOOT				3000 3600.00 ✓
M FRONT BUMPER	1.00	1557.32	00.00	1557.32
M UPPER BUMPER COVER SEALING	1.00	27.55	00.00	27.55
M DISTANCE SENSOR	2.00	176.11	00.00	352.22
M SPACER RING	2.00	6.35	00.00	12.70
M LICENSE PLATE MOLDING	1.00	126.10	00.00	126.10
M BOTTOM BASIC MOUNTING FOR BUMPER	1.00	139.42	00.00	139.42
M TOP BASIC MOUNTING FOR BUMPER	1.00	86.01	00.00	86.01
M IMPACT ABSORBER	1.00	158.73	00.00	158.73
M BLIND RIVET	4.00	4.43	00.00	17.72
M LEFT MOUNTING RAIL	1.00	12.19	00.00	12.19
M RIGHT MOUNTING RAIL	1.00	12.50	00.00	12.50
M FRONT AIR DUCT	1.00	127.48	00.00	127.48

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLC3663J

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information
WIP No 37659
Reg No/Reg Date SLC3663J / 28/04/2016
Date In/Mileage / 0
Chassis No WDD2050402R154602
Engine No 27491030529699
Make/Model MB/MB C 180 SEDAN (W205) *AVANTGARDE / A
Colour/Trim 027 792 Palladium S/ 041 118 Alpaca grey

Account No	Terms	Date/Time Printed	CSE	Operator
WI000558	Credit	22/10/2019/ 10:48	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M COMPANY SIGN	1.00	77.91	00.00	77.91
M HOOD REPAIR	1.00	2083.09	00.00	2083.09
M FRONT SUPPORT CONSOLE	1.00	209.91	00.00	209.91
M CROSS MEMBER	1.00	423.49	00.00	423.49
M REAR BUMPER	1.00	1635.44	00.00	1635.44
M CENTRE BASIC MOUNTING FOR BUMPER	1.00	91.92	00.00	91.92
M LHR BASIC MOUNTING FOR BUMPER	1.00	56.64	00.00	56.64
M RHR BASIC MOUNTING FOR BUMPER	1.00	56.64	00.00	56.64
M LHR BRACKET	1.00	33.30	00.00	33.30
M RHR BRACKET	1.00	33.96	00.00	33.96
M REAR LOWER CENTER BUMPER COVER	1.00	104.89	00.00	104.89
M REAR MODULE BRACKET	1.00	39.80	00.00	39.80
M REAR SWITCHING MODULE	1.00	307.73	00.00	307.73
M REAR SWITCH MODULE, CODE A	1.00	121.95	00.00	121.95
M REAR SWITCH MODULE, CODE B	1.00	121.95	00.00	121.95
M REAR LOWER BUMPER	1.00	217.29	00.00	217.29
M REAR BUMPER CENTRE CHROME MOULDING	1.00	255.71	00.00	255.71
M BLIND RIVET	4.00	4.43	00.00	17.72
M DISTANCE SENSOR	6.00	176.11	00.00	1056.66
M SPACER RING	6.00	6.35	00.00	38.10
M BLIND RIVET	2.00	4.43	00.00	8.86
M LHR BUMPER EXHAUST COVER	1.00	97.89	00.00	97.89
M LHR SIDE STABILITY	1.00	55.82	00.00	55.82
M RHR SIDE STABILITY	1.00	56.01	00.00	56.01
M TOP LEFT BASIC MOUNTING FOR BUMPER	1.00	32.64	00.00	32.64
M TOP RIGHT BASIC MOUNTING FOR BUMPER	1.00	32.14	00.00	32.14
M REAR CROSS MEMBER	1.00	651.93	00.00	651.93
M LOAD COMPARTMENT WELL	1.00	538.00	00.00	538.00
M COVER, REAR-END FLOOR	1.00	41.34	00.00	41.34
M REAR END PANEL	1.00	1414.23	00.00	1414.23
M LEFT REAR LAMP COMBINATION	1.00	702.52	00.00	702.52
M RIGHT REAR LAMP COMBINATION	1.00	702.52	00.00	702.52
M LHR GASKET TAIL LIGHT HOUSING	1.00	31.64	00.00	31.64

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLC3663J

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information
WIP No 37659
Reg No/Reg Date SLC3663J / 28/04/2016
Date In/Mileage / 0
Chassis No WDD2050402R154602
Engine No 27491030529699
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 027 792 Palladium S/ 041 118 Alpaca grey

Account No	Terms	Date/Time Printed	CSE	Operator
WI000558	Credit	22/10/2019/ 10:48	VS	356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RHR GASKET TAIL LIGHT HOUSING	1.00	31.64	00.00	31.64
M TRUNK LID	1.00	2127.67	00.00	2127.67
M REAR BOOT WEATHER-STRIP	1.00	195.71	00.00	195.71
M REAR BOOT CHROME MOULDING	1.00	132.35	00.00	132.35
M SEALING GROMMET	3.00	2.20	00.00	6.60
M MERCEDES STAR	1.00	47.69	00.00	47.69
M C180 MODEL PLATE	1.00	89.09	00.00	89.09
M REAR ELECTRICAL WIRING HARNESS	1.00	382.65	00.00	382.65

MSIG Auto Consultants Hence Notify
the Repaired of the following:
• To resurvey before and after painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5363
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Page 3 of 3



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-6500111-X

ESTIMATE FOR SLC3663J

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information

WIP No 37659
Reg No/Reg Date SLC3663J / 28/04/2016
Date In/Mileage 22/10/2019 / 55367
Chassis No WDD2050402R154602
Engine No 27491030529699
Make/Model MB/MB C 180 SEDAN (W205) *AVANTGARDE / A
Colour/Trim 027 792 Palladium 5/ 041 118 Alpaca grey

Account No	Terms	Date/Time Printed	GSE	Operator
WI000558	Credit	13/11/2019/ 09:03	VS	356 / Vincent Seah
Description of Goods / Services				
Qty	Unit Price	Disc%	Amount	

M. BPNSUN

DATE IN/DATE SURVEY: 22.10.19 // 22.10.19 RASUL-LKK 10:30AM
BY/AUTHORIZED ON : SHIRLEY-LKK // 22.10.19 17:00PM

X TS TWO-COMPONENT ADHESIVE	1.00	776.81	00.00	776.81
X BLIND RIVET	12.00	1.29	00.00	23.22
X RIVET	4.00	2.51	00.00	10.04
X LHR BRACKET	1.00	27.86	00.00	27.86
X HEXAGON NUT W COLLAR	4.00	2.51	00.00	10.04
X RETAINER WEDGE	2.00	11.53	00.00	23.06
X NUT	4.00	5.37	00.00	21.48
X RETAINER WEDGE	2.00	10.59	00.00	21.18

ESTIMATE

SUPPLEMENTARY

Confirmed & accepted by

7% GST on Nett 913.69 63.96

Total Payable 977.65

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128379
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 195400367W
GST Reg No. M2-8500111-X

ESTIMATE FOR SLC3663J

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information

WIP No 37659
Reg No/Reg Date SLC3663J / 28/04/2016
Date In/Mileage 22/10/2019 / 55367
Chassis No WDD2050402R154502
Engine No 27491030529699
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 027 792 Palladium S/ 041 118 Alpaca grey

Account No	Terms	Date/Time Printed	CSE	Operator			
WI000558	Credit	13/11/2019/ 09:04	V5	356 / Vincent Seah			
Description of Goods/ Services				Qty	Unit Price	Disc%	Amount

M BPNSUN

DRIVE IN/EXCESS : 18410.19 // 4500
DATE IN/DATE SURVEY: 22.10.19 // 22.10.19 RASUL-LKK 10:30AM
BY/AUTHORIZED ON : SHIRLEY-LKK // 22.10.19 17:00PM

A BPILAB

"USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NET"

A BPILAB

REMOVE REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NET

S BPNSUB

SUPPLY 1 PC NO PLATE

A BPILAB

"REMOVE & INSTALL INTERIOR GARNISH, SEAT AND UPHOLSTERY
FOR NECESSARY REPAIR."

A BPILAB

REMOVE & REPLACE ON FRONT BUMPER, BONNET REAR BUMPER, END PANEL

A BPIRES

RESPRAY ON FRONT BUMPER, BONNET REAR BUMPER, END PANE,BOOT

X BPNEXC

INSURANCE EXCESS

X FRONT BUMPER

X LICENSE PLATE MOLDING

X BLIND RIVET

X REAR BUMPER

X LHR BRACKET

X RHR BRACKET

X REAR LOWER CENTER BUMPER COVER

X REAR LOWER BUMPER

X REAR BUMPER CENTRE CHROME MOULDING

X BLIND RIVET

X DISTANCE SENSOR

0.10 380.00

120.00

60.00

480.00

5280.00

3000.00

-500.00

1.00 1557.32 00.00 1557.32

1.00 126.10 00.00 126.10

4.00 4.43 00.00 17.72

1.00 1635.44 00.00 1635.44

1.00 33.30 00.00 33.30

1.00 33.96 00.00 33.96

1.00 104.89 00.00 104.89

1.00 217.29 00.00 217.29

1.00 255.71 00.00 255.71

4.00 4.43 00.00 17.72

1.00 176.11 00.00 176.11

Finalization

10 days

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

Page 1 of 2



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLC3663J

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT
16 RAFFLES QUAY #24-01
HONG LEONG BUILDING
SINGAPORE 048581
66431303

Vehicle & Document Information

WIP No 37659
Reg No/Reg Date SLC3663J / 28/04/2016
Date In/Mileage 22/10/2019/ 55867
Chassis No WDD2050402F154602
Engine No 27491030529699
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 027 792 Palladium S/ 041 118 Alpaca grey

Account No	Terms	Date/Time Printed	CSE	Operator				
WI000558	Credit	13/11/2019/ 09:04	V5	356 / Vincent Seah				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X TOP LEFT BASIC MOUNTING FOR BUMPER					1.00	32.64	00.00	32.64
X TOP RIGHT BASIC MOUNTING FOR BUMPER					1.00	32.64	00.00	32.64
X LOAD COMPARTMENT WEL					1.00	938.00	00.00	938.00
X COVER, REAR-END FLOOR					1.00	41.34	00.00	41.34
X REAR END PANEL					1.00	1414.23	00.00	1414.23
X RIGHT REAR LAMP COMBINATION					1.00	702.52	00.00	702.52
X TRUNK LID					1.00	2127.67	00.00	2127.67
X REAR BOOT WEATHER-STRIP					1.00	195.71	00.00	195.71
X REAR BOOT CHROME MOULDING					1.00	132.35	00.00	132.35
X SEALING GROMMET					3.00	2.20	00.00	6.60
X MERCEDES STAR					1.00	47.69	00.00	47.69
X C180 MODEL PLATE					1.00	89.09	00.00	89.09
X TS TWO-COMPONENT ADHESIVE					1.00	776.81	00.00	776.81
X BLIND RIVET					18.00	1.29	00.00	23.22
X RIVET					4.00	2.51	00.00	10.04
X LHR BRACKET					1.00	27.86	00.00	27.86
X HEXAGON NUT W COLLAR					4.00	2.51	00.00	10.04
X RETAINER WEDGE					2.00	11.53	00.00	23.06
X NUT					4.00	5.37	00.00	21.48
X RETAINER WEDGE					2.00	10.59	00.00	21.18

Finalization

Confirmed & accepted by

Nett 19,269.23
7% GST on 19269.23 1348.85

Total Payable 20,618.08

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Oct 2019		21 Oct 2019 13:37 Edit Adj Rpt	S\$19,769.23 Edit Estimates	S\$19,769.23 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Seah Ngee Boon, ID: S1508938E, Tel: +6594877332								
Vehicle Reg. No.:	SLC3663J	Date of Loss:	08/10/2019 21:00 - :59 [41 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 608425	Policy/Cover Note No.:	29123465 (Comprehensive) Coverage: 28/04/2019 - 27/04/2020						
		Excess:	S\$500.00						
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 12837B West Coast - Tel: 91865300								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jeannie Cheng Jin Rong - 6594 2537]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 20/11/2019]								
Driver/Custodian:	Neo Bee Lian (55 / Female) , NRIC: S1573647Z, Tel: +6591287662 Email: snbseah@gmail.com								
Adj Asg. Remarks:	Survey appt 22/10/19, 10am. Owner waiting. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Manual assigned to LKK via email on 21/10/19. LKK Auto Consultants will be attending survey. Please revert.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (22/11/2019): Alert - Adj Mandate Approved (S\$19769.23) - SLC3663J - Claim Handler: Jeannie Ch... - MSIG_SG (19/11/2019): Alert - Adj Mandate Approved (S\$25143.58) - SLC3663J - Claim Handler: Jeannie Ch... - MSIG_SG (22/10/2019): Alert - Adj Mandate Approved (S\$17985.77) - SLC3663J - Claim Handler: Jeannie Ch...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLC3663J (608425)
 OD
 Oct 8 2019 9:00PM
 [Seah Ngee Boon]
 Cycle & Carriage Industries Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/10/19 14:21	Adjuster Immediate Advice		Load HTM	
2	18/11/19 10:15	Adjuster Immediate Advice		Load HTM	
3	21/11/19 14:56	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/10/19 17:39	General View		Load JPG	
2	23/10/19 17:39	General View		Load JPG	
3	23/10/19 17:39	General View		Load JPG	
4	23/10/19 17:39	General View		Load JPG	
5	23/10/19 17:39	General View		Load JPG	
6	23/10/19 17:39	General View		Load JPG	
7	23/10/19 17:39	General View		Load JPG	
8	23/10/19 17:39	General View		Load JPG	
9	23/10/19 17:39	General View		Load JPG	
10	23/10/19 17:39	General View		Load JPG	
11	23/10/19 17:39	General View		Load JPG	
12	23/10/19 17:39	General View		Load JPG	
13	23/10/19 17:39	General View		Load JPG	
14	23/10/19 17:39	General View		Load JPG	
15	23/10/19 17:39	General View		Load JPG	
16	23/10/19 17:39	General View		Load JPG	
17	23/10/19 17:39	General View		Load JPG	
18	23/10/19 17:39	General View		Load JPG	
19	23/10/19 17:39	General View		Load JPG	
20	23/10/19 17:39	General View		Load JPG	
21	23/10/19 17:39	General View		Load JPG	
22	23/10/19 17:39	General View		Load JPG	
23	23/10/19 17:39	General View		Load JPG	
24	23/10/19 17:39	General View		Load JPG	
25	23/10/19 17:39	General View		Load JPG	
26	23/10/19 17:39	General View		Load JPG	
27	23/10/19 17:39	General View		Load JPG	
28	23/10/19 17:39	General View		Load JPG	
29	23/10/19 17:39	General View		Load JPG	
30	23/10/19 17:39	General View		Load JPG	
31	23/10/19 17:39	General View		Load JPG	
32	23/10/19 17:39	General View		Load JPG	
33	23/10/19 17:39	General View		Load JPG	
34	23/10/19 17:39	General View		Load JPG	
35	23/10/19 17:39	General View		Load JPG	
36	23/10/19 17:39	General View		Load JPG	
37	23/10/19 17:39	General View		Load JPG	
38	23/10/19 17:39	General View		Load JPG	
39	23/10/19 17:39	General View		Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
40	23/10/19 17:39	General View	 Load JPG	☒
41	23/10/19 17:39	General View	 Load JPG	☒
42	23/10/19 17:39	General View	 Load JPG	☒
43	23/10/19 17:39	General View	 Load JPG	☒
44	23/10/19 17:39	General View	 Load JPG	☒
45	23/10/19 17:39	General View	 Load JPG	☒
46	23/10/19 17:39	General View	 Load JPG	☒
47	23/10/19 17:39	General View	 Load JPG	☒
48	23/10/19 17:39	General View	 Load JPG	☒
49	23/10/19 17:39	General View	 Load JPG	☒
50	23/10/19 17:39	General View	 Load JPG	☒
51	23/10/19 17:39	General View	 Load JPG	☒
52	23/10/19 17:39	General View	 Load JPG	☒
53	23/10/19 17:39	General View	 Load JPG	☒
54	23/10/19 17:39	General View	 Load JPG	☒
55	23/10/19 17:39	General View	 Load JPG	☒
56	23/10/19 17:39	General View	 Load JPG	☒
57	23/10/19 17:39	General View	 Load JPG	☒
58	23/10/19 17:39	General View	 Load JPG	☒
59	23/10/19 17:39	General View	 Load JPG	☒
60	23/10/19 17:39	General View	 Load JPG	☒
61	23/10/19 17:39	General View	 Load JPG	☒
62	23/10/19 17:39	General View	 Load JPG	☒
63	23/10/19 17:39	General View	 Load JPG	☒
64	23/10/19 17:39	General View	 Load JPG	☒
65	23/10/19 17:39	General View	 Load JPG	☒
66	23/10/19 17:39	General View	 Load JPG	☒
67	23/10/19 17:39	General View	 Load JPG	☒
68	23/10/19 17:39	General View	 Load JPG	☒
69	18/11/19 10:16	Reinspection Photo	 Load JPG	☒
70	18/11/19 10:16	Reinspection Photo	 Load JPG	☒
71	18/11/19 10:16	Reinspection Photo	 Load JPG	☒
72	18/11/19 10:16	Reinspection Photo	 Load JPG	☒
73	18/11/19 10:16	Reinspection Photo	 Load JPG	☒
74	18/11/19 10:16	Reinspection Photo	 Load JPG	☒
75	18/11/19 10:16	Reinspection Photo	 Load JPG	☒
76	18/11/19 10:16	Reinspection Photo	 Load JPG	☒
77	18/11/19 10:16	Reinspection Photo	 Load JPG	☒
78	18/11/19 10:16	Reinspection Photo	 Load JPG	☒
79	18/11/19 10:16	Reinspection Photo	 Load JPG	☒
80	21/11/19 14:53	Reinspection Photo	 Load JPG	☒
81	21/11/19 14:53	Reinspection Photo	 Load JPG	☒
82	21/11/19 14:53	Reinspection Photo	 Load JPG	☒
83	21/11/19 14:53	Reinspection Photo	 Load JPG	☒
84	21/11/19 14:53	Reinspection Photo	 Load JPG	☒
85	21/11/19 14:53	Reinspection Photo	 Load JPG	☒
86	21/11/19 14:53	Reinspection Photo	Load JPG	☒
87	21/11/19 14:53	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/10/19 11:40	Appointed LKK to survey vehicle	 Load PDF	
2	21/10/19 13:28	Estimate	 Load PDF	
3	21/10/19 13:28	Transfer Fee Enquiry	 Load PDF	
4	21/10/19 13:28	PARF_COE Rebate Enquiry	 Load PDF	
5	21/10/19 13:29	OI Accident Report - Addendum #1	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	21/10/19 13:33	Survey Request - Manual Assigned	 Load PDF	

Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
2	21/10/19 13:33	LKK Auto Consultants Pte Ltd (HQ)			
		Outsource Instruction		Load PDF	
No	Relabel/Reorder			Thumbnail	Print
1	22/10/19 13:49	LKK Auto Consultants Pte Ltd (HQ)			
		ESTIMATE.pdf		Load PDF	
2	22/10/19 13:49	SLC 3663J GIA.pdf			
3	22/10/19 13:49	POLICE REPORT.pdf			
4	18/11/19 10:15	SUPP.pdf			
5	21/11/19 14:54	ESTIMATE & SUPP MARKED.pdf			

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
1	11/10/19 16:48	STA INSPECTION PTE LTD (Sin Ming)			
		Accident Statement		Load HTM	
2	19/10/19 09:11	Addendum Sheet			
3	19/10/19 09:13	Accident Statement Addm. #1			
Photos/Images				3 per page	☒
No	Finalized On			Thumbnail	Print
1	11/10/19 16:46	STA INSPECTION PTE LTD (Sin Ming)			
		Accident Photo		Load JPG	☒
2	11/10/19 16:46	Accident Photo			☒
3	11/10/19 16:46	Accident Photo			☒
4	11/10/19 16:46	Accident Photo			☒
5	11/10/19 16:46	Accident Photo			☒
6	11/10/19 16:46	Accident Photo			☒
7	11/10/19 16:46	Accident Photo			☒
8	11/10/19 16:46	Accident Photo			☒
9	11/10/19 16:46	Accident Photo			☒
10	11/10/19 16:46	Accident Photo			☒
11	11/10/19 16:46	Accident Photo			☒
12	11/10/19 16:46	Accident Photo			☒
Documentation				1 per page	☒
No	Finalized On			Thumbnail	Print
1	11/10/19 16:46	STA INSPECTION PTE LTD (Sin Ming)			
		Sketch Plan		Load TIF	
2	11/10/19 16:46	Sketch Plan #2			
3	11/10/19 16:47	Common Statement			
4	11/10/19 16:47	Common Statement			
5	11/10/19 16:47	Common Statement			

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19018535/R1SD3E2

Date: 27/11/2019

REFERENCE

Insured/Claimant:	Seah Ngee Boon	Policy No:	29123465	
Date of Loss:	08/10/2019	Nature of Claim:	OD	Claim No: 608425

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC3663J		
Make & Model:	MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A)	Engine No:	27491030529699
Reg. Date:	28/04/2016 (Man. Year: 2016)	Chassis No:	WDD2050402R154602
Colour:	Grey	Odometer:	55367 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	S\$107,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,966.67	10,509.23	7,457.44	41.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,780.00	9,260.00	2,520.00	21.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,746.67	19,769.23	9,977.44	33.54
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	29,246.67	19,269.23	9,977.44	34.11
+ GST 7.00/7.00% (S\$)	2,047.27	1,348.85	698.42	34.11
Nett Amount (S\$)	31,293.94	20,618.08	10,675.86	34.11

INSPECTION

Date of Assignment: 21/10/2019

Date Inspected: 22/10/2019 Inspected At:

Cycle & Carriage Industries Pte Ltd
(Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Nov 2019)
Parts:	143	MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC3663J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE WITH HOUSING	Bent	60.00 FS	*60.00 FS
2	1		*FRONT BUMPER	Cut	1,557.32 FS	*1,557.32 FS
3	1		*UPPER BUMPER COVER SEALING	Serviceable	27.55 FS	*- FS
4	2		*DISTANCE SENSOR	Serviceable	352.22 FS	*- FS
5	2		*SPACER RING	Serviceable	12.70 FS	*- FS
6	1		*LICENSE PLATE MOLDING	Deformed	126.10 FS	*126.10 FS
7	1		*BOTTOM BASIC MOUNTING FOR BUMPER	Serviceable	139.42 FS	*- FS
8	1		*TOP BASIC MOUNTING FOR BUMPER	Serviceable	86.01 FS	*- FS
9	1		*IMPACT ABSORBER	Serviceable	158.73 FS	*- FS
10	4		*BLIND RIVET	Necessary	17.72 FS	*17.72 FS
11	1		*LEFT MOUNTING RAIL	Serviceable	12.19 FS	*- FS
12	1		*RIGHT MOUNTING RAIL	Serviceable	12.50 FS	*- FS
13	1		*FRONT AIR DUCT	Serviceable	127.48 FS	*- FS
14	1		*COMPANY SIGN	Not Necessary	77.91 FS	*- FS
15	1		*HOOD	Repair	2,083.09 FS	*- FS
16	1		*FRONT SUPPORT CONSOLE	Serviceable	209.91 FS	*- FS
17	1		*CROSS MEMBER	Serviceable	423.49 FS	*- FS
18	1		*REAR BUMPER	Deformed	1,635.44 FS	*1,635.44 FS
19	1		*CENTRE BASIC MOUNTING FOR BUMPER	Serviceable	91.92 FS	*- FS
20	1		*LHR BASIC MOUNTING FOR BUMPER	Serviceable	56.64 FS	*- FS
21	1		*RHR BASIC MOUNTING FOR BUMPER	Serviceable	56.64 FS	*- FS
22	1		*LHR BRACKET	Cracked	33.30 FS	*33.30 FS
23	1		*RHR BRACKET	Cracked	33.96 FS	*33.96 FS
24	1		*REAR LOWER CENTER BUMPER COVER	Missing	104.89 FS	*104.89 FS
25	1		*REAR MODULE BRACKET	Serviceable	39.80 FS	*- FS
26	1		*REAR SWITCHING MODULE	Serviceable	307.73 FS	*- FS
27	1		*REAR SWITCH MODULE, CODE A	Serviceable	121.95 FS	*- FS
28	1		*REAR SWITCH MODULE, CODE B	Serviceable	121.95 FS	*- FS
29	1		*REAR LOWER BUMPER	Deformed	217.29 FS	*217.29 FS
30	1		*REAR BUMPER CENTRE CHROME MOULDING	Cracked	255.71 FS	*255.71 FS
31	4		*BLIND RIVET	Necessary	17.72 FS	*17.72 FS
32	1		*DISTANCE SENSOR (6PCS)	Cut (1Pc Only)	1,056.66 FS	*176.11 FS
33	6		*SPACER RING	Not Necessary	38.10 FS	*- FS
34	2		*BLIND RIVET	Not Necessary	8.86 FS	*- FS
35	1		*LHR BUMPER EXHAUST COVER	Serviceable	97.89 FS	*- FS
36	1		*LHR SIDE STABILITY	Serviceable	55.82 FS	*- FS
37	1		*RHR SIDE STABILITY	Serviceable	56.01 FS	*- FS
38	1		*TOP LEFT BASIC MOUNTING FOR BUMPER	Necessary	32.64 FS	*32.64 FS
39	1		*TOP RIGHT BASIC MOUNTING FOR BUMPER	Necessary	32.14 FS	*32.14 FS
40	1		*REAR CROSS MEMBER	Serviceable	651.93 FS	*- FS
41	1		*LOAD COMPARTMENT WELL	Cracked	538.00 FS	*538.00 FS
42	1		*COVER, REAR-END FLOOR	Missing	41.34 FS	*41.34 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR END PANEL	Bent	1,414.23 FS	*1,414.23 FS
44	1		*LEFT REAR LAMP COMBINATION	Serviceable	702.52 FS	*- FS
45	1		*RIGHT REAR LAMP COMBINATION	Cracked	702.52 FS	*702.52 FS
46	1		*LHR GASKET TAIL LIGHT HOUSING	Serviceable	31.64 FS	*- FS
47	1		*RHR GASKET TAIL LIGHT HOUSING	Serviceable	31.64 FS	*- FS
48	1		*TRUNK LID	Bent	2,127.67 FS	*2,127.67 FS
49	1		*REAR BOOT WEATHER-STRIP	Necessary	195.71 FS	*195.71 FS
50	1		*REAR BOOT CHROME MOULDING	Necessary	132.35 FS	*132.35 FS
51	3		*SEALING GROMMET	Necessary	6.60 FS	*6.60 FS
52	1		*MERCEDES STAR	Necessary	47.69 FS	*47.69 FS
53	1		*C180 MODEL PLATE	Necessary	89.09 FS	*89.09 FS
54	1		*REAR ELECTRICAL WIRING HARNESS	Serviceable	382.65 FS	*- FS
55	1		*TS TWO-COMPONENT ADHESIVE	Necessary	776.81 FS	*776.81 FS
56	18		*BLIND RIVET	Necessary	23.22 FS	*23.22 FS
57	4		*RIVET	Necessary	10.04 FS	*10.04 FS
58	1		*LHR BRACKET	Necessary	27.86 FS	*27.86 FS
59	4		*HEXAGON NUT W COLLAR	Necessary	10.04 FS	*10.04 FS
60	2		*RETAINER WEDGE	Necessary	23.06 FS	*23.06 FS
61	4		*NUT	Necessary	21.48 FS	*21.48 FS
62	2		*RETAINER WEDGE	Necessary	21.18 FS	*21.18 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	17,966.67	10,509.23
--------------------	-----------	-----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
2	REMOVE REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
3	REMOVE & INSTALL INTERIOR GARNISH, SEAT AND UPHOLSTERY FOR NECESSARY REPAIR	New	960.00	480.00
4	REMOVE & REPLACE ON FRONT BUMPER, BONNET, REAR BUMPER, END PANEL	New	6,720.00	5,280.00
5	RESPRAY ON FRONT BUMPER, BONNET, REAR BUMPER, END PANE, BOOT	New	3,600.00	3,000.00
Gross Labour Cost (S\$)			11,780.00	9,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >