



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2005154
INV Date 23/07/2020
Reference CC4/LPC19018536/Aea3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SFB 3339Y
Insured Veh. YN 1247D
Claim No. 19/19/19/VC05/022537
Policy No. Z19VC05002486
Accident Date 18/10/2019
Inspection Date 21/10/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19018536/Aea3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 23-07-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 1247D	Veh. Inspected	SFB 3339Y	
Policy No.	Z19VC05002486	Coverage (\$)	0.00	
Claim No.	19/19/19/VC05/022537	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	21/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	MR053ZEE106161603	Colour	BLUE	
Odometer	157747	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS				
5. General Information				
Accident Date	18/10/2019	Inspection Date	21/10/2019	
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFB 3339Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEAD LAMP LH	CRACKED	392.45	392.45
1	FRONT FENDER	DISTORTED	581.90	581.90
1	FRONT FENDER SPLASH SHIELD	NOT NECESSARY	181.60	-
8	FRONT FENDER SPLASH SHIELD CLIPS @\$12.90	NOT NECESSARY	103.20	-
1	FRONT FENDER EMBLEM 'VVTI'	NECESSARY	83.75	83.75
1	FRONT BUMPER FASCIA	TORN	561.60	561.60
1	FRONT BUMPER SIDE RETAINER LH	NECESSARY	125.10	48.00
8	FRONT BUMPER CLIPS @\$12.90	NECESSARY	103.20	30.00
1	SIDE MIRROR LH	DAMAGED	987.30	987.30
1	SIDE MIRROR COVER	TO REPAIR SEE LABOUR	151.20	-
	LESS 25% DISCOUNT		-817.83	-671.25
			2,453.47	2,013.75
	<u>LABOUR</u>			
	TO CHECK WIRING SYSTEM.		60.00	30.00
	TO TUFF COAT AFFECTED AREAS.		120.00	30.00
	TO CHECK & ADJUST COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO RESPRAY AFFECTED AREAS.		800.00	600.00
	TO RENEW DAMAGED PARTS ,STRAIGHTEN & REPAIR FRONT LH WHEEL HOUSING PANEL ,BONNET & ALIGNED ALL PARTS.INCLUSIVE OF THE REPAIR OF SIDE MIRROR COVER .		800.00	400.00
			1,900.00	1,060.00
GRAND TOTAL			4,353.47	3,073.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CC4/LPC19018536/Aea3n2

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFB 3339Y

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

