

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

07-11-19

Date Of Accident : 18-10-19

OUR REF : SFB 3339Y/T/19

Joyride Car Rental Pte Ltd

1 Kaki Bukit Ave 6

#02-34 (BLK D)

Singapore 417883

Lkk - Adrian

Date In/cut: 18/10/19 to 30/10/19
7P on Poc
Asher.

ESTIMATE BILL ON VEH. NO. : SFB 3339Y

MODEL : TOYOTA ALTIS

CHASSIS NO. : MR053ZEE106161603

LIST ITEM

Head Lamp LH	Cracked.	✓	392.45
Front Fender	Distorted	✓	581.90
Front Fender Splash Shield	{ 14 rev	X	181.60
Front Fender Splash Shield Clips	8pcs @ 12.90	X	103.20
Front Fender Emblum "VVTi"	NEC	✓	83.75
Front Bumper Fascia	torn	✓	561.60
Front Bumper Side Retainer LH	NEC	48	125.10
Front Bumper Clips	8pcs @ 12.90	30	103.20
Side Mirror LH	Damaged	2685	✓ 987.30
Side Mirror Cover	Regis	2013.75	X 151.20
			3,271.30
Less Discount 25%:			817.83
			2,453.48

LABOUR CHARGE

To check wiring system	30	60.00
To tuff coat affected areas	30	120.00
To check & adjust computer wheel alignment	X	120.00
To respray affected areas	600	800.00

To renew damaged parts, straighten & repair front LH wheel housing panel, bonnet & aligned all parts

1060

400. 800.00

GST 7% :

TOTAL AMOUNT :

4,353.48

304.74

4,658.22

total: 3073.75

L/S: 2 HK ✓

0 Days ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: