

INS. CASE OWNER:

SHERINI

CC4/III19018538/Upa3

LKK:

IDAC:

Surveyor:

MARCUS

DOI: 18/10/2019

Date / Time: 18/10/2019

Registered in Merimen: 21/10/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SHC 2602P

Claim No. :

Name of Insured : COMFORT TRANSPORTATION PTE LTD

Policy No. :

MCOM0015

Insured Tel No. : HP:

Make / Model :

HYUNDAI I40

Excess Sec II :SS D.O.A : 17/10/2019 19:45

Place of Accident :

TPE(PIE) PUNGGOL ENTRANCE

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : LIM KIAN HUAT

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. : +65-81271878 (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SKM 7636X

INSRS:
WSP: ZOOM
Tel: AUTOWERKS
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/>
	LTA / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PIR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>
PRELIMINARY ADVICE Date/Time: Sent By:		
FINALIZATION Date/Time: Confirm with: Confirm by:		
Repair Cost:	SS	days) Reduction: % Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT Date/Time: Confirm with: Email <input checked="" type="checkbox"/> Call <input checked="" type="checkbox"/>		
Final Liability:	9E (Agreed / Assessed) BOLA S/N No. : 012	If NO or B 28, Ass. Lia :
Repair Cost:	SS 5600.00	
Loss of Rental (LOR):	SS (days)	
Loss of Use (LOU):	SS 540.00 (\$ 60 x 9 days)	
Loss of Income (LOI):	SS (\$ x days)	
LOR only <input type="checkbox"/> LOU only <input checked="" type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]	
GIA/LTA Search:	SS 36.45	
Medical:	SS =	1) Claim status: Normal/Reject/Private Settle
Disbursement:	SS = (e.g. Tow/ Independent)	2) Report Format:
Legal Cost:	SS =	3) Survey fee: \$ 500.00
Total:	SS 6176.45 Global Sum SS:	
FINAL PAYMENT Date/Time: Confirm with: Email <input checked="" type="checkbox"/> Call <input checked="" type="checkbox"/>		
Payee 1:	SS 6176.45 Name 1: Zoom Autowerks Pte Ltd	
Payee 2: (Strike if N.A.)	SS Name 2:	
Payee 3: (Strike if N.A.)	SS Name 3:	

20/10/19 - III ✓ DS

30/10/19 - File -> Marcus to finalize

11/11/19 - File -> type machine

19/11/19 - DV sent

24/12/19 - File -> MIC to close

COPY SENT
23/11/19



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

18 October 2019

ACCIDENT DATE: 17 October 2019
 OWNER: CHEN JING HUA

Not Authorized
 take photo after repair
 18/10/19
 2/5 @ \$600 / 9 day

REG NO.: SKM 7636 X
 MAKE/MODEL: TOYOTA VIOS

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	LIST ITEMS	
1	Rear windscreen moulding	\$ 11 82.10 X
1	Rear boot lid <i>659.20</i>	\$ PD/SUC 781.70 ✓
2	Rear boot hinges <i>64.90</i>	\$ OLS/TM 129.80 120
1	Rear boot inner lock	\$ TWI 145.60 ✓
1	Rear boot logo	\$ REU 48.50 ✓
1	Rear boot weatherstrip	\$ TWI 181.20 ✓
1	Rear boot "VIOS" emblem	\$ REU 42.90 ✓
1	Rear boot "E" emblem	\$ REU 38.90 ✓
1	Rear boot number plate garnish	\$ IN 98.30 X
2	Rear taillamps	\$ CRA 671.80 ✓
2	Rear taillamp panels	\$ R 337.30 X
1	Rear end panel <i>617.30</i>	\$ Sub/D 775.90 ✓
1	Rear end panel inner garnish <i>186.30</i>	\$ TWI 211.10 ✓
1	Rear bumper <i>363.10</i>	\$ DIS 685.50 ✓
2	Rear bumper brackets	\$ SUC 171.00 X
2	Rear bumper reflectors <i>92.90</i>	\$ O/S/CR 185.80 120
2	Rear bumper side retainers	\$ BEU 97.30 ✓
1	Rear floor panel	\$ CRAMP/SUC 782.90 ✓
1	Rear floor board	\$ TORN 183.60 ✓
2	Rear floor side boards	\$ BE/TORN 170.24 ✓
1	Rear exhaust silencer <i>525.10</i>	\$ BEU 654.20 ✓
2	Rear exhaust mountings	\$ 11 97.00 X
2	Rear fenders	\$ R 1,745.80 X
2	Rear fender inner air vents	\$ 11 179.20 X
2	Rear fender inner trims	\$ BE/TORN 461.60 ✓
		\$ 8,959.24
	Less 25%	\$ 2,239.81
		\$ 6,719.43

P-5332.34
 25%
 P-3999.25
 S.N-245.00
 L-2770.00
 7014.25
 202
 5611.40

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$ 17	80.00	X
1	Rear bumper clip (1 set)	\$ nu	45.00	✓
1	Rear number plate with holder	\$ 50	50.00	X
1	Rear reverse sensor (1 set)	\$ Shorted	350.00	200 s.n
		\$	<u>525.00</u>	

S/N LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	30
2	To remove and refit inner garnishes.	\$	150.00	80
3	To remove and refit rear reverse sensor.	\$	150.00	50
4	To transfer boot lid mechanism and wiring assembly.	\$	120.00	60
5	To remove and refit rear windscreen glass.	\$ 17	180.00	X
6	To remove, refit and replace exhaust silencer and mountings.	\$	150.00	60
7	To apply undercoating.	\$	200.00	90
8	Panel beating.	\$	1,800.00	1300
9	To re-spray painting on the affected areas.	\$	1,600.00	1100
		\$	<u>4,430.00</u>	
				2770.00

GRAND TOTAL :

\$ 11,674.43

LKK Auto Consultants hence notify the Repairer of the following:

- To receive before/after spray painting
- To supply damaged parts during resurvey
- Parts prices are subject to confirmation
- This entry survey is on a "Without Prejudice" basis
- No further modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	244I
Vehicle Details	
Vehicle No.:	SKM7636X
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS G AUTO
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	1NZX913014
Chassis No.:	MR053HY9305114669
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,876.00
Original Registration Date:	03 Jun 2009
First Registration Date:	03 Jun 2009
Transfer Count:	3
Actual ARF Paid:	\$13,876.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 May 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,943.00
COE Rebate Amount:	\$12,856.00
Total Rebate Amount:	\$12,856.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 21 Oct 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

ATTRACTIVE BMW 523I DEAL!



Top Condition, Metallic Blue,
With (Lease) Being (Import)
(Warranty Covered)
StarAd

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality work
- Member of SVTA and hire purchase approved
- 100% deposit refund for unapproved

YONG LEE SENG MOTOR

Browse by Category

« Back (1 2 3 4 5 6) Next »

Sort by Date Posted

113 vehicles

vios

Advanced Search

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection vios	Any	Any	> 10 year(s) old	Any	Any	Any
 Toyota Vios 1.5A E (New 5-yr COE)	\$29,500	\$5,890 /yr	28-Sep-2009	1,497 cc	-	Sedan
1st Owner, Serviced By Borneo Motors. Option For New 10 Years COE At \$44.8k.						
Posted: 21-Oct-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota						
 Toyota Vios 1.5A E (COE till 08/2024)	\$25,800	\$5,350 /yr	17-Aug-2009	1,497 cc	-	Sedan
2.88%P.A By GV Inhouse Financing. No Admin Fees! STA Graded B! All Wear & Tear Done! 2 Years Warranty Engine And Gearbox. New Paintwork Of Your Choice! New Leathers! New Rims And Tyres Of Your Choice! New Pioneer DVD Player! New Recording Camera Front...						
GV Credit Pte Ltd						
Posted: 20-Oct-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota						
 Toyota Vios 1.5A E (COE till 07/2024)	\$25,800	\$5,450 /yr	15-Jul-2009	1,497 cc	-	Sedan
Graded B by STR						
2.88%P.A By GV Inhouse Financing. No Admin Fees! STA Graded B! All Wear & Tear Done! 2 Years Warranty Engine And Gearbox. New Paintwork Of Your Choice! New Leathers! New Rims And Tyres Of Your Choice! New Pioneer DVD Player! New Recording Camera Front...						
GV Credit Pte Ltd						
Posted: 20-Oct-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota						
 Toyota Vios 1.5A E (New 5-yr COE)	\$25,800	\$5,150 /yr	07-Aug-2009	1,497 cc	-	Sedan
2.88%P.A By GV Inhouse Financing. No Admin Fees! STA Graded B! All Wear & Tear Done! 2 Years Warranty Engine And Gearbox. New Paintwork Of Your Choice! New Leathers! New Rims And Tyres Of Your Choice! New Pioneer DVD Player! New Recording Camera Front...						
GV Credit Pte Ltd						
Posted: 20-Oct-2019 Tags: 2009 Toyota Vios, 2009 toyota vios, Toyota Vios, toyota vios, Toyota, Vios, vios, Used Toyota						

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and approval in 2 days without effort! Enquire today.

Compare

18/10/19

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 18 October 2019 2:50 PM
To: Zoom Autowerks; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Sherini Pillai
Subject: RE: Pre-Repair Inspection for SKM 7636 X// Accident on 17/10/2019 @ 19:40HR at along TPE(PIE), Sengkang East Road Entrance involving Vehicle Number SKM 7636 X & SHC 2602 P
Attachments: SKM 7636 X.PDF

2.08pm @ 18/10/19
 vehicle In
 p: Elaine
 s: Marcus

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SKM7636X and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
 Singapore 049711
 Tel: 6347 6100, Ext - 248

From: Zoom Autowerks [mailto:zoomautowerks@gmail.com]
Sent: 18 October, 2019 2:37 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Subject: Re: Pre-Repair Inspection for SKM 7636 X// Accident on 17/10/2019 @ 19:40HR at along TPE(PIE), Sengkang East Road Entrance involving Vehicle Number SKM 7636 X & SHC 2602 P

Dear all,

Kindly arrange lkk.

On Fri, Oct 18, 2019, 14:36 Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: Zoom Autowerks [<mailto:zoomautowerks@gmail.com>]

Sent: 18 October, 2019 11:17 AM

To: Gabriel Wee <Gabriel@iii.com.sg>; Motor Claim - III <motorclaim@iii.com.sg>

Subject: Pre-Repair Inspection for SKM 7636 X// Accident on 17/10/2019 @ 19:40HR at along TPE(PIE), Sengkang East Road Entrance involving Vehicle Number SKM 7636 X & SHC 2602 P

Dear Sir/Madam,

We are instructed by Chen Jing Hua to notify you of a road traffic accident on 17

/10/2019

at about 19:40HR at along TPE(PIE), Sengkang East Road Entrance involving our client's vehicle registration number SKM 7636 X and vehicle registration number SHC 2602 P driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 4178 08.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached

you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Hsiao Tong (LKKAuto)

From: Zoom Autowerks <zoomautowerks@gmail.com>
Sent: Friday, 1 November 2019 3:01 PM
To: Hsiao Tong (LKKAuto)
Subject: Letter of Claim SKM 7636 X
Attachments: combinepdf (2).pdf

Dear Hsiao Tong,

- Without Prejudice -

Enclosed please find Letter of Claim for your kind attention.

Look forward to your favorable reply.

Warmest Regards,
Elin Cai

Zoom Autowerks Pte Ltd
130 Bedok Reservoir Road
#08-1339 Singapore 470130
☎9450 7920
✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

Claim Audit

AUDIT TRAIL				
No.	Dn	Audit	Remarks	By
1	21 Oct 2019 15:42	Cim Dtl Modified	Claimant's Name: -> CHEN JING HUA, Claimant's ID: -> S80842441.	[A] HOW MEI KWAN
2	21 Oct 2019 15:42	Cim Veh Model Changed	(201044) TOYOTA VIOS 1.5 G (A).	[A] HOW MEI KWAN
3	21 Oct 2019 15:42	Cim Created	Reg No: SKM7636X, Acct Date: 2019/10/17, Claim Type: TP, Insurer: India International Insurance Pte Ltd (HQ), TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ), Workshop: Zoom Autowerks Pte Ltd (Bedok)	[A] HOW MEI KWAN
4	21 Oct 2019 15:42	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	21 Oct 2019 15:42	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/31	[A] HOW MEI KWAN
6	21 Oct 2019 15:42	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	21 Oct 2019 15:43	Label Added	(30653):Direct Settlement.	[A] HOW MEI KWAN
8	21 Oct 2019 15:43	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HOW MEI KWAN
9	26 Oct 2019 08:52	Adj Mandate Request	Cur.Req:0.00:PODS Liability: 100% (BOLA 27)	[A] CHEW HSIAO TONG
10	29 Oct 2019 08:51	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/31	[I] Sherini Pillai
11	29 Oct 2019 08:51	Adj Mandate Set	Approved:0.00.	[I] Sherini Pillai
12	20 Nov 2019 12:07	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN
13	20 Nov 2019 12:07	Cim Dtl Modified	Insured Name: -> -. Insured ID: -> -.	[A] JOANNE LEE KHANG MIN
14	20 Nov 2019 12:07	Cim Dtl Modified	JPJ Reg. Date: -> 2009/06/03.	[A] JOANNE LEE KHANG MIN
15	20 Nov 2019 12:07	Cim Details Notified		[A] JOANNE LEE KHANG MIN
16	22 Nov 2019 08:42	Adj Mandate Request	Cur.Req:6176.45:PODS Liability: 100% *Quantum: (a)COR: \$5,600.00 + (b)LOU(9days x \$60.00): \$540.00 + (c)LTA/GIA search fee: \$36.45 = Total: \$6,176.45 *Vehicle Model: Toyota Vios (1497cc) *9 recommendation repair days *For your approval please.	[A] CHEW HSIAO TONG

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc. Typm	Acc Name	Co Name (Business)	Ref 1	Ref 2	Amount
2320484	22 Oct 2019 08:46:48	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International	SKM7636X	SHC2602P	11.77

Print Received Message

This mail is associated with :

*SKM7636X (MCT19100400)
[SHC2602P]
TP
CHEN JING HUA
Oct 17 2019 7:00PM
[-]
Zoom Autowerks Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 27/11/2019 10:00 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6176.45) - SKM7636X - Claim Handler: Sherini Pillai

Approved:6176.45:Please upload GIA and LTA receipt

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Nov 2019 Edit Reg		18 Oct 2019 00:00 Edit Adj Rpt	S\$5,600.00 Edit Estimates	S\$5,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	CHEN JING HUA , ID: S80842441								
Vehicle Reg. No.:	SKM7636X	Date of Loss:	17/10/2019 19:00 - :59 [124 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19100400	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC2602P	Policy No. (Claimant):	5109855384						
		Excess:							
Repairer:	Zoom Autowerks Pte Ltd (Bedok) 130 Bedok Reservoir Road, #08-1339, 470130 Eunos - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 31/10/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
<ul style="list-style-type: none"> • III_SG (27/11/2019): Alert - Adj Mandate Approved (S\$6176.45) - SKM7636X - Claim Handler: Sherini Pli... • III_SG (29/10/2019): Alert - Adj Mandate Approved (S\$0.00) - SKM7636X - Claim Handler: Sherini Pillai 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKM7636X (MCT19100400)
 [SHC2602P]
 TP
 CHEN JING HUA
 Oct 17 2019 7:00PM
 [COMFORT TRANSPORTATION PTE LTD]
 Zoom Autowerks Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/11/19 11:03	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
3	01/11/19 11:03	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
4	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
5	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
6	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
7	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
8	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
9	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
10	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
11	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
12	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
13	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
14	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
15	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
16	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
17	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
18	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
19	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
20	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
21	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
22	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
23	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
24	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
25	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
26	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
27	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
28	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
29	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
30	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
31	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
32	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
33	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
34	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
35	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
36	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
37	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
38	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
39	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
40	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
41	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
42	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
43	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
45	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
46	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
47	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
48	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
49	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
50	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
51	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
52	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
53	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
54	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
55	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
56	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
57	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
58	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
59	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
60	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
61	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
62	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
63	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
64	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
65	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
66	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
67	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
68	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
69	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
70	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
71	01/11/19 11:03	General View	 Load JPG	<input checked="" type="checkbox"/>
72	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	01/11/19 11:03	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	01/11/19 11:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
91	01/11/19 11:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
92	01/11/19 11:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
93	01/11/19 11:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
94	01/11/19 11:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
95	01/11/19 11:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
96	01/11/19 11:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
97	01/11/19 11:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
98	01/11/19 11:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
99	01/11/19 11:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
101	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
102	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
103	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
104	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
105	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
106	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
107	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
108	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
109	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
110	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
111	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
112	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
113	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
114	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
115	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
116	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
117	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
118	01/11/19 11:03	Reinspection Photo		<input checked="" type="checkbox"/>
119	04/11/19 08:33	After Repair Photo		<input checked="" type="checkbox"/>
120	04/11/19 08:33	After Repair Photo		<input checked="" type="checkbox"/>
121	04/11/19 08:33	After Repair Photo		<input checked="" type="checkbox"/>
122	04/11/19 08:33	After Repair Photo		<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/10/19 15:43	TP GIA REPORT		<input type="checkbox"/>
2	21/10/19 15:43	ACKNOWLEDGEMENT EMAIL TO III DD 18.10.19		<input type="checkbox"/>
3	01/11/19 11:06	TP ESTIMATE_MARKED		<input type="checkbox"/>
4	01/11/19 11:06	PARF_COE REBATE		<input type="checkbox"/>
5	30/11/19 09:20	LOD		<input type="checkbox"/>
6	30/11/19 09:20	Authorisation to Act		<input type="checkbox"/>
7	30/11/19 09:20	LTA Search Fee		<input type="checkbox"/>
8	30/11/19 09:20	GIA RPT Search Fee.		<input type="checkbox"/>
9	27/12/19 15:48	DISCHARGE VOUCHER		<input type="checkbox"/>
10	27/12/19 15:48	WORKSHOP INVOICE		<input type="checkbox"/>

No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	22/10/19 08:46	Singapore Accident Statement		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19018538/UPA3Q2

Date: 27/12/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant		Insured Vehicle No :	SHC2602P
Vehicle No :	SKM7636X		
Date of Loss:	17/10/2019	Nature of Claim:	TP
		Claim No:	MCT19100400

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM7636X	Engine No:	1NZX913014
Make & Model:	TOYOTA VIOS, 1.5 G (A)	Chassis No:	MR053HY9305114669
Reg. Date:	03/06/2009 (Man. Year: 2009)	Odometer:	150011 km
Colour:	Red		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,244.43	4,244.25	3,000.18	41.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	2,770.00	1,660.00	37.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,674.43	7,014.25	4,660.18	39.92
Approved Total (Overridden) (S\$)		5,600.00		
Nett Amount (S\$)	11,674.43	5,600.00	6,074.43	52.03
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,176.45		

INSPECTION

Date of Assignment:	18/10/2019	
Date Inspected:	18/10/2019 Inspected At:	Zoom Autowerks Pte Ltd (Bedok) 130 Bedok Reservoir Road, #08-1339 Singapore 470130
Estimated Period of Repair:	9.0 days	

Adjuster: MARCUS CHUA

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

Market Value: \$24,000.00(est) less LTA Rebate: \$12,856.00(est) = Nett Value :\$11,144.00(est).

Please note that third party COE Expiry Date is 31 May 2024.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2019)
Parts: 143	TOYOTA VIOS 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKM7636X)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	82.10 FL	*- FL
2	1		*REAR BOOT LID	Dented / Buckled	781.70 FL	*659.20 FL
3	1		*REAR BOOT HINGES	O/S Twisted	129.80 FL	*64.90 FL
4	1		*REAR BOOT INNER LOCK	Twisted	145.60 FL	*145.60 FL
5	1		*REAR BOOT LOGO	Necessary	48.50 FL	*48.50 FL
6	1		*REAR BOOT WEATHERSTRIP	Twisted	181.20 FL	*181.20 FL
7	1		*REAR BOOT VIOS EMBLEM	Necessary	42.90 FL	*42.90 FL
8	1		*REAR BOOT G EMBLEM	Necessary	38.90 FL	*38.90 FL
9	1		*REAR BOOT NUMBER PLATE GARNISH	Not Necessary	98.30 FL	*- FL
10	2		*REAR TAILLAMPS	Cracked	671.80 FL	*671.80 FL
11	2		*REAR TAILLAMP PANELS	Repair	337.30 FL	*- FL
12	1		*REAR END PANEL	Badly Dented	775.90 FL	*617.30 FL
13	1		*REAR END PANEL INNER GARNISH	Twisted	211.10 FL	*185.30 FL
14	1		*REAR BUMPER	Distorted	685.50 FL	*363.10 FL
15	2		*REAR BUMPER BRACKETS	Serviceable	171.00 FL	*- FL
16	1		*REAR BUMPER REFLECTORS	O/S Cracked	185.80 FL	*92.90 FL
17	2		*REAR BUMPER SIDE RETAINERS	Bent	97.30 FL	*97.30 FL
18	1		*REAR FLOOR PANEL	Crumpled / Buckled	782.90 FL	*782.90 FL
19	1		*REAR FLOOR BOARD	Torn	183.60 FL	*183.60 FL
20	2		*REAR FLOOR SIDE BOARDS	Deformed / Torn	170.24 FL	*170.24 FL
21	1		*REAR EXHAUST SILENCER	Bent	654.20 FL	*525.10 FL
22	2		*REAR EXHAUST MOUNTINGS	Not Necessary	97.00 FL	*- FL
23	2		*REAR FENDERS	Repair	1,745.80 FL	*- FL
24	2		*REAR FENDER INNER AIR VENTS	Not Necessary	179.20 FL	*- FL
25	2		*REAR FENDER INNER TRIMS	Deformed / Torn	461.60 FL	*461.60 FL
26	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
27	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*45.00 FS
28	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	50.00 FS	*- FS
29	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,484.24	5,577.34
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,239.81	1,333.09
Total Parts (\$\$)	7,244.43	4,244.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
6	TO REMOVE,REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	150.00	60.00
7	TO APPLY UNDERCOATING	New	200.00	90.00
8	PANEL BEATING	New	1,800.00	1,300.00
9	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,600.00	1,100.00
Gross Labour Cost (S\$)			4,430.00	2,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >