



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

18 October 2019

ACCIDENT DATE : 17 October 2019
 OWNER : CHEN JING HUA

Not Authorized
 wkk
 Take photo after repair
 18/10/19
 1/5 @ \$600 /
 9 day

REG NO. : SKM 7636 X
 MAKE/MODEL : TOYOTA VIOS

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen moulding	\$ 11 82.10 X
1	Rear boot lid <i>659.20</i>	\$ PD/3uc 781.70 ✓
2	Rear boot hinges <i>64.90</i>	\$ O/S TM 129.80 W/C
1	Rear boot inner lock	\$ TWI 145.60 ✓
1	Rear boot logo	\$ NU 48.50 ✓
1	Rear boot weatherstrip	\$ TWI 181.20 ✓
1	Rear boot "VIOS" emblem	\$ NU 42.90 ✓
1	Rear boot "G" emblem	\$ NU 38.90 ✓
1	Rear boot number plate garnish	\$ IN 98.30 X
2	Rear taillamps	\$ CNA 671.80 ✓
2	Rear taillamp panels	\$ R 337.30 X
1	Rear end panel <i>617.30</i>	\$ Sodyo 775.90 ✓
1	Rear end panel inner garnish <i>186.30</i>	\$ TWI 211.10 ✓
1	Rear bumper <i>363.10</i>	\$ O/S 685.50 ✓
2	Rear bumper brackets	\$ SUC 171.00 X
2	Rear bumper reflectors <i>92.90</i>	\$ O/S CNE 185.80 W/C
2	Rear bumper side retainers	\$ Best 97.30 ✓
1	Rear floor panel	\$ Cramp/3uc 782.90 ✓
1	Rear floor board	\$ Torn 183.60 ✓
2	Rear floor side boards	\$ Oct/3.1 170.24 ✓
1	Rear exhaust silencer <i>525.10</i>	\$ Best 654.20 ✓
2	Rear exhaust mountings	\$ 17 97.00 X
2	Rear fenders	\$ R 1,745.80 X
2	Rear fender inner air vents	\$ 17 179.20 X
2	Rear fender inner trims	\$ Belt/1.1 461.60 ✓
		\$ 8,959.24
	Less 25%	\$ 2,239.81
		\$ 6,719.43

P-5332-34
 25%
 P-3999-25
 S.N-245.00
 L-2770.00
 7014.25
 202
 5611.40

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$	11	80.00	X
1	Rear bumper clip (1 set)	\$	nr	45.00	✓
1	Rear number plate with holder	\$	svr	50.00	X
1	Rear reverse sensor (1 set)	\$	shorted	350.00	2005.2
		\$		<u>525.00</u>	

S/N LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$		80.00	30
2	To remove and refit inner garnishes.	\$		150.00	80
3	To remove and refit rear reverse sensor.	\$		150.00	50
4	To transfer boot lid mechanism and wiring assembly.	\$		120.00	60
5	To remove and refit rear windscreen glass.	\$	11	180.00	X
6	To remove, refit and replace exhaust silencer and mountings.	\$		150.00	60
7	To apply undercoating.	\$		200.00	90
8	Panel beating.	\$		1,800.00	1300
9	To re-spray painting on the affected areas.	\$		1,600.00	1100
		\$		<u>4,430.00</u>	
					<u>2770.00</u>

GRAND TOTAL :

\$ 11,674.43

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: