



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2104116

INV Date 11/06/2021

Reference CC4/LPC19018539/Ers3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMB 77P
Insured Veh. SJL 5388S
Claim No. 18/19/19/VP05/022284
Policy No. Z/18/VP05/021188-001
Accident Date 14/10/2019
Inspection Date 18/10/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC19018539/Ers3q2 Date: 11/06/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJL 5388S	Veh. Inspected	SMB 77P	
Policy No.	Z/18/VP05/021188-001	Coverage (\$)	0.00	
Claim No.	18/19/19/VP05/022284	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	18/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ OC500LE	c.c	11967	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WEB63442021000186	Colour	MULTI COLOUR	
Odometer	850993 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	275/70 R22.5	FIRENZA	5 mm	
L/H Front Tyre	275/70 R22.5	FIRENZA	5 mm	
R/H Rear Tyre	275/70 R22.5	FIRENZA	5 mm	
L/H Rear Tyre	275/70 R22.5	FIRENZA	5 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	14/10/2019	Inspection Date	18/10/2019	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 77P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	PANEL,SKIRT:R4 ,FOR MB OC500 BUS	DENTED	1,442.10	1,442.10
1	PANEL ,SKIRT:R9,FOR MB OC500 BUS	DENTED	307.10	307.10
1	PANEL,SKIRT:R11,FOR MB OC500 BUS	NECESSARY	642.80	642.80
1	FRAME,SKIRT PANEL:R11,FOR MB OC500 BUS	DENTED	365.70	365.70
2	WHEEL ARCH TRIM @\$124.20	DENTED	248.40	248.40
1	PANEL ,SKIRT:R6 ,FOR MB OC500 BUS	TO REPAIR SEE LABOUR	518.20	-
1	PANEL ,SKIRT:R12,FOR MB OC500 BUS	NOT NECESSARY	2,430.20	-
2	GAS SPRING 22N @\$94.90	NOT NECESSARY	189.80	-
	LESS 10% DISCOUNT		-	-300.61
			6,144.30	2,705.49
<u>SPECIAL NETT ITEMS</u>				
10	SEALANT:SIKATACK-MOVE TRANSPORTATION @\$37.00 (SN)	NECESSARY	370.00	370.00
1	ACTIVATOR (SN)	NECESSARY	80.00	80.00
1	PRIMER (SN)	NECESSARY	80.00	80.00
1	SMRT STICKER (SN)	NECESSARY	75.00	75.00
			605.00	605.00
<u>LABOUR</u>				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF PANEL ,SKIRT:R6 ,FOR MB OC500 BUS.		2,120.00	1,855.00
	TO PUTTY & RESPRAY .		1,112.00	942.00
			3,232.00	2,797.00
GRAND TOTAL			9,981.30	6,107.49

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,450.00
---	--	--	-----------------

Report Ref No. CC4/LPC19018539/Ers3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMB 77P

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMB 77P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

