



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/10/2019

User ID : JeongCH

Section A - Accident Details

Registration Number	SMB77P
Case Reference Number	BUS/10/19/5012
Registration Date	6/30/2009
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Mohamad Naqib Bin Mohamed Khalid
Type of Accident	Head To Side
Accident Date and Time	10/14/2019 12:27 PM
Accident Reported Date and Time	10/14/2019 2:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB77P - RIGHT CENTRE TO REAR PORTION SJL5388S (TP) - INSURED WITH LONPAC
Prepared Date and Time	10/15/2019 4:45 PM
Chassis Number	WEB63442021000186
Mileage	
Work Shop	
Repair Completion Date and Time	


Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$3,320.88	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,320.88	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	5
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	15/10/2019 5:12 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

18/10/19, 4.00 pm
Steve (LKK) with Mr. Al Sy
5 days
L/S
My Al Sy





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/10/2019

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	\$2,120.00	1855
Total Labour	\$2,120.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$0.00	942
Total Spray Painting & Panel Beating	\$0.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010227	BODY RH	5019	PANEL SKIRT:R4, FOR MB OC500 BUS	1.00	\$1,442.10	10.00	\$1,297.89	Replace	/ DD
6010229	BODY RH	5021	PANEL SKIRT:R6, FOR MB OC500 BUS	1.00	\$518.20	100.00	\$0.00	Repair	X R
6010232	BODY RH	5024	PANEL SKIRT:R9, FOR MB OC500 BUS	1.00	\$307.10	10.00	\$276.39	Replace	/ DD
6010234	BODY RH	5026	PANEL SKIRT:R11, FOR MB OC500 BUS	1.00	\$642.80	10.00	\$578.52	Replace	/ DD
6010235	BODY RH	5027	PANEL SKIRT:R12, FOR MB OC500 BUS	1.00	\$2,430.20	10.00	\$2,187.18	Replace	/ DD
6010244	Body	5039	FRAME SKIRT PANEL:R11, FOR MB OC500 BUS	1.00	\$365.70	10.00	\$329.13	Replace	/ DD
			SMRT STCKER	1.00	\$75.00	0.00	\$75.00	Replace	/ RCL
Total					\$5,781.10		\$4,744.11		

(Whu arch)
(A/c cam)
(Rear Eng. RCL)
(Frame i aw)

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: