

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 5985A (Supplementary)

DATE : 22.10.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Aircon Condenser <i>bt puncture</i>			\$ 927.50
	Rear Spare Tyre Bracket <i>hic</i>			\$ 248.00
	SUB TOTAL			\$ 1,175.50
	LESS 20%			\$ 235.10
	DISCOUNTED TOTAL			\$ 940.40

23/10/2019
[Signature]
Lee Ann

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.