

利汽車噴漆私人有限公司

Raaim Car Bodyworks Pte Ltd (Co.Reg. No: 201327842N)

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

SMC9022H

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA

OWN INSURER : AXA

CLAIM TYPE : TP

Date of Accident : 16/10/2019

Vehicle Reg. No. : SMC9022H

Vehicle Reg. Date: 27-Jul-2018

Make / Model : HYUNDAI ELANTRA AD 1

Engine No. : G4FGJU221450

Chassis No. : KMHD841CMJU716984

COST OF CLAIMS

Parts Cost / List Items : \$ -

Plus/Less	20%	\$	-
-----------	-----	----	---

Total Cost / List : \$ -

Special Nett Items :	\$	1,160.00
----------------------	----	----------

Total Parts Amount : \$ 1,160.00

Total Labour Amount : \$ 3,110.00

Gross Total :	\$	4,270.00
---------------	----	----------

GST % :	7%	\$	298.90
----------------	-----------	-----------	---------------

Nett Amount : \$ 4,568.90

Surveyor Name and Company :

Date of survey : _____

Part by Part / Lump Sum : days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email :

Fax No :

HP No : _____

This claim is handled by : **CHARLIE**

CHARLIE

利汽车喷漆私人有限公司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No. : **SMC9022H**
Vehicle Reg. Date: **27/7/2018**
Make / Model : **HYUNDAI ELANTRA AD 1.6 GLS AT (AMS)**
Engine No. : **G4FGJU221450**
Chassis No. : **KMHD841CMJU716984**

Steve (LKK) Mr. P. 18/10/19, 4.30pm
3 day
L/S
By Alfay

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER / DR				
2	1	REAR BUMPER RETAINER RH / DR				
3	1SET	REAR BUMPER CLIPS / NR				
4	1	REAR BUMPER REFLECTOR RH				
5	1	TAIL LAMP RH				
6	1	TAIL LAMP CLIP RH				
7	1	REAR FENDER RH				
8	1	REAR FENDER INNER SHIELD RH				
9	1SET	REAR FENDER INNER SHIELD CLIPS RH				
10	1	REAR DOOR RH				
11	1	REAR DOOR HINGE TOP				
12	1	REAR DOOR HINGE BOTTOM				
13	1	REAR DOOR CHECKER RH				
14	1	REAR DOOR INNER TRIM RH				
15	1SET	REAR DOOR INNER TRIM RH CLIPS				
16	1	REAR DOOR POWER WINDOW MOTOR RH				
17	1	REAR DOOR OUTER HANDLE RH				
18	1	REAR DOOR LOCK RH				
19	1	REAR DOOR STICKER UPPER RH				
20	1	REAR DOOR STICKER RR RH				
21	1	ROCKER PANEL RH				
22	1	REAR SHOCK ABSORBER RH				
23	1	REAR WHEEL HUB ASSY RH				
24	1	REAR AXLE				
25	1	REAR RIM RH			\$ 500.00	
26	1	REAR TYRE RH			\$ 300.00	
27	1	REVERSE SENSOR			\$ 300.00	
28	1	SUNDRIES			\$ 60.00	30
29	0	0				
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

Blk 2 Kranji Loop #01-04 Singapore 739538
Tel: 6694 3197 Fax: 6694 3191

PAGE 1

[illegible]

Date: