

利 汽 車 噴 漆 私 人 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

FINALIZATION FORM

ATTN TO: STEVE/LKK
Surveyor Name and Company

Date of Accident : 16-Oct-2019

BILL TO: AXA
TP Insurer

VEHICLE REG. NO.

TYPE OF CLAIM: TP

SMC9022H

Make / Model : JNDAI ELANTRA AD 1.6 GLS AT (AI

COST OF CLAIMS

Parts Cost / List : \$ 1,204.50

Supp. Parts : \$ -

Special Nett : \$ 530.00

Total Parts : \$ 1,493.60

Total Labour : \$ 1,180.00

TOTAL REPAIR COST : \$ 2,673.60

Total Parts Cost/List :	\$	1,204.50
Plus / Less : 20%	\$	240.90
Total :	\$	963.60

20%	\$	-
	\$	-

Final Part by Part Amount : \$ 2,673.60

Submitted by / Date : CHARLIE

No. of Repair Days: 4

Confirmed by / Date : _____

利 汽 車 噴 漆 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No.: **SMC9022H**
Vehicle Reg. Date: **27/7/2018**
Make / Model: **HYUNDAI ELANTRA AD 1.6 GLS AT (AMS)**
Engine No.: **G4FGJU221450**
Chassis No.: **KMHD841CMJU716984**

Steve (CLKK) WHL Nish 18/10/19 4.00pm
4 days
Ry AF SPY

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER		\$ 551.28		\$ 551.28
2	1	REAR BUMPER RETAINER RH		\$ 45.40		\$ 45.40
3	1SET	REAR BUMPER CLIPS		\$ 30.00		\$ 30.00
4	1	REAR BUMPER REFLECTOR RH		\$ 32.90		\$ 32.90
5	1	TAIL LAMP RH		\$ 362.60		
6	1	TAIL LAMP CLIP RH		\$ 20.00		
7	1	REAR FENDER RH		\$ 1,768.30		
8	1	REAR FENDER INNER SHIELD RH		\$ 72.28		
9	1SET	REAR FENDER INNER SHIELD CLIPS RH		\$ 20.00		
10	1	REAR DOOR RH		\$ 1,775.00		
11	1	REAR DOOR HINGE TOP		\$ 41.20		
12	1	REAR DOOR HINGE BOTTOM		\$ 41.20		
13	1	REAR DOOR CHECKER RH		\$ 77.90		
14	1	REAR DOOR INNER TRIM RH		\$ 690.00		
15	1SET	REAR DOOR INNER TRIM RH CLIPS		\$ 30.00		
16	1	REAR DOOR POWER WINDOW MOTOR RH		\$ 208.65		
17	1	REAR DOOR OUTER HANDLE RH		\$ 91.20		
18	1	REAR DOOR LOCK RH		\$ 201.50		
19	1	REAR DOOR STICKER UPPER RH		\$ 21.20		
20	1	REAR DOOR STICKER RR RH		\$ 21.20		
21	1	ROCKER PANEL RH		\$ 1,191.70		
22	1	REAR SHOCK ABSORBER RH		\$ 287.04		
23	1	REAR WHEEL HUB ASSY RH		\$ 544.92		\$ 544.92
24	1	REAR AXLE		\$ 1,611.70		
25	1	REAR RIM RH			\$ 500.00	
26	1	REAR TYRE RH				
27	1	REVERSE SENSOR				
28	1	SUNDRIES			\$ 30.00	
29	0	0				
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

180 / 1039.58
-20%
831.66

Blk 2 Kranji Loop #01-04 Singapore 739538
Tel: 6694 3197 Fax: 6694 3191

PAGE 1

[illegible]

Acknowledged by Repairer
Signature: _____
Date: _____

P-831.66
NI-180
L-1180
2191.66