

利 汽 車 噴 漆 私 人 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

FINALIZATION FORM

ATTN TO: STEVE/LKK
Surveyor Name and Company

Date of Accident : 16-Oct-2019

BILL TO: AXA
TP Insurer

VEHICLE REG. NO.

TYPE OF CLAIM: TP

SMC9022H

Make / Model : JNDAI ELANTRA AD 1.6 GLS AT (AI

COST OF CLAIMS

Parts Cost / List : \$ 1,204.50

Supp. Parts : \$ -

Special Nett : \$ 530.00

Total Parts : \$ 1,493.60

Total Labour : \$ 1,180.00

TOTAL REPAIR COST : \$ 2,673.60

Total Parts Cost/List :	\$	1,204.50
Plus / Less : 20%	\$	240.90
Total :	\$	963.60

20%	\$	-
	\$	-

Final Part by Part Amount : \$ 2,673.60

Submitted by / Date : CHARLIE

No. of Repair Days: 4

Confirmed by / Date : _____

利 汎 車 噴 漆 社 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Bik 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No.: **SMC9022H**
Vehicle Reg. Date: **27/7/2018**
Make / Model: **HYUNDAI ELANTRA AD 1.6 GLS AT (AMS)**
Engine No.: **G4FGJU221450**
Chassis No.: **KMHD841CMJU716984**

Steve (LKK) WHL Arnh 18/10/19 4.00pm
4 days
Ry At Spj

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER / NR		\$ 551.28		\$ 551.28
2	1	REAR BUMPER RETAINER RH / BR		\$ 45.40		\$ 45.40
3	1SET	REAR BUMPER CLIPS / NR		\$ 30.00		\$ 30.00
4	1	REAR BUMPER REFLECTOR RH / BR		\$ 32.90		\$ 32.90
5	1	TAIL LAMP RH X NR		\$ 362.60		
6	1	TAIL LAMP CLIP RH X NR		\$ 20.00		
7	1	REAR FENDER RH X R		\$ 1,768.30		
8	1	REAR FENDER INNER SHIELD RH X NR		\$ 72.28		
9	1SET	REAR FENDER INNER SHIELD CLIPS RH X NR		\$ 20.00		
10	1	REAR DOOR RH X R		\$ 1,775.00		
11	1	REAR DOOR HINGE TOP X NR		\$ 41.20		
12	1	REAR DOOR HINGE BOTTOM X NR		\$ 41.20		
13	1	REAR DOOR CHECKER RH X NR		\$ 77.90		
14	1	REAR DOOR INNER TRIM RH X NR		\$ 690.00		
15	1SET	REAR DOOR INNER TRIM RH CLIPS X NR		\$ 30.00		
16	1	REAR DOOR POWER WINDOW MOTOR RH X NR		\$ 208.65		
17	1	REAR DOOR OUTER HANDLE RH X NR		\$ 91.20		
18	1	REAR DOOR LOCK RH X NR		\$ 201.50		
19	1	REAR DOOR STICKER UPPER RH X NR		\$ 21.20		
20	1	REAR DOOR STICKER RR RH X NR		\$ 21.20		
21	1	ROCKER PANEL RH X NR		\$ 1,191.70		
22	1	REAR SHOCK ABSORBER RH X NR		\$ 287.04		
23	1	REAR WHEEL HUB ASSY RH / Jomari		\$ 544.92		\$ 544.92
24	1	REAR AXLE X NR		\$ 1,611.70		
25	1	REAR RIM RH / cut (Local repair)			\$ 500.00	180
26	1	REAR TYRE RH X NR				
27	1	REVERSE SENSOR X NR				
28	1	SUNDRIES / NR			\$ 30.00	
29	0	0				
30	0	0				
31	0	0				
32	0	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	0	0				
38	0	0				
39	0	0				
40	0	0				

180 / 1039.58
-29%
831.66 /

Blk 2 Kranji Loop #01-04 Singapore 739538

Vehicle Reg. No. :	SMC9022H
Vehicle Reg. Date:	27/7/2018
Make / Model :	HYUNDAI ELANTRA AD 1.6 GLS AT (AMS)
Engine No. :	4GFGJU221450
Chassis No. :	KMHD841CMJU716984

Estimates on Labour

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Date:

P-831.66
NI-180
L-1180
2191.66

1180

11,429.74#