

AIG INSURNACE

Vehicle number	SLF5330R
Make / Model	NISSAN SYLPHY
Chassis number	MNTBBAB17Z0027434
Accident date	18/10/2019
Reference	1910-24

Qty	Particulars	Unit Price - SGD \$
	<u>PARTS REPLACEMENT - LIST ITEMS</u>	
1	BONNET	769.93 <i>bt</i>
2	BONNET HINGE	96.60 <i>KP</i>
1	BONNET LOCK	180.30 <i>X</i>
1	BONNET LOCK STRIKER	91.30 <i>X</i>
1	FRONT BUMPER	646.30 <i>de</i>
1	FRONT BUMPER LOWER GRILLE	341.50 <i>de</i>
2	FRONT BUMPER SIDE RETAINER	150.60 <i>re</i>
1	FRONT BUMPER REINFORCEMENT	646.19 <i>?</i>
2	FRONT BUMPER REINFORCEMENT BRACKET	210.92 <i>?</i>
1	FRONT BUMPER TOW COVER	88.30 <i>de</i>
1	FRONT BUMPER SPONGE	134.78 <i>eng</i>
2	FRONT BUMPER SIDE COVER	220.90 <i>X</i>
1	FRONT GRILLE	485.07 <i>eng</i>
1	FRONT GRILLE EMBLEM	101.00 <i>eng</i>
1	FRONT GRILLE CHROME MOULDING	260.10 <i>eng</i>
1	FRONT HEADLAMP	609.73 <i>cut</i>
1	FRONT HEADLAMP BRACKET	47.10 <i>?</i>
1	FRONT LH FENDER	416.60 <i>KR</i>
1	FRONT LH FENDER INNER SHIELD	98.40 <i>X</i>
1	FRONT SUPPORT PANEL	454.93 <i>KP</i>
1	FRONT SUPPORT PANEL TOP GARNISH	211.50 <i>de</i>
1	AIRCON CONDENSER	864.00 <i>X</i>
1	RADIATOR	782.58 <i>X</i>
1	RADIATOR FAN COWLING	358.90 <i>X</i>
		8267.53
	Less 10%	826.75
	Subtotal	7440.78
	Balance C/F	7440.78

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	7440.78
1	FRONT NUMBER PLATE	80.00 45 bl
1 SET	FRONT BUMPER CLIP	50.00 30 wh
1 SET	FRONT GRILLE CLIP	60.00 20 wh
1 SET	FRONT SUPPORT PANEL TOP GARNISH CLIP	60.00 X
1 SET	FRONT FENDER INNER SHIELD CLIP	60.00 X
1	BRAKE FUILD	150.00 X
	Subtotal	460.00
	Balance C/F	7900.78
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	7900.78
1	CHECK FRONT WIRING AND LIGHTING SYSTEM	120.00 30.
2	REMOVE AND REFIT GARNISH ,LINING AND TRIM FOR REPAIR	200.00 40
7	REMOVE, RENEW CONDENSER AND TOP UP GAS	150.00 X
8	REMOVE, RENEW RADIATOR AND TOP UP COOLANT	150.00 X
9	PANEL BEATING ON AFFECTED AREAS	1200.00 600 700
10	SPRAY PAINTING ON AFFECTED AREAS	1200.00 600 700
11	APPLY ANTI-RUST ON AFFECTED AREAS	200.00 30.
	Subtotal	3220.00
	Grand total	11120.78

Tanpin 9795714
up

21/10/14 R440.

ump sum

Resurvey after repair
sure (LKK Auto Consultants)
5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: