



AIG Singapore  
78 Shenton Way  
Singapore 079120

Tan Kah  
21/10/19  
3 days  
Resurvey after repair  
sure the amount

TeamWork Garage Pte Ltd  
53 Ubi Avenue 1 #01-23/24 Spore 408934  
Paya Ubi Industrial Park  
Tel : 6844 2475  
E-mail : claims@teamworkgarage.com  
ROC number : 201015366H  
3RD PARTY CLAIM ESTIMATION

PARTS : +7,108.15  
- 5%  
+6,153.31  
S/N : + 30.00  
LABOUR : +1,140.00  
+7,923.31  
# 4s : +6,200.

Vehicle number SLZ34Z  
Make / Model BMW/523i  
Chassis number WBAFP32090C547607  
Accident date 18 October 2019  
Reference 1910-23

| Qty                                           | Particulars                       | Unit Price - SGD \$        |
|-----------------------------------------------|-----------------------------------|----------------------------|
| <u>PARTS REPLACEMENT - LIST ITEMS</u>         |                                   |                            |
| 1                                             | FRONT BUMPER                      | 1468.55 de → 1277.55       |
| 2                                             | FRONT BUMPER RETAINER             | RH x 205.00 ? LH de 102.50 |
| 2                                             | FRONT BUMPER BRACKET              | RH x 215.00 ? LH de 107.50 |
| 1                                             | FRONT BUMPER REINFORCEMENT        | 787.75 X                   |
| 1                                             | FRONT IMPACT ABSORBER TOP         | 55.20 ? 2000 ✓             |
| 1                                             | FRONT MOUNT BUMPER LOWER          | 181.70 X                   |
| 1                                             | NOZZLE LH                         | 62.00 X } un               |
| 1                                             | NOZZLE MOTOR LH                   | 207.00 X }                 |
| 1                                             | LOWER CENTRE GRILLE               | 78.20 X }                  |
| 1                                             | FRONT LH SIDE GRILLE              | 82.80 ? de ✓               |
| 1                                             | FRONT LH FINISHER ROD             | 40.24 X un.                |
| 1                                             | FRONT LH HEADLAMP                 | 3024.50 un → 2927          |
| 1                                             | FRONT LH HEADLAMP BALLAST         | 1801.90 X un               |
| 1                                             | FRONT LH HEADLAMP MODULE          | 1801.90 ? 2000 ✓ → 750     |
| 1                                             | FRONT LH FOG LAMP                 | 299.00 ? 2000 ✓            |
| 1                                             | PDC SENSOR                        | 1085.60 ? 2000 ✓ 200.      |
| 4                                             | SENSOR HOLDER                     | 147.20 un                  |
| 1                                             | INTAKE AIR DUCT CENTRE            | 259.90 X un                |
| 1                                             | AIR DUCT LH                       | 59.80 X un.                |
| 1                                             | FRONT LH FENDER                   | 2500.98 de → 1160          |
|                                               |                                   | 14364.22 7108.75           |
| Less 5 %                                      |                                   | 718.21                     |
| Subtotal                                      |                                   | 13646.01                   |
| Balance C/F                                   |                                   | 13646.01                   |
| <u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u> |                                   |                            |
| 1 SET                                         | FRONT BUMPER CLIP                 | 40.00 3000 ✓               |
| Subtotal                                      |                                   | 40.00                      |
| Balance C/F                                   |                                   | 13686.01                   |
| <u>LABOUR AND MISCELLANEOUS CHARGES</u>       |                                   |                            |
| Balance B/F                                   |                                   | 13686.01                   |
| 1                                             | CHECK WIRING AND LIGHTNING SYSTEM | 60.00 30                   |
| 2                                             | DIAGNOIS CHECK CLEAR FAULT CODE   | 300.00 180                 |
| 3                                             | PANEL BEATING ON AFFECTED AREAS   | 800.00 400                 |
| 4                                             | SPRAY PAINTING ON AFFECTED AREAS  | 800.00 500                 |
| 5                                             | APPLY ANTI RUST ON AFFECTED AREAS | 150.00 30                  |
| Subtotal                                      |                                   | 2110.00                    |
| Grand total                                   |                                   | 15796.01                   |

Confirm with Danner 4 days.  
from e-mail

1140.  
7401.85  
4s \$5900  
2 days