



AIG Singapore
78 Shenton Way
Singapore 079120

Pte Ltd
Taylor 9749549
WP 21/10/19 e 430
3 days
Resurvey after repair
sure@thekantam.com

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC number : 201015366H

3RD PARTY CLAIM ESTIMATION

Vehicle number	SLZ34Z
Make / Model	BMW/523I
Chassis number	WBAFP32090C547607
Accident date	18 October 2019
Reference	1910-23

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER	1468.55 de ✓
2	FRONT BUMPER RETAINER	205.00 ?
2	FRONT BUMPER BRACKET	215.00 ?
1	FRONT BUMPER REINFORCEMENT	787.75 X
1	FRONT IMPACT ABSORBER TOP	55.20 ?
1	FRONT MOUNT BUMPER LOWER	181.70 X
1	NOZZLE LH	62.00 X
1	NOZZLE MOTOR LH	207.00 X
1	LOWER CENTRE GRILLE	78.20 X
1	FRONT LH SIDE GRILLE	82.80 ?
1	FRONT LH FINISHER ROD	40.24 ?
1	FRONT LH HEADLAMP	3024.50 one ✓
1	FRONT LH HEADLAMP BALLAST	1801.90 ?
1	FRONT LH HEADLAMP MODULE	1801.90 ?
1	FRONT LH FOG LAMP	299.00 ?
1	PDC SENSOR	1085.60 ?
4	SENSOR HOLDER	147.20 one ✓
1	INTAKE AIR DUCT CENTRE	259.90 X
1	AIR DUCT LH	59.80 ?
1	FRONT LH FENDER	2500.98 by ✓
		14364.22
Less 5 %		718.21
Subtotal		13646.01
Balance C/F		13646.01
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1 SET	FRONT BUMPER CLIP	40.00 30 one ✓
Subtotal		40.00
Balance C/F		13686.01
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
Balance B/F		13686.01
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 30
2	DIAGNOIS CHECK CLEAR FAULT CODE	300.00 180
3	PANEL BEATING ON AFFECTED AREAS	800.00 400
4	SPRAY PAINTING ON AFFECTED AREAS	800.00 500
5	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
Subtotal		2110.00
Grand total		15796.01

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: