

1552111

INS. CASE OWNER

CC4/TP19018572/Dga3/12

IDAC

ASSIGNMENT

Surveyor: BRYAN

DOI: 21/10/2019

Date/Time: 18/10/2019

Registered in Merimen: 21/10/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : \_\_\_\_\_

Claim No. : \_\_\_\_\_

Name of Insured : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_

Make / Model : \_\_\_\_\_

Excess Sec II : \$\$ \_\_\_\_\_ D.O.A : 17.10.19

Place of Accident : \_\_\_\_\_

Is driver the owner? ( YES / NO ) Nature of Accident : \_\_\_\_\_

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : \_\_\_\_\_ (V/L: YES / NO )

Insured Liability : % Final ? Yes / No

SHC 8550R



INSRS: WSP: CHUNNI  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_

Date/Time	STAGE	DATE / PIC
	Non-Reporting Itr (1st):	
	Non-Reporting Itr (2nd):	
	Non-Reporting Itr (Final):	
	Notification Itr (if non-pickup):	
	Call OI:	
	After call Itr to OI:	
	Documentation Check List: Handler	Typist
	Notification Itr (if non-pickup)	
	After call Itr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE Date/Time:	Sent By:	
FINALIZATION Date/Time:	Confirm with:	Confirm by: <u>BRYAN</u>
Repair Cost: <u>US \$5 16,500/-</u> ( <u>2</u> days) Reduction: <u>\$19,255.08 @ 54</u>	Email <input type="checkbox"/> Call <input type="checkbox"/>	
FINAL SETTLEMENT Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability: % (Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :	
Repair Cost: \$\$		
Loss of Rental (LOR): \$\$ ( days)		
Loss of Use (LOU): \$\$ (5 x days)		
Loss of Income (LOI): \$\$ (5 x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/> [Tick only one]		
GIA/LTA Search: \$\$		
Medical: \$\$		
Disbursement: \$\$ (e.g. Tow/ Independent )		
Legal Cost: \$\$		
Total: \$\$	Global Sum \$\$:	
FINAL PAYMENT Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Power 1: \$\$	Name 1: _____	

*07/11/2019 please d/s 16500/- with 2 days of car*

COPY SENT

Independent

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format:
- 3) Survey fee: \$980

REF:

1002/Dg

COE Dec 2023

ASS. REC. BY:

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: 8HC850R Yr Regn: 2015, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

Truck / Trailer or

Make: Hyundai I40 c.c 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 551833 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDEU410568

C/No: KMHLB41UMG081006

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front Rear

R/Bal. S mm R/Bal. S mm

L/Bal. S mm L/Bal. S mm

D.O.A. 17/10/2019 D.O.I. 21/10/2019

Survey held at Churni AMK

Des. of Damage: Frt (Rear) O/S / N/S / U/C / Rooftop or

Front of Rm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	FWD SJY1156C
	Not insured with FWD. (Red = \$19,255.08 / 54%)
	Churni will buy survey report.
07/11/2019	Journal 2/5 165001- with 8 days given

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: \_\_\_\_\_

1)

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

Survey Fee: \$545

Transportation: \$150

2)

Add Fee:  : Site Insp (\$)

5.00 \$

: Interview (\$)

1980

: Tech. Invs (\$)

Photos \$276

: Weekend (\$)

\$80

Pop. Format: \_\_\_\_\_

Admin File

Lump Sum / T.B.: \_\_\_\_\_

20/11/19

\$1011

## Bryan Ang (LKKAuto)

---

**From:** Chunni Motor <chunnimotor@gmail.com>  
**Sent:** Wednesday, 23 October 2019 3:41 PM  
**To:** Bryan Ang (LKKAuto)  
**Subject:** SHC 8550R

Hi Bryan,

We need to buy the survey report for this vehicle.

Owner sold vehicle and no more insured by FWD.

Regards,  
Lynn

MCD619138318 / ComfortDelGro Engineering Pte Ltd - Loyal  
 ENTRY DATE & TIME: 18/10/2019 15:17  
 SUBMITTED BY: Janet Lim Siang Gek

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	18/10/2019 15:17
Date Of Accident	17/10/2019 23:30
Exact Location Of Accident	CTE TOWARDS SLE BEFORE ANG MO KIO AVE 3 EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC8550R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
<b>Insurance Company</b>	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

### Driver

Name of Driver	LAU TECK SOON
NRIC No	S7625318H
Date Of Birth	22/08/1976
Occupation	OUTDOOR
Date Of Driving Pass	20/03/2000
Driving Experience	19 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97369292
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 343 BUKIT BATOK STREET 34  
#08-104

Postcode 650343

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

#### General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 5

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1

NAME: : -

GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] ANG MO KIO NORTH NPC

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

REFER POLICE REPORT NO: T/20191018/2012

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: -

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJY1156C

Vehicle Make/Model/Colour HONDA

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver CHUA KAK LEE

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name  
Nature Of Damage FRONT AND REAR  
No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SHA5985A  
Vehicle Make/Model/Colour COMFORT TAXI  
Details Of Properties  
Vehicle Category TAXI  
Name of Driver TAY GUAN KIM STEPHEN  
NRIC/Passport Number  
Contact Number 81393297  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage FRONT AND REAR  
No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number SJU105C  
Vehicle Make/Model/Colour TOYOTA  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver UNKNOWN  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage REAR  
No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 4**

Vehicle Registration Number GBC5000C  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver UNKNOWN  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage FRONT  
No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name LAU TECK SOON  
Approximate Age  
Injuries Sustain LOWER BACK AND RIGHT FOREARM  
Injured person in which vehicle? SHC8550R  
Were seat belts worn? YES  
Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

**DETAILS OF INJURED PERSON 2**

Name	TAY GUAN KIM STEPHEN
Approximate Age	
Injuries Sustain	BACK AND NECK
Injured person in which vehicle?	SHA5985A
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD  
CO. REG. NO. 199303821R

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 18.10.2019@12:20hrs

\_\_\_\_\_  
Lisa  
Reporting Centre Personnel's Signature  
Name: -  
NRIC/FIN No.: -




**SINGAPORE  
POLICE FORCE**


T/20191018/2012

1 of 4

Report No. T/20191018/2012

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 18/10/2019 01:51		Vide Report No.:		Station Diary No.: 28	
<b>Informant's Particulars</b>					
Name of Informant: LAU TECK SOON			Address: APT BLK 343 BUKIT BATOK STREET 34 #08-104 SINGAPORE 650343		
ID Type / ID No.: NRIC NO / S7625318H			Contact No.:		Mobile: 97369692
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 43	Date of Birth: 22/08/1976	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: TAXI DRIVER		Driving Licence Information: Class: 2B,2A,2,3,4		Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 17/10/2019 23:30	Type of Location: Expressway
Location: Along Road 1 Traveling Toward Road 2 CENTRAL EXPRESSWAY SELETAR EXPRESSWAY Before exit of AMK Ave 3				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 90 Km/h
Traffic Flow: One Way		Traffic Control:		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBC5000C	Van				Slightly Damaged	0
SHA5985A	Car				Slightly Damaged	1
SHC8550R	Car				Slightly Damaged	1
SJU105C	Car				Slightly Damaged	0
SJY1156C	Car				Slightly Damaged	0



**SINGAPORE  
POLICE FORCE**



T/20191018/2012

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

2 of 4

Report No. T/20191018/2012

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAY GUAN KIM STEPHEN	ID No.	S1272177C
Related Vehicle	SHA5985A (Car)	Contact No.	81393297
Hospital/Clinic	INTEMEDICAL 24 HRS CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	18/10/2019	Date Discharge	18/10/2019
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Driver			
Name	LAU TECK SOON	ID No.	S7625318H
Related Vehicle	SHC8550R (Car)	Contact No.	97369692
Hospital/Clinic	INTEMEDICAL 24 HRS CLINIC	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4 Date of Expiry: NIL
Date Treatment	18/10/2019	Date Discharge	18/10/2019
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Driver			
Name	CHUA KAK LEE	ID No.	S6912897I
Related Vehicle	SJY1156C (Car)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 17/10/2019 at or about 2330hrs, along CTE towards SLE before AMK Ave 3 exit, my car was involved in chain accident involving a total of 5 vehicles. My car was number 3. There was one car behind me and one car in front of me. The car in front of me is another taxi whereas the car behind me is a HONDA CIVIC. I recall before the accident happen I was driving when I heard a loud tyre sound and then I noticed that the car in front of me almost stopped so I did an e-brake also. Out of a sudden I felt my car hit from behind and my car moved forward thus hitting the car in front. I made a check on my passenger to see if he was ok or not and he told me that he was ok. I then alighted from my car and checked for the damages to my car before proceeding to exchange particulars and numbers with the drivers for both the



**SINGAPORE  
POLICE FORCE**



T/20191018/2012

3 of 4

Report No. T/20191018/2012

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

**CONTINUATION OF REPORT**

rear and front car. At the accident scene, I did not see any visible injuries on either the two drivers whom I engaged. I myself did not sustain any serious injuries. After moving off from the accident scene, I exited AMK Ave 3 and made a call to my Company to inform them about the accident. It was at that time then I started to feel pain in my lower back and right forearm. My Company then advised me to go see a Doctor for my bodily pains. I then went to the nearest clinic and the examining Doctor issued me with 3-days MC. After that I proceeded to lodge this Traffic Accident report.



**SINGAPORE  
POLICE FORCE**



T/20191018/2012

4 of 4

Report No, T/20191018/2012


Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / SI MOHAMMED BIN ZAINOL 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 18/10/2019 01:51
Officer In Charge Of Case: TP / AEIT / SI ANG YI TING, STEPHANIE Contact No.: 65476414	Classification Of Case: 

Authentication Stamp  
NP168

**CHUNNI MOTOR WORK PTE LTD****REPAIR ESTIMATE\***

VEHICLE NO : SHC 8550R

DATE : 18.10.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI I40

FAX : 6542 6039

Aw B

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet St			\$ 2,265.90
	Bonnet Hinge (LH/RH) NW		\$ 41.00	\$ 82.00
	Bonnet Lock St			\$ 36.90
	Bonnet Absorber NW		\$ 58.10	\$ 116.20
	Bonnet Insulator NW			\$ 196.50
	Bonnet Insulator Clips SW			\$ 8.40
	Radiator Grille broken			\$ 1,110.10
	Radiator Grille H Emblem broken			\$ 39.50
	Front Bumper Cover broken			\$ 1,052.20
	Front Bumper Sponge torn			\$ 99.20
	Front Bumper Reinforcement Rented			\$ 402.10
	Front Bumper Grille (LH/RH) NW		\$ 93.60	\$ 187.20
	Front Bumper Grille Airduct (LH/RH) NW		\$ 26.20	\$ 52.40
	Front Bumper Lip NW			\$ 54.90
	Front Bumper Bracket Top (LH/RH) NW		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) NW		\$ 24.60	\$ 49.20
	Headlamp Support Top Cover NW			\$ 222.60
	Headlamp Support Panel Assy St / broken			\$ 907.40
	Headlamp (LH/RH) broken wandy		\$ 1,388.00	\$ 2,776.00
	Radiator St / punctured			\$ 698.30
	Radiator Fan Blade, Cowling, Motor Assy St broken			\$ 792.95
	Radiator Bracket (RH/LH) NW		\$ 6.50	\$ 13.00
	Radiator Hose Upper NW			\$ 36.50
	Radiator Hose Lower NW			\$ 36.50
	Radiator Guard N/S broken o/s NW		\$ 20.00	\$ 40.00
	Horn Unit (LH/RH) broken		\$ 73.80	\$ 147.60
	Horn Wire Socket broken			\$ 156.50
	Front Fender (LH/RH) N/S Rented o/s repair		\$ 566.30	\$ 1,132.60
	Front Fender Apron Panel (LH) NW			\$ 637.00
	Front Fender Shield (LH/RH) NW		\$ 174.90	\$ 349.80
	Air Cleaner Assy NW			\$ 118.60
	Air Duct NW			\$ 134.60
	Air Flow Sensor NW			\$ 502.20
	Air Cleaner Bottom Assy NW			\$ 325.00
	Aircon Condenser St			\$ 927.50
	Battery Tray NW			\$ 52.00
	Battery Stay NW			\$ 20.90
	Inter Cooler St punctured / St			\$ 1,032.50
	Inter Cooler Mounting (2 PCS) NW			\$ 25.90
	Hose B To Inter Cooler NW			\$ 229.70
	Hose C To Inter Cooler Inlet deformed		13325-45	\$ 294.50
	Pipe To Inter Cooler NW			\$ 167.05
	Pipe To Inter Cooler Outlet NW		10660-36	\$ 244.55
	Wiring-Engine NW			\$ 3,326.00
	Wiring-ECM NW			\$ 3,243.00

SHC 8550R

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	<b>SUB TOTAL</b>			\$ 24,388.25	
	<b>LESS 20%</b>			\$ 4,877.65	
	<b>DISCOUNTED TOTAL</b>			\$ 19,510.60	
	Front Number Plate <i>broken</i>			\$ <sup>45</sup> 25.00	Nett ✓
	Front No Plate Trim Cover <i>broken</i>			\$ 30.00	Nett ✓
	Front Fender Advertisement Logo (LH/RH) <i>NEC</i>	\$	100.00	\$ 200.00	Nett ✓
	New Battery <i>new</i>			\$ 207.00	Nett X
			<b>245.00</b>		
				\$ 462.00	
	<b>Labour Charge</b>				
	Panel Beating			\$ 1,500.00	700/-
	Spray Painting Charge			\$ 1,250.00	600/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 100.00	40/-
	Towing Charge			\$ 50.00	new
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Remove/Refix Dashboard			\$ 450.00	new
	Remove/Refix Fuse Box			\$ 180.00	new
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00	new
	<b>TOTAL LABOUR</b>			\$ 4,210.00	
	Boot Lid <i>vt</i>			\$ 2,174.90	✓
	Boot Lid Rubber <i>defunct</i>			\$ 96.50	✓
	Boot Lid Hinge (LH/RH) <i>new</i>	\$	142.30	\$ 284.60	X
	Boot Lid Lock Upper <i>vt</i>			\$ 102.60	✓
	Boot Lid Lock Lower <i>new</i>			\$ 31.70	new X
	Boot Lid 'H' Emblem <i>NEC</i>			\$ 28.70	✓
	Boot Lid CRDI Plate <i>new</i>			\$ 27.90	✓
	Boot Lid Lamp (LH/RH) <i>code missing</i>	\$	565.60	\$ 1,131.20	✓
	Boot Lid Trimboard <i>new</i>			\$ 116.40	X
	Boot Lid Trimboard Clips (10pcs) <i>new</i>			\$ 11.00	X
	Bootlid Moulding <i>new</i>			\$ 85.00	X
	Bootlid i40 Emblem <i>new</i>			\$ 27.90	X
	Bootlid Lower Garnish <i>new</i>			\$ 227.90	X
	Rear Bumper <i>defunct</i>			\$ 553.00	✓
	Rear Bumper Reinforcement <i>code missing</i>			\$ 428.40	X
	Rear Bumper Reinforcement Bracket (LH/RH) <i>new</i>	\$	80.30	\$ 160.60	X
	Rear Bumper Clip 10 pcs <i>NEC</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>old broken new</i>	\$	<u>35.60</u>	\$ 71.20	✓
	Rear Bumper Sponge <i>form</i>			\$ 118.40	✓
	Rear Bumper Under Cover <i>defunct</i>			\$ 228.00	✓
	Tail Lamp (LH/RH) <i>code missing</i>	\$	697.80	\$ 1,395.60	✓
	Rear Panel <i>Defunct</i>			\$ 526.70	✓
	Rear Panel Garnish <i>vt   mostly defunct</i>			\$ 57.70	✓
	Rear Panel Lower Panel <i>new Defunct</i>			\$ 495.50	X

SHC 8550R

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Exhaust Pipe Insulator <i>7</i>		\$ 58.55	\$ 117.10 <i>X</i>
	Exhaust Silencer <i>0/2 wt 2/S 2W</i>		\$ 967.70	\$ 1,935.40 <i>LL photo</i>
	Exhaust Pipe Hanger <i>2</i>		\$ 58.55	\$ 117.10 <i>X</i>
	Exhaust Pipe Centre <i>2</i>			\$ 730.10 <i>X</i>
	<b>SUB TOTAL</b>		<i>8390.40</i>	\$ 11,303.10
	<b>LESS 20%</b>			\$ 2,260.62
	<b>DISCOUNTED TOTAL</b>		<i>6712.32</i>	\$ 9,042.48
	Boot Lid Comfort Logo & Tel No. Sticker <i>1pc</i>			\$ 30.00 <i>Nett ✓</i>
	Boot Lid Advertisement Logo <i>1pc</i>		<i>130.00</i>	\$ 100.00 <i>Nett ✓</i>
				\$ 130.00
	<b>Labour Charge</b>			
	Panel Beating			\$ 1,000.00 <i>700/-</i>
	Spray Painting Charge			\$ 1,000.00 <i>600/-</i>
	Wiring Charge			\$ 50.00 <i>30/-</i>
	Tuff Kote			\$ 50.00 <i>40/-</i>
	Remove/Refix Exhaust Pipe		<i>1430.00</i>	\$ 300.00 <i>60/-</i>
	<b>TOTAL LABOUR</b>			\$ 2,400.00
	<b>ESTIMATE TOTAL</b>			\$ 35,755.08
	<i>21/10/2019 @ 0930am</i>			
	<i>NA Andrew</i>			
	<i>+/Name</i>			
	<i>8 d.p.s.</i>			
	<i>nyu</i>			
	<i>LKT Auto</i>			
			<i>20627.68</i>	
			<i>4/9 16500/-</i>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

18/10/19

**Nivitha (LKK Auto)**

**From:** venessa.chan@fwd.com  
**Sent:** Friday, 18 October 2019 4:50 PM  
**To:** admin-a@lkkauto.com; admin-d@lkkauto.com  
**Cc:** lionel.tan@fwd.com; motorclaims.sg@fwd.com  
**Subject:** Accident involving veh no: SHC 8550R & SJY 1156C on 17.10.19

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.


Thank you.

Best Regards,

Venessa Chan  
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986  
E [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)  
W [www.fwd.com.sg](http://www.fwd.com.sg)



5:07pm @ 18/10/19  
P. Lynn  
N: In  
agreed sury on 21/10/19

**From:** Venessa Chan - SGUser  
**Sent:** Friday, October 18, 2019 4:47 PM  
**To:** 'Chunni Motor'  
**Cc:** Lionel Tan Tian Pei - SGUser; Motor Claims SG - SG Common  
**Subject:** RE: Accident involving veh no: SHC 8550R & SJY 1156C on 17.10.19

Hi Sir/Madam,

Thank you for your selection of LKK Auto Consultants Pte Ltd.  
We will proceed to assign survey.


Thank you.

Best Regards,

Venessa Chan  
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986  
E [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)  
W [www.fwd.com.sg](http://www.fwd.com.sg)



**From:** Chunni Motor [<mailto:chunnimotor@gmail.com>]  
**Sent:** Friday, October 18, 2019 4:44 PM  
**To:** Venessa Chan - SGUser  
**Cc:** Lionel Tan Tian Pei - SGUser; Motor Claims SG - SG Common  
**Subject:** Re: Accident involving veh no: SHC 8550R & SJY 1156C on 17.10.19

Dear Sir,

We appoint LKK Auto Consultants P/L

Thank you

Regards,  
Chunni Motor Work P/L

On Fri, Oct 18, 2019 at 4:28 PM <[venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)> wrote:

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to your email dated on 18.10.2019 of the PRI Notice of your client's vehicle SHC8550R.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. RT APPRAISAL PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

\*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.

\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com).

Thank you.

Best Regards,

Venessa Chan

Administrative Assistant, Claims




FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

E [venessa.chan@fwd.com](mailto:venessa.chan@fwd.com)

W [www.fwd.com.sg](http://www.fwd.com.sg)



**From:** Chunni Motor [mailto:[chunnimotor@gmail.com](mailto:chunnimotor@gmail.com)]

**Sent:** Friday, October 18, 2019 3:45 PM

**To:** Motor Claims SG - SG Common

**Subject:** Accident involving veh no: SHC 8550R & SJY 1156C on 17.10.19

Dear Sir/Mdm,

We refer the above mentioned matter.

We enclosed herewith the relevant documents for your necessary action.

In line with the new protocol, kindly provide us with the list of surveyors on your panel for assessment of the damaged accident taxi involved.

Kindly survey at AMK Autopoint, Soon Hock Motor, #01-05/06.

Should you have any queries, please do not hesitate to contact Ms Lynn or Ms Irene at 65425119 or 6542 7162

Thank you for your kind assistance.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHUNNI MOTOR WORK PTE LTD		Ref : CC4/TP19018572/Dga3n2	
BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINTSINGAPORE 568047		Date : 22-11-2019	
ON BEHALF OF COMFORT TRANSPORTATION PTE LTD		Code : TP356	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	SHC 8550R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/10/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KMHLB41UMGU081006	Colour	BLUE
Odometer	551833	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/10/2019	Inspection Date	21/10/2019
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>8 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8550R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BONNET	BENT	2,265.90	2,265.90
2	BONNET HINGE (LH/RH) @\$41.00	NOT NECESSARY	82.00	-
1	BONNET LOCK	BENT	36.90	36.90
2	BONNET ABSORBER @\$58.10	NOT NECESSARY	116.20	-
1	BONNET INSULATOR	NOT NECESSARY	196.50	-
1	BONNET INSULATOR CLIPS	SERVICEABLE	8.40	-
1	RADIATOR GRILLE	BROKEN	1,110.10	1,110.10
1	RADIATOR GRILLE H EMBLEM	NECESSARY	39.50	39.50
1	FRONT BUMPER COVER	BROKEN	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	TORN	99.20	99.20
1	FRONT BUMPER REINFORCEMENT	DENTED	402.10	402.10
2	FRONT BUMPER GRILLE (LH/RH) @\$93.60	NOT NECESSARY	187.20	-
2	FRONT BUMPER GRILLE AIRDUCT (LH/RH) @\$26.20	NOT NECESSARY	52.40	-
1	FRONT BUMPER LIP	NOT NECESSARY	54.90	-
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	NOT NECESSARY	44.80	-
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	NOT NECESSARY	49.20	-
1	HEADLAMP SUPPORT TOP COVER	NOT NECESSARY	222.60	-
1	HEADLAMP SUPPORT PANEL ASSY	BENT / BROKEN	907.40	907.40
2	HEADLAMP (LH/RH) @\$1388.00	MOUNTING BROKEN	2,776.00	2,776.00
1	RADIATOR	BENT / PUNCTURE	698.30	698.30
1	RADIATOR FAN BLADE,COWLING,MOTOR ASSY	BROKEN	792.95	792.95
2	RADIATOR BRACKET (RH/LH) @\$6.50	NOT NECESSARY	13.00	-
1	RADIATOR HOSE UPPER	NOT NECESSARY	36.50	-
1	RADIATOR HOSE LOWER	NOT NECESSARY	36.50	-
2	RADIATOR GUARD @\$20.00	N/S BROKEN / O/S NOT NECESSARY	40.00	20.00
2	HORN UNIT (LH/RH) @\$73.80	BROKEN	147.60	147.60
1	HORN WIRE	SOCKET BROKEN	156.50	156.50
2	FRONT FENDER (LH/RH) @\$566.30	N/S DENTED / O/S TO REPAIR SEE LABOUR	1,132.60	566.30
1	FRONT FENDER APRON PANEL (LH)	NOT NECESSARY	637.00	-
2	FRONT FENDER SHIELD (LH/RH) @\$174.90	NOT NECESSARY	349.80	-
1	AIR CLEANER ASSY	NOT NECESSARY	118.60	-

Report Ref No. CC4/TP19018572/Dga3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AIR DUCT	NOT NECESSARY	134.60	-
1	AIR FLOW SENSOR	NOT NECESSARY	502.20	-
1	AIR CLEANER BOTTOM ASSY	NOT NECESSARY	325.00	-
1	AIRCON CONDENSER	BENT	927.50	927.50
1	BATTERY TRAY	NOT NECESSARY	52.00	-
1	BATTERY STAY	NOT NECESSARY	20.90	-
1	INTER COOLER	PUNCTURE / BENT	1,032.50	1,032.50
1	INTER COOLER MOUNTING (2 PCS)	NOT NECESSARY	25.90	-
1	HOSE B TO INTER COOLER	NOT NECESSARY	229.70	-
1	HOSE C TO INTER COOLER INLET	DEFORMED	294.50	294.50
1	PIPE TO INTER COOLER	NOT NECESSARY	167.05	-
1	PIPE TO INTER COOLER OUTLET	NOT NECESSARY	244.55	-
1	WIRING-ENGINE	NOT NECESSARY	3,326.00	-
1	WIRING-ECM	NOT NECESSARY	3,243.00	-
1	BOOT LID	BENT	2,174.90	2,174.90
1	BOOT LID RUBBER	DEFORMED	96.50	96.50
2	BOOT LID HINGE (LH/RH) @\$142.30	NOT NECESSARY	284.60	-
1	BOOT LID LOCK UPPER	BENT	102.60	102.60
1	BOOT LID LOCK LOWER	TO REPAIR SEE LABOUR	31.70	-
1	BOOT LID 'H' EMBLEM	NECESSARY	28.70	28.70
1	BOOT LID CRDI PLATE	NECESSARY	27.90	27.90
2	BOOT LID LAMP (LH/RH) @\$565.60	MOUNTING CRACKED	1,131.20	1,131.20
1	BOOT LID TRIMBOARD	SERVICEABLE	116.40	-
10	BOOT LID TRIMBOARD CLIPS	NOT NECESSARY	11.00	-
1	BOOTLID MOULDING	NOT NECESSARY	85.00	-
1	BOOTLID I40 EMBLEM	NOT NECESSARY	27.90	-
1	BOOTLID LOWER GARNISH	NOT NECESSARY	227.90	-
1	REAR BUMPER	DEFORMED	553.00	553.00
1	REAR BUMPER REINFORCEMENT	CRACKED	428.40	428.40
2	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$80.30	NOT NECESSARY	160.60	-
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
2	REAR BUMPER BRACKET @\$35.60	O/S BROKEN / N/S NOT NECESSARY	71.20	35.60
1	REAR BUMPER SPONGE	TORN	118.40	118.40

Report Ref No. CC4/TP19018572/Dga3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER UNDER COVER	DISTORTED	228.00	228.00
2	TAIL LAMP (LH/RH) @\$697.80	MOUNTING CRACKED	1,395.60	1,395.60
1	REAR PANEL	DENTED	526.70	526.70
1	REAR PANEL GARNISH	BENT / MOUNTING DEFORMED	57.70	57.70
1	REAR PANEL LOWER PANEL	DENTED	495.50	495.50
2	EXHAUST PIPE INSULATOR @\$58.55	NOT NECESSARY	117.10	-
2	EXHAUST SILENCER @\$967.70	O/S BENT / N/S NOT NECESSARY	1,935.40	967.70
2	EXHAUST PIPE HANGER @\$58.55	NOT NECESSARY	117.10	-
1	EXHAUST PIPE CENTRE	NOT NECESSARY	730.10	-
	LESS 20% DISCOUNT		-7,138.27	-4,343.17
			<b>28,553.08</b>	<b>17,372.68</b>
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NO PLATE TRIM COVER (SN) }	BROKEN	30.00	45.00
1	FRONT NUMBER PLATE (SN) }	BROKEN	25.00	-
2	FRONT FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	NECESSARY	200.00	200.00
1	NEW BATTERY (SN)	NOT NECESSARY	207.00	-
1	BOOT LID COMFORT LOGO & TEL NO STICKER (SN)	NECESSARY	30.00	30.00
1	BOOT LID ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	100.00
			<b>592.00</b>	<b>375.00</b>
	<b><u>LABOUR</u></b>			
	PANEL BEATING, INCLUSIVE OF THE REPAIR OF O/S FRONT FENDER AND BOOT LID LOCK LOWER.		2,500.00	1,400.00
	SPRAY PAINTING CHARGE.		2,250.00	1,200.00
	WIRING CHARGE.		100.00	60.00
	TUFF KOTE.		150.00	80.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.		150.00	80.00
	REMOVE/REFIX DASHBOARD.	NOT NECESSARY	450.00	-
	REMOVE/REFIX FUSE BOX.	NOT NECESSARY	180.00	-
	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE.	NOT NECESSARY	480.00	-
	REMOVE/REFIX EXHAUST PIPE.		300.00	60.00
			<b>6,610.00</b>	<b>2,880.00</b>
	<b>GRAND TOTAL</b>		<b>35,755.08</b>	<b>20,627.68</b>

Report Ref No. CC4/TP19018572/Dga3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			16,500.00
---	--	--	-----------

Report Ref No. CC4/TP19018572/Dga3n2

**ANG BRYAN TANI**

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.