

Surveyor:

MARCUS

DOI: 21/10/2019

Date / Time: 21/10/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.: GBG 5699R

Claim No.:

Name of Insured: GUAN LEE VEGETABLES & FRUITS PTE LTD

Policy No.: DMCVSN3075531902

Insured Tel No.: HP:

Make / Model: TOYOTA DYNA

Excess Sec II :SS D.O.A: 18/10/2019 19:30

Place of Accident: KAKI BUKIT RD 3 TWDS KAKI BUKIT AVE 3

Is driver the owner? (YES / ☒ NO) Nature of Accident:

If NO, Driver Name / Age: ROKIMIN BIN UDA DIN

OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NODriver Tel No.: +65-97339433 (V/L: ☒ YES / NO)

Insured Liability: % Final ? Yes / No

SGY 800T

INSRS:
WSP: FASTECH
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time	SGY 800T GBG 5699R	NA/AIG19018470/h4; DOA: 18/10/19 NA/CTI19018547/h4; DOA: 18/10/19	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	
			After call ltr to OI:	
			Documentation Check List: Handler Typist	
			Notification ltr (if non-pickup):	☒
			After call ltr to OI:	☒
			Authorisation To Act:	☒
			Release Voucher:	☒
			Final Repair Bill:	☒
			Car Rental Invoice:	☒
			Towing Invoice:	☒
			LTA / GIA:	☒
			Medical Bill:	☒
			PIR:	☒
			Mandate/Reject Instruction:	☒
			LOD	☒
			Payment Breakdown Form:	☒
			Post-Repair Photos:	☒
			Others:	☒

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by:
Repair Cost:	SS	(days) Reduction:	%	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 12/2/2020	Confirm with: Jason	Email ☒ Call ☐	
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. NIL	If NO or B 28, Ass. Lia:	
Repair Cost: (w/4M)	SS 8560.00	OL HIT TP VEH WHILE TURNING		
Loss of Rental (LOR):	SS 600.00	(6 days) x \$100		
Loss of Use (LOU):	SS -	(\$ x days)		
Loss of Income (LOI):	SS -	(\$ x days)		
LOR only ☒ LOU only ☐	LOR + LOU ☐ LOR + LOI ☐	(Tick only one)		
GIA/LTA Search	SS 2.00			
Medical:	SS -			
Disbursement:	SS -	(e.g. Tow/ Independent)		
Legal Cost	SS -			
Total:	SS 9162.00	Global Sum SS:		
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐	
Payee 1:	SS 9162.00	Name 1: Fastech Auto Pte Ltd		
Payee 2: (Strike if N.A.)	SS	Name 2:		
Payee 3: (Strike if N.A.)	SS	Name 3:		

COPY SENT 3/3/2020

1) Claim status: Normal/Reject/Private Settle
2) Report Format: ☒ PIP
3) Survey fee: \$400

ASS. REC. BY: *MGR*

REF:

C71/

185-16/11049

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD *6* / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *SGY800T*
 at Workshop m/s *Hy.*
 of _____
 Insured: *GRG5899R*
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: *SGY800T* Yr Regn: *5/17*
 Type: *M.C.* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or *CA7*
 Make: *Honda Shuttle* CC *1496*
 Colour: *shw* A/C: Insured / Std / NI / NA
 Sp. Reading: *35092* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *GK81004114*
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: *185/60R15*
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO *YOKO* or
 Front *6* mm Rear *6* mm
 R/Bal. *6* mm L/Bal. *6* mm
 D.O.A. *18/10/19* D.O.I. *21/10/19*
 Survey held at: _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S Body &

The *U/C* / Chassis frame / Body Structure affected due to collision.

Date: _____ Person Contacted: *Dep 7800*

Vehicle: IN / OUT

Date / Time Action / Instruction

have G.M. LTA 40896 7/17/19
no second hand parts only 2.1m
14/11/19 2/5 x 8000 confirm with H.M.
(Red \$14316/642)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Site Insp (\$ _____) Photos _____

Interview (\$ _____) Others _____

Tech. Invs (\$ _____)

Weekend (\$ _____)

TOTAL

☐ : Prel. Report

☐ : Final Report

Add Fee:

☐ : Site Insp

☐ : Interview

☐ : Tech. Invs

☐ : Weekend

☐ : TOTAL

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$ _____)

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

Get More Cash for Your Car, Post an Ad Today

Receive a higher selling price by selling your car yourself.
Advertise it for sale at just \$58, list till sold.

Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loan, Trade In Are Welcome. 100% Deposit Refund For Unapproved Loan. Classic Credit StarAd



VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND

HOTLINE: 6741 9997

View our cars

Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

Sort by Date Posted

20 results/page

10 vehicles

Shuttle

Advanced Search

Submit

https://www.sgcarmart.com/used_cars/listing.php?RGD=2017&MOD=Shuttle&RPG=20&VEH=0&AV... 21-Oct-19

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 198G

Vehicle Details

Vehicle No.: SGY800T

Vehicle to be Exported: No

Intended Deregistration Date: 21 Oct 2019

Vehicle Make: HONDA

Vehicle Model: SHUTTLE 1.5G CVT ABS D/AIRBAG 2WD 5DR

Primary Colour: Silver

Manufacturing Year: 2015

Engine No.: L15B3534862

Chassis No.: GK81004114

Maximum Power Output: 97.0 kW (130 bhp)

Open Market Value: \$17,457.00

Original Registration Date: 26 May 2017

First Registration Date: 26 May 2017

Transfer Count: 0

Actual ARF Paid: \$7,457.00 3728

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 25 May 2027

PARF Rebate Amount: \$5,592.00

Intended COE Rebate Details

COE Expiry Date: 25 May 2027

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$46,489.00

COE Rebate Amount: \$35,304.00

Total Rebate Amount: \$40,896.00

The information contained herein is correct as at 21 Oct 2019

OK

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
21/10/18
2/5 #8000/
Gdy. The phd. & the up.

VEHICLE NO :SGY 800T

QTY	PARTICULAR		
1 PCS	FRONT DOOR O/S	945.50	20/cent \$1,650.00
1 PCS	FRONT DOOR OUTER HANDLE O/S		suu \$366.50 X
1 PCS	FRONT DOOR INNER LOCK O/S		suu \$399.20 X
1 PCS	FRONT DOOR INNER RUBBER LOWER O/S	115.30	suu \$211.20
1 SET	FRONT DOOR FRAME STICKER O/S	68.00	suu \$105.00
1 PCS	FRONT DOOR MIRROR ASSY O/S	550.50	cu/page \$1,020.00
1 PCS	FRONT DOOR MIRROR COVER O/S	50.20	suu \$145.00
1 PCS	REAR DOOR O/S	921.20	sub/10 \$1,450.00
1 PCS	REAR DOOR OUTER HANDLE O/S	245.50	cut \$366.50
1 PCS	REAR DOOR INNER LOCK O/S	311.20	tw/100 \$399.20
1 PCS	REAR DOOR INNER RUBBER O/S	115.20	suu \$215.20
1 SET	REAR DOOR FRAME STICKER O/S	68.00	suu \$105.00
1 PCS	REAR DOOR INNER TRIM BOARD O/S	491.20	de/100 \$688.20
1 PCS	REAR DOOR GLASS REGULATOR		suu \$311.20
1 PCS	REAR DOOR GLASS REGULATOR MOTOR O/S	complete 428.20	suu \$450.50
2 PCS	REAR DOOR HINGES @\$195.00	65 x 2 = 130	twi \$390.00
1 PCS	REAR DOOR CHECKER O/S	62.20	twi \$125.00
1 PCS	REAR FENDER O/S	1021.20	sub/10 \$1,280.50
1 PCS	REAR FENDER INNER TRIM BOARD O/S		11 \$515.00 X
1 PCS	REAR FENDER GLASS O/S	725.50	suu \$850.00
1 PCS	REAR FENDER SPLASH SHIELD O/S		to.1 \$148.20
1 PCS	REAR BUMPER	1050.20	suu \$1,250.00
1 PCS	REAR BUMPER SIDE HOLDER O/S		cuu \$66.50
1 SET	REAR BUMPER CLIPS		suu \$50.00
1 PCS	TAILLAMP O/S		suu \$450.50 X
1 PCS	REAR SHOCK ABSORBER O/S	315.30	twi \$392.50
1 PCS	REAR WHEEL HUB BEARING O/S	450.50	page \$685.10
1 PCS	REAR AXLE BEAM		suu \$1,685.00 X
1 PCS	ROCKER PANEL GARNISH O/S		11 \$665.00 X
		8328.60	\$16,536.00
		6663.68	
	S.NETT		
1 SET	DOOR VISOR	0/1	suu \$120.00 80
1 PCS	REAR FENDER GLASS SEALANT O/S		suu \$50.00 40
1 PCS	REAR SPORT RIM O/S		20/cent \$1,050.00 480
1 PCS	REAR TYRE O/S		cut \$200.00 602 120
1 SET	REAR BUMPER REVERSE SENSOR		suu \$250.00 X
	LABOUR CHARGES		
	TO CHECK WIRING		\$80.00 20
	TO DISMANTLE & REFIX REAR REVERSE SENSOR		\$80.00 50
	TO DISMANTLE & REFIX CUSHION UPHOLTSTERY		\$120.00 80
	TO TRANSFER BOTH O/S DOOR MECHANISM		\$180.00 120
	TO CONDUCT WHEEL ALIGNEMENT		\$120.00 60
	TO DISMANTLE & REPLACING REAR UNDERCARRIAGE		\$380.00 250
	TO DISMANTLE & REPLACING REAR FENDER GLASS O/S		\$120.00 100
	TO SPRAY RUSTPROOFING		\$150.00 90



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI19018576/Uda3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 03-03-2020	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBG 5699R	Veh. Inspected	SGY 800T
Policy No.	DMCVSN3075531902	Coverage (\$)	0.00
Claim No.	SNM19D204998C02/9	Excess (\$)	0.00
Assign From		Assign Date	21/10/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA SHUTTLE (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GK81004114	Colour	SILVER
Odometer	35092	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/10/2019	Inspection Date	21/10/2019
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 800T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR O/S	DENTED / BENT	1,650.00	945.50
1	FRONT DOOR OUTER HANDLE O/S	SERVICEABLE	366.50	-
1	FRONT DOOR INNER LOCK O/S	SERVICEABLE	399.20	-
1	FRONT DOOR INNER RUBBER LOWER O/S	NECESSARY	211.20	115.30
1	SET FRONT DOOR FRAME STICKER O/S	NECESSARY	105.00	68.00
1	FRONT DOOR MIRROR ASSY O/S	CRACKED / DAMAGED	1,020.00	550.50
1	FRONT DOOR MIRROR COVER O/S	BROKEN	145.00	50.20
1	REAR DOOR O/S	BADLY DENTED	1,450.00	921.20
1	REAR DOOR OUTER HANDLE O/S	CUT	366.50	245.50
1	REAR DOOR INNER LOCK O/S	TWISTED / JAMMED	399.20	311.20
1	REAR DOOR INNER RUBBER O/S	NECESSARY	215.20	115.20
1	SET REAR DOOR FRAME STICKER O/S	NECESSARY	105.00	68.00
1	REAR DOOR INNER TRIM BOARD O/S	DEFORMED / CRACKED	688.20	491.20
1	REAR DOOR GLASS REGULATOR MOTOR O/S)	JAMMED	450.50	428.20
1	REAR DOOR GLASS REGULATOR)		311.20	-
2	REAR DOOR HINGES @\$195.00	TWISTED	390.00	130.00
1	REAR DOOR CHECKER O/S	TWISTED	125.00	62.20
1	REAR FENDER O/S	BADLY DENTED	1,280.50	1,021.20
1	REAR FENDER INNER TRIM BOARD O/S	NOT NECESSARY	615.00	-
1	REAR FENDER GLASS O/S	NECESSARY	850.00	725.50
1	REAR FENDER SPLASH SHIELD O/S	TORN	148.20	148.20
1	REAR BUMPER	DISTORTED	1,250.00	1,050.20
1	REAR BUMPER SIDE HOLDER O/S	CRACKED	66.50	66.50
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	TAILLAMP O/S	SERVICEABLE	450.50	-
1	REAR SHOCK ABSORBER O/S	TWISTED	392.50	315.30
1	REAR WHEEL HUB BEARING O/S	DAMAGED	685.10	450.50
1	REAR AXLE BEAM	SERVICEABLE	1,685.00	-
1	ROCKER PANEL GARNISH O/S	NOT NECESSARY	665.00	-

Report Ref No. CC6/CTI19018576/Uda3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-	-1,665.92
			16,536.00	6,663.68
	<u>SPECIAL NETT ITEMS</u>			
1	SET DOOR VISOR O/S (SN)	NECESSARY	120.00	80.00
1	REAR FENDER GLASS SEALANT O/S (SN)	NECESSARY	50.00	40.00
1	REAR SPORT RIM O/S (SN)	DENTED / BENT	1,050.00	480.00
1	REAR TYRE O/S (60%)(SN)	CUT	200.00	120.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SERVICEABLE	250.00	-
			1,670.00	720.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	20.00
	TO DISMANTLE & REFIX REAR REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO TRANSFER BOTH O/S DOOR MECHANISM.		180.00	120.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	60.00
	TO DISMANTLE & REPLACING REAR UNDERCARRIAGE.		380.00	250.00
	TO DISMANTLE & REPLACING REAR FENDER GLASS O/S.		120.00	100.00
	TO SPRAY RUSTPROOFING.		150.00	90.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.		1,280.00	850.00
	TO PUTTY & SPRAY PAINTING.		1,600.00	1,000.00
			4,110.00	2,620.00
GRAND TOTAL			22,316.00	10,003.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,000.00

Report Ref No. CC6/CT119018576/Uda3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.