

INS. CASE OWNER:

Bennie Tan

CC3/AIG19018589/ Gea3

Surveyor:

ADRIAN

DOI:

ASSIGNMENT

Date / Time: 21/10/19

Registered in Merimen: 21/10/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJN 810L

Claim No.:

4777526432SG

Name of Insured:

TAY LORRAINE ANNE

Policy No.:

2100350233

Insured Tel No.:

HP: +65-97603436

Make / Model:

HYUNDAI DM SANTA FE 2.4L GDI ABS

Excess Sec II :SS

D.O.A: 21/10/2019 12:15

Place of Accident: ALEXANDRA ROAD JUST AFTER DAWSON PLACE

Is driver the owner? (YES / NO)

Nature of Accident:

If NO, Driver Name / Age: CHAN PEGGY

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.: +65-98808857

(V/L: YES / NO)

Insured Liability:

Final ? Yes / No

SML124J



INSRS:

WSP: PREMIUM

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time		STAGE	DATE / PIC
	SML 124J - X	Non-Reporting ltr (1st):	
	SJN 810L - CC6/AIG16012199/eb3XX; DOA: 27/6/16	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
23-10-19	EMAIL WSP LIABILITY CLEAR.	Call OI: <u>EMAIL 23-10-19</u>	
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐
		After call ltr to OI:	☒
		Authorisation To Act:	☒
		Release Voucher:	☒
		Final Repair Bill:	☒
		Car Rental Invoice:	☐
		Towing Invoice:	☐
		LTA / GIA:	☒
		Medical Bill:	☐
		PIR:	☐
		Mandate/Reject Instruction:	☒
		LOD:	☒
		Payment Breakdown Form:	☐
		Post-Repair Photos:	☐
		Others:	☐

PRELIMINARY ADVICE Date/Time:		Sent By:		Confirm by: <u>ASG</u>	
Repair Cost:	<u>P/P SS 18,430.88</u>	(12 days) Reduction:	<u>42 %</u>	Email ☒	Call ☐
FINAL SETTLEMENT Date/Time: <u>21-10-19</u>		Confirm with WADs		Email ☒	Call ☐
Final Liability:	<u>% 100</u>	(Agreed / Assessed) BOLA S/N No.:	<u>21</u>	If NO or B 28, Ass. Lia:	
Repair Cost:	<u>SS 19,121.04</u>	<u>NO REAR ENDOR TP</u>			
Loss of Rental (LOR):	SS -	(days)			
Loss of Use (LOU):	SS <u>700.00</u>	(\$ 50 x 14 days)			
Loss of Income (LOI):	SS -	(\$ x days)			
LOR only ☐	LOU only ☒	LOR + LOU ☐	LOR + LOI ☐	[Tick only one]	
GIA/LTA Search	SS <u>20.00</u>				
Medical:	SS -			1) Claim status: <u>Normal/Reject/Private Settle</u>	
Disbursement:	SS -	(e.g. Tow/Independent)		2) Report Format: <u>TP</u>	
Legal Cost	SS -			3) Survey fee: <u>+330</u>	
Total:	SS <u>20,423.07</u>	Global Sum SS:			
FINAL PAYMENT Date/Time: <u>21-10-19</u>		Confirm with: <u>WADs</u>		Email ☒	Call ☐
Payee 1:	SS <u>20,423.07</u>	Name 1:	<u>PREMIUM Automobiles PTE LTD</u>		
Payee 2: (Strike if N.A.)	SS	Name 2:			
Payee 3: (Strike if N.A.)	SS	Name 3:			

COPY SENT

PASS. REC. BY: CELREF: A1918584/6(2)

ASSIGNMENT

From: _____ Date: 23/10/2019

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: SML 124 Jat Workshop m/s Premium
of 281 Alexandru Road

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 100cm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or NoLum Sum: - % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS imp

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SML 124 J Yr Regn: 30 Apr 2019Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 1.0 C.C. 999Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 1966 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ8V8K A073869Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD / A/Rim orTyre Size: F: 205/55R16R: 11☒ BS1 DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mm

D.O.A. _____

Survey held at w/sDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop orRear o/s
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PIP: +18,430.98 (RED: +13,334.12 42%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Weekend (\$

Report Format: _____

Lump Sum / L.E.J: (\$

Survey Fee:

Transportation:

E + PS: \$

Photos

Others

TOTAL

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SML 124]

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function	S/N S	280.00	✓ ✓
2	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N S	600.00	✓ ✓
3	To install rear windscreen solar film.	S/N S	400.00	✓ ✓
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N S	1,400.00	✓ ✓
SUB TOTAL LABOUR CHARGES		:	<u>\$ 2,680.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SML 1241

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00	✓
6	To dismantle rear bumper and rear lid. To renew rear bumper. Cut out and weld rhs rear fender, rhs rear inner wheel housing connecting plate and end panelling. Re-organise crash management components. Reinstall all parts removed.	7 \$ 9,100.00	3500 ✓
7	To respray rear bumper, rhs rear fender, rhs inner wheel housing connecting plate, door entrances roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works. <i>bootlid</i>	5 \$ 5,000.00	2750 ✓
8	To carry out diagnostic check. /	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 18,372.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 1241

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER / CBA.	\$ 1,793.00	1434.90
2	REAR BUMPER STICKY PAD X	\$ 21.00	
3	REAR BUMPER FIXING PARTS X	\$ 175.00	
4	WHEEL HOUSING LINER ADAPTER - RH X	\$ 34.00	
5	REAR BUMPER GUIDE SECTION - RH	\$ 15.00	11.49
6	REAR BUMPER LOCKING MECHANISM	\$ 27.00	21.20
7	REAR BUMPER SPOILER / wt.	\$ 216.00	172.80
8	REAR BUMPER LIGHT REFLECTOR - RH / SCR	\$ 38.00	29.68
9	REAR BUMPER SIDE REINFORCEMENT BEAM X NN	\$ 522.00	
10	REAR BUMPER BRACKET LH / RH X NN	\$ 51.00	
11	REAR BUMPER GUIDE SECTION - RH / RE.	\$ 60.00	47.84
12	REAR PARKING AID SENSOR - INNER / OUTER / M1 X	\$ 462.00	184.80
13	REAR PARKING AID SENSOR SEAL RING X	\$ 12.00	
14	REAR BUMPER WIRING SET X	\$ 472.00	
15	VENT TRIM X	\$ 64.00	
16	SIDE PANEL - RH / BUC	\$ 2,110.00	1688.00
17	REAR WINDSCREEN /	\$ 742.00	593.20
18	SIDE WINDOW - RH /	\$ 520.00	415.60
19	CROSS PANEL REINFORCEMENT X	\$ 669.00	
20	REAR CROSS PANEL X	\$ 329.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 8,332.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 1241

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	REAR CROSS PANEL CONNECTING PLATE - RH <i>R</i>		131.00
22	REAR CROSS PANEL CONNECTING PLATE - RH REAR <i>R</i> } <i>NN</i> S	\$	89.00
23	REAR WHEEL HOUSING LINER - RH <i>/</i> <i>be</i> .	\$	223.00 <i>178.40</i>
24	WHEEL HOUSING LINER ATTACHMENT PARTS <i>X</i> <i>NN</i> S	\$	81.00
25	LED TAIL LIGHT - RH OUTER <i>/</i> <i>CHA</i> .	\$	800.00 <i>640.00</i>
26	TAIL LIGHT TRIM - RH OUTER <i>X</i> <i>NN</i>	\$	27.00
27	LED TAIL LIGHT - RH INNER <i>R</i> <i>/</i> <i>SCR</i>	\$	800.00 <i>640.00</i>
28	TAIL LIGHT TRIM - INNER <i>R</i> <i>/</i> <i>SCR</i> .	\$	27.00 <i>21.50</i>
29	REAR SILENCER HEAT SHIELD <i>X</i> <i>NN</i> <i>SCR</i>	\$	153.00
30	ACRYLIC SEALANT <i>/</i>	S/N \$	180.00 ✓
31	CAVITY WAX <i>/</i>	S/N \$	140.00 ✓
32	STONE CHIP <i>/</i>	S/N \$	180.00 ✓
33	METAL FILLER POWDER <i>/</i> <i>ML</i> .	S/N \$	280.00 ✓
34	REAR W/S SEALANT <i>/</i>	S/N \$	200.00 ✓
35	1/4 GLASS SEALNT <i>/</i>	S/N \$	100.00 ✓
36	SUNDRIES <i>/</i> <i>NN</i>	\$	600.00
TOTAL SPARE PARTS CHARGES		:	\$ 12,343.00
TOTAL LABOUR CHARGES		:	\$ 18,372.00
GRAND TOTAL		:	\$ 30,715.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Emo Qiang - 82880282
Surveyed Date :
Authorised Date : 23/10/19.
Excess Cost :
Liability : before part photos,
Remarks : 12 Days.

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/TP/1272/2019/NS
Date 31-Oct-19
Service Advisor Glory Tan
Pages 1 of 1
Regn No SML 124 J
Model No Audi A3 SEDAN 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To repair rhs rear inner D-pillar reinforcement.	\$ 1,050.00	\$ 750.00 ✓
TOTAL		\$ 1,050.00	\$ 750.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 16619

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1272/2019/NS
Date : 22-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : **SJN 810L**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian, Guo Qiang

12 days exclude 2 Sundays

jb 11 Dec 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Muniyandi Vanitha
Address : Blk 170 Stirling Road
#05-1135
Singapore 140170
Telephone : HP +65 81125764
Type of Claim : Third Party Claim
Policy No. : 1900094367
Vehicle No : **SML 124 J**
Model Code : Audi A3 SEDAN 1.0 TFSI 8V
Model / Year : Apr-19
Engine No : CHZ C29860
Chassis No : WAUZZZ8V8KA073869
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Oct-19
Place of Accident : Alexandra Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SML 124 J

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function	S/N \$	280.00	\$ 280.00
2	To renew rear windscreen and rhs 1/4 glass to facilitate fender renewal.	S/N \$	600.00	\$ 600.00
3	To install rear windscreen solar film.	S/N \$	400.00	\$ 400.00
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	\$ 1,400.00
SUB TOTAL LABOUR CHARGES		:	<u>\$ 2,680.00</u>	<u>\$ 2,680.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SML 124 J

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
	c/f		\$ 2,680.00
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00	\$ 1,400.00
6	To dismantle rear bumper and rear lid. To renew rear bumper. Cut out and weld rhs rear fender, rhs rear inner wheel housing connecting plate and end panelling. Re-organise crash management components. Reinstall all parts removed.	\$ 9,100.00	\$ 3,500.00
7	To respray rear bumper, rhs rear fender, rhs inner wheel housing connecting plate, door entrances roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 5,000.00	\$ 2,750.00
8	Added labour - see attached	\$ 1,050.00	\$ 750.00
9	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		\$ 19,422.00	\$ 11,272.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 124 J

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
1	REAR BUMPER	\$ 1,793.00	\$ 1,434.40
2	REAR BUMPER STICKY PAD	4 \$ 21.00	
3	REAR BUMPER FIXING PARTS	\$ 175.00	
4	WHEEL HOUSING LINER ADAPTER - RH	\$ 34.00	
5	REAR BUMPER GUIDE SECTION - RH	\$ 15.00	\$ 11.44
6	REAR BUMPER LOCKING MECHANISM	\$ 27.00	\$ 21.20
7	REAR BUMPER SPOILER	\$ 216.00	\$ 172.80
8	REAR BUMPER LIGHT REFLECTOR - RH	\$ 38.00	\$ 29.68
9	REAR BUMPER SIDE REINFORCEMENT BEAM	\$ 522.00	
10	REAR BUMPER BRACKET LH / RH	2 \$ 51.00	
11	REAR BUMPER GUIDE SECTION - RH	\$ 60.00	\$ 47.84
12	REAR PARKING AID SENSOR - INNER / OUTER	2 \$ 462.00	\$ 184.80
13	REAR PARKING AID SENSOR SEAL RING	4 \$ 12.00	
14	REAR BUMPER WIRING SET	\$ 472.00	
15	VENT TRIM	\$ 64.00	
16	SIDE PANEL - RH	\$ 2,110.00	\$ 1,688.00
17	REAR WINDSCREEN	\$ 742.00	\$ 593.20
18	SIDE WINDOW - RH	\$ 520.00	\$ 415.60
19	CROSS PANEL REINFORCEMENT	\$ 669.00	
20	REAR CROSS PANEL	\$ 329.00	
SUB TOTAL SPARE PARTS CHARGES		\$ 8,332.00	\$ 4,598.96

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SML 124 J

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
			\$ 4,598.96
21	REAR CROSS PANEL CONNECTING PLATE - RH	\$ 131.00	
22	REAR CROSS PANEL CONNECTING PLATE - RH REAR	\$ 89.00	
23	REAR WHEEL HOUSING LINER - RH	\$ 223.00	\$ 178.40
24	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 81.00	
25	LED TAIL LIGHT - RH OUTER	\$ 800.00	\$ 640.00
26	TAIL LIGHT TRIM - RH OUTER	\$ 27.00	
27	LED TAIL LIGHT - RH INNER	\$ 800.00	\$ 640.00
28	TAIL LIGHT TRIM - INNER	\$ 27.00	\$ 21.52
29	REAR SILENCER HEAT SHIELD	\$ 153.00	
30	ACRYLIC SEALANT	S/N \$ 180.00	\$ 180.00
31	CAVITY WAX	S/N \$ 140.00	\$ 140.00
32	STONE CHIP	S/N \$ 180.00	\$ 180.00
33	METAL FILLER POWDER	S/N \$ 280.00	\$ 280.00
34	REAR W/S SEALANT	S/N \$ 200.00	\$ 200.00
35	1/4 GLASS SEALNT	S/N \$ 100.00	\$ 100.00
36	SUNDRIES	\$ 600.00	
TOTAL SPARE PARTS CHARGES		\$ 12,343.00	\$ 7,158.88
TOTAL LABOUR CHARGES		\$ 19,422.00	\$ 11,272.00
GRAND TOTAL		\$ 31,765.00	\$ 18,430.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	B20B
Vehicle No.:	SML124J
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Oct 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED & NAV)
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	CHZC29860
Chassis No.:	WAUZZZ8V8KA073869
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$23,357.00
Original Registration Date:	30 Apr 2019
First Registration Date:	30 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$24,700.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2029
PARF Rebate Amount:	\$18,525.00
COE Expiry Date:	29 Apr 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$41,000.00
COE Rebate Amount:	\$25,370.00
Total Rebate Amount:	\$43,895.00

The information contained herein is correct as at 23 Oct 2019

OK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 16619

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1272/2019/NS
Date : 22-Oct-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SJN 810L

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Muniyandi Vanitha
Address : Blk 170 Stirling Road
 #-05-1135
 Singapore 140170
Telephone : HP +65 81125764
Type of Claim : Third Party Claim
Policy No. : 1900094367
Vehicle No : **SML 124 J**
Model Code : Audi A3 SEDAN 1.0 TFSI 8V
Model / Year : Apr-19
Engine No : CHZ C29860
Chassis No : WAUZZZ8V8KA073869
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Oct-19
Place of Accident : Alexandra Road

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Wednesday, 23 October 2019 10:26 AM
To: Mei Kwan (LKKAUTO); Claims
Cc: Admin A; assignments
Subject: RE: ACCIDENT BETWEEN SML 124 J AND YOUR INSURED SJN 810 L ON 21/10/2019 ***
LKK REF: CC3/AIG19018589/ea3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

**** LOU \$50/day or LOR \$100/day (Subject to our principal approval)****

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Sent: Wednesday, 23 October 2019 9:44 AM
To: Claims <claims@premiumauto.com.sg>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: RE: ACCIDENT BETWEEN SML 124 J AND YOUR INSURED SJN 810 L ON 21/10/2019 *** LKK REF: CC3/AIG19018589/ea3

'WITHOUT PREJUDICE'


SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

Fyi, OI has reported. Please refer to the below OI's sketch plan and statement.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENCE PLATE: SJN 310L	ACCIDENT DATE & TIME: 21st October - 12:10pm
CONTACT NUMBER: [REDACTED]	E-MAIL ADDRESS:
LOCATION: Alexandra Road just after Dawson Place	
On the 21st of October I was travelling along Alexandra Road. After Dawson Place I swerved to the right to avoid hitting the car SML 124J. I hit the right rear corner of her car.	

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

Meanwhile, please arrange appointment for survey.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>

Sent: Tuesday, 22 October, 2019 5:21 PM

To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: 'Claims' <claims@premiumauto.com.sg>

Subject: RE: ACCIDENT BETWEEN SML 124 J AND YOUR INSURED SJN 810 L ON 21/10/2019

Dear all,

Attached is the estimate for your kind reference.

Best Regards,
Syafiq
Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims <claims@premiumauto.com.sg>

Sent: Monday, 21 October 2019 6:00 PM

To: 'Admin A' <admin-a@lkkauto.com>; 'Admin-D [LKKAuto]' <admin-d@lkkauto.com>; 'SUR' <sur@lkkauto.com>

Cc: 'Claims' <claims@premiumauto.com.sg>

Subject: ACCIDENT BETWEEN SML 124 J AND YOUR INSURED SJN 810 L ON 21/10/2019

Dear all,

Kindly assist in the liability clearance for the above mentioned case. We propose for 100% direct settlement in our clients favour.

We herein attached the GIA report for direct settlement for your reference.

We will forward you the estimate once is available.

Kindly assist on liability clearance before survey.

Please assist to register this case mentioned, and arrange the survey on 23/10/2019, 10AM@ Owner Waiting.

Location 35 Alexandra.

Thanks.

Best Regards,
Troy Goh
Claims Advisor

Premium Automobiles Pte Ltd (Reg No: 200622170K)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	21 Oct 2019 19:34	Cim Dtl Modified	Claimant's Name: -> MUNIYANDI VANITHA. Claimant's ID: -> S7877820B.	[A] HOW MEI KWAN
2	21 Oct 2019 19:34	Cim Veh Model Changed	(205252) AUDI A3 999cc TFSI S TRONIC (LED) (A).	[A] HOW MEI KWAN
3	21 Oct 2019 19:34	Cim Created	Reg No: SML124J, Acct Date: 2019/10/21. Claim Type: TP, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Workshop: Premium Automobiles Pte Ltd - Alexandra (HQ)	[A] HOW MEI KWAN
4	21 Oct 2019 19:34	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HOW MEI KWAN
5	21 Oct 2019 19:34	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/10/31	[A] HOW MEI KWAN
6	21 Oct 2019 19:34	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HOW MEI KWAN
7	21 Oct 2019 19:34	Cim Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[I] Merimen Administrator
8	21 Oct 2019 19:39	Label Added	(23):Express.	[A] HOW MEI KWAN
9	21 Oct 2019 19:39	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] HOW MEI KWAN
10	23 Oct 2019 09:36	Cim Registration Modified	Acct Time:12:00:00->12:10:00.	[I] AIG OneClaim Integration User
11	24 Oct 2019 20:13	Adj Adjuster Assigned	ADRIAN LING -> XING GUO QIANG	[A] HOW MEI KWAN
12	24 Oct 2019 20:14	Cim Dtl Modified	Insured Name: -> TAY LORRAINE ANNE. Insured ID: -> S7144473B.	[A] HOW MEI KWAN
13	24 Oct 2019 20:14	Cim Registration Modified	Init.Est.:8,000 - 9,000->30,000 - 40,000.	[A] HOW MEI KWAN
14	17 Dec 2019 13:50	Adj Rpt Initiated		[A] Asher Sng Rong Yi
15	17 Dec 2019 13:50	Insured Phone No Updated	[None] -> [+6581125764]	[A] Asher Sng Rong Yi
16	17 Dec 2019 13:50	Cim Dtl Modified	Claim Conclusion: -> 1.	[A] Asher Sng Rong Yi
17	17 Dec 2019 13:50	Cim Dtl Modified	JPJ Reg. Date: -> 2019/04/30.	[A] Asher Sng Rong Yi
18	17 Dec 2019 13:50	Cim Details Notified		[A] Asher Sng Rong Yi
19	16 Jan 2020 12:51	Adj Mandate Request	Cur.Reg:20423.04:LIABILITY: 100% B:27 OID REAR ENDED TP	[A] Asher Sng Rong Yi

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Adj Name	Co Name (Insurer)	Ref 1	Ref 2	Amount
2320343	21 Oct 2019 19:42:00	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	AIG Asia Pacific Insurance Pte. Ltd. (Express)	SML124J	SJN810L	11.77
2379389	17 Dec 2019 13:50:11	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SML124J	SJN810L	11.77

Print Received Message

This mail is associated with :

***SML124J (4777526432SG)**
[SJN810L]

TP

MUNIYANDI VANITHA

Oct 21 2019 12:10PM

[TAY LORRAINE ANNE]

Premium Automobiles Pte Ltd - Alexandra

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 20/01/2020 18:06 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$20423.04) - SML124J - Claim Handler: Tan, Bennie-WZ

Approved:20423.04:*subject to Final Repair Bill, GIA Search Bill in order

Your Ref: SJN 810 L

Authorization letter

PA/TP/01272/2019/TG

12 November 2019

Ms. Muniyandi Vanitha
Blk 170 Stirling Road
#05-1135
Singapore 140170

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept

Dear Sir/ Mdm,

**ACCIDENT INVOLVING VEHICLES SML 124 J / SJN 810 L AT ALEXANDRA
ROAD ON 21/10/2019.**

I am the owner of SML 124 J, Ms. Muniyandi Vanitha.

I confirmed that I will be claiming for Loss of Usages / Rental Charges and hereby authorized your esteemed company to settle the repair bill and Loss of Usages / Rental Charges and directly with Premium Automobiles Pte Ltd.

Your kind attention will be greatly appreciated.

Yours faithfully,



Ms. Muniyandi Vanitha

Copy to Norah Khai, Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SML 124 J

Norah Khai
6768 9828
6841 1183

Body Repair

PA/TP/1272/2019/TG
12 November 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SEDAN 1.0 TFSI 8V
Vehicle Chassis No. : WAUZZZ8V8KA073869
Vehicle Regn No. : SML 124 J
Vehicle Mileage : 1985 KM
Vehicle Owner : Ms. Muniyandi Vanitha
Liability : Direct Settlement by Asher Sng of
LKK Auto Consultant Pte Ltd via email
dated 23/10/2019 with LOU.
Accident Date : 21/10/2019
Place : Alexandra Road
Repair Cost : \$ 19721.04
WIP No. : 16619
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


3.00 pm
12/11/2019

BREAKDOWN OF PAYMENT

Vehicle No: SML 124 J.
Accident on 21/10/2019 at Alexander Road.
Involving vehicle/s SJN 810 L

1) Repair cost \$ 19721.04 Payable to: Premium Automobiles Pte Ltd

2) GIA/LTA search fee \$ 2.00 Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or Rental Car \$ 700.00 Payable to: Muniyandi Vairthar

4) Medical fees \$ N.A. Payable to: N.A.

5) Others \$ _____ Payable to: _____



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : MUNIYANDI VANITHA
Period of Insurance : 30 Apr 2019 To 29 Apr 2021
Engine No. : CHZ C29860
Chassis No. : WAUZZZ8V8KA073869

Vehicle No. : SML124J
Policy No. : 1900094367
Endorsement No. :
Issued Date : 06 May 2019

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2019
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 5 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

MUNIYANDI VANITHA - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125264

PREMIUM LEASING -QKT

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Sherry Lim

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Oct 2019 Edit Reg		23 Oct 2019 00:00 Edit Adj Rpt	S\$18,430.88 Edit Estimates	S\$18,430.88 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	TAY LORRAINE ANNE, ID: S7144473B, Tel: +6581125764		
Main Claimant:	MUNIYANDI VANITHA, ID: S7877820B		
Vehicle Reg. No.:	SML124J	Date of Loss:	21/10/2019 12:00 - :59 [5 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4777526432SG	Policy/Cover Note No.:	2100350233 (Comprehensive)
Vehicle Reg. No. (Insured):	SJNB10L	Policy No. (Claimant):	1900094367
	Excess:		
Repairer:	Premium Automobiles Pte Ltd - Alexandra (HQ) 281 Alexandra Pte Ltd, Level B2, 159938 Alexandra - Tel: 63882233		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/10/2019]		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

- AIG_SG_EXPRESS (20/01/2020): Alert - Adj Mandate Approved (S\$20423.04) - SML124J - Claim Handler: Tan, Bennie...

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SML124J (4777526432SG)

[SJN810L]

TP

MUNIYANDI VANITHA

Oct 21 2019 12:10PM

[TAY LORRAINE ANNE]

Premium Automobiles Pte Ltd - Alexandra

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Letters/Correspondences

1 per page

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1 Edit	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/12/19 13:45	General View	1 Load JPG	
2	17/12/19 13:45	General View	1 Load JPG	
3	17/12/19 13:45	General View	1 Load JPG	
4	17/12/19 13:45	General View	1 Load JPG	
5	17/12/19 13:45	General View	1 Load JPG	
6	17/12/19 13:45	General View	1 Load JPG	
7	17/12/19 13:45	General View	1 Load JPG	
8	17/12/19 13:45	General View	1 Load JPG	
9	17/12/19 13:45	General View	1 Load JPG	
10	17/12/19 13:45	General View	1 Load JPG	
11	17/12/19 13:45	General View	1 Load JPG	
12	17/12/19 13:45	General View	1 Load JPG	
13	17/12/19 13:45	General View	1 Load JPG	
14	17/12/19 13:45	General View	1 Load JPG	
15	17/12/19 13:45	General View	1 Load JPG	
16	17/12/19 13:45	Odometer Reading	1 Load JPG	
17	17/12/19 13:45	Chassis Number	1 Load JPG	
18	17/12/19 13:45	General View	1 Load JPG	
19	17/12/19 13:45	General View	1 Load JPG	
20	17/12/19 13:45	General View	1 Load JPG	
21	17/12/19 13:45	General View	1 Load JPG	
22	17/12/19 13:45	General View	1 Load JPG	
23	17/12/19 13:45	General View	1 Load JPG	
24	17/12/19 13:45	General View	1 Load JPG	
25	17/12/19 13:45	General View	1 Load JPG	
26	17/12/19 13:45	General View	1 Load JPG	
27	17/12/19 13:45	General View	1 Load JPG	
28	17/12/19 13:45	General View	1 Load JPG	
29	17/12/19 13:45	General View	1 Load JPG	
30	17/12/19 13:45	General View	1 Load JPG	
31	17/12/19 13:45	General View	1 Load JPG	
32	17/12/19 13:45	General View	1 Load JPG	
33	17/12/19 13:45	General View	1 Load JPG	
34	17/12/19 13:45	General View	1 Load JPG	
35	17/12/19 13:45	General View	1 Load JPG	
36	17/12/19 13:45	General View	1 Load JPG	
37	17/12/19 13:45	General View	1 Load JPG	
38	17/12/19 13:45	General View	1 Load JPG	
39	17/12/19 13:45	Reinspection Photo	1 Load JPG	
40	17/12/19 13:45	Reinspection Photo	1 Load JPG	

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					☒
41	17/12/19 13:45	Reinspection Photo		Load JPG	☒
42	17/12/19 13:45	Reinspection Photo		Load JPG	☒
43	17/12/19 13:45	Reinspection Photo		Load JPG	☒
44	17/12/19 13:45	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/10/19 19:40	TP GIA REPORT		Load PDF	
2	23/10/19 10:22	LETTER TO OI		Load PDF	
3	25/10/19 16:48	TP ESTIMATE - MARKED		Load PDF	
4	13/02/20 09:45	WORKSHOP INVOICE		Load PDF	
5	13/02/20 09:45	AUTHORISATION TO ACT FORM		Load PDF	
6	13/02/20 09:45	Release Voucher		Load PDF	
7	13/02/20 09:45	LOD		Load PDF	
8	13/02/20 09:45	GIA SEARCH		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	23/10/19 09:31	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJN810L (Insd veh)	Model:	AUDI A3 999CC TFSI S
	SML124J (TP veh)		TRONIC (LED) (A)
Date of Accident:	21/10/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	33,988.55
Final Repair Cost	:	\$	19,721.04
Loss of Use	:	\$	700.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	20,423.04

14.00 days at \$50.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	:	\$ 20,423.04
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

13 Feb

2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19018589/GEA3Q2

Date: 13/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100350233
Claimant
Vehicle No : SML124J **Insured Vehicle No :** SJN810L
Date of Loss: 21/10/2019 **Nature of Claim:** TP **Claim No:** 4777526432SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SML124J**
 Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZC29860
 Reg. Date: 30/04/2019 (Man. Year: 2019) Chassis No: WAUZZZ8V8KA073869
 Colour: Blue Odometer: 1966 km
 Engine Capacity: 999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
 Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 9 mm
 Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,343.00	7,158.88	5,184.12	42.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,422.00	11,272.00	8,150.00	41.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	31,765.00	18,430.88	13,334.12	41.98
+ GST 7.00/7.00% (S\$)	2,223.55	1,290.16	933.39	41.98
Nett Amount (S\$)	33,988.55	19,721.04	14,267.51	41.98
+ Loss of Use (14.0 x S\$50.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		20,423.04		

INSPECTION

Date of Assignment: 23/10/2019
 Date Inspected: 23/10/2019 Inspected At: Premium Automobiles Pte Ltd -
 Alexandra (HQ)
 281 Alexandra Pte Ltd, Level B2
 Singapore 159938
 Estimated Period of Repair: 12.0 days

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	1,793.00 FS	*1,434.40 FS
2	4		*REAR BUMPER STICKY PAD	Not Necessary	21.00 FS	*- FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	175.00 FS	*- FS
4	1		*WHEEL HOUSING LINER ADAPTER - RH	Not Necessary	34.00 FS	*- FS
5	1		*REAR BUMPER GUIDE SECTION - RH	Necessary	15.00 FS	*11.44 FS
6	1		*REAR BUMPER LOCKING MECHANISM	Necessary	27.00 FS	*21.20 FS
7	1		*REAR BUMPER SPOILER	Cut	216.00 FS	*172.80 FS
8	1		*REAR BUMPER LIGHT REFLECTOR - RH	Scratched	38.00 FS	*29.68 FS
9	1		*REAR BUMPER SIDE REINFORCEMENT BEAM	Not Necessary	522.00 FS	*- FS
10	2		*REAR BUMPER BRACKET LH / RH	Not Necessary	51.00 FS	*- FS
11	1		*REAR BUMPER GUIDE SECTION - RH	Deformed	60.00 FS	*47.84 FS
12	2		*REAR PARKING AID SENSOR - INNER / OUTER	Damaged (1 PCS ONLY)	462.00 FS	*184.80 FS
13	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	12.00 FS	*- FS
14	1		*REAR BUMPER WIRING SET	Not Necessary	472.00 FS	*- FS
15	1		*VENT TRIM	Not Necessary	64.00 FS	*- FS
16	1		*SIDE PANEL - RH	Buckled	2,110.00 FS	*1,688.00 FS
17	1		*REAR WINDSCREEN	Necessary	742.00 FS	*593.20 FS
18	1		*SIDE WINDOW - RH	Necessary	520.00 FS	*415.60 FS
19	1		*CROSS PANEL REINFORCEMENT	Not Necessary	669.00 FS	*- FS
20	1		*REAR CROSS PANEL	Not Necessary	329.00 FS	*- FS
21	1		*REAR CROSS PANEL CONNECTING PLATE - RH	Not Necessary	131.00 FS	*- FS
22	1		*REAR CROSS PANEL CONNECTING PLATE - RH REAR	Not Necessary	89.00 FS	*- FS
23	1		*REAR WHEEL HOUSING LINER - RH	Deformed	223.00 FS	*178.40 FS
24	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	81.00 FS	*- FS
25	1		*LED TAIL LIGHT - RH OUTER	Cracked	800.00 FS	*640.00 FS
26	1		*TAIL LIGHT TRIM - RH OUTER	Not Necessary	27.00 FS	*- FS
27	1		*LED TAIL LIGHT - RH INNER	Scratched	800.00 FS	*640.00 FS
28	1		*TAIL LIGHT TRIM - INNER	Scratched	27.00 FS	*21.52 FS
29	1		*REAR SILENCER HEAT SHIELD	Not Necessary	153.00 FS	*- FS
30	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
31	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
32	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
33	1		*METAL FILLER POWER	Necessary	280.00 FS	*280.00 FS
34	1		*REAR W/S SEALANT	Necessary	200.00 FS	*200.00 FS
35	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
36	1		*SUNDRIES	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 12,343.00 7,158.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	New	280.00	280.00
2	TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	600.00
3	TO INSTALL REAR WINDSCREEN SOLAR FILM	New	400.00	400.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	New	1,400.00	1,400.00
5	TO REMOVE AND REINSTALL REAR SEATS, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
6	TO DISMANTLE REAR BUMPER AND REAR LID. TO RENEW REAR BUMPER. CUT OUT AND WELD RHS REAR FENDER, RHS REAR INNER WHEEL HOUSING CONNECTING PLATE AND END PANELLING. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	9,100.00	3,500.00
7	TO RESPRAY BOOTLID, REAR BUMPER, RHS REAR FENDER, RHS REAR INNER WHEEL HOUSING CONNECTING PLATE, DOOR ENTRANCES ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	New	5,000.00	2,750.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
9	TO REPAIR RHS REAR INNER D-PILLAR REINFORCEMENT	New	1,050.00	750.00
Gross Labour Cost (\$\$)			19,422.00	11,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >