

2/7/03/2002

ASS. REC. BY:

REF: CS/MSG NO18607/KSF3<sup>SV</sup>

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Christina Wong of MSG Date/Time: 22.10.19 9.10a.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMG 6933C Insured: SLK 3607E

at Workshop m/s E m Solution Tel: 910 18302

of 160 sin ming drive #03-18

Policy No: 29114756MKF Claim No: 609019

Sum Insured: Excess:

Make of Veh: D.O.A. 21.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 22.10.19 9.48a.m Person Contacted: Bernard H.O.D. Endorsement:

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SMG 6933C - X
	SLK 3607E - X
23/10/19	@ 16.27 pm checked with Bernard got estimate and email to Kenneth already.
31/10	61pm @ 2000 email & confirmed (\$ 7,222.52 Red - 78%)

Maximum

ASS. REC. BY:

REF:

MSG/

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Soon:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMG 6933C

Yr Regn:

12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda

c.c.

1496

Colour:

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

15411

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMBN24A8K 0252308

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

21/10/19

D.O.I.

22/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to  
EM NOT ready

RECEIVED 4 NOV 2019

1/11/2019

Date/Time, File Pass to?

04/11/19



: Prel. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

3

Resurvey No. of Trip:

2

Survey Fee:

150

Transportation:

S + RS. SI

FUEL/OS

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

2,000/- 45

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Oct 2019		22 Oct 2019 09:10 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	GRAB RENTALS PTE.LTD., Co. Reg. No.: 201617200G								
Main Claimant:	LI YANG, ID: S8380064Z								
Vehicle Reg. No.:	SMG6933C	Date of Loss:	21/10/2019 07:00 - :59 [21 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 609019	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	SLK3607E	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/10/2019]								
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 21/10/19. (Manual Assign). OI:Grab. Liab: NR. Agree on SJE. Assign: Kenneth Kong from LKK Auto Consultants Pte Ltd. Contact: Mr Bernard @ 6456 0226 / 9101 8302.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;">View All Compose Case Mail</span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;">View All Search Tasks Create New Task Complete</span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## View Sent Message

This mail is associated with :

**\*SMG6933C (609019)**  
**[SLK3607E]**

TP  
LI YANG  
Oct 21 2019 7:00AM  
[GRAB RENTALS PTE.LTD.]  
E M Solution Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **23/10/2019 16:38 PM.**  
**To** christina\_wong@sg.msg-asia.com  
**CC** sur@lkkauto.com  
**Subject** **SMG6933C (609019) [SLK3607E] TP**

Dear Christina,

Please be informed that we have inspected the vehicle SMG 6933C on 22/10/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/10/2019 11:33
Date Of Accident	21/10/2019 07:25
Exact Location Of Accident	YISHUN RING ROAD TOWARDS YISHUN STREET 41
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG6933C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LI YANG
NRIC No	S8380064Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81634289
Alternative Phone No	OTHERS-91390003

### Vehicle Particulars

Manufacturer	MAZDA
Model	3 1.5 SKYACTIV
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900010115
Cover Note Number	

### Driver

Name of Driver	WEI WEI
NRIC No	S8380064Z
Date Of Birth	03/11/1983
Occupation	INDOOR
Date Of Driving Pass	16/01/2019
Driving Experience	0 YEAR AND 9 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91390003
Fax Number	
Contact Number	
Email Address	FORZAWEIWEI@GMAIL.COM

Address	33 YISHUN STREET 51 #08-27 SIGNATURE AT YISHUN
Postcode	767991
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO - EM SOLUTION PTE LTD
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK3607E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

21 OCT 2019  
11:33am

Driver's Signature

(if driver is not the policyholder)

Date & Time: 21 OCT 2019

11:33am


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No: Poh Kwee Choo



## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/10/2019 @ 07:26 am, I was driving along Yishun Ring Road towards Yishun Street 41. Vehicle in front of me stopped to give way to pedestrian, I followed and stopped my vehicle also. Vehicle behind could not on time and collided onto the rear portion of my vehicle.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 21 OCT 2019

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 21 OCT 2019

Reporting Centre Personnel's Signature  
Name: Poh Kwee Choo  
NRIC/FIN No.:



# E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax:

64584500

Registration No: 201016308K

Li Yang

22.10.2019

*Not Notarized  
61 Sep 8 2000h  
Repair After Paint*

## REPAIR ESTIMATE FOR MAZDA 3 - SMG 6933 C

*3 days*

1 pc	rear bumper	<i>Bur/cm</i>	1,174.80	✓
2 pcs	rear bumper reflectors	56.00	<i>h</i> 112.00	X
2 pcs	rear bumper tow hood covers	21.20	<i>h</i> 42.40	X
2 pcs	rear bumper side retainers	38.10	<i>h</i> 76.20	X
1 pc	rear bumper reinforcement	<i>Bur</i>	573.30	✓
2 pcs	rear bumper brackets	54.60	<i>n</i> 109.20	X
2 pcs	rear bumper reverse sensors	<i>shen</i> 193.90	387.80	✓
2 pcs	tail lamps assy	915.00	<i>h</i> 1,830.00	X
1 pc	boot lid		<i>n</i> 975.40	X
1 pc	boot emblem		<i>nn</i> 84.40	X
1 pc	boot "Mazda 3" badge		<i>nn</i> 56.40	X
1 pc	boot "Skyactiv Technology" badge		<i>nn</i> 66.60	X
2 pcs	boot lamps	261.00	<i>h</i> 522.00	X
1 pc	boot inner lock		<i>n</i> 183.00	X
1 pc	boot rubber		<i>h</i> 192.30	X
1 pc	rear end panel		<i>n</i> 556.10	X
1 pc	rear end panel top garnish		<i>h</i> 105.10	X
1 pc	spare tyre cover		<i>h</i> 350.00	X
1 pc	rear exhaust silencer		<i>n</i> 1,075.80	X
2 pcs	rear exhaust mountings	43.30	<i>h</i> 86.60	X
			8,559.40	
		Less 20%	1,711.88	
			6,847.52	
1 pc	rear number plate	<i>h</i>	60.00	SN X
1 set	rear bumper clips	<i>h</i>	45.00	SN ✓
1 set	rear end panel top garnish clips	<i>nn</i>	30.00	SN X
1)	Check electrical wirings and headlamp focus		60.00	<i>15h</i>
2)	Renew reverse sensors		80.00	<i>50h</i>
3)	Repair accident damages and renew above parts.		980.00	<i>300h</i>
4)	Renew rear exhaust silencer	<i>nn</i>	80.00	X
6)	Spray paint on affected portions		980.00	<i>400h</i>
7)	Tuff kote on affected portions	<i>nn</i>	60.00	X
			<u>9,222.52</u>	

Auto Consultants hence notify

The Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Oct 2019		22 Oct 2019 09:10 <a href="#">Edit Adj Rpt</a>	<b>S\$2,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>GRAB RENTALS PTE.LTD.,</b> Co. Reg. No.: 201617200G								
Main Claimant:	<b>LI YANG,</b> ID: S8380064Z								
Vehicle Reg. No.:	<b>SMG6933C</b>	Date of Loss:	21/10/2019 07:00 - :59 [10 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 609019</b>	Policy/Cover Note No.:	29114756MKF (Comprehensive) Coverage: 01/02/2019 - 31/01/2020						
Vehicle Reg. No. (Insured):	<b>SLK3607E</b>	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	<b>E M Solution Pte Ltd (HQ)</b> 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Imm.Advice due 23/10/2019]								
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 21/10/19. (Manual Assign). OI:Grab, Liab: NR. Agree on SJE. Assign: Kenneth Kong from LKK Auto Consultants Pte Ltd. Contact: Mr Bernard @ 6456 0226 / 9101 8302.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SMG6933C (609019)**  
**[SLK3607E]**  
**TP**  
**LI YANG**  
**Oct 21 2019 7:00AM**  
**[GRAB RENTALS PTE.LTD.]**  
**E M Solution Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/11/19 09:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	01/11/19 09:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	01/11/19 09:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	01/11/19 09:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	01/11/19 09:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	01/11/19 09:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	01/11/19 09:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	01/11/19 09:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	01/11/19 09:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	01/11/19 09:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	01/11/19 09:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	01/11/19 09:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	01/11/19 09:58	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	01/11/19 09:58	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
15	01/11/19 09:58	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
16	01/11/19 09:58	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
17	01/11/19 09:58	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
18	01/11/19 09:58	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
19	01/11/19 09:58	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
20	01/11/19 09:58	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
21	01/11/19 09:58	<b>Reinspection Photo</b>	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/10/19 17:33	<b>TPD SMG6933C GIA REPORT</b>	Load PDF	
2	21/10/19 17:33	<b>TPD SMG6933C - PRI</b>	Load PDF	
3	21/10/19 17:59	<b>Agree on SJE</b>	Load PDF	
4	21/10/19 18:00	<b>Workshop Details</b>	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	22/10/19 09:06	<b>Survey Request - Manual Assigned</b>	Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>		<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.				



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19018607/KSF3S2  
Date: 06/11/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756MKF
Claimant Vehicle No :	SMG6933C	Insured Vehicle No :	SLK3607E
Date of Loss:	21/10/2019	Nature of Claim:	TP
		Claim No:	609019

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SMG6933C	Engine No:	P520552217
Make & Model:	MAZDA 3, 1.5 Deluxe SkyActiv (A)	Chassis No:	JM6BN24A8K0252308
Reg. Date:	01/12/2018 (Man. Year: 2018)	Odometer:	15411 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,982.52	1,753.72	5,228.80	74.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	765.00	1,475.00	65.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,222.52</b>	<b>2,518.72</b>	<b>6,703.80</b>	<b>72.69</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>(S\$)</b>	9,222.52	2,000.00	7,222.52	78.31
<b>+ GST 7.00/7.00% (S\$)</b>	645.58	140.00	505.58	78.31
<b>Nett Amount (S\$)</b>	<b>9,868.10</b>	<b>2,140.00</b>	<b>7,728.10</b>	<b>78.31</b>

## INSPECTION

Date of Assignment:	22/10/2019	
Date Inspected:	22/10/2019	Inspected At: E M Solution Pte Ltd (HQ) 160 Sin Ming Drive., #03-18, Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Nov 2019)
<b>Parts:</b>	143	MAZDA 3 1.5 Deluxe SkyActiv (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMG6933C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	1,174.80 FL	*1,174.80 FL
2	2		*REAR BUMPER REFLECTORS	Serviceable	112.00 FL	*- FL
3	2		*REAR BUMPER TOW HOOD COVERS	Serviceable	42.40 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINERS	Serviceable	76.20 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Buckled	573.30 FL	*573.30 FL
6	2		*REAR BUMPER BRACKETS	Repair	109.20 FL	*- FL
7	2		*REAR BUMPER REVERSE SENSORS	Shorted	387.80 FL	*387.80 FL
8	2		*TAIL LAMPS ASSY	Serviceable	1,830.00 FL	*- FL
9	1		*BOOT LID	Repair	975.40 FL	*- FL
10	1		*BOOT EMBLEM	Not Necessary	84.40 FL	*- FL
11	1		*BOOT MAZDA 3 BADGE	Not Necessary	56.40 FL	*- FL
12	1		*BOOT SKYACTIV TECHNOLOGY BADGE	Not Necessary	66.60 FL	*- FL
13	2		*BOOT LAMPS	Serviceable	522.00 FL	*- FL
14	1		*BOOT INNER LOCK	Repair	183.00 FL	*- FL
15	1		*BOOT RUBBER	Serviceable	192.30 FL	*- FL
16	1		*REAR END PANEL	Repair	556.10 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Serviceable	105.10 FL	*- FL
18	1		*SPARE TYRE COVER	Serviceable	350.00 FL	*- FL
19	1		*REAR EXHAUST SILENCER	Repair	1,075.80 FL	*- FL
20	2		*REAR EXHAUST MOUNTINGS	Serviceable	86.60 FL	*- FL
21	1		*REAR NUMBER PLATE	Serviceable	60.00 FS	*- FS
22	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
23	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,694.40</b>	<b>2,180.90</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>1,711.88</b>	<b>427.18</b>
<b>Total Parts (\$\$)</b>	<b>6,982.52</b>	<b>1,753.72</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK ELECTRICAL WIRINGS.	New	60.00	15.00
2	RENEW REVERSE SENSORS.	New	80.00	50.00
3	REPAIR ACCIDENT DAMAGES AND RENEW ABOVE PARTS.	New	980.00	300.00
4	RENEW REAR EXHAUST SILENCER.	New	80.00	0.00
5	SPRAY PAINT AFFECTED PORTIONS.	New	980.00	400.00
6	TUFF KOTE ON AFFECTED PORTIONS.	New	60.00	0.00
Gross Labour Cost (S\$)			2,240.00	765.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >