

ASS. REC. BY:

REF: CS/SM019018640/04f3n2 Special Instruction:

SURVIVOR: Marcus

ASSIGNMENT (Office)

From (Person): Ruth Chun Get Tiang of SMO Date/Time: 22.10.19 13.28P.M.

Estimated Cost: Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SMC 5617T Insured: FBK 5945J

at Workshop n/s: Euro Success Tel: 98289277

of 1 Kaki Bukit Ave 6 #02-03

Policy No: D19M7MC 01003683 Claim No: CMD1904940

Sum Insured: Excess:

Make of Veh: D.O.A. 20.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS "up"

Date/Time: 22.10.2019 1.40p.m. Person Contacted: Ah Huat Vehicle IN OUT

H.O.D. Endorsement:

Date/Time Action/Instruction (✓) Estimate

SMC 5617T - X

FBK 5945J - CS/CT1 19005735/04f3n2 DCA 29/04/2019

23/10 Sent Preli to Insurance Co (Pending Estimate) Meriman

photo ok

ASST. REC. BY:

REF:

marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

29/10/19 1586. Coe 31-55-2024
1/5 #1800 confirmed with weyjie

31/10/19

Sent Preli to Merimen

RECEIVED 31 OCT 2019

Date/Time, File Pass to?

☐

Preli. Report

i)

☐

Final Report

Date/Time, File Return to?

ii)

31/10/19 Typist

Report Format:

Lump Sum

FEET:

\$1800f

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp. (\$

☐

Interview (\$

☐

Tech. Inve (\$

☐

Meal and

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

250

11

261

Veh No:

SMC 56177

Yr Regn:

6.09

Type:

M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Fit

C.C.

1339

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

96380

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GE6 1158329

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

22/10/18

Survey held at

Des. of Damages:

Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rpt

The U/C / Chassis frame / Body Structure affected due to collision.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 31 Oct 2019

Preliminary Advice

Insured Vehicle No	: FBK5945J	Accident Date	: 20/10/2019
TP Vehicle No	: SMC5617T	Assignment Date	: 22/10/2019
Make	: HONDA FIT	Est. Duration of Repair	: 3.00
Date of Inspection	: 22/10/2019		
Inspection At	: EURO SUCCESS SERVICES PTE LTD (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,761.60
Revised Amount	:S\$	1,800.00 Lump sum
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00
Lump Sum Repair	:S\$	0.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a "without" prejudice basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Oct 2019		22 Oct 2019 13:28 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	MUHAMMAD SALIKIN BIN OMAR, ID: S9506788D								
Main Claimant:	LIM SWEE LIAN								
Vehicle Reg. No.:	SMC5617T	Date of Loss:	20/10/2019 17:00 - :59						
Claim Type:	TP / CMTD1904940	Policy/Cover Note No.:	D19MTMC01003683 (Third Party Only)						
Vehicle Reg. No. (Insured):	FBK5945J	Policy No. (Claimant):							
		Excess:							
Repairer:	Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY, 417883 Kaki Bukit - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/11/2019]								
Adj Asg. Remarks:	LKK Auto Consultants, Marcus Chua (East Area) Ah Huat (Tel. 9828 9277 / 6742 6231)								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SMC5617T (CMTD1904940)
[FBK5945J]**

TP
LIM SWEE LIAN
Oct 20 2019 5:00PM
[MUHAMMAD SALIKIN BIN OMAR]
Euro Success Services Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 23/10/2019 16:50 PM.
To ruth.chua@sompo.com.sg
CC sur@lkkauto.com
Subject VEHICLE NO: SMC5617T (CMTD1904940) FBK5945J

Dear Ruth

Please be informed that we have inspected the vehicle SMC5917T on 22/10/2019.

We are still pending estimate from repairer,

Thank you

Regards
YC Wong
LKK Auto Consultants Pte Ltd

DOCUMENTS SUMMARY

There are no documents,

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

AVIVA

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Toyota C-Hr Hybrid 1.8A G (High Spec Cbu Japan)



Sell This Great Unit Bcuz Owner
Would Station Overseas, Change
Small Car For Wife
Direct Owner - [Scan Ad](#)

PRIME MOTOR 8

JOHNSON YONG CREDIT ENTERPRISES PTE LTD

With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.

Browse by Category

« Back (1 2 3 4 5) Next »

Sort by Date Posted

87 vehicles

honda fit

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	honda fit		Any	Any	2009	Any	Any	Any
	Honda Fit 1.3A G (COE till 03/2029)		\$40,800	\$4,320 /yr	15-Jul-2009	1,339 cc	-	Hatchb
Very Well Maintained By Previous Owner With No Accident Records. As Good And Clean As It Gets, Car Is In Very Mint Condition. No Repairs Needed. Owner Selling Due To Increase In Family Size. Cheapest In The Market!. High Trade In And Loan Available!								
Posted: 23-Oct-2019 Tags: 2009 Honda Fit, 2009 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda								
	Honda Fit 1.3A G (COE till 10/2024)		\$27,888	\$5,620 /yr	07-Oct-2009	1,339 cc	115,550 km	Hatchb
New Arrival								
Posted: 22-Oct-2019 Tags: 2009 Honda Fit, 2009 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda								
	Honda Fit 1.3A G (New 5-yr COE)		\$27,800	\$5,550 /yr	26-Nov-2009	1,339 cc	120,000 km	Hatchb
Beautiful Condition, Low Mileage, Low Depreciation, Loan Available, Trade-In Welcome.								
Posted: 22-Oct-2019 Tags: 2009 Honda Fit, 2009 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda								
	Honda Fit 1.3A G (New 5-yr COE)		\$28,800	\$5,750 /yr	24-Dec-2009	1,339 cc	140,500 km	Hatchb
Driven By Lady Owner. Well Maintained.								
Posted: 22-Oct-2019 Tags: 2009 Honda Fit, 2009 honda fit, Honda Fit, honda fit, Honda, Fit, fit, Used Honda								

**GET YOUR
COE
RENEWAL
LOAN**

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and approval in 2 days without effort! Enquire today.

Honda Fit 1.3A G (New 5-yr COE) **\$30,800** **\$6,150 /yr** **19-Oct-2009** **1,339 cc** **110,005 km** **Hatchb**

Compare

in Welcome! Interest Rate From 3.98%! Monthly Of \$500 Plus. Showroom Condition Guarantee, Comes With 6 Months Engine
Box Warranty, Brand New Leather Seats! Brand New Paintwork! All Our Quality Preowned Car Are Selling At Low Depreciation...

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 158G

Vehicle Details

Vehicle No.: SMC5617T

Vehicle to be Exported: No

Intended Deregistration Date: 23 Oct 2019

Vehicle Make: HONDA

Vehicle Model: FIT 1.3G A

Primary Colour: Red

Manufacturing Year: 2009

Engine No.: L13A4173049

Chassis No.: GE61158329

Maximum Power Output: 73.0 kW (97 bhp)

Open Market Value: \$14,380.00

Original Registration Date: 09 Jun 2009

First Registration Date: 09 Jun 2009

Transfer Count: 3

Actual ARF Paid: \$14,380.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 31 May 2024

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$13,943.00

COE Rebate Amount: \$12,841.00

Total Rebate Amount: \$12,841.00**Message**

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/10/2019 16:07
Date Of Accident	20/10/2019 17:30
Exact Location Of Accident	OUTRAM ROAD / SENG POH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC5617T
Insured/Policyholder	
Name Of Registered Owner	LIM SWEE LIAN
NRIC No	S7116158G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97997096
Alternative Phone No	OFFICE-97997096

Vehicle Particulars

Manufacturer	HONDA
Model	FIT 1.3G A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5110829345 CLASSIC
Cover Note Number	

Driver

Name of Driver	BRANDON WONG JING JIE
NRIC No	S9520155E
Date Of Birth	13/06/1995
Occupation	INDOOR
Date Of Driving Pass	11/07/2018
Driving Experience	1 YEAR AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97813466
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	184 CANBERRA DRIVE #07-29
Postcode	767954
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBK5945J
Vehicle Make/Model/Colour	YAMAHA / YZF-R15
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	MUHAMMAD SALIKIN BIN OMAR
NRIC/Passport Number	S9508788D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan #2

SKETCH PLAN



A: SM15617T

B: FBK5945J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above stated date and time, I was traveling along Entrance Road I was traveling straight when suddenly vehicle B dash out from Seng Poh Road and collided on to my vehicle front left portion.

DECLARATION

(We declare the foregoing particulars to be true and correct)

[Signature]
 Policyholder's Signature
 Date & Time

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 67492305
 Email: vacb@singnet.com.sg

EURO SUCCESS SERV PTE. LTD
Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231 FAX: 67411019 H/P: 98289277 (AH HUAT)

Vehicle No: SMC5617T

Model: HONDA FIT 6E6

QTY	List Items	Price \$
1	FRONT BUMPER <i>S35-20</i>	<i>re/cut</i> 750.50 ✓
1	FRONT BONNET	<i>11</i> 850.00 X
2	FRONT L-R BUMPER RETAINER @38.60 <i>25.00</i>	<i>11/5604</i> 77.20 <i>IPC</i>
1	FRONT BUMPER REFORMENT <i>re. reinforcement</i>	<i>11</i> 523.70 X
1	FRONT BUMPER REFORMENT PAD <i>re. - bump.</i>	<i>11</i> 161.20 X
1	FRONT BUMPER L/H BRACKETS	<i>11</i> 85.50 X
1	FRONT BUMPER LOWER GRILL	<i>11</i> 86.20 X
1	FRONT L/H SHOCK ABSORBER	<i>11</i> 320.00 X
1	FRONT L/H LOWER ARM	<i>11</i> 260.00 X
1	FRONT L/H KNUCKLE ARM	<i>11</i> 436.20 X
1	FRONT L/H WHEEL BEARING	<i>11</i> 430.00 X
1	FRONT L/H FENDER	<i>R</i> 450.00 X
1	FRONT L/H FENDER INNER SHIELD <i>167.20</i>	<i>11-1</i> 250.00 ✓
1	FRONT GRILL	<i>11</i> 481.60 X
1	FRONT GRILL LOGO	<i>11</i> 58.60 X
1	FRONT L/H HEADLAMP <i>S&G-10</i>	<i>scu</i> 950.00 ✓
1	FRONT L/H MIRROR W/ MOTO	<i>R</i> 450.00 X
TOTAL		\$6,620.70
LESS 20%		\$1,324.14
TOTAL		\$5,296.60

56

Special Nett Items		
1 SET	FRONT BUMPER CLIP	<i>re</i> 45.00 <i>30</i>
1 SET	FRONT GRILL CLIP	<i>11</i> 45.00 X
1 SET	FRONT FENDER SHEILD CLIP	<i>11</i> 45.00 X
1	FRONT L/H SPORT RIM	<i>cu</i> 900.00 <i>350</i>
1	FRONT L/H TYRE	<i>scu</i> 500.00 X

\$1,535.00

p-1314
20%
p-1057.20
S.N-380.00
L-820.00

2251.20
20%

1800.96

Not Authorized
make
to be photo After repair
+ / S \$ 1800 / 2
3 day.

Labour Charges

TO REMOVE AND REFIX FRONT UNDERCARRIAGE
TO RESPRAY UNDERCOATING
TO CHECK ELECTRICAL WIRING
TO RESPRAY PAINTING AND ETC
PANEL BEATING, CUT, WELD, REMOVE AND
REPLACING ABOVE PARTS

11	180.00	X
11	250.00	X
	100.00	20
	1000.00	500
	1300.00	300

\$2,930.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$9,761.60

9661.56

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part(s) to be subject to confirmation
- To display survey is on a "Without Prejudice" basis
- To display condition(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19018640/UYF3N2

Date: 06/11/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTMC01003683
Claimant Vehicle No :	SMC5617T	Insured Vehicle No :	FBK5945J
Date of Loss:	20/10/2019	Nature of Claim:	TP
		Claim No:	CMTD1904940

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC5617T	Engine No:	L13A4173049
Make & Model:	HONDA FIT, 1.3 G (A)	Chassis No:	GE61158329
Reg. Date:	09/06/2009 (Man. Year: 2009)	Odometer:	96380 km
Colour:	Red		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R16	Rear Tyre Size:	185/55R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,831.56	1,431.20	5,400.36	79.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,830.00	820.00	2,010.00	71.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,661.56	2,251.20	7,410.36	76.70
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	9,661.56	1,800.00	7,861.56	81.37
+ GST 7.00/7.00% (S\$)	676.31	126.00	550.31	81.37
Nett Amount (S\$)	10,337.87	1,926.00	8,411.87	81.37

INSPECTION

Date of Assignment:	22/10/2019	
Date Inspected:	22/10/2019 Inspected At:	Euro Success Services Pte Ltd (HQ) 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Nov 2019)
Parts:	144	HONDA FIT 1.3 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC5617T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed/Cut	750.50 FL	*535.20 FL
2	1		*FRONT BONNET	Not Necessary	850.00 FL	*- FL
3	1		*FRONT L-R BUMPER RETAINER	N/s Bent	77.20 FL	*25.50 FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	523.70 FL	*- FL
5	1		*FRONT BUMPER PAD REINFORCEMENT	Not Necessary	161.20 FL	*- FL
6	1		*FRONT BUMPER L/H BRACKETS	Not Necessary	85.50 FL	*- FL
7	1		*FRONT BUMPER LOWER GRILL	Not Necessary	86.20 FL	*- FL
8	1		*FRONT L/H SHOCK ABSORBER	Not Necessary	320.00 FL	*- FL
9	1		*FRONT L/H LOWER ARM	Not Necessary	260.00 FL	*- FL
10	1		*FRONT L/H KNUCKLE ARM	Not Necessary	436.20 FL	*- FL
11	1		*FRONT L/H WHEEL BEARING	Not Necessary	430.00 FL	*- FL
12	1		*FRONT L/H FENDER	Repair	450.00 FL	*- FL
13	1		*FRONT L/H FENDER INNER SHIELD	Torn	250.00 FL	*167.20 FL
14	1		*FRONT GRILL	Not Necessary	481.60 FL	*- FL
15	1		*FRONT GRILL LOGO	Not Necessary	58.60 FL	*- FL
16	1		*FRONT L/H HEADLAMP	Scratched	950.00 FL	*586.10 FL
17	1		*FRONT L/H MIRROR W/MOTO	Repair	450.00 FL	*- FL
18	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
19	1		*SET FRONT GRILLE CLIP	Not Necessary	45.00 FS	*- FS
20	1		*SET FRONT FENDER SHIELD CLIP	Not Necessary	45.00 FS	*- FS
21	1		*FRONT L/H SPORT RIM	Cut	900.00 FS	*350.00 FS
22	1		*FRONT L/H TYRE	Serviceable	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,155.70	1,694.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,324.14	262.80

Total Parts (S\$)	6,831.56	1,431.20
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	New	180.00	0.00
2	TO RESPRAY UNDERCOATING	New	250.00	0.00
3	TO CHECK ELECTRICAL WIRING	New	100.00	20.00
4	TO RESPRAY PAINTING AND ETC	New	1,000.00	500.00
5	PANEL BEATING,CUT,WELD,REMOVE AND REPLACING ABOVE PARTS	New	1,300.00	300.00
Gross Labour Cost (\$\$)			2,830.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >