

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883

Tel: 6747-4810 Fax: 6745-5018

cmmotors@singnet.com.sg

Our Ref: EST398/19/TP

Your Ref: TP claim against SMB65Z

18-Nov-19

Denise

MS First Capital Insurance Ltd

36 Robinson Road

#16-01 City House

Singapore 068877

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to Kawasaki no: FV8060L

Date of accident: 27-05-2019

Parts supply:

2 pcs Handle bar @\$78.00 *Best LH new*
2 pcs Handle bar grip @\$25.00 *new*
2 pcs Handle bar balancer @\$12.00 *LH ut*
1 pc Brake lever *for new*
1 pc Brake lever cable *new*
1 pc Clutch lever *ut*
1 pc R/h throttle unit *? new*
1 pc R/h throttle unit cable *? new*
2 pcs Mirror assy @\$45.00 *Damaged*
1 pc Speedometer unit *could*
1 pc Speedometer unit bracket *Best*
1 pc Headlamp *missing*
1 pc Headlamp stay *Best*
1 pc Headlamp cowling *missing*
2 pcs Front signal lamp @\$25.00 *missing*
2 pcs Front signal lamp garnish @\$35.00 *Delivered*
1 pc Horn *Dented*
1 pc Horn bracket *Best*
1 pc Front visor *missing*
1 pc Front mudguard *could*
2 pcs Front fork @\$250.00 *Best*
1 pc Front fork centre bracket *? Best*
1 pc Front fork top bracket *Best*
1 pc Front fork centre bracket *Best*
1 pc Front rim *new*
1 pc Radiator *Dented*
1 pc Radiator lower hose *new*
2 pcs Front fairing @\$160.00 *missing*
1 pc Fuel tank *Dented*
2 pcs Rear fairing @\$150.0 *Lt ut*
1 pc Front L/h footrest with bracket *could*
1 pc Front L/h gearshift lever *ut*
1 pc Rear footrest L/h *ut*
1 pc L/h side stand *new*
1 pc Rear rim *new*

S\$	156.00	<i>78</i>
	50.00	<i>+</i>
	24.00	<i>12</i>
	25.00	<i>+</i>
	45.00	<i>+</i>
	25.00	<i>✓</i>
	180.00	<i>+</i>
	65.00	<i>+</i>
	90.00	<i>✓</i>
	380.00	<i>✓</i>
	120.00	<i>✓</i>
	110.00	<i>✓</i>
	45.00	<i>✓</i>
	110.00	<i>✓</i>
	50.00	<i>✓</i>
	70.00	<i>✓</i>
	35.00	<i>✓</i>
	35.00	<i>✓</i>
	55.00	<i>✓</i>
	45.00	<i>✓</i>
	500.00	<i>✓</i>
	65.00	<i>✓</i>
	80.00	<i>✓</i>
	80.00	<i>✓</i>
	250.00	<i>+</i>
	280.00	<i>✓</i>
	25.00	<i>+</i>
	320.00	<i>✓</i>
	350.00	<i>✓</i>
	300.00	<i>157</i>
	45.00	<i>45</i>
	65.00	<i>✓</i>
	25.00	<i>✓</i>
	35.00	<i>+</i>
	250.00	<i>+</i>
	<u>4,385.00</u>	

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Re: Estimated cost of repair to Kawasaki no: FV8060L

Date of accident: 27-05-2019

Parts supply:

Balance b/f:

3220

2898

S\$ 4,385.00
Less 10%: (438.50)
3,946.50

S/Nett Items

1 pc Front tyre (S/Nett)

1 pc Rear tyre (S/Nett)

3 new

150.00 +

120.00 +

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To apply underseal

To respray affected part.

Transportation charges

To check wirings.

630

500.00 ~~280~~
50.00 ~~30~~
350.00 ~~250~~
40.00 ✓
30.00 ✓

S\$ 5,186.50

*Adrian Lj
w/s 26/11/19
04 days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3528

w/s: 2.8/c