

GUAN HIN MOTOR WORKSHOP

NO 10 ANG MO KIO INDUSTRIAL PARK 2A

#02-03 AMK AUTOPOINT 568047

Tel No. : 64837111 Fax No. : 64837221

E-Mail : guanhinmotor@yahoo.com

Buss. Reg. No. : 06035200X

Kp

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department

Contact : 63387288 Fax No. : 68804838

Estimate : ES000889

Date : 29/10/2019

Vehicle Num. : SLD 1727 S

Make/Model : VOLVO S80 T5 2.0 A/T-2015

Chassis/Eng# : YV1AS40CDG1196627/B4204T1113478

Accident Date : 10/10/2019

Claim No. :

Reference :

Policy No. : (18/11/2015)

Not Withdraw

11/10/2019

Recovery After Repair

3 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	NETT ITEMS :		
2.		REAR TOP BUMPER	cm 1,654.80	✓
3.	1	REAR BUMPER CENTRE GARNISH	cm 196.00	✓
4.				
5.	1	REAR BUMPER LOWER SPOILER	cm 535.00	✓
6.				
7.	2	REVERSE SENSOR	shon 250.00	1,000.00 ✓
8.				
9.	1	REAR BUMPER STICKER	re 150.00	✓
10.				
11.	1	REAR LOWER SPOILER STICKER	re 140.00	✓

Nett Total S\$:

3,675.80

LABOUR :

LABOUR CHARGE

TO FIXING REAR BUMPER, LOWER SPOILER

320 450.00

TO FIXING REVERSE SENSOR (4 PCS)

120.00 600

TO FIXING 2 PCS STICKER

100.00 400

SPRAY PAINTING

350.00 3200

Labour Total S\$:

1,020.00

E. & O.E.

Total S\$:

4,695.80

for GUAN HIN MOTOR WORKSHOP

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: