

2/9/03/2002

ASS. REC. BY:

REF: CS/FCI 19018662/ Eaf⁵²

Special Instruction:

Surveyor: Steve ASSIGNMENT (Office)From (Person): Merina Chia San San of FCI Date/Time: 22.10.19 2.50 p.m

Estimated Cost: _____ Bill to: _____

CD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV 1056E Insured: SHB 4684 Uat Workshop m/s Trans Eurokars Tel: 63310680of A Tanjung BenjuruPolicy No: _____ Claim No: D19006684 mpsH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 18.10.2019(Client's Record) mpv 23.10.2019

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: _____

Date/Time: 22.10.19 3.01 p.m Person Contacted: Eva Vehicle-IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV 1056E - X
	SHB 4684 U - CS/FCI 19005497/Tlvcl3er D.O.A. 21/03/2019
23/10/19 @ 1.14 p.m	revised to Merina Chia by email -
13/12/19 @ 2.13 p.m	confirmed with Catherine Chia from fig \$8335.60, 7 days. (Ref \$9634.70, 54%/-)

ASS. REC. BY:

Sten

REF:

FC1

ASSIGNMENT

From:

Date:

24.10.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLU 1056E

at Workshop n/s

Trans Eurokars

of

27A Tanjung Binjura

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

After 12.00 p.m

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLU 1056E

Yr Regn:

23/11/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

c.c

1496

Colour

Blk

A/C:

Insured / Std / NI / NA

Sp. Reading

3454

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM 68N 22 A 8H015 7120

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205 160R16

R:

4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Toyo

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

18/10/19

D.O.I.

24/10/19

Survey held at

Trans Eurokars

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV - 69K

RECEIVED 13 DEC 2019

Date/Time, File Pass to?



Preli. Report

1) 13/12 trans



Final Report

Date/Time, File Return to?

2)

Rep. Form:

TP

Engr. Sign / F.B. 12

8335.60

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Week end (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

7x15 = 105

105 + 170 = 275

275

50

50

48

423

MOTOR SURVEY ASSIGNMENT

Date	21-10-2019	Our Ref No. D19006684MFSH
Accident Date	18-10-2019	Claim Type. Third Party
Insured Vehicle	SHB4684U	Third Party Vehicle. SLU1056E
Survey Location	27A TANJONG PENJURU	
Contact Person.	JOBİ THOMAS	
Contact No.	63310680/ 0	Fax No. 63310690
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS EUROKARS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MERINA CHIA SAN SAN	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 13 December 2019 2:13 PM
To: catherinechua@eurokars.com.sg; Steve Chen (LKK Auto)
Cc: jobithomas@eurokars.com.sg
Subject: RE: SLU1056E - FINALIZATION OF COR

Dear Catherine,

WITHOUT PREJUDICE

Confirm final fig \$8,335.60 before GST and 7 repair days.

Kindly send the relevant documents to MS First Capital Insurance company.

Best Wishes for Merry Christmas & Happy New Year 2020

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: catherinechua@eurokars.com.sg <catherinechua@eurokars.com.sg>
Sent: Friday, 13 December 2019 9:37 AM
To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Cc: jobithomas@eurokars.com.sg; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Subject: SLU1056E - FINALIZATION OF COR

Dear Steve

Our COR computation with B4 paint photos is attached for your agreement.

COR: \$8335.60 before GST

7 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible.

Thanks n Regards



Driving luxury experiences since 1985

Catherine Chua

Insurance Claims Executive

23 Leng Kee Road Singapore 159095

T: (65) 6603 6128 **D:** (65) 6603 6121 **F:** (65) 6476 7417

E: catherinechua@mazda.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

Shiau Chan (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Monday, 25 November 2019 2:52 PM
To: SUR
Subject: FW: SLU1056E - Supplementary
Attachments: IMG_5424.jpg; IMG_5426.jpg; IMG_5428.jpg; IMG_5431.jpg; IMG_5433.jpg; IMG_5443.jpg; IMG_5445.jpg; IMG_5447.jpg; IMG_5987.jpg; IMG_5988.jpg; IMG_5989.jpg; IMG_5990.jpg; IMG_5991.jpg; SLU1056E - Marked estiamte.pdf

CS/FC119018662/Eqf3

From: samuel.ng@eurokars.com.sg <samuel.ng@eurokars.com.sg>
Sent: Saturday, 23 November, 2019 10:21 AM
To: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; jobithomas@eurokars.com.sg; jessicahs@eurokars.com.sg
Subject: SLU1056E - Supplementary

Dear Steve,

Kindly refer to the marked estimate with highlight and damaged items need to replace as attached.

We would like to request additional \$ 400.00 to respray Front Reinforcement and Rear Reinforcement.

2	MZ-SP-SFRT03	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP. 690	830
4	MZ-SP-SREAR5	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID. 1260	1260

Kindly confirm the check items and revert to us.

Thank you.

Best Regards,
Samuel Ng
Insurance Claims Officer
Trans Eurokars Pte Ltd

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 25 October 2019 1:14 PM
To: 'CWS Motor Claims'; assignments; SUR
Cc: 'Merina Chia'
Subject: RE: SURVEY ASSESSMENT - D19006684MFSH/1
Attachments: CSFCI19018662Eqf3.pdf

Dear Merina,

Enclosed herewith preliminary advice of SLU 1056E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Tuesday, 22 October 2019 3:13 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Merina Chia' <MerinaChia@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006684MFSH/1

Dear Sir/Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Tuesday, 22 October, 2019 2:50 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Merina Chia <MerinaChia@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006684MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006684MFSH

Date: 25 October 2019

Our Ref: CS/FCI19018662/Eqd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLU 1056E

Please be informed that we had conducted the inspection of the abovementioned vehicle on 24/10/2019 at the premises of M/s TRANS EUROKARS, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>17,970.30</u>
Revised Estimate Amount	: S\$ <u>7,214.00</u>
"Check" Items Amount	: S\$ <u>3,539.50</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front and rear portion.



Yours faithfully

Steve
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/10/2019 10:13
Date Of Accident	18/10/2019 17:50
Exact Location Of Accident	BKE TO SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU1056E
Insured/Policyholder	
Name Of Registered Owner	KU SWEE HWA
NRIC No	S7273183B
Email Address	KUSH@MAZDA.COM.SG
Mobile Phone No	(LOCAL) +65-97312134
Alternative Phone No	OFFICE-97312134

Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	KU SWEE HWA
NRIC No	S7273183B
Date Of Birth	31/07/1972
Occupation	INDOOR
Date Of Driving Pass	06/10/1992
Driving Experience	27 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97312134
Fax Number	
Contact Number	OFFICE-97312134
EEmail Address	KUSH@MAZDA.COM.SG

Address	479 SEMBAWANG DRIVE #09-375
Postcode	750479
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : LAM YOKE HENG GENDER: : MALE
Passenger 2	NAME: : YAU ZHI WEN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

KINDLY REFER TO THE ATTACHED SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB4684U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SMD579Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

KU SWEE HWA

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLU1056E

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 2

Name

LAM YOKE HENG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLU1056E

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

DETAILS OF INJURED PERSON 3

Name

YAU ZHI WEN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLU1056E

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SHB4684 U SL41056E SMD579Y

LICENSE PLATE NO: SLV 1056U.

CONTACT NUMBER: 97312134 .

EMAIL: kush9maza@gmail.com

I was driving along BKE to SLE and my car A was stationary position. Suddenly, car B hit me and my car A move forward and hit car C.

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY.

PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

PLEASE STATE: ☐ CLAIM OWN POLICY ☒ CLAIM THIRD PARTY ☐ REPORTING ONLY

I/We declare the foregoing particulars are true in every respect.

Driver's Signature

(If driver is not the policyholder)

Reporting Centre Personnel's Signature

NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	183B
Vehicle Details	
Vehicle No.:	SLU1056E
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 SEDAN 1.5 AT EU6
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520449962
Chassis No.:	JM6BN22A8H0157120
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$14,937.00
Original Registration Date:	23 Nov 2017
First Registration Date:	23 Nov 2017
Transfer Count:	1
Actual ARF Paid:	\$9,937.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Nov 2027
PARF Rebate Amount:	\$7,452.00
Intended COE Rebate Details	
COE Expiry Date:	22 Nov 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,201.00
COE Rebate Amount:	\$36,522.00
Total Rebate Amount:	\$43,974.00

The information contained herein is correct as at 24 Oct 2019

OK



CERTIFICATE OF INSURANCE

MAZDA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : KU SWEE HWA
Period of Insurance : 24 May 2019 To 23 May 2020
Engine No. : P520449962
Chassis No. : JM6BN22A8H0157120

Vehicle No. : SLU1056E
Policy No. : 1800072264-01
Endorsement No. :
Issued Date : 24 Apr 2019

ABOUT THE COVER

Make/Model : MAZDA 3 1.5 SKYACTIV

Engine Capacity/Tonnage : 1,496.00 CC

Driver Restriction : NA

Sum Insured : Market Value

Off Peak Car : No

First Year of Registration : 2017

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

KU SWEE HWA - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Trans Eurokars Pte Ltd Add: 27A Tanjong Penjuru, Singapore 609042 63310608

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0503599155

ARF (AP) PTE LTD - TE STAFF

7 MAXWELL ROAD #01-100 ANNEX B MND COMPLEX

SINGAPORE 069111

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

AIGSGMOBILEAPP



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Ku Swee Hwa ADDRESS: Sembawang TEL: 97312134		WIP: 53991 EXCESS: DATE: 21-Oct-19	
VEH NO:	SLU1056E	DATE IN:		CONTACT PERSON:	Jobi 63310682
CHASSIS NO:	JM6BN22A8H0157120	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA3	DATE REG.:	23-Nov-17	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY	REVISED	PRICES		
1	FRONT BUMPER x R 1		MB63B-50-0318BB	\$	866.80 X
2	FRONT REINFORCEMENT ? 1		MB61K-50-070A	\$	502.80 ✓
3	COVER LHF, FRONT BUMPER / MIS 1		MB63B-50-102	\$	36.60 ✓
4	CLIP, FRONT BUMPER / N/C 12		MC274-50-133	\$	44.40 ✓
5	FASTENER, FRONT BUMPER / N/C 2		MB45A-56-146A	\$	6.00 ✓
6	GROMMET, FRONT BUMPER / N/C 2		MGHP9-50-025	\$	5.80 ✓
7	SEAL RUBBER, FRONT BUMPER / N/C 2		MB63B-50-2G2	\$	4.80 ✓
8	GRILLE TOP x R 1		MB63B-50-033A2P	\$	329.40 X
9	RIVET, GRILLE TOP / N/C 4		MTK21-50-355	\$	36.80 ✓
10	RIVET, GRILLE TOP / N/C 4		M5515-51-833	\$	16.00 ✓
11	BRACKET TOP, GRILLE ? x NN 1		MB63B-50-717	\$	95.40 X
12	FASTENER, GRILLE / N/C 8		MGD7A-50-EA1	\$	25.60 ✓
13	MASCOT, FRONT / N/C 1		MD10J-51-730	\$	61.50 ✓
14	BRACKET LHS, FRONT GRILLE ? / DR 1		MB63B-50-163	\$	27.30 ✓
15	BRACKET RHS, FRONT GRILLE ? / DR 1		MB63B-50-153	\$	27.30 ✓
16	PIN LOCATOR, FRONT GRILLE ? x NN 2		MKD45-50-1K5A	\$	5.80 X
17	GROMMET, FRONT GRILLE ? / N/C 2		MKD45-50-ES1	\$	5.80 ✓
18	RIVET, FRONT GRILLE / N/C 4		MEA01-50-037	\$	32.00 ✓
19	CLIP, FRONT GRILLE / N/C 1		MGHP9-50-EB1A	\$	3.40 ✓
20	SEAL RUBBER, FRONT GRILLE x NN 2		MB63C-50-2G2	\$	5.60 X
21	STAY LOCK ? x NN 1		MB45A-52-15Y	\$	40.80 X
22	PLATE SEAL LHS ? x NN 1		MB63B-50-1V1	\$	32.70 X
23	FASTENER, PLATE SEAL ? x NN 4		MKD45-50-EA1	\$	10.80 X
24	PLATE SET, FRONT REINFORCEMENT / DR 1		MB63E-50-1C0A	\$	70.40 ✓
25	FASTENER, PLATE SET / N/C 4		MGD7A-50-EA1	\$	12.80 ✓
26	HEADLAMP LHS ? x NN 1		MBABK-51-0LOE	\$	1,070.50 X
27	HEADLAMP RHS ? x NN 1		MBABK-51-0KOE	\$	1,070.50 X
28	CLIP, HEADLAMP ? x NN 4		MDR61-50-133	\$	26.00 X
29	RIVET, HEADLAMP ? x NN 2		MB092-51-833	\$	7.00 X
30	REAR BUMPER / DR 1		MBHN1-50-221ABB	\$	1,128.60 ✓

31	BRACKET CENTER	✓ X NA	1	MKD53-50-251		\$ 5.40	X
32	TOWING COVER LHS	✓ MIS	1	MBHN1-50-EL1 BB		\$ 16.50	✓
33	TOWING COVER RHS	✓ MIS	1	MBHN1-50-EK1 BB		\$ 17.10	✓
34	REFLECTOR RHS	✓ X NA	1	MD350-51-5M0E		\$ 53.00	X
35	REAR REINFORCEMENT	✓ DO	1	MB45A-50-260		\$ 564.20	✓
36	GROMMET, REAR BUMPER	✓ NC	4	MBHN1-50-0Z1A		\$ 10.80	✓
37	GROMMET, REAR BUMPER	✓ NC	2	M9991-00-501		\$ 6.00	✓
38	FASTENER, REAR BUMPER	✓ NC	4	MB45A-56-146A		\$ 12.00	✓
39	RIVET, REAR BUMPER	✓ NC	4	MBBM4-50-355		\$ 18.00	✓
40	ORNAMENT, MAZDA	✓ MIS	1	MBHN1-51-721		\$ 56.10	✓
41	MASCOT, REAR	✓ X NA	1	MBHN1-51-730		\$ 78.20	X
42	ORNAMENT, SKYACTIVE	✓ X NA	1	MBHN1-51-771		\$ 66.80	X
43	FASTENER, BOOTLID	✓ NC	2	MEG21-51-146		\$ 12.40	✓
44	GROMMET, BOOTLID	✓ NC	2	MGA7B-51-146		\$ 6.60	✓
45	GASKET LHS, BOOTLID	✓ NC	1	MB45A-51-3J8		\$ 22.00	✓
46	GASKET RHS, BOOTLID	✓ NC	1	MB45A-51-3H8		\$ 22.00	✓
47	GASKET LHS, TAILLAMP	✓ NC	1	MBHN1-51-163		\$ 22.00	✓
48	GASKET RHS, TAILLAMP	✓ NC	1	MBHN1-51-153		\$ 22.00	✓
TOTAL PARTS						\$ 6,620.30	
TOTAL PARTS COST						\$ 6,620.30	

Labour Description

1	MZ-BR-FRONT3	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. 660	660	\$ 1,650.00
2	MZ-SP-SFRT03	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP. 690	830 + 200 = 1030	\$ 1,575.00
3	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL, BOOTLID AND ALL AREAS AFFECTED BY THE ACCIDENT. 1481.5	990	\$ 2,640.00
4	MZ-SP-SREAR5	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.	1260 + 400 = 1660	\$ 2,835.00
5		TO SUPPLY FRONT GRILLE ASSY. NR	NETT	\$ 560.00
6	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	NETT	\$ 660.00
7	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	NETT	\$ 330.00
8	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE. (SPECIAL PLATE) NR	NETT	\$ 150.00
9	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
10	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00

11	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180 ✓	\$ 350.00
12	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 11,350.00
TOTAL PARTS	\$ -	\$ 6,620.30
TOTAL	\$ -	\$ 17,970.30
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

[Signature]
25/10/19 Steve (LKK)

WTL MTL 24/10/19, 12:00 PM
7 dy
P/P
By Bel Smy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Ku Swee Hwa ADDRESS: Sembawang TEL: 97312134		WIP: 53991 EXCESS: DATE: 21-Oct-19	
VEH NO:	SLU1056E	DATE IN:		CONTACT PERSON:	Jobi 63310682
CHASSIS NO:	JM6BN22A8H0157120	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA3	DATE REG.:	23-Nov-17	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY	REVISED	PRICES		
1	FRONT BUMPER x R	1	MB63B-50-031BBB		\$ 866.80
2	FRONT REINFORCEMENT ?	1	MB61K-50-070A		\$ 502.80
3	COVER LHF, FRONT BUMPER / MIS	1	MB63B-50-102		\$ 36.60
4	CLIP, FRONT BUMPER / NC	12	MC274-50-133		\$ 44.40
5	FASTENER, FRONT BUMPER / NC	2	MB45A-56-146A		\$ 6.00
6	GROMMET, FRONT BUMPER / NC	2	MGHP9-50-025		\$ 5.80
7	SEAL RUBBER, FRONT BUMPER / NC	2	MB63B-50-2G2		\$ 4.80
8	GRILLE TOP x R	1	MB63B-50-033A2P		\$ 329.40
9	RIVET, GRILLE TOP / NC	4	MTK21-50-355		\$ 36.80
10	RIVET, GRILLE TOP / NC	4	MS515-51-833		\$ 16.00
11	BRACKET TOP, GRILLE ?	1	MB63B-50-717		\$ 95.40
12	FASTENER, GRILLE / NC	8	MGD7A-50-EA1		\$ 25.60
13	MASCOT, FRONT / NC	1	MD10J-51-730		\$ 61.50
14	BRACKET LHS, FRONT GRILLE ?	1	MB63B-50-163		\$ 27.30
15	BRACKET RHS, FRONT GRILLE ?	1	MB63B-50-153		\$ 27.30
16	PIN LOCATOR, FRONT GRILLE ?	2	MKD45-50-1K5A		\$ 5.80
17	GROMMET, FRONT GRILLE ? / NC	2	MKD45-50-ES1		\$ 5.80
18	RIVET, FRONT GRILLE / NC	4	MEA01-50-037		\$ 32.00
19	CLIP, FRONT GRILLE / NC	1	MGHP9-50-EB1A		\$ 3.40
20	SEAL RUBBER, FRONT GRILLE x	2	MB63C-50-2G2		\$ 5.60
21	STAY LOCK ?	1	MB45A-52-15Y		\$ 40.80
22	PLATE SEAL LHS ?	1	MB63B-50-1V1		\$ 32.70
23	FASTENER, PLATE SEAL ?	4	MKD45-50-EA1		\$ 10.80
24	PLATE SET, FRONT REINFORCEMENT / DR	1	MB63E-50-1C0A		\$ 70.40
25	FASTENER, PLATE SET / NC	4	MGD7A-50-EA1		\$ 12.80
26	HEADLAMP LHS ?	1	MBABK-51-0L0E		\$ 1,070.50
27	HEADLAMP RHS ?	1	MBABK-51-0K0E		\$ 1,070.50
28	CLIP, HEADLAMP ?	4	MDR61-50-133		\$ 26.00
29	RIVET, HEADLAMP ?	2	MB092-51-833		\$ 7.00
30	REAR BUMPER / DR	1	MBHN1-50-221ABB		\$ 1,128.60

31	BRACKET CENTER	1	MKD53-50-251	\$ 5.40
32	TOWING COVER LHS / MIS	1	MBHN1-50-EL1 BB	\$ 16.50
33	TOWING COVER RHS / MIS	1	MBHN1-50-EK1 BB	\$ 17.10
34	REFLECTOR RHS	1	MD350-51-5M0E	\$ 53.00
35	REAR REINFORCEMENT	1	MB45A-50-260	\$ 564.20
36	GROMMET, REAR BUMPER / RL	4	MBHN1-50-021A	\$ 10.80
37	GROMMET, REAR BUMPER / RL	2	M9991-00-501	\$ 6.00
38	FASTENER, REAR BUMPER / RL	4	MB45A-56-146A	\$ 12.00
39	RIVET, REAR BUMPER / RL	4	M8BM4-50-355	\$ 18.00
40	ORNAMENT, MAZDA / MIS	1	MBHN1-51-721	\$ 56.10
41	MASCOT, REAR X	1	MBHN1-51-730	\$ 78.20
42	ORNAMENT, SKYACTIVE X	1	MBHN1-51-771	\$ 66.80
43	FASTENER, BOOTLID / RL	2	MEG21-51-146	\$ 12.40
44	GROMMET, BOOTLID / RL	2	MGA7B-51-146	\$ 6.60
45	GASKET LHS, BOOTLID / RL	1	MB45A-51-3J8	\$ 22.00
46	GASKET RHS, BOOTLID / RL	1	MB45A-51-3H8	\$ 22.00
47	GASKET LHS, TAILLAMP / RL	1	MBHN1-51-163	\$ 22.00
48	GASKET RHS, TAILLAMP / RL	1	MBHN1-51-153	\$ 22.00
TOTAL PARTS				\$ 6,620.30
TOTAL PARTS COST				\$ 6,620.30

Labour Description

1	MZ-BR-FRONT3	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. 660	660	\$ 1,650.00
2	MZ-SP-SFRT03	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP. 690	830	\$ 1,575.00
3	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL, BOOTLID AND ALL AREAS AFFECTED BY THE ACCIDENT. LHS 1.5	990	\$ 2,640.00
4	MZ-SP-SREAR5	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID. 1260	1260	\$ 2,835.00
5		TO SUPPLY FRONT GRILLE ASSY. / OR	NETT	\$ 560.00
6	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	NETT	\$ 330 \$ 660.00
7	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	NETT	\$ 330.00 ✓
8	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE. (SPECIAL PLATE) OR	NETT	\$ 150.00 ✓
9	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00 X
10	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150.	\$ 250.00

11	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
12	MZ-BR-SUNDRI	SUNDRIES.	NETT	\$ 100.00
				40
			TOTAL LABOUR	\$ - \$ 11,350.00
			TOTAL PARTS	\$ - \$ 6,620.30
			TOTAL	\$ - \$ 17,970.30
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

Steve (LKK) WTL Amw 24/10/19, 12.30 PM
7 dy
P/P
Ry BpL sm



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Ku Swee Hwa ADDRESS : Sembawang TEL : 97312134		WIP : 53991 EXCESS : DATE: 21-Oct-19	
VEH NO :	SLU1056E	DATE IN :		CONTACT PERSON :	Jobi 63310682
CHASSIS NO :	JM6BN22A8H0157120	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3	DATE REG.:	23-Nov-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	FRONT BUMPER	1	MB63B-50-0318BB		\$ 866.80
2	FRONT REINFORCEMENT	1	MB61K-50-070A	\$ 502.80	\$ 502.80
3	COVER LHF, FRONT BUMPER	1	MB63B-50-102	\$ 36.60	\$ 36.60
4	CLIP, FRONT BUMPER	12	MC274-50-133	\$ 44.40	\$ 44.40
5	FASTENER, FRONT BUMPER	2	MB45A-56-146A	\$ 6.00	\$ 6.00
6	GROMMET, FRONT BUMPER	2	MGHP9-50-025	\$ 5.80	\$ 5.80
7	SEAL RUBBER, FRONT BUMPER	2	MB63B-50-2G2	\$ 4.80	\$ 4.80
8	GRILLE TOP	1	MB63B-50-033A2P		\$ 329.40
9	RIVET, GRILLE TOP	4	MTK21-50-355	\$ 36.80	\$ 36.80
10	RIVET, GRILLE TOP	4	MS51S-51-833	\$ 16.00	\$ 16.00
11	BRACKET TOP, GRILLE	1	MB63B-50-717		\$ 95.40
12	FASTENER, GRILLE	8	MGD7A-50-EA1	\$ 25.60	\$ 25.60
13	MASCOT, FRONT	1	MD10J-51-730	\$ 61.50	\$ 61.50
14	BRACKET LHS, FRONT GRILLE	1	MB63B-50-163	\$ 27.30	\$ 27.30
15	BRACKET RHS, FRONT GRILLE	1	MB63B-50-153	\$ 27.30	\$ 27.30
16	PIN LOCATOR, FRONT GRILLE	2	MKD45-50-1K5A		\$ 5.80
17	GROMMET, FRONT GRILLE	2	MKD45-50-ES1	\$ 5.80	\$ 5.80
18	RIVET, FRONT GRILLE	4	MEA01-50-037	\$ 32.00	\$ 32.00
19	CLIP, FRONT GRILLE	1	MGHP9-50-EB1A	\$ 3.40	\$ 3.40
20	SEAL RUBBER, FRONT GRILLE	2	MB63C-50-2G2		\$ 5.60
21	STAY LOCK	1	MB45A-52-15Y		\$ 40.80
22	PLATE SEAL LHS	1	MB63B-50-1V1		\$ 32.70
23	FASTENER, PLATE SEAL	4	MKD45-50-EA1		\$ 10.80
24	PLATE SET, FRONT REINFORCEMENT	1	MB63E-50-1COA	\$ 70.40	\$ 70.40
25	FASTENER, PLATE SET	4	MGD7A-50-EA1	\$ 12.80	\$ 12.80
26	HEADLAMP LHS	1	MBABK-51-0LOE		\$ 1,070.50
27	HEADLAMP RHS	1	MBABK-51-0KOE		\$ 1,070.50
28	CLIP, HEADLAMP	4	MDR61-50-133		\$ 26.00
29	RIVET, HEADLAMP	2	MB092-51-833		\$ 7.00
30	REAR BUMPER	1	MBHN1-50-221A8B	\$ 1,128.60	\$ 1,128.60
31	BRACKET CENTER	1	MKD53-50-251		\$ 5.40

32	TOWING COVER LHS	1	MBHN1-50-EL1 BB	\$ 16.50	\$ 16.50
33	TOWING COVER RHS	1	MBHN1-50-EK1 BB	\$ 17.10	\$ 17.10
34	REFLECTOR RHS	1	MD350-51-5M0E		\$ 53.00
35	REAR REINFORCEMENT	1	MB45A-50-260	\$ 564.20	\$ 564.20
36	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	\$ 10.80	\$ 10.80
37	GROMMET, REAR BUMPER	2	M9991-00-501	\$ 6.00	\$ 6.00
38	FASTENER, REAR BUMPER	4	MB45A-56-146A	\$ 12.00	\$ 12.00
39	RIVET, REAR BUMPER	4	MBBM4-50-355	\$ 18.00	\$ 18.00
40	ORNAMENT, MAZDA	1	MBHN1-51-721	\$ 56.10	\$ 56.10
41	MASCOT, REAR	1	MBHN1-51-730		\$ 78.20
42	ORNAMENT, SKYACTIVE	1	MBHN1-51-771		\$ 66.80
43	FASTENER, BOOTLID	2	MEG21-51-146	\$ 12.40	\$ 12.40
44	GROMMET, BOOTLID	2	MGA7B-51-146	\$ 6.60	\$ 6.60
45	GASKET LHS, BOOTLID	1	MB45A-51-3J8	\$ 22.00	\$ 22.00
46	GASKET RHS, BOOTLID	1	MB45A-51-3H8	\$ 22.00	\$ 22.00
47	GASKET LHS, TAILLAMP	1	MBHN1-51-163	\$ 22.00	\$ 22.00
48	GASKET RHS, TAILLAMP	1	MBHN1-51-153	\$ 22.00	\$ 22.00
TOTAL PARTS COST				\$ 2,855.60	\$ 6,620.30

Labour Description					
1	MZ-BR-FRONT3	TO REPLACE FRONT REINFORCEMENT. TO REPAIR FRONT BUMPER, GRILLE TOP AND AREAS AFFECTED IN THE ACCIDENT.	\$ 660.00	\$ 1,650.00	
2	MZ-SP-SFRT03	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP.	\$ 830.00	\$ 1,575.00	
3	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR AREAS AFFECTED BY THE ACCIDENT.	\$ 990.00	\$ 2,640.00	
4	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	\$ 1,260.00	\$ 2,835.00	
5		TO SUPPLY FRONT GRILLE ASSY.	\$ 560.00	\$ 560.00	
6	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	\$ 330.00	\$ 660.00	
7	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	\$ 330.00	\$ 330.00	
8	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE. (SPECIAL PLATE)	\$ 150.00	\$ 150.00	
9	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00	
10	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00	
11	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 180.00	\$ 350.00	
12	MZ-BR-SUNDRI	SUNDRIES.	\$ 40.00	\$ 100.00	
TOTAL LABOUR			\$ 5,480.00	\$ 11,350.00	
TOTAL PARTS			\$ 2,855.60	\$ 6,620.30	
TOTAL			\$ 8,335.60	\$ 17,970.30	
LESS EXCESS			\$ -	\$ -	
TOTAL AFTER EXCESS			\$ 8,335.60		
GST 7%			\$ 583.49	\$ -	
GRAND TOTAL			\$ 8,919.09	\$ -	

REMARKS:

7 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FC19018662/Eqf3s2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-12-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4684U	Veh. Inspected	SLU 1056E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006684MFSH	Excess (\$)	0.00	
Assign From	MERINE CHIA SAN SAN	Assign Date	22/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8H0157120	Colour	BLUE	
Odometer	34154	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TOYO	5 mm	
L/H Front Tyre	205/60 R16	TOYO	5 mm	
R/H Rear Tyre	205/60 R16	TOYO	5 mm	
L/H Rear Tyre	205/60 R16	TOYO	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORITON. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/10/2019	Inspection Date	24/10/2019	
Survey held at	27A TANJONG PENJURU SINGAPORE 609042			
Repairer	TRANS EUROKARS PTE LTD			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 1056E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	866.80	-
1	FRONT REINFORCEMENT	DENTED	502.80	502.80
1	COVER LHF, FRONT BUMPER	MISSING	36.60	36.60
12	CLIP, FRONT BUMPER	NECESSARY	44.40	44.40
2	FASTENER, FRONT BUMPER	NECESSARY	6.00	6.00
2	GROMMET, FRONT BUMPER	NECESSARY	5.80	5.80
2	SEAL RUBBER, FRONT BUMPER	NECESSARY	4.80	4.80
1	GRILLE TOP	TO REPAIR SEE LABOUR	329.40	-
4	RIVET, GRILLE TOP	NECESSARY	36.80	36.80
4	RIVET, GRILLE TOP	NECESSARY	16.00	16.00
1	BRACKET TOP, GRILLE	NOT NECESSARY	95.40	-
8	FASTENER, GRILLE	NECESSARY	25.60	25.60
1	MASCOT, FRONT	NECESSARY	61.50	61.50
1	BRACKET LHS, FRONT GRILLE	BROKEN	27.30	27.30
1	BRACKET RHS, FRONT GRILLE	BROKEN	27.30	27.30
2	PIN LOCATOR, FRONT GRILLE	NOT NECESSARY	5.80	-
2	GROMMET, FRONT GRILLE	NECESSARY	5.80	5.80
4	RIVET, FRONT GRILLE	NECESSARY	32.00	32.00
1	CLIP, FRONT GRILLE	NECESSARY	3.40	3.40
2	SEAL RUBBER, FRONT GRILLE	NOT NECESSARY	5.60	-
1	STAY LOCK	NOT NECESSARY	40.80	-
1	PLATE SEAL LHS	NOT NECESSARY	32.70	-
4	FASTENER, PLATE SEAL	NOT NECESSARY	10.80	-
1	PLATE SET, FRONT REINFORCEMENT	BROKEN	70.40	70.40
4	FASTENER, PLATE SET	NECESSARY	12.80	12.80
1	HEADLAMP LHS	NOT NECESSARY	1,070.50	-
1	HEADLAMP RHS	NOT NECESSARY	1,070.50	-
4	CLIP, HEADLAMP	NOT NECESSARY	26.00	-
2	RIVET, HEADLAMP	NOT NECESSARY	7.00	-

Report Ref No. CS/FCI19018662/Eqf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER	BROKEN	1,128.60	1,128.60
1	BRACKET CENTER	NOT NECESSARY	5.40	-
1	TOWING COVER LHS	MISSING	16.50	16.50
1	TOWING COVER RHS	MISSING	17.10	17.10
1	REFLECTOR RHS	NOT NECESSARY	53.00	-
1	REAR REINFORCEMENT	DENTED	564.20	564.20
4	GROMMET, REAR BUMPER	NECESSARY	10.80	10.80
2	GROMMET, REAR BUMPER	NECESSARY	6.00	6.00
4	FASTENER, REAR BUMPER	NECESSARY	12.00	12.00
4	RIVET, REAR BUMPER	NECESSARY	18.00	18.00
1	ORNAMENT, MAZDA	MISSING	56.10	56.10
1	MASCOT, REAR	NOT NECESSARY	78.20	-
1	ORNAMENT, SKYACTIVE	NOT NECESSARY	66.80	-
2	FASTENER, BOOTLID	NECESSARY	12.40	12.40
2	GROMMET, BOOTLID	NECESSARY	6.60	6.60
1	GASKET LHS, BOOTLID	NECESSARY	22.00	22.00
1	GASKET RHS, BOOTLID	NECESSARY	22.00	22.00
1	GASKET LHS, TAILLAMP	NECESSARY	22.00	22.00
1	GASKET RHS, TAILLAMP	NECESSARY	22.00	22.00
			6,620.30	2,855.60
	SPECIAL NETT ITEMS			
1	FRONT GRILLE ASSY (SN)	BROKEN	560.00	560.00
1	NUMBER PLATE (SPECIAL PLATE) (SN)	BROKEN	150.00	150.00
1	SUNDRIES (SN)	NECESSARY	100.00	40.00
			810.00	750.00
	LABOUR			
	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND GRILLE TOP.		1,650.00	660.00
	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP.		1,575.00	830.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. TO REPAIR REAR END PANEL, BOOTLID AND ALL AREAS AFFECTED BY THE ACCIDENT.		2,640.00	990.00
	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND BOOT LID.		2,835.00	1,260.00
	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)		660.00	330.00
	TO TRANSFER REVERSE CAMERA.		330.00	330.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	180.00
			10,540.00	4,730.00
	GRAND TOTAL		17,970.30	8,335.60
RECOMMENDED COST OF REPAIRS				8,335.60

Report Ref No. CS/FCI19018662/Eqf3s2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.