

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1335/2019/NS
Date : 08-Nov-19

Vehicle not IN workshop. Kindly arrange for survey.

Your insured vehicle is : **SGH 150 A**

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120



Attn: Mr.Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr.Tan Soon Pheng
Address : Blk 52 Strathmore Avenue
#18-239
Singapore 141052
Telephone : (HP) + 65 97893265
Type of Claim : Third Party Claims
Policy No. : 1800068072-01
Vehicle No : **SMA 5054 C**
Model Code : Q3 1.4 TFSI S tronic
Model / Year : 11/6/118
Engine No : CZD 872649
Chassis No : WAUZZZ8U5JR073576
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 07-Nov-19
Place of Accident : Killiney Road Side Parking ; Outside Fook Kin

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMA 5054C

S/N	Nature of Jobs	Estimated Charges	
1	To remove and transfer rear parking aid. Check function and renew according to damage	S/N \$ 280.00	\$ 280.00 /
2	To dismantle and renew rear bumper. Reorganise crash management components. Reinstall all parts removed.	\$ 1,200.00	\$ 500.00 /
3	To respray rear bumper	\$ 1,000.00	\$ 550.00 /
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00 /
TOTAL LABOUR CHARGES		: \$ 2,672.00	\$ 1,522.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn NoJ SMA 5054 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,354.00	
2	REAR BUMPER FIXING PARTS	\$ 112.00	
3	REAR BUMPER SPOILER-LH	\$ 434.00	\$ 346.80
4	REAR BUMPER TOWING EYE COVER-RH	\$ 24.00	
5	REAR BUMPER TOWING EYE COVER-LH	\$ 39.00	
6	TAIL LIGHT-RH	\$ 418.00	\$ 334.40
7	REAR PARKING AID SENSOR	\$ 231.00	
8	REAR WHEEL COVER-LH/RH	2 \$ 472.00	\$ 377.60
9	REAR BUMPER CARRIER	\$ 569.00	
10	REAR BUMPER GUIDE SECTION-RH	\$ 91.00	
11	REAR BUMPER FOAM FILLER PIECE-RH	\$ 78.00	
12	SUNDRIES	\$ 200.00	
TOTAL SPARE PARTS		: \$ 4,022.00	\$ 1,058.80
TOTAL LABOUR CHARGE		: \$ 2,672.00	\$ 1,522.00
GRAND TOTAL		: \$ 6,694.00	\$ 2,580.80 /

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 18601

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1335/2019/NS
Date : 8-Nov-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SGH 150 A

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tan Soon Pheng
Address : Blk 52 Strathmore Avenue
#18-239
Singapore 141052
Telephone : (HP)+65 97893265
Type of Claim : Third Party Claim
Policy No. : 1800068072-01
Vehicle No : **SMA 5054 C**
Model Code : Q3 1.4 TFSI S tronic
Model / Year : 11/6/118
Engine No : CZD 872649
Chassis No : WAUZZZ8U5JR073576
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Nov-19
Place of Accident : Killiney Road Side Parking ; Outside Fook Kin

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMA 5054 C

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 /	
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.	\$ 1,200.00	50%
3	To respray rear bumper.	\$ 1,000.00	55%
4	To carry out diagnostic check.	S/N \$ 192.00 /	
TOTAL LABOUR CHARGES		: <u>\$ 2,672.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMA 5054 C

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR BUMPER X R	\$ 1,354.00	
2	REAR BUMPER FIXING PARTS X NAI	\$ 112.00	
3	REAR BUMPER SPOILER - HT / CAT	\$ 434.00	346.80
4	REAR BUMPER TOWING EYE COVER - RH X NAI	\$ 24.00	
5	REAR BUMPER TOWING EYE COVER - LH X NAI	\$ 39.00	
6	TAIL LIGHT - RH MC / BR	\$ 418.00	374.40
7	REAR PARKING AID SENSOR ? X NAI	\$ 231.00	
8	REAR WHEEL COVER - LH / RH / MC 2	\$ 472.00	77.60
9	REAR BUMPER CARRIER X NAI	\$ 569.00	
10	REAR BUMPER GUIDE SECTION - RH X NAI	\$ 91.00	
11	REAR BUMPER FOAM FILLER PIECE - RH X NAI	\$ 78.00	
12	SUNDRIES ? X NAI	\$ 200.00	

TOTAL SPARE PARTS	:	\$ 4,022.00
TOTAL LABOUR CHARGES	:	\$ 2,672.00
GRAND TOTAL	:	\$ 6,694.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Steve (LKK)
Surveyed Date : 11/11/19, 10.15 am
Authorised Date : WKL PHL
Excess Cost : 3 days
Liability :
Remarks : Rj AL SM
P/P

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant