

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047

Tel : 64810304

Fax : 64815587

Reg No : 200600989K

AXA Insurance Singapore Pte Ltd

Motorcar Claim Department

Attn Officer In Charge

Estimate Repair

Date : 22/10/2019

Accident Involving SKU5944C & SKX6569E On 21/10/2019 At Carpark Of Serangoon North Ave 4

SKX6569E

Mazda 3

*Not Authorized
Returning Bepoint*

Item	Descriptions	Amount	
1	Bonnet Cover	\$ 1,264.00	✓
2	Bonnet Cover Rubber Seal	\$ 104.20	✓
3	Bonnet Lock	\$ 198.00	X
4	Fender - Front Right	\$ 383.00	X
5	Fender - Front Left	\$ 383.00	—
6	Fender Inner Shield RH & LH @\$114 X 2	\$ 228.00	✓
7	Front Bumper	\$ 383.00	✓
8	Front Bumper Retainer RH & LH @\$17.70 X 2	\$ 35.40	✓
9	Front Bumper Reinforcement	\$ 552.00	?
10	Front Bumper Sponge	\$ 73.30	✓
11	Front Bumper Top Nose	\$ 471.00	✓
12	Engine Subframe	\$ 2,197.00	?
13	Radiator Grill Assy	\$ 640.80	✓
14	Mazda Logo	\$ 52.80	✓
15	Mazda Logo Base	\$ 49.90	?
16	Support Panel Assy	\$ 469.70	?
17	HID Headlamp Assy - RH	\$ 3,369.00	✓
18	HID Headlamp Assy - LH	\$ 3,369.00	✓
19	Fog Lamp - RH	\$ 736.00	?
20	Fog Lamp - LH	\$ 736.00	?
21	Fog Lamp Cover RH & LH @\$33 X 2	\$ 66.00	?
22	Fog Lamp Cover Garnish RH & LH @\$98 X 2	\$ 196.00	?
23	Radiator Assy	\$ 1,015.00	X
24	Aircon Condenser	\$ 1,063.00	?
25	LH Chassis Frame - Repair	\$ -	
Total For Parts (Less 20%)		\$ 18,035.10	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

S/N Item (s)

1	Towing Service	\$ 93.00	?
2	Fender Inner Shield Clips x 2 Set @\$35 x 2	\$ 70.00	—
3	Front Bumper Clips - 1 Set	\$ 28.00	—
4	RH Sport Rim	\$ 1,350.00	X
5	Radiator Coolant	\$ 22.00	?
Total For S/N		\$ 1,470.00	

Labour & Misc

1	To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel Panel, Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	\$ 1,800.00	<i>To confirm</i>
2	Spray Painting For New And Repair Parts Including Supply Of Paints Materials	\$ 1,300.00	<i>1000h</i>
3	Check Wiring, Lighting System & Focus Headlamp	\$ 30.00	<i>20h</i>
4	Remove & Replace Undercarriage Damaged Parts	\$ 350.00	?
5	Computerise 4 Wheels Alignment	\$ 60.00	✓
6	Renew Aircon Parts, Vacuum & Refill R134a Aircon Gas	\$ 100.00	?
7	Cavity Preservation On All Affected Areas	\$ 220.00	<i>60h</i>
		\$ 3,860.00	

Ready Auto Care Pte Ltd
Sulynn - 96606551

Total For Parts & Labour \$ 23,365.10

Days Of Repair 8 Days