

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047
Tel: 64810304 Fax: 64815587 Reg No: 200600989K

AXA Insurance Singapore Pte Ltd

Estimate Repair

Motorcar Claim Department

Attn: Officer In Charge

Date: 22/10/2019

Accident Involving SKU5944C & SKX6569E On 21/10/2019 At Carpark Of Serangoon North Ave 4

SKX6569E

Mazda 3

NOT AUTHORIZED
RETURN BY PRINT
@ 11492.96

Item	Descriptions	Amount
1	Bonnet Cover 1204	\$ 1,264.00
2	Bonnet Cover Rubber Seal	\$ 104.20
3	Bonnet Lock	\$ 198.00
4	Fender - Front Right	\$ 383.00
5	Fender - Front Left	\$ 383.00
6	Fender Inner Shield RH & LH @\$114 X 2	\$ 228.00
7	Front Bumper	\$ 383.00
8	Front Bumper Retainer RH & LH @\$17.70 X 2	\$ 35.40
9	Front Bumper Reinforcement 552	\$ 552.00
10	Front Bumper Sponge	\$ 73.30
11	Front Bumper Top Nose	\$ 471.00
12	Engine Subframe	\$ 2,197.00
13	Radiator Grill Assy	\$ 640.80
14	Mazda Logo	\$ 52.80
15	Mazda Logo Base	\$ 49.90
16	Support Panel Assy	\$ 469.70
17	HID Headlamp Assy - RH 3209	\$ 3,369.00
18	HID Headlamp Assy - LH 3209	\$ 3,369.00
19	Fog Lamp - RH	\$ 736.00
20	Fog Lamp - LH	\$ 736.00
21	Fog Lamp Cover RH & LH @\$33 X 2	\$ 66.00
22	Fog Lamp Cover Garnish (RH) & LH @\$98 X 2	\$ 196.00
23	Radiator Assy	\$ 1,015.00
24	Aircon Condenser	\$ 1,063.00
25	LH Chassis Frame - Repair	\$ -

Parts = \$11641.10
Supplymentary = \$ 303.10

\$11944.20
-20% \$ 2388.84

\$ 9555.36

\$ 120

\$ 2140

\$11815.36

Supplimentary = Undercarriage Base \$117

Bumper Lower Grill \$77.10

S/N Item (s) Radiator Guide \$76

1 Towing Service R4 Air Guide \$33

2 Fender Inner Shield Clips x 2 Set @\$35 x 2

3 Front Bumper Clips - 1 Set \$303.10

4 RH Sport Rim

5 Radiator Coolant

Total For Parts (Less 20%) \$ 18,035.10

Total For S/N \$ 1,470.00

Labour & Misc

1	To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel Panel, Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	\$ 1,800.00
2	Spray Painting For New And Repair Parts Including Supply Of Paints Materials	\$ 1,300.00
3	Check Wiring, Lighting System & Focus Headlamp	\$ 30.00
4	Remove & Replace Undercarriage Damaged Parts	\$ 350.00
5	Computerise 4 Wheels Alignment	\$ 60.00
6	Renew Aircon Parts, Vacuum & Refill R134a Aircon Gas	\$ 100.00
7	Cavity Preservation On All Affected Areas	\$ 220.00

(52140) \$ 3,860.00

Ready Auto Care Pte Ltd

Sulynn - 96606551

Total For Parts & Labour \$ 23,365.10

Days Of Repair 8 Days