

# S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg\_motor\_enterprise@yahoo.com.sg

Date: 22 October 2019

To : LKK

By Fax: 6256-4315

Attn: *By*

Tel:

VEHICLE NO : JQH 1173

Yamaha LC 135

ACCIDENT DATE: 27 September 2019

| Description                            | Qty   | Quotation \$    |
|----------------------------------------|-------|-----------------|
| 1 Handle Bar <i>2x4</i>                | 1     | 135.00 <i>✓</i> |
| 2 Head Lamp <i>Cut</i>                 | 1     | 280.00 <i>✓</i> |
| 3 Head Lamp Cover <i>Cut</i>           | 1     | 180.00 <i>✓</i> |
| 4 Front Cover <i>Cut</i>               | 1     | 145.00 <i>✓</i> |
| 5 Front Signal LH <i>broken</i>        | 1     | 65.00 <i>✓</i>  |
| 6 Leg Shield <i>cut NN</i>             | 1     | 135.00 <i>X</i> |
| 7 Front Mudguard <i>run</i>            | 1     | 250.00 <i>X</i> |
| 8 Fork Under Bracket <i>2 Down</i>     | 1     | 135.00 <i>✓</i> |
| 9 Front Fork <i>2x down (1st)</i>      | 1 set | 480.00 <i>✓</i> |
| 10 Front LH Side Fairing <i>broken</i> | 1     | 135.00 <i>✓</i> |
| 11 Gear Pedal <i>NH</i>                | 1     | 65.00 <i>X</i>  |
| 12 Front Footrest <i>NH</i>            | 1     | 75.00 <i>X</i>  |
| 13 Footrest Rubber <i>NH</i>           | 1     | 55.00 <i>X</i>  |
| 14 Mirror <i>broken ops</i>            | 1 set | 135.00 <i>✓</i> |
| 15 Brake Lever <i>Cut</i>              | 1     | 65.00 <i>✓</i>  |
| 16 Front RH Fairing <i>Cut</i>         | 1     | 155.00 <i>✓</i> |
| 17 Exhaust Guard <i>Cut</i>            | 1     | 185.00 <i>✓</i> |
| 18 Pillion Grip <i>Cut</i>             | 1     | 65.00 <i>✓</i>  |
| 19 Rear RH Footrest <i>Cut</i>         | 1     | 78.00 <i>✓</i>  |
| 20 Meter Cover <i>2 NH</i>             | 1     | 210.00 <i>X</i> |
| 21 LH Fairing Inner Garnish <i>Cut</i> | 1     | 158.00 <i>✓</i> |
| 22 Front Rim <i>run</i>                | 1     | 325.00 <i>X</i> |

Sub-Total 3,511.00

Less 10% 351.10

Sub-Total 3,159.90

23) Radiator Assy - *350.00 ✓*  
*4/1/2020*

VEHICLE NO : JQH 1173

Yamaha LC 135

Nett Items

|   |                                                   |                                |
|---|---------------------------------------------------|--------------------------------|
| 1 | Front number plate - 1 set <i>NLG</i>             | 25.00 <i>15/-</i>              |
| 2 | Rear number plate <i>NLG</i>                      | 15.00 <i>X -</i>               |
| 3 | Towing fee <i>NLG</i>                             | 40.00 <i>X</i>                 |
| 4 | Remove & replace necessary parts, align & etc     | <del>280.00</del> <i>200/-</i> |
| 5 | Remove & replace fork assy, rim & top up fork oil | <del>150.00</del> <i>80/-</i>  |
| 6 | Supply body decal sticker                         | <del>120.00</del> <i>80/-</i>  |

|            |          |
|------------|----------|
| Sub-Total  | 630.00   |
| Nett Total | 3,789.90 |

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.  
Thank you

**S9 MOTOR TRADING PTE LTD**

LG

*22/10/2019 @ 1600m*

*Nbt Andro*

*2/Sum 4 days*

*[Signature]*

*LKK Andro*

*Check Sum insured.*

LKK & Consultants - please notify the Repairer of the following:

- Resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: