



Reg No : 196700086Z
ST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	Ms Lim Andrea 987A Buangkok Green #18-11 Singapore 531987 Mobile: 91558753
	Document No 0	
	Document Date 21/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AHXNXQ	A1	NGX10R	22/05/2018	SLZ8561R	0	49612 72/DS/SLZ8561R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTNKY3BXX01007010	8NRU183145	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: LONPAC INSURANCE TP VEH: SJF3505R DATE OF ACC: 21.10.2019				50 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				? 100.00
3	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				180.00
4	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST				122.40
5	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				360 ? 720.00
6	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
7	B	BP-MECH2 REPLACE REAR EXHAUST PIPE TO FAC REPAIR				720.00
8	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				1440 3600.00
9	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				1180 3540.00
10	1	T52159-10910 COVER, RR BUMPER	1.00	353.10		353.10
11	2	T52453-10901 GUARD, RR BUMPER	1.00	372.70		372.70
12	3	T75392-35200 OUTSIDE RETAINER,	6.00	3.90		23.40
13	4	T52162-10010 PLATE, RR BUMPER	1.00	17.70		17.70
14	5	T52575-10010 RETAINER, RR BUMPER	1.00	102.20		102.20
15	6	T52562-10010 RETAINER, RR BUMPER	1.00	51.70		51.70
16	7	T52576-10010 RETAINER, RR BUMPER	1.00	102.20		102.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
LKK Auto Consultants Hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4116247

4116247

TO SECURITY GUARD
Acknowledged by Repairer
Signature: _____ DATE 21/10/2019
Date: _____ TIME 14:36
PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLZ8561R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motor**

Inchcape



Reg No : 196700086Z
ST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg
Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1166

Account Detail		Account No	Customer Detail	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1	Ms Lim Andrea 987A Buangkok Green #18-11 Singapore 531987 Mobile: 91558753	
		Document No		
		Document Date		
		0		
		21/10/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AHXNXQ	A1	22/05/2018	SLZ8561R	0	49612	72/DS/SLZ8561R

Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On
PTNKY3BXX01007010	8NRU183145	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
17	8	T52563-10010 RETAINER, RR BUMPER, ?	1.00	51.70		51.70
18	9	T52023-10040 REINFORCEMENT ?	1.00	332.70		332.70
19	0	T52163-10030 PLATE, RR BUMPER, RH ?	1.00	90.80		90.80
20	1	T52164-10010 PLATE, RR BUMPER, LH ?	1.00	90.80		90.80
21	2	S52161-OK040 PIECE, RR BUMPER re -	10.00	4.10		41.00
22	3	T52154-10020 STAY, RR BUMPER ?	1.00	32.30		32.30
23	4	T81481-10050 BRACKET, FOG LAMP ?	1.00	80.20		80.20
24	5	T81910-10031 REFLECTOR ASSY, ?	1.00	59.80		59.80
25	6	T81920-10031 REFLECTOR ASSY, ?	1.00	59.80		59.80
26	7	T58307-10361 PANEL SUB-ASSY, BODY repair -	1.00	716.00		716.00
27	8	T64716-10090 C1 COVER, DECK TRIM, RR ?	1.00	254.40		254.40
28	9	T58460-33020 STRIKER ASSY, X	2.00	27.20		54.40
29	0	T89348-F4140 C0 RETAINER, ULTRASONIC re -	2.00	20.30		40.60
30	1	T89348-F4120 RETAINER, ULTRASONIC re -	1.00	15.40		15.40
31	2	T89348-F4130 RETAINER, ULTRASONIC re -	1.00	15.40		15.40
32	3	T89341-F4030 C1 SENSOR, ULTRASONIC, ?	2.00	392.80		785.60
33	4	T89341-F4020 C1 SENSOR, ULTRASONIC, ?	2.00	392.80		785.60
34	5	T17430-47250 PIPE ASSY, EXHAUST	1.00	1463.60		1463.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	15,255.50
	Please acknowledge receipt of vehicle	Parts 5,993.10	GST 7.00%	1,067.89
		Labour 9,262.40	Less	0.00
		Materials 0.00		
		Lubrication/Fluid 0.00		
		Others 0.00	Amount Due	16,323.39

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis. Illegal modification(s) is allowed

Supplementary item(s) must be resurveyed. This estimate is subject to final approval by Insurance

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLZ8561R

DATE 21/10/2019
TIME 14:36

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape