



Reg No : 196700086Z
ST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg
Toyota Borneo Centre
No. 2 Far Eastern Road
Singapore 140602
Tel no.: 663 1111

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Account Detail		Account No	Customer Details
Lompac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLP11	Ms Lim Andrea 987A Buangkok Green #18-11 Singapore 531987 Mobile: 91558753
		Document No	
		0	
		Document Date	
		21/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AHXNXQ A1	NGX10R	22/05/2018	SLZ8561R	0	49612	72/DS/SLZ8561R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTNKY3BXX01007010	8NRU183145	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: LONPAC INSURANCE TP VEH: SJF3505R DATE OF ACC: 21.10.2019				50 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00 XAA
3	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				180.00
4	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST				122.40
5	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				720.00 XAA
6	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
7	B	BP-MECH2 REPLACE REAR EXHAUST PIPE TO FAC REPAIR				720.00
8	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				1440 3600.00
9	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				1180 3540.00
10	1	T52159-10910 COVER, RR BUMPER	1.00	353.10		353.10
11	2	T52453-10901 GUARD, RR BUMPER	1.00	372.70		372.70
12	3	T75392-35200 OUTSIDE RETAINER	6.00	3.90		23.40
13	4	T52162-10010 PLATE, RR BUMPER	1.00	17.70		17.70
14	5	T52575-10010 RETAINER, RR BUMPER	1.00	102.20		102.20
15	6	T52562-10010 RETAINER, RR BUMPER	1.00	51.70		51.70
16	7	T52576-10010 RETAINER, RR BUMPER	1.00	102.20		102.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
LKK Auto Consultants hence acknowledge receipt of vehicle		Parts Labour Materials Lubrication/Fluid Others	Less
the Repairer of the following:			Amount Due
- To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			

PLEASE TEAR ALONG PERFORATED LINE

4116247

4116247

TO SECURITY GUARD
Signature: DATE 21/10/2019
TIME 14:36
PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.


VEHICLE NO SLZ8561R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motor



Reg No : 196700086Z
IT Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	Ms Lim Andrea 987A Buangkok Green #18-11 Singapore 531987 Mobile: 91558753
	Document No 0	
	Document Date 21/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AHXNQ	A1	NGX10R	22/05/2018	SLZ8561R	0	49612 72/DS/SLZ8561R

Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On
TKNY3BXX01007010	8NRU183145	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
17	8	T52563-10010 RETAINER, RR BUMPER	1.00	51.70		51.70
18	9	T52023-10040 REINFORCEMENT	1.00	332.70		332.70
19	0	T52163-10030 PLATE, RR BUMPER, RH	1.00	90.80		90.80
20	1	T52164-10010 PLATE, RR BUMPER, LH	1.00	90.80		90.80
21	2	S52161-0K040 PIECE, RR BUMPER	10.00	4.10		41.00
22	3	T52154-10020 STAY, RR BUMPER	1.00	32.30		32.30
23	4	T81481-10050 BRACKET, FOG LAMP	1.00	80.20		80.20
24	5	T81910-10031 REFLECTOR ASSY, ?	1.00	59.80		59.80
25	6	T81920-10031 REFLECTOR ASSY, ?	1.00	59.80		59.80
26	7	T58307-10361 PANEL SUB-ASSY, BODY	1.00	716.00		716.00
27	8	T64716-10090 C1 COVER, DECK TRIM, RR	1.00	254.40		254.40
28	9	T58460-33020 STRIKER ASSY, X-SVC	2.00	27.20		54.40
29	0	T89348-F4140 C0 RETAINER, ULTRASONIC	2.00	20.30		40.60
30	1	T89348-F4120 RETAINER, ULTRASONIC	1.00	15.40		15.40
31	2	T89348-F4130 RETAINER, ULTRASONIC	1.00	15.40		15.40
32	3	T89341-F4030 C1 SENSOR, ULTRASONIC, ?	2.00	392.80		785.60
33	4	T89341-F4020 C1 SENSOR, ULTRASONIC, ?	2.00	392.80		785.60
34	5	T17430-47250 PIPE ASSY, EXHAUST	1.00	1463.60		1463.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 5,993.10	15,255.50
		Labour 9,262.40	GST 7.00% 1,067.89
		Materials 0.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 16,323.39

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

Legal modification(s) is allowed

Accessory item(s) must be resurveyed

subject to final approval Insurance

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLZ8561R

CUSTOMER

DATE 21/10/2019
TIME 14:36

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Page 3 of 3
Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail		Account No S1000007 / ICLPI1		Customer Detail				
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		Document No 0		Ms Lim Andrea 987A Buangkok Green #18-11 Singapore 531987 Mobile: 91558753				
		Document Date 02/12/2019						
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	
18	AHXNXQ A1	NGX10R	22/05/2018	SLZ8561R	0	49612	72/DS/SLZ8561R	
Chassis No		Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTNKY3BXX01007010		8NRU183145	60	Thomas Pang W T	23/10/2019	8.00	14/11/2019 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: LONPAC INSURANCE TP VEH: SJF3505R DATE OF ACC: 21.10.2019 BY:LKK-RASUL @ 22.10.2019 05 WORKING DAYS						50.00 ✓
2	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR *						180.00 ✓
3	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST *						122.40 ✓
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME			18			180.00 ✓
5	B	BP-MECH2 REPLACE REAR EXHAUST PIPE TO FAC REPAIR			18			720.00 ✓
6	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS *						1440.00 ✓
7	B	BP-RES2 RESPRAY ACC AFFECTED AREAS *						1180.00 ✓
8	Z	BP-SUNDRY TITANIUM COATING *						150.00 ✓
9	1	T52159-10910 COVER, RR BUMPER			1.00	353.10		353.10 ✓
10	2	T52453-10901 GUARD, RR BUMPER,			1.00	372.70		372.70 ✓
11	3	T75392-35200 RETAINER, OUTSIDE			6.00	3.90		23.40 ✓
12	4	T52162-10010 PLATE, RR BUMPER,			1.00	17.70		17.70 ✓
13	5	S52161-0K040 PIECE, RR BUMPER			10.00	4.10		41.00 ✓
14	6	T89348-F4140 CO RETAINER, ULTRASONIC			2.00	20.30		40.60 ✓
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.								
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total		
		Please acknowledge receipt of vehicle		Parts Labour Materials Lubrication/Fluid Others		Less		
						Amount Due		

PLEASE TEAR ALONG PERFORATED LINE

4131780

TO SECURITY GUARD

4131780

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 02/12/2019
TIME 10:42

VEHICLE NO SLZ8561R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No S1000007 / ICLPI1	Customer Detail
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	Document No 0	Ms Lim Andrea 987A Buangkok Green #18-11 Singapore 531987
	Document Date 02/12/2019	Mobile: 91558753

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AHXNQ	A1	22/05/2018	SLZ8561R	0	49612	72/DS/SLZ8561R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTNKY3BXX01007010	8NRU183145	60	Thomas Pang W T	23/10/2019	8.00	14/11/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	7	T89348-F4120	1.00	15.40		15.40
16	8	T89348-F4130	1.00	15.40		15.40
17	9	T17430-47250	1.00	1463.60		1463.60
18	0	T52023-10040	1.00	332.70		332.70

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	6,698.00
	Please acknowledge receipt of vehicle	Parts 2,675.60	GST 7.00%	468.86
		Labour 4,022.40	Less	0.00
		Materials 0.00		
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	7,166.86

PLEASE TEAR ALONG PERFORATED LINE

4131781

TO SECURITY GUARD

4131781

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 02/12/2019
TIME 10:42

VEHICLE NO SLZ8561R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



UNIQUE CAR BEAUTY SHOP

53 Ubi Ave 1 #01-40 Paya Ubi Industrial Park S(408934)

Bill to

Customer MR.Andrea Lim

Address:

Telephone: 91558753

INV NO UCBS 00002660

DATE 23/11/2019

VEHICLE NO.	MAKE / MODEL	COLOR
SLZ8561R	Toyota CH-R	Maroon

NO	DESCRIPTION	QTY	PRICE	AMOUNT
1	Titanium Coating for (Rear Side	1	\$ 150.00	\$ 150.00
	Bumper Area)			
Amount (SGD)				\$ 150.00
Discount (SGD)				\$ -
Net Amount (SGD)				\$ 150.00

All remittance must be crossed "A/c Payee Not Negotiable"
and made payable to "Unique Car Beauty Shop"

UNIQUE CAR BEAUTY SHOP

Sherine Chan

Authorised Signature

Enquiry: 68442235, Fax: 68427357, Phone Booking: 64631311, 67451311, Online Booking: www.cs2.sg



CS-II
53 UBI AVENUE 1
#01-40 PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934
Date/Time : 23/11/2019 18:16:55
MID: 6816846256 TID: 7688266
B/C: 12M : 000002 INVOICE#: 165104

Sale

VISA CREDIT
XXXX XXXX XXXX 9340
EXP DATE : 12/11
PAN CODE : 683138
REF NUM : 537716975529
APP CRYPT : 7482657C3B4C499
TIN VALUE : 0000000000
ACQ VALUE : 00000000001818
ENT TYPE : CHIP

AMOUNT : S\$150.00

NO SIGNATURE REQUIRED
(Express Payment)

I AGREE TO PAY THE ABOVE TOTAL AMOUNT
ACCORDING TO THE CARD ISSUER AGREEMENT

***** CUSTOMER'S COPY *****

