



Vehicle grounded.

Reg No : 196700086Z
ST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking :

www.toyota.com.sg Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1	Ms Lim Andrea	
		Document No 0	987A Buangkok Green #18-11 Singapore 531987	
		Document Date 21/10/2019	Mobile: 91558753	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AHXNXQ	A1	22/05/2018	SLZ8561R	0	49612	72/DS/SLZ8561R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTNKY3BXX01007010	8NRU183145	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: LONPAC INSURANCE TP VEH: SJF3505R DATE OF ACC: 21.10.2019				100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
3	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				180.00
4	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST				122.40
5	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				720.00
6	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
7	B	BP-MECH2 REPLACE REAR EXHAUST PIPE TO FAC REPAIR				720.00
8	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				3600.00
9	B	BP-RES2 RESPRAY ACC AFFECTED AREAS				3540.00
10	1	T52159-10910 COVER, RR BUMPER	1.00	353.10		353.10
11	2	T52453-10901 GUARD, RR BUMPER,	1.00	372.70		372.70
12	3	T75392-35200 OUTSIDE RETAINER,	6.00	3.90		23.40
13	4	T52162-10010 PLATE, RR BUMPER,	1.00	17.70		17.70
14	5	T52575-10010 RETAINER, RR BUMPER	1.00	102.20		102.20
15	6	T52562-10010 RETAINER, RR BUMPER,	1.00	51.70		51.70
16	7	T52576-10010 RETAINER, RR BUMPER	1.00	102.20		102.20
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

4116247

4116247

21/10/2019
14:36

SLZ8561R



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Vehicle grounded.

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg
Toyota Head Office Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	Ms Lim Andrea 987A Buangkok Green #18-11 Singapore 531987 Mobile: 91558753
	Document No 0	
	Document Date 21/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AHXNXQ	A1	22/05/2018	SLZ8561R	0	49612	72/DS/SLZ8561R

Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On
JTNKY3BXX01007010	8NRU183145	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
17	8	T52563-10010 RETAINER, RR BUMPER,	1.00	51.70		51.70
18	9	T52023-10040 REINFORCEMENT	1.00	332.70		332.70
19	0	T52163-10030 PLATE, RR BUMPER, RH	1.00	90.80		90.80
20	1	T52164-10010 PLATE, RR BUMPER, LH	1.00	90.80		90.80
21	2	S52161-0K040 PIECE, RR BUMPER	10.00	4.10		41.00
22	3	T52154-10020 STAY, RR BUMPER	1.00	32.30		32.30
23	4	T81481-10050 BRACKET, FOG LAMP	1.00	80.20		80.20
24	5	T81910-10031 REFLECTOR ASSY,	1.00	59.80		59.80
25	6	T81920-10031 REFLECTOR ASSY,	1.00	59.80		59.80
26	7	T58307-10361 PANEL SUB-ASSY, BODY	1.00	716.00		716.00
27	8	T64716-10090 C1 COVER, DECK TRIM, RR	1.00	254.40		254.40
28	9	T58460-33020 STRIKER ASSY,	2.00	27.20		54.40
29	0	T89348-F4140 C0 RETAINER, ULTRASONIC	2.00	20.30		40.60
30	1	T89348-F4120 RETAINER, ULTRASONIC	1.00	15.40		15.40
31	2	T89348-F4130 RETAINER, ULTRASONIC	1.00	15.40		15.40
32	3	T89341-F4030 C1 SENSOR, ULTRASONIC,	2.00	392.80		785.60
33	4	T89341-F4020 C1 SENSOR, ULTRASONIC,	2.00	392.80		785.60
34	5	T17430-47250 PIPE ASSY, EXHAUST	1.00	1463.60		1463.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	15,255.50
	Please acknowledge receipt of vehicle	Parts 5,993.10	GST 7.00%	1,067.89
		Labour 9,262.40		
		Materials 0.00	Less	0.00
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	16,323.39

4116248

4116248

21/10/2019
14:36

SLZ8561R



Borneo Motors