

INS. CASE OWNER:

CC⁶ /EQI1901 8674, AprilLKK:
IDAC:

Surveyor:

Adrian

DOI:

ASSIGNMENT

11/10/19

Date / Time:

11/10/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJI 6249A

Name of Insured:

LUXS LEASING & FINANCE

Insured Tel No.:

HP:

SERVING #12

Excess Sec II :S\$

D.O.A.:

16/10/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MO SHENG HAN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

001424-000096

Honda

WEST LANE HIGHWAY

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLS 9474B

INSRS:
WSP:
Tel:
Liability:
RMKS:

SM

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SLS 9474B - X

SJI 6249A - X

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia.:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(days)

Loss of Use (LOU):

S\$

(\$ x days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP

\$300-00

(up)
Return

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

ON SI YUAN JOAB

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

24/10/2019

TP E W
Xiao Tang

Accident date: 16/07/2017

Estimated repair cost for vehicle no: SLS9935B MERCEDES E250 1.8 A '13

CHASSIS: WDD2120472A635792

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Repair</i>		\$3,125.00 +
2	2	Rear Boot Lid Hinge <i>Not nec</i>	\$166.00	\$332.00 X
3	1	Rear Boot Lid E250 Logo <i>3 nec</i>		\$87.00 ✓
4	1	Rear Boot Lid Emblem Logo		\$65.00 ✓
5	3	Rear Boot Lid Emblem Logo Clip <i>Nec</i>	\$8.00	\$24.00 ✓
6	1	Rear Boot Lid C&C Logo <i>2</i>		\$55.00 ✓
7	1	Rear Boot Lid 7G Logo <i>1 nec</i>		\$55.00 ✓
8	1	Rear Boot Lid Tronic Logo		\$60.00 ✓
9	2	Rear Boot Lid Side Reflector <i>3 nec</i>	\$495.00	\$990.00 +
10	1	Rear Boot Lid Top Chrome Moulding <i>3 nec</i>		\$125.00 +
11	1	Rear Boot Lid Number Plate <i>2</i>		\$50.00 +
12	2	Rear Boot Lid Number Plate Lamp		\$60.00 +
13	1	Rear Boot Lid Center Garnish <i>NP</i>		\$306.00 ✓
14	1	Rear Boot Lid Inner Rubber <i>Nec</i>		\$225.00 +
15	1	Rear Boot Lid Inner Lock		\$385.00 +
16	1	Rear Boot Lid Inner Trim Board		\$305.00 +
17	10	Rear Boot Lid Inner Trim Board Clip	\$6.50	\$65.00 +
18	2	Rear Tail Lamp <i>crushed</i>	\$695.00	\$1,390.00 ✓
19	4	Rear Tail Lamp Clip <i>Nec</i>	\$8.00	\$32.00 ✓
20	2	Rear Tail Lamp Lower Bracket <i>crushed</i>	\$80.00	\$160.00 ✓
21	2	Rear Tail Lamp Inner Cover <i>Nec</i>	\$185.00	\$370.00 +
22	1	Rear Bumper <i>Deformed.</i>		\$2,070.00 1620
23	1	Rear Bumper Lower <i>Deformed.</i>		\$670.00 375
24	10	Rear Bumper Clip <i>Nec</i>	\$6.50	\$65.00 30.
25	1	Rear Bumper Inner Bracket <i>crushed</i>		\$305.00 185
26	2	Rear Bumper Inner Side Bracket <i>Nec</i>	\$59.00	\$118.00 +
27	2	Rear Bumper Side Retainer <i>Nec</i>	\$65.00	\$130.00 ✓

22	1	Rear Bumper Towing Cover	Not Nec		\$76.00	X
29	1	Rear Bumper Reinforcement	Bent		\$870.00	✓
30	1	Rear L/H Bumper Under Cover	cracked		\$91.00	✓
31	1	Rear End Panel	Dented		\$1,450.00	979
32	1	Rear End Panel Top Garnish	cracked		\$183.00	✓
33	2	Rear Fender Inner Trim Board	3 All	\$390.00	\$780.00	X
34	16	Rear Fender Inner Trim Board Clip	1 Nec	\$6.50	\$104.00	X
35	1	Rear Spare Tyre Panel	Nec		\$390.00	+
36	1	Rear Spare Tyre Panel & End Panel Sealant	Nec		\$450.00	+
37	1	Rear Spare Tyre Panel Top Cover	Not Nec		\$460.00	X
38	2	Rear Exhaust	Nec	\$1,470.00	\$2,940.00	+
39	1	Rear Centre Exhaust	3 All		\$1,870.00	X
40	4	Rear Exhaust Mounting	1 m	\$45.00	\$180.00	X
41	2	Rear Exhaust Chrome Pipe	LH Bent	\$380.00	\$760.00	220

6611
5949.80

Subtotal :- \$22,228.00

Labour charges

To remove & refit rear & centre exhaust		\$380.00	X
To reset computer		\$380.00	100.
To check wiring		\$100.00	30
Towing fee	2190	\$100.00	X
Tuff kote		\$150.00	60.
Panel beating		\$2,000.00	Too
Spray painting		\$1,800.00	1000.

Subtotal :- \$4,910.00

Total :- \$27,138.00



total 8138.80

4/5 6.5K

06 Days

6.5K

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 041J

Vehicle Details

Vehicle No.: SLS9935B
Vehicle to be Exported: No
Intended Deregistration Date: 17 Oct 2019
Vehicle Make: MERCEDES BENZ
Vehicle Model: E 250 BLUEEFFICIENCY
Primary Colour: Grey
Manufacturing Year: 2012
Engine No.: 27186030486498
Chassis No.: WDD2120472A635792
Maximum Power Output: 150.0 kW (201 bhp)
Open Market Value: \$52,192.00
Original Registration Date: 15 Jan 2013
First Registration Date: 15 Jan 2013
Transfer Count: 2
Actual ARF Paid: \$52,192.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 14 Jan 2023
PARF Rebate Amount: \$33,924.00

Intended COE Rebate Details

COE Expiry Date: 14 Jan 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$90,200.00
COE Rebate Amount: \$29,242.00
Total Rebate Amount: \$63,166.00

The information contained herein is correct as at 17 Oct 2019

OK

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 19 November 2019 8:27 AM
To: sm automotive
Cc: Admin A
Subject: Your Ref: SLS9935B *Our Ref: CC6/EQI19018674/Apb3 [ACCIDENT INVOLVING SJL 6259A(EQ) AND SLS 9935B ON 16/10/2019]

Your Ref: **SLS9935B** Without Prejudice
Our Ref: CC6/EQI19018674/Apb3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SJL 6259A(EQ) AND SLS 9935B ON 16/10/2019

We refer to the above matter.

Please be informed that EQ claim officer will handle the matter at their end.

Kindly submit your LOD & document to EQ directly.

Email Address: egiprs@eqinsurance.com.sg

Fax Number: 65 6223 4190

Thank you.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Monday, 9 December 2019 4:05 PM
To: 'Jaime Tay'
Cc: Admin A
Subject: RE: Direct Settlement - Accident Involving SJL6259A (OI : EQI - DM19HO02892) and SLS9935B (TP : LKK REF - CC6/EQI19018674/Ab3) on 16.10.2019
Attachments: TP_ESTIMATE_MARKED.pdf; Preliminary Advice-SLS9935B.pdf; LKK Survey Photos.pdf

Dear Sirs/ Mdm,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

"Best Wishes for Merry Christmas, and Happy New Year 2020"

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jaime Tay <jaime.tay@eqinsurance.com.sg>

Sent: Friday, 8 November 2019 10:17 AM

To: Shu Pei (LKKAUTO) <shupeil@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving SJL6259A (OI : EQI - DM19HO02892) and SLS9935B (TP : LKK REF - CC6/EQI19018674/Ab3) on 16.10.2019

Dear Shu Pei,

Please find enclosed GIA report as requested.

Please let us have your survey report and advise workshop to forward their letter of claim to our office or our handling.

Thank you.

Regards,

Jaime Tay

Executive | Claims




EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9882 | tel 65 6223 9433 ext 882 | fax 65 6223 4190
www.eqinsurance.com.sg



A Member of Citystate



you've got a friend

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: 08 November 2019 09:42

To: EQI PRS <EQIPRS@eqinsurance.com.sg>

Subject: RE: Direct Settlement - Accident Involving SJL6259A (OI : EQI - TBA) and SLS9935B (TP : LKK REF - CC6/EQI19018674/Apb3) on 16.10.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Sent: Tuesday, 22 October 2019 4:53 PM

To: eqiprs@eqinsurance.com.sg

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving SJL6259A (OI : EQI - TBA) and SLS9935B (TP : LKK REF - CC6/EQI19018674/Apb3) on 16.10.2019

WITHOUT PREJUDICE

Dear Sir/ Madam,

We refer to the above matter.

We have inspected TP vehicle SLS 9935B at M/s SM Automotive on a WP basis and TP repairer proposed for a direct settlement.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Total Control Panel

[Login](#)

To: eqiprs@eqinsurance.com.sg

[Remove](#) lkkauto.com from my allow list

From: shupeil@lkkauto.com

You received this message because the domain lkkauto.com is on your allow list.

Shu Pei (LKKAuto)

From: Jaime Tay <jaime.tay@eqinsurance.com.sg>
Sent: Friday, 8 November 2019 10:17 AM
To: Shu Pei (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving SJL6259A (OI : EQI - DM19HO02892) and SLS9935B (TP : LKK REF - CC6/EQI19018674/Apb3) on 16.10.2019
Attachments: OI - SJL6259A.PDF

Dear Shu Pei,

Please find enclosed GIA report as requested.

Please let us have your survey report and advise workshop to forward their letter of claim to our office or our handling.

Thank you.

Regards,

Jaime Tay
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9882 | tel 65 6223 9433 ext 882 | fax 65 6223 4190
www.eqinsurance.com.sg



A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of it.

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: 08 November 2019 09:42
To: EQI PRS <EQIPRS@eqinsurance.com.sg>
Subject: RE: Direct Settlement - Accident Involving SJL6259A (OI : EQI - TBA) and SLS9935B (TP : LKK REF - CC6/EQI19018674/Apb3) on 16.10.2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC6/EQ19018674/Apb3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 11-12-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJL 6259A	Veh. Inspected	SLS 9935B	
Policy No.	DMCFHQ19-000096	Coverage (\$)	0.00	
Claim No.	DM19HO02892	Excess (\$)	0.00	
Assign From		Assign Date	21/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E 250	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WDD2120472A635792	Colour	GREY	
Odometer	169827	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	GOODYEAR	6 mm	
L/H Front Tyre	245/40 R18	GOODYEAR	6 mm	
R/H Rear Tyre	245/40 R18	GOODYEAR	6 mm	
L/H Rear Tyre	245/40 R18	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/10/2019	Inspection Date	21/10/2019	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 9935B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LID	TO REPAIR SEE LABOUR	3,125.00	-
2	REAR BOOT LID HINGE @\$160.00	NOT NECESSARY	332.00	-
1	REAR BOOT LID E250 LOGO	NECESSARY	87.00	87.00
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	65.00	65.00
3	REAR BOOT LID EMBLEM LOGO CLIP @\$8.00	NECESSARY	24.00	24.00
1	REAR BOOT LID C&C LOGO	NECESSARY	55.00	55.00
1	REAR BOOT LID 7G LOGO	NECESSARY	55.00	55.00
1	REAR BOOT LID TRONIC LOGO	NECESSARY	60.00	60.00
2	REAR BOOT LID SIDE REFLECTOR @\$495.00	NOT NECESSARY	990.00	-
1	REAR BOOT LID TOP CHROME MOULDING	NOT NECESSARY	125.00	-
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
1	REAR BOOT LID NUMBER PLATE LAMP	NOT NECESSARY	60.00	-
1	REAR BOOT LID CENTER GARNISH	NOT NECESSARY	306.00	-
1	REAR BOOT LID INNER RUBBER	NOT NECESSARY	225.00	-
1	REAR BOOT LID INNER LOCK	NOT NECESSARY	385.00	-
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	305.00	-
10	REAR BOOT LID INNER TRIM BOARD CLIP	NOT NECESSARY	65.00	-
2	REAR TAIL LAMP @\$695.00	CRACKED	1,390.00	1,390.00
4	REAR TAIL LAMP CLIP @\$8.00	NECESSARY	32.00	32.00
2	REAR TAIL LAMP LOWER BRACKET @\$80.00	CRACKED	160.00	160.00
2	REAR TAIL LAMP INNER COVER @\$185.00	NOT NECESSARY	370.00	-
1	REAR BUMPER	DEFORMED	2,070.00	1,620.00
1	REAR BUMPER LOWER	DEFORMED	670.00	375.00
10	REAR BUMPER CLIP @\$6.50	NECESSARY	65.00	30.00
1	REAR BUMPER INNER BRACKET	CRACKED	305.00	185.00
2	REAR BUMPER INNER SIDE BRACKET @\$59.00	NOT NECESSARY	118.00	-
2	REAR BUMPER SIDE RETAINER @\$65.00	NECESSARY	130.00	130.00
1	REAR BUMPER TOWING COVER	NOT NECESSARY	76.00	-
1	REAR BUMPER REINFORCEMENT	BENT	870.00	870.00
1	REAR L/H BUMPER UNDER COVER	CRACKED	91.00	91.00

Report Ref No. CC6/EQ19018674/Apb3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL	DENTED	1,450.00	979.00
1	REAR END PANEL TOP GARNISH	CRACKED	183.00	183.00
2	REAR FENDER INNER TRIM BOARD @\$390.00	NOT NECESSARY	780.00	-
16	REAR FENDER INNER TRIM BOARD CLIP @\$6.50	NOT NECESSARY	104.00	-
1	REAR SPARE TYRE PANEL	NOT NECESSARY	390.00	-
1	REAR SPARE TYRE PANEL & END PANEL SEALANT	NOT NECESSARY	450.00	-
1	REAR SPARE TYRE PANEL TOP COVER	NOT NECESSARY	460.00	-
2	REAR EXHAUST @\$1470.00	NOT NECESSARY	2,940.00	-
1	REAR CENTRE EXHAUST	NOT NECESSARY	1,870.00	-
4	REAR EXHAUST MOUNTING @\$45.00	NOT NECESSARY	180.00	-
2	REAR EXHAUST CHROME PIPE @\$380.00	N/S BENT	760.00	220.00
	LESS 10% DISCOUNT		-	-661.10
			22,228.00	5,949.90
	LABOUR			
	TO REMOVE & REFIT REAR & CENTRE EXHAUST .	NOT NECESSARY	380.00	-
	TO RESET COMPUTER .		380.00	100.00
	TO CHECK WIRING .		100.00	30.00
	TOWING FEE.	NOT NECESSARY	100.00	-
	TUFF KOTE.		150.00	60.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BOOT LID.		2,000.00	1,000.00
	SPRAY PAINTING .		1,800.00	1,000.00
			4,910.00	2,190.00
GRAND TOTAL			27,138.00	8,139.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,500.00

Report Ref No. CC6/EQ119018674/Apb3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.