

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

ON SI YUAN JOAB

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

24/10/2019

TPEQ
Xiao Tong

Accident date: 16/07/2017

Estimated repair cost for vehicle no: SLS9935B MERCEDES E250 1.8 A '13

CHASSIS: WDD2120472A635792

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Rep</i>		\$3,125.00 +
2	2	Rear Boot Lid Hinge <i>NP</i>	\$166.00	\$332.00 X
3	1	Rear Boot Lid E250 Logo <i>3</i>		\$87.00 ✓
4	1	Rear Boot Lid Emblem Logo <i>3</i>		\$65.00 ✓
5	3	Rear Boot Lid Emblem Logo Clip <i>NP</i>	\$8.00	\$24.00 ✓
6	1	Rear Boot Lid C&C Logo <i>2</i>		\$55.00 ✓
7	1	Rear Boot Lid 7G Logo <i>1</i>		\$55.00 ✓
8	1	Rear Boot Lid Tronic Logo <i>1</i>		\$60.00 ✓
9	2	Rear Boot Lid Side Reflector <i>3</i>	\$495.00	\$990.00 +
10	1	Rear Boot Lid Top Chrome Moulding <i>1</i>		\$125.00 +
11	1	Rear Boot Lid Number Plate <i>2</i>		\$50.00 +
12	2	Rear Boot Lid Number Plate Lamp <i>2</i>		\$60.00 +
13	1	Rear Boot Lid Center Garnish <i>NP</i>		\$306.00 X
14	1	Rear Boot Lid Inner Rubber <i>NP</i>		\$225.00 +
15	1	Rear Boot Lid Inner Lock <i>NP</i>		\$385.00 +
16	1	Rear Boot Lid Inner Trim Board <i>NP</i>		\$305.00 +
17	10	Rear Boot Lid Inner Trim Board Clip <i>NP</i>	\$6.50	\$65.00 +
18	2	Rear Tail Lamp <i>crushed</i>	\$695.00	\$1,390.00 ✓
19	4	Rear Tail Lamp Clip <i>NP</i>	\$8.00	\$32.00 ✓
20	2	Rear Tail Lamp Lower Bracket <i>crushed</i>	\$80.00	\$160.00 ✓
21	2	Rear Tail Lamp Inner Cover <i>NP</i>	\$185.00	\$370.00 +
22	1	Rear Bumper <i>Deformed</i>		\$2,070.00 1620
23	1	Rear Bumper Lower <i>Deformed</i>		\$670.00 375
24	10	Rear Bumper Clip <i>NP</i>	\$6.50	\$65.00 30.
25	1	Rear Bumper Inner Bracket <i>crushed</i>		\$305.00 185
26	2	Rear Bumper Inner Side Bracket <i>NP</i>	\$59.00	\$118.00 +
27	2	Rear Bumper Side Retainer <i>NP</i>	\$65.00	\$130.00 ✓

28	1	Rear Bumper Towing Cover	Not Nec		\$76.00	X
29	1	Rear Bumper Reinforcement	Bent.		\$870.00	✓
30	1	Rear L/H Bumper Under Cover	crushed		\$91.00	✓
31	1	Rear End Panel	Dented		\$1,450.00	979
32	1	Rear End Panel Top Garnish	crushed.		\$183.00	✓
33	2	Rear Fender Inner Trim Board	2 N/A	\$390.00	\$780.00	X
34	16	Rear Fender Inner Trim Board Clip	1 N/A	\$6.50	\$104.00	X
35	1	Rear Spare Tyre Panel	N/A		\$390.00	+
36	1	Rear Spare Tyre Panel & End Panel Sealant	N/A		\$450.00	+
37	1	Rear Spare Tyre Panel Top Cover	Not Nec		\$460.00	X
38	2	Rear Exhaust	N/A	\$1,470.00	\$2,940.00	+
39	1	Rear Centre Exhaust	2 N/A		\$1,870.00	X
40	4	Rear Exhaust Mounting	1 N/A	\$45.00	\$180.00	X
41	2	Rear Exhaust Chrome Pipe	2 H Bent.	\$380.00	\$760.00	220

6611
5949.80


Subtotal :- \$22,228.00

Labour charges

To remove & refit rear & centre exhaust		\$380.00	X
To reset computer		\$380.00	100.
To check wiring		\$100.00	30.
Towing fee	21.90	\$100.00	X
Tuff kote		\$150.00	60.
Panel beating		\$2,000.00	1000
Spray painting		\$1,800.00	1000.

Subtotal :- \$4,910.00

Total:- \$27,138.00



Total: 8139.80

4/5: 6.5K

06 Days

6.5K