

SGC90188

Rear bumper de ✓ \$456.30
 Rear bumper clips nec ✓ \$30
 Rear bumper side retainers ^{73.20} X2 nec ✓ \$146.40
 Rear Reverse sensor nw ✓ \$200
 Rear end panel ht ✓ \$434.40
 Rear bumper sponge de ✓ \$37
 Rear end panel top garnish de ✓ \$92.40
 Bootlid ht ✓ \$787.50
 Bootlid lock ht ✓ \$109.
 Bootlid chrome moulding de ✓ \$280.60
 Bootlid 'Nissan' emblem nec ✓ \$50.70
 Bootlid 'Latio' emblem nec ✓ \$73.60
 Rear taillamp \$259.40 X2 con ✓ \$518.80.
 Rear fender LH nec ✓ \$627
 Rear fender RH RX ✓ \$627.
 Rear windscreen moulding nec ✓ \$130.90.
 Rear windscreen sealant nec ✓ \$50.
 Rear fender inner trim LH & RH de ✓ \$585
 Spare tyre panel R X \$495.50

Frt number plate - mis ✓ \$45
 Frt bumper de ✓ \$476
 Frt bumper clips nec ✓ \$30.
 Frt bumper side retainers nec ✓ \$64
 Frt bumper sponge de ✓ \$207.20
 Frt bumper reinforcement ht ✓ \$444.90
 Frt headlamps \$386.30 X2 con ✓ \$772.60
 Frt LH fender ht ✓ \$457.40
 Frt LH fender inner shield de ✓ \$63.60
 Frt bonnet ht ✓ \$860
 Frt bonnet lock ht ✓ \$45.80
 Frt bonnet hinge ht ✓ \$102
 Frt support panel ht ✓ \$811.20.
 Air-Con Condenser ht ✓ \$675.90
 Radiator ht ✓ \$596.30
 Radiator cooling fan ✓ \$120.30.
 Radiator fan jrn ✓ \$433.30
 Air-con fan motor assy con ✓ \$335.40
 Radiator coolant nec ✓ \$40.
 Radiator coolant spare tank de ✓ \$60
 11250.50
 Parts Total - 10% - 10125.45

Labour

To repair & replace Rear portion 1500
 \$2000
 To spray painting Rear portion \$1800
 Wiring - \$100.60
 Tuff coat - \$100.80.
 To repair & replace front portion 1200
 \$2000
 To spray painting front portion 1000
 \$1800
 To remove/repair rear windscreen \$150 120

Top up Air con gas - \$180 100

Total labour - 5460

10125.45

5460

15585.45

20% - 12468.36

4/5 \$12,450, 14 days
 #