

ASIA MOTORSPORTS SOLUTION PTE LTD

5 Jalan Masjid, #01-14, (Kembangan Court), Singapore 418924

H/P: 9622 0160 (SG Loo) // Tel: 6745 3811 // Fax: 6746 5110

Email: asiamotorsports@hotmail.com

SJW 7628D

Vehicle number: SJW7628D

Vehicle Made & Model: TOYOTA ALTIS

Qty	List Items	Amount \$
1	Rear bumper	<i>de/to</i> 512.60 ✓
2	Rear bumper side retainers - L/R @ 64.43	<i>17</i> 128.86 X
10	Rear bumper clips @ 4.50	<i>neu</i> 45.00 ✓
1	Rear fender - LH	<i>2</i> 1,260.50 X
1	Rear fender inner shield	<i>17</i> 151.43 X
1	Rear door - LH	<i>2</i> 1,210.50 X
1	Rear door protector	<i>cut/neu</i> 126.20 ✓
1	Rear door protector moulding	<i>neu</i> 61.50 ✓
1	Rear door w/strip	<i>17</i> 132.60 X
1	Rear shock absorber - LH	<i>17</i> 321.60 X
1	Rear wheel hub bearing	<i>17</i> 671.50 X
1	Rear axle beam	<i>17</i> 1,895.60 X
1	Rear windscreen moulding	<i>17</i> 120.60 X
1	Side sill panel skirt - LH	<i>2</i> 681.92 X
Sub-total		7,320.41
Less 25%		1,830.10
Total List		5,490.31

Special Nett Items

1	Rear sport wheel - LH	<i>cut/seat</i> 550.00 <i>350 s.w</i>
1	Rear tyre - LH	<i>800</i> 350.00 X
1 set	Rear windscreen sealant	<i>17</i> 80.00 X
1 set	Rear door black tape	<i>17</i> 80.00 X
Total Special Nett		1,060.00

not allowed
2/5 *\$2000* *Hdy.*
take the other rep.

Vehicle number: SIW7628D

Vehicle Make & Model: TOYOTA ALTIS

Labour charges

To check front electrical wiring	50.00	20
To remove, refix rear interior trims to assist repair	120.00	80
To remove, refix rear undercarriage	11 300.00	X
To check wheel alignment	120.00	60
To respray undercoating	11 150.00	X
To respray painting and etc	1,200.00	800
Panel beating, cut, weld remove & replacing above parts	1,200.00	650
Total Labour	3,140.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

9,690.31

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P - 745.30
257
1 - 558.57
S.W - 350.00
L - 1610.00
2518.57
202
201517