

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 16457**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/1267/2019/NS  
**Date** : 19-Oct-19

**Vehicle NOT IN workshop. Kindly arrange for survey.**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mrs Anne Tian  
**Address** : Blk 229 serangoon Avenue 4  
#10-29  
Singapore 550229  
**Telephone** : (HP) +65 88787685  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 1900141723  
**Vehicle No** : **SMN 3121 L**  
**Model Code** : Audi A3 SB 1.0 TF  
**Model / Year** : 31/7/2019  
**Engine No** : CHZ C31243  
**Chassis No** : WAUZZZ8V6KA099127  
**Mileage** :  
**Date In** :  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 17-Oct-19  
**Place of Accident** : Bukit Merah Road (Near ABC Market)

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SMN 3121 L

| S/n                  | Nature of Jobs                                                                                                                                    | Estimated Charges    | Surveyor's Recommendations |
|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|----------------------------|
| 1                    | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.                    | S/N \$ 360.00 ✓      | ✓                          |
| 2                    | To dismantle and reinstall front bumper. To repair front bumper and bonnet. Re-organise crash management components. Reinstall all parts removed. | \$ 2,100.00 500 ✓    | ✓                          |
| 3                    | To respray front bumper and bonnet.                                                                                                               | \$ 2,000.00 550 ✓    | ✓                          |
| 4                    | To carry out diagnostic check.                                                                                                                    | S/N \$ 192.00 ✓      | ✓                          |
| TOTAL LABOUR CHARGES |                                                                                                                                                   | : <u>\$ 4,652.00</u> |                            |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SMN 3121 L

| S/N                         | Parts Description                 | Damaged Parts & Prices |               |
|-----------------------------|-----------------------------------|------------------------|---------------|
|                             |                                   | S/Nett                 | Remarks       |
| 1                           | FRONT BUMPER GIRLLE - CENTRE      | \$ 146.00              | ? X nn        |
| 2                           | RADIATOR GRILLE                   | \$ 1,301.00            | cr ✓ 1040.80  |
| 3                           | RADIATOR GRILLE CLOSING ELEMENT   | \$ 174.00              | ? cr ✓ 138.80 |
| 4                           | AIRCON STICKER                    | NEC \$ 7.00            | nei ✓ 5.12    |
| 5                           | CAUTION SIGN STICKER              | NEC \$ 13.00           | nei ✓ 9.76    |
| 6                           | RADIATOR AIR GUIDE - UPPER CENTRE | \$ 11.00               | X nn          |
| 7                           | RADIATOR AIR GUIDE - LH / RH      | 2 \$ 44.00             | X nn          |
| 8                           | FRONT NO PLATE                    | S/N \$ 40.00           | bt ✓ 40       |
| 9                           | SUNDRIES                          | \$ 200.00              | ? X nn        |
| <b>TOTAL SPARE PARTS</b>    |                                   | <b>\$ 1,936.00</b>     |               |
| <b>TOTAL LABOUR CHARGES</b> |                                   | <b>\$ 4,652.00</b>     |               |
| <b>GRAND TOTAL</b>          |                                   | <b>\$ 6,588.00</b>     |               |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name :  
Surveyed Date :  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks :

*Handwritten:*  
Tanglu 97445749  
Ex: to be advise  
not otherwise  
22/10/19 @ 1050.  
Resurvey new parts  
03 days  
sure to be done.

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant