

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-Oct-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8080 K

1 pc	Bonnet grille	/	\$	385.00
1 pc	Bonnet	/	\$	979.00
1 pc	Bonnet insulator	X	\$	219.00
1 pc	Bonnet lock	/	\$	36.00
1 pc	Bonnet lifter	X	\$	70.00
1 pc	Bonnet hinge o/s & n/s @ \$23.00	X	\$	46.00
1 pc	Bonnet weatherstrip	X	\$	58.00
1 pc	Support panel	/	\$	645.00
1 pc	Front bumper	/	\$	531.00
1 pc	Front bumper emblem	/	\$	44.00
1 pc	Front bumper centre grille	/	\$	174.00
1 pc	Front bumper lower stiffer	X	\$	134.00
1 pc	Front bumper tow hook cover	/	\$	14.00
1 pc	Front bumper lip	X	\$	52.00
1 pc	Front bumper inner sponge	?	\$	110.00
1 pc	Front bumper reinforcement	?	\$	328.00
1 pc	Front bumper upper reinforcement	?	\$	40.00
2 pcs	Front bumper o/s & n/s side retainer @ \$16.00	X	\$	32.00
2 pcs	Front bumper o/s & n/s upper bracket @ \$16.00	X	\$	32.00
2 pcs	Front bumper o/s & n/s support bracket @ \$16.00	X	\$	32.00
2 pcs	n/s & o/s headlamp @ \$1028.00	/	\$	2,056.00
2 pcs	Front bumper n/s & o/s protector @ \$51.00	X	\$	102.00
2 pcs	Front bumper o/s & n/s fog lamp cover @ \$66.00	X	\$	132.00
2 pcs	Front n/s & o/s fenders \$384.00	X 14.00	\$	768.00
2 pcs	Front n/s & o/s fender inner shield @ \$120.00	X	\$	240.00
1 pc	Radiator	X	\$	669.00
1 pc	Air-con condensor	X	\$	805.00
1 pc	Intercooler	X	\$	800.00
1 pc	Air duct	X	\$	210.00
1 pc	Blower Assy	X	\$	596.00
1 pc	Boot lid	/	\$	1,119.00
1 pc	Boot lid lock	X	\$	99.00
1 pc	Bootlid lock cable	X	\$	35.00
1 pc	Bootlid striker	X	\$	21.00
1 pc	Bootlid emblem	/	\$	27.00
1 pc	Bootlid CRDi	/	\$	29.00
1 pc	Boot lid rubber weatherstrip	X	\$	96.00
1 pc	Boot lid lower garnish	/	\$	290.00
2 pcs	Bootlid hinges @ \$66.00	/	\$	132.00
1 pc	Bootlid inner trim	X	\$	190.00
2 pcs	Bootlid rear license plate lamps @ \$30.00	X	\$	60.00
1 pc	End panel inner garnish	X	\$	74.00

21-Oct-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8080 K

1 pc	End panel		\$	250.00
1 pc	Floorboard compartment panel	X n/s o/s	\$	625.00
1 pc	Floorboard panel trim	X	\$	205.00
1 pc	Spare tyre clamp	X	\$	8.00
1 pc	Rear o/s fender		\$	1,205.00
1 pc	Rear bumper		\$	696.00
1 pc	Rear bumper lower cover		\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	X	\$	58.00
1 pc	Rear bumper inner sponge		\$	114.00
1 pc	Rear bumper reinforcement		\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	X	\$	108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00		\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00		\$	36.00
1 pc	Exhaust pipe		\$	1,009.00
1 pc	Exhaust pipe hanger	X n/s	\$	40.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	n/s X o/s	\$	92.00
2 pcs	Rear n/s & o/s tail lamps	n/s X o/s	\$	842.00
2 pcs	Bootlid n/s & o/s reflector @ \$350.00	X	\$	700.00
1 pc	Rear windscreen moulding		\$	87.00
				\$ 19,435.00
				Less 10%
				\$ 1,943.50
				\$ 17,491.50

S/NETT

1 set	Rear bumper clips		\$	48.00
1 set	End panel inner garnish clips	X	\$	30.00
1 set	Bootlid inner trim clips	X	\$	52.00
1 set	Bootlid lower garnish clips	X	\$	60.00
1 set	Bootlid stickers		\$	100.00
1 set	Reverse sensor		\$	280.00 200
1 pc	Rear o/s fender sticker		\$	60.00
1 set	Floorboard compartment insulating paddings	X	\$	120.00
1 set	Sealant		\$	50.00
1 pc	Rear bumper top protector		\$	80.00 50
1 pc	Rear number plate with casing	X	\$	50.00
1 pc	Front number plate with casing		\$	50.00 35
1 pc	Front bumper clips		\$	48.00
2 pcs	Front n/s & o/s head lamp lower clip @ \$6.00		\$	12.00
2 pcs	Front n/s & o/s head lamp side clip @ \$3.00		\$	6.00
2 pcs	Front n/s & o/s fender stickers @ \$30.00	X	\$	60.00

2 sets	Front n/s & o/s fender inner shield clips @ \$28.00	X	\$	56.00
1 set	Coolant - 8L	X	\$	80.00

21-Oct-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8080 K

Towing fee	\$	50.00	/
Sundry	\$	50.00	20
To check for wiring and to focus front n/s & o/s head lamps	\$	80.00	20
To dismantle/refit old rear windscreen glass onto new moulding	\$	120.00	100
To dismantle / refit rear exhaust pipe	\$	120.00	60
To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	30
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld & cut end panel, floorboard compartment panel, rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the rear n/s & o/s tail lamp panels, rear n/s & o/s chassis, etc	\$	3,600.00	1200
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, end panel, floorboard compartment, rear o/s fender, rear n/s & o/s tail lamp panels, rear n/s & o/s chassis, front bumper, front n/s & o/s fenders, bonnet	\$	3,000.00	1980
To apply rustproofing on the repaired and replaced panels.	\$	350.00	100
	\$	26,403.50	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalin 11/10/19
21/10/19 1710h
7 Days
4/5
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary cost(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CASH SALE/WORK ORDER

No: AE 4746



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date, 19.10.19

寶號 premier

Messrs:

車號 SHB 8080K

車型

Model No: OPTIMA

由 Changi Airport

到 omega

其他 1 key

Remark:

時間

Time : 00:27:00:57:01:37

AMOUNT: \$

注意：本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by:

收貨人

Received by: