

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 376A

AAD1910-148

*Not Authorized
1/Qty @ 1250/-*

Vehicle No.:
Chassis No.:
Vehicle Make: **21 OCT 2019**
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHD 376A
VF1ABL15AUC282665
RENAULT
LATITUDE
17.10.19
AIG
10/6/2016

		PART		LIST		
1	1	BUMPER COVER REAR	\$	<i>Ad/UM</i> 561.70	✓	
2	1	BUMPER LOWER REAR	\$	<i>Ad</i> 411.90	✓	
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 98.10	}	
4	1	BUMPER BRACKET SIDE RH REAR	\$	<i>Sn</i> 82.10		
5	1	BUMPER RETAINER RH REAR	\$	<i>Sn</i> 59.80		
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 16.60		
7	1	BUMPER BRACKET SIDE LH REAR	\$	<i>Sn</i> 80.80		
8	1	BUMPER RETAINER LH REAR	\$	<i>Sn</i> 54.20		
9	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 16.60		
10	1	BUMPER BEAM REAR	\$	<i>K</i> 547.80		
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>K</i> 114.50		
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>K</i> 100.90		
13	1	OUTER PANEL REAR (End Panel)	\$	<i>K</i> 745.80		
14	1	OUTER PANEL REAR (End Panel) TRIM	\$	<i>Sn</i> 404.56		} X
15	1	TAILLAMP RH	\$	<i>Sn</i> 313.10		
16	1	TAILLAMP PANEL RH	\$	<i>K</i> 401.40		
17	1	TAILLAMP LH	\$	<i>Sn</i> 401.40		
18	1	TAILLAMP PANEL LH	\$	<i>K</i> 401.40		
19	1	BOOT REAR	\$	<i>K</i> 1,677.20		
20	1	BOOT FINISHER	\$	<i>Sn</i> 344.70		
21	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 178.20		
22	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 277.70		
23	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 277.70		
24	1	BOOT BADGE 'RENAULT'	\$	<i>un</i> 82.40		
25	1	BOOT BADGE	\$	<i>un</i> 95.80		
26	1	BOOT STRUT LH	\$	<i>Sn</i> 145.10		
27	1	BOOT STRUT RH	\$	<i>Sn</i> 145.10		

Trans-cab Auto Services Pte Ltd

AAD1910-148

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 376A

28	1	BOOT HINGE LH	\$	<i>M</i>	254.20	}
29	1	BOOT HINGE RH	\$	<i>M</i>	253.80	
30	1	BOOT INNER TRIM BOARD	\$	<i>Sn</i>	611.00	
31	1	BOOT SWITCH	\$	<i>Sn</i>	113.00	
32	1	BOOT LOCK	\$	<i>M</i>	246.60	
33	1	BOOT LOCK CATCH	\$	<i>M</i>	41.70	
34	1	EXHAUST CAP REAR	\$	<i>Sn</i>	125.40	
TOTAL			\$		9,682.26	
10%			\$		968.23	
			\$		8,714.03	

Special Nett

1	1SET	PARKING AID	\$	<i>Sn</i>	700.00	X
2	1SET	REAR BUMPER CLIP	\$	<i>M</i>	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>M</i>	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i>	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	<i>nn</i>	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>nn</i>	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	<i>nn</i>	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i>	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	<i>M</i>	66.00	—
10	1	BOOT STICKER "Trans-cab"	\$	<i>nn</i>	30.00	}
11	1	BOOT STICKER "6555-3333"	\$	<i>nn</i>	30.00	
12	1	EXHAUST MOUNTING REAR	\$	<i>nn</i>	16.00	
13	2	REAR WINDSCREEN SEALANT	\$	<i>na</i>	80.00	
14	1	WINDSCREEN MOULDING	\$	<i>nn</i>	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i>	100.00	
16	1	BOOT INNER TRIM CLIP	\$	<i>na</i>	45.00	
17	1SET	BOOT FINISHER CLIP	\$	<i>na</i>	24.20	
18	1	TAILLAMP CLIP LH	\$	<i>nn</i>	5.00	
19	1	TAILLAMP CLIP RH	\$	<i>nn</i>	5.00	
20	1	Rear Bumper Protector	\$	<i>M</i>	100.00	<i>4000</i>
TOTAL			\$		1,482.20	
TOTAL PARTS			\$		10,196.23	

LABOUR

Trans-cab Auto Services Pte Ltd

AAD1910-148

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 376A

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>100</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>600</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>2000</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>4</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>4</i> 220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>4</i> 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>4</i> 380.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	<i>2200</i>
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	X

TOTAL \$ 14,720.00
Over All Total \$ 24,916.23
LUMP SUM (REPAIR DAY) 20 DAYS

Putty and spray painting of the affected portion.
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
