

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ZHEN HE JIA HUAN HAND MADE NOODLE
636A SENJA ROAD
#11-313 SENJA PARC VIEW
S 671636

TPAXA
Xiao Tong

Date :30.10.2019
Vehicle No :SMK 4734 C
Make/Model :TOYOTA ALPHARD
Accident date :19.10.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Front RH fender Repair	1	\$ 1068.6 X.
2	Front RH door Dented	1	\$ 1884.2
3	Front RH door lower garnish Dented	1	\$ 858 550(SW)
4	Front RH door protector Repair	1	\$ 121 X
5	Front RH door lower inner garnish Xtem	1	\$ 628.5 X.
6	Front RH door weather strip Xtem	1	\$ 452.5 X
7	Front RH door sunrise Visor Xtem	1	\$ 165 60(SW)
8	Rear RH door Repair	1	\$ 1890.1 X
9	Rear RH door lower garnish Dented	1	\$ 858 550(SW)
10	Rear RH door protector Repair	1	\$ 121 X
11	Rear RH door inner garnish Xtem	1	\$ 628.5 X
12	Rear RH door sunrise Visor	1	\$ 165 X.
			\$ 8840.4
Less 25% Disc			\$ 2210.1
Total			\$ 6630.3

Special Nett Items

1	Front RH tyre Xtem	\$ 680 X
2	Front RH sport rim Xtem	\$ 1800 850
Total		\$ 2480

Labour Cost

1	To check wheel alignment	1580 \$ 100 80
2	Remove ,replace & repair consistent to the accident	\$ 1200 400
3	Respray painting	\$ 1400 1000
4	Remove & reinstall door glass fittings	\$ 200 100
Total		\$ 2900

Grand Total \$ 12010.3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 5003.15

1/5: 4K.

04Days.

HIC.