

ASS. REC. BY:

REF: CS/FCI 19018729/ALF3

n2

Special Instruction:

Surveyor:

Adnan

ASSIGNMENT (Office)

From (Person):

Sitharan

of

FCI

Date/Time:

22.10.19 10:16 a.m

Estimated Cost:

Bill to:

OD / TP / VS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLZ 87202

Insured:

SHC 7272A

at Workshop n/a:

N-51 Automotive

Tel:

68420051

of

2 Kati Bukit Ave 2 #01-14

Policy No:

Claim No:

D19006709MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 21.10.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time:

22.10.19 10:27 a.m

Person Contacted:

Zi Ting

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLZ 87202 - CS31MSG 19006444/Ekt202 -1 D.O.A - 09/04/2019

SHC 7272A - NBT/IN/19022107/1 D.O.A. 06/03/2019

25/10@ 4:48pm - Sent email pending estimate

Lump Sum \$14,500 - Cred: 8346.84' 36%

ASS. REC. BY:

REF: FCI

ASSIGNMENT

From: _____ Date: 23.10.2019

Estimated Cost: _____

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No: SL2 87202

at Workshop m/s N-51 Automotive

of 2 Kaki Bukit Pk 2 #01-18

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SL287202 Yr Regn: 2018 May

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius Plus c.c 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 142523 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDZS3E400J027479

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16 -

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Habiles d

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 23/10/19

Survey held at N51

Des. of Damages: ☒ Fr / ☒ Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP 1st Cap.

RECEIVED 09 MAR 2020

Date/Time, File Pass in?

1) 913 Typist

Date/Time, File Return to?

2)

Pop. Format: TP

Lump Sum / T.B. is 14,500/-

Days Of Repair: 10

Resurvey No. of Trip: 2

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photo

Other

TOTAL

10/3/20

12x15=180

170+180

50

50+50

133

580

633

MOTOR SURVEY ASSIGNMENT

Date	22-10-2019	Our Ref No.	D19006709MFSH
Accident Date	21-10-2019	Claim Type.	Third Party
Insured Vehicle	SHC7272A	Third Party Vehicle.	SLZ8720Z
Survey Location	2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB		
Contact Person.	ZI TING		
Contact No.	68420051/ 67440510	Fax No.	67410510
Survey Type	WITHOUT PREJUDICE:		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	N-51 AUTOMOTIVE PTE LTD	Attention.	NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No.	NA
Officer Incharge	SITHARA		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 25 October 2019 4:48 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments; SUR
Cc: 'Sithara'
Subject: RE: SURVEY ASSESSMENT - D19006709MFSH/1

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLZ 8720Z on 23/10/219
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 23 October 2019 10:25 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19006709MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>
Sent: Wednesday, 23 October, 2019 10:16 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19006709MFSH/1

Dear Sir/Mdm,

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/10/2019 16:41
Date Of Accident	21/10/2019 14:45
Exact Location Of Accident	ALONG PIE (TUAS)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ8720Z
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31388644

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS PLUS-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29114756MKF
Cover Note Number	

Driver

Name of Driver	KER CHUAN CHYE
NRIC No	S1387298H
Date Of Birth	03/12/1959
Occupation	OUTDOOR
Date Of Driving Pass	05/12/1977
Driving Experience	41 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98186439
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 734 TAMPINES ST 71 #14-89
Postcode	520734
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LESSEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	DRIZZLING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NOT APPLICABLE GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 21/10/19 ABOUT 2:45PM, I WAS TRAVELLING STRAIGHT TOWARDS TUAS ON PIE (TUAS) LANE 1. VEHICLE C JAMMED BRAKE IN FRONT OF ME AND I STOP IN TIME BUT VEHICLE B COLLIDED INTO MY REAR CAUSING ME TO HIT VEHICLE C'S REAR. NOBODY WAS INJURED AT THE POINT OF TIME.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SD CARD WITH WORKSHOP
Was there any audio recorded?	NO

Details of Witness 1

Name	RAHIM
Phone Number	91188600
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC7272A
Vehicle Make/Model/Colour	TOYOTA / PRIUS / YELLOW
Details Of Properties	VEH B
Vehicle Category	TAXI
Name of Driver	

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage FRONT PORTION

No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number EX1987K

Vehicle Make/Model/Colour BMW

Details Of Properties VEH C

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver) 2

Passenger 1 NAME: : NOT APPLICABLE

GENDER: : FEMALE


SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A SLZ 87202
 B SKC 7272A
 C EX 1987K

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 21/10/19 ABOUT 345pm, I WAS TRAVELLING STRAIGHT TOWARDS
 TUES ON PIE (TUES) LANE 1. VEH C JAMMED BRAKE IN FRONT OF
 ME AND I STOP IN TIME BUT VEH B COLLIDED INTO MY REAR
 CAUSING ME TO HIT VEH C'S REAR. NOBODY WAS INJURED AT THE
 POINT OF TIME.

[Signature]

21/10/2019

4.16 pm

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP 1st Cap.

Denise.

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 98186439

ESTIMATE

Repair Code : CLM15675

Date in : 21/10/2019

Vehicle Num. : SLZ8720Z

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU00J027479/2ZR0B71427

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER AIR GUIDE L/R <i>Cracked</i>	2	172.10	✓ 344.20
FRONT BONNET LOCK <i>new</i>	1	174.85	+ 174.85
FRONT BUMPER <i>Deformed</i>	1	576.87	✓ 576.87
FRONT BUMPER 'LOGO' EMBLEM <i>new</i>	1	72.10	✓ 72.10
* FRONT BUMPER CENTER GRILLE <i>Cracked</i>	1	758.85	✓ 758.85
FRONT BUMPER SIDE LOCK CLIPS <i>new</i>	6	9.50	✓ 57.00
FRONT BUMPER SIDE LOCK CLIPS HOLDER <i>new</i>	6	12.90	✓ 77.40
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	132.25	✓ 264.50
FRONT BUMPER UPPER SEAL RUBBER <i>new</i>	1	104.50	+ 104.50
FRONT GRILLE <i>Cracked</i>	1	651.60	✓ 651.60
FRONT HEADLAMP L/R <i>Cracked</i>	2	2625.00	✓ 5,250.00
FRONT HEADLAMP LOWER BRACKET L/R <i>new</i>	2	72.45	+ 144.90
FRONT INVERTER RADIATOR <i>Best</i>	1	780.90	✓ 780.90
FRONT SUPPORT PANEL UPPER TOP GARNISH <i>Deformed</i>	1	561.60	231 561.60
RADIATOR UPPER BRACKET <i>Cracked</i>	1	230.00	✓ 230.00
REAR BUMPER <i>Deformed</i>	1	523.90	✓ 523.90
REAR BUMPER LOWER COVER <i>Deformed</i>	1	179.00	✓ 179.00
REAR BUMPER LOWER SPOILER <i>Deformed</i>	1	721.00	✓ 721.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 98186439

ESTIMATE

Repair Code : CLM15675

Date in : 21/10/2019

Vehicle Num. : SLZ8720Z

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU00J027479/2ZR0B71427

REAR BUMPER REINFORCEMENT <i>Bent</i>	1	350.50	✓	350.50
REAR BUMPER REINFORCEMENT BRACKET L/R <i>Bent</i>	2	198.70	✓	397.40
REAR BUMPER SIDE RETAINER L/R <i>Nec</i>	2	98.00	✓	196.00
REAR END PANEL <i>Dented</i>	1	781.45	✓	781.45
REAR END PANEL ANTENNA SENSOR <i>Nec Nec</i>	1	285.00	+	285.00
REAR END PANEL INNER TOP GARNISH <i>Deformed</i>	1	287.90	✓	287.90
REAR EXHAUST SILENCER BOX <i>Nec Nec</i>	1	1010.70	+	1,010.70
REAR EXHAUST SILENCER GASKET <i>Nec Nec</i>	1	35.00	+	35.00
REAR EXHAUST SILENCER RUBBER MOUNTING <i>Nec</i>	2	55.00	+	110.00
REAR FENDER INNER TRIM GARNISH L/R <i>Deformed</i>	2	656.00	✓	1,312.00
REAR SPARE TYRE SPONGE TRAY <i>crushed</i>	1	396.70	✓	<u>396.70</u>
REAR SPONGE COMPARTMENT TRAY <i>crushed</i>	1	459.70	✓	459.70
REAR SPONGE COMPARTMENT TRAY TOP COVER <i>crushed</i>	1	655.00	✓	655.00
REAR TAILGATE <i>Dented</i>	1	929.60	✓	929.60
REAR TAILGATE 'HYBRID' EMBLEM <i>Nec</i>	1	50.00	✓	50.00
REAR TAILGATE 'PRIUS' EMBLEM <i>Nec</i>	1	52.30	✓	52.30
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH <i>crushed</i>	1	578.00	✓	578.00
REAR TAILGATE MECHANISM LOCK <i>Damaged</i>	1	425.00	✓	425.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 98186439

ESTIMATE

Repair Code : CLM15675

Date in : 21/10/2019

Vehicle Num. : SLZ8720Z

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU00J027479/2ZR0B71427

REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>Not Nec</i>	2	29.00	X	58.00
REAR TAILGATE WEATHER STRIP <i>Not</i>	1	360.70	✓	360.70
REAR TAILGATE WINDSCREEN LOWER SEAL <i>Nec</i>	1	42.00	✓	42.00
REAR TAILGATE WINDSCREEN MOULDING L/R <i>Nec</i>	2	65.00	✓	130.00
REAR TAILGATE WINDSCREEN UPPER SEAL <i>Nec</i>	1	38.00	✓	38.00
REAR TAILLAMP BACK RUBBER SEAL L/R <i>Nec</i>	2	69.50	40	139.00
REAR TAILLAMP L/R <i>Crack</i>	2	630.00	✓	1,260.00
REAR TAILLAMP LOWER BRACKET L/R <i>Nec</i>	2	68.00	X	136.00
Subtotal before discount				21,949.12
Percentage discount 25%				5,487.28
Sub-total 1				16,461.84
FRONT BUMPER CLIPS - SET <i>Nec</i>	1	50.00	30	50.00
FRONT NUMBER PLATE <i>Best</i>	1	25.00	✓	25.00
FRONT NUMBER PLATE HOLDER <i>Deland</i>	1	50.00	30	50.00
FRONT SUPPORT PANEL UPPER TOP GARNISH CLIPS - SET <i>Nec</i>	1	30.00	10	30.00
RADIATOR COOLANT <i>Nec</i>	1	60.00	30	60.00
REAR BUMPER ARTWORK STICKER <i>Nec</i>	1	280.00	150	280.00
REAR BUMPER CLIPS - SET <i>Nec</i>	1	50.00	30	50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 98186439

ESTIMATE

Repair Code : CLM15675

Date in : 21/10/2019

Vehicle Num. : SLZ8720Z

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU00J027479/2ZR0B71427

REAR BUMPER LOWER COVER CLIPS - SET <i>New</i>	1	20.00	✓	20.00
REAR BUMPER LOWER SPOILER CLIPS - SET <i>New</i>	1	60.00	20	60.00
REAR BUMPER REVERSE SENSOR - SET <i>Damaged</i>	1	250.00	200	250.00
REAR BUMPER UPPER RUBBER PAD <i>2hd</i>	1	300.00	150	300.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>New</i>	1	20.00	10	20.00
REAR FENDER ARTWORK STICKER - SET <i>Not new</i>	1	150.00	X	150.00
REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET <i>New</i>	2	30.00	✓	60.00
REAR TAILGATE INNER REFLECTIVE STICKER - SET <i>Not new</i>	1	100.00	X	100.00
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS - SET <i>Repacked</i>	1	50.00	X	50.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	60.00	✓	60.00
REAR TAILLAMP CLIPS L/R - SET <i>New</i> <i>845</i>	2	30.00	20	60.00
Subtotal before discount				1,675.00
Percentage discount 0%				0.00
Sub-total 2				1,675.00
Parts-total				18,136.84

LABOUR

To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	✓	100.00
To remove, reinstall tailgate windscreen	120	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80	140.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005-GRAB 98186439

ESTIMATE

Repair Code : CLM15675

Date in : 21/10/2019

Vehicle Num. : SLZ8720Z

Model : TOYOTA PRIUS PLUS (AUTO)

Chassis/Eng# : JTDZS3EU00J027479/2ZR0B71427

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

800 1,400.00

To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.

250 1,000.00

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

80 120.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

1100 1,600.00

To apply anti-rust chemical on repaired and replaced panel.

2670

80 120.00

To remove, reinstall tailgate mechanism and check for function

80.00

Labour Total

4,710.00

Parts & Labour Total

22,846.84

*** This is a computer-generated document which requires no signature.***

page 5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 188042

2/s: 145K.

10 Days.

145K



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19018729/Atf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-03-2020	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh. SHC 7272A	Veh. Inspected	SLZ 8720Z
	Policy No.	Coverage (\$)	0.00
	Claim No. D19006709MFSH	Excess (\$)	0.00
	Assign From SITHARA	Assign Date	23/10/2019
2. Vehicle Particulars & Condition			
	Make & Model TOYOTA PRIUS PLUS	c.c	1798
	Engine No. HIDDEN	Year of Reg.	2018
	Chassis No. JTDZS3EU00J027479	Colour	BLUE
	Odometer 143423	Steering	IN ORDER
	Brakes IN ORDER	Modification	SPORTS RIM
	General GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
	R/H Front Tyre 205/60 R16	HABILEAD	6 mm
	L/H Front Tyre 205/60 R16	HABILEAD	6 mm
	R/H Rear Tyre 205/60 R16	HABILEAD	6 mm
	L/H Rear Tyre 205/60 R16	HABILEAD	6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.		
5. General Information			
	Accident Date 21/10/2019	Inspection Date	23/10/2019
	Survey held at N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
	A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 8720Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	AIRCON CONDENSER AIR GUIDE-L/R @\$172.10	CRACKED	344.20	344.20
1	FRONT BONNET LOCK	NOT NECESSARY	174.85	-
1	FRONT BUMPER	DEFORMED	576.87	576.87
1	FRONT BUMPER "LOGO" EMBLEM	NECESSARY	72.10	72.10
1	FRONT BUMPER CENTER GRILLE	CRACKED	758.85	758.85
6	FRONT BUMPER SIDE LOCK CLIPS @\$9.50	NECESSARY	57.00	57.00
6	FRONT BUMPER SIDE LOCK CLIPS HOLDER @\$12.90	NECESSARY	77.40	77.40
2	FRONT BUMPER SIDE RETAINER L/R @\$132.25	NECESSARY	264.50	264.50
1	FRONT BUMPER UPPER SEAL RUBBER	NOT NECESSARY	104.50	-
1	FRONT GRILLE	CRACKED	651.60	651.60
2	FRONT HEADLAMP L/R @\$2625.00	CRACKED	5,250.00	5,250.00
2	FRONT HEADLAMP LOWER BRACKET L/R @\$72.45	NOT NECESSARY	144.90	-
1	FRONT INVERTER RADIATOR	BENT	780.90	780.90
1	FRONT SUPPORT PANEL UPPER TOP GARNISH	DEFORMED	561.60	231.00
1	RADIATOR UPPER BRACKET	CRACKED	230.00	230.00
1	REAR BUMPER	DEFORMED	523.90	523.90
1	REAR BUMPER LOWER COVER	DEFORMED	179.00	179.00
1	REAR BUMPER LOWER SPOILER	DEFORMED	721.00	721.00
1	REAR BUMPER REINFORCEMENT	BENT	350.50	350.50
2	REAR BUMPER REINFORCEMENT BRACKET L/R @\$198.70	BENT	397.40	397.40
2	REAR BUMPER SIDE RETAINER L/R @\$98.00	NECESSARY	196.00	196.00
1	REAR END PANEL	DENTED	781.45	781.45
1	REAR END PANEL ANTENNA SENSOR	NOT NECESSARY	285.00	-
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	287.90	287.90
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	1,010.70	-
1	REAR EXHAUST SILENCER GASKET	NOT NECESSARY	35.00	-
2	REAR EXHAUST SILENCER RUBBER MOUNTING @\$55.00	NOT NECESSARY	110.00	-
2	REAR FENDER INNER TRIM GARNISH L/R @\$656.00	DEFORMED	1,312.00	1,312.00
1	REAR SPARE TYRE SPONGE TRAY	CRACKED	396.70	396.70

Report Ref No. CS/FCI19018729/Att3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR SPONGE COMPARTMENT TRAY	CRACKED	459.70	459.70
1	REAR SPONGE COMPARTMENT TRAY TOP COVER	CRACKED	655.00	655.00
1	REAR TAILGATE	DENTED	929.60	929.60
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	50.00	50.00
1	REAR TAILGATE "PRIUS" EMBLEM	NECESSARY	52.30	52.30
1	REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	CRACKED	578.00	578.00
1	REAR TAILGATE MECHANISM LOCK	DAMAGED	425.00	425.00
2	REAR TAILGATE RUBBER GUIDE STOPPER L/R @\$29.00	NOT NECESSARY	58.00	-
1	REAR TAILGATE WEATHER STRIP	CUT	360.70	360.70
1	REAR TAILGATE WINDSCREEN LOWER SEAL	NECESSARY	42.00	42.00
2	REAR TAILGATE WINDSCREEN MOULDING L/R @\$65.00	NECESSARY	130.00	130.00
1	REAR TAILGATE WINDSCREEN UPPER SEAL	NECESSARY	38.00	38.00
2	REAR TAILLAMP BACK RUBBER SEAL L/R @\$69.50	NECESSARY	139.00	40.00
2	REAR TAILLAMP L/R @\$630.00	CRACKED	1,260.00	1,260.00
2	REAR TAILLAMP LOWER BRACKET L/R @\$68.00	NOT NECESSARY	136.00	-
	LESS 25% DISCOUNT		-5,487.28	-4,865.14
			16,461.84	14,595.43
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT NUMBER PLATE (SN)	BENT	25.00	25.00
1	FRONT NUMBER PLATE HOLDER (SN)	DEFORMED	50.00	30.00
1	SET FRONT SUPPORT PANEL UPPER TOP GARNISH CLIPS (SN)	NECESSARY	30.00	10.00
1	RADIATOR COOLANT (SN)	NECESSARY	60.00	30.00
1	REAR BUMPER ARTWORK STICKER (SN)	NECESSARY	280.00	150.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR BUMPER LOWER COVER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET REAR BUMPER LOWER SPOILER CLIPS (SN)	NECESSARY	60.00	20.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
1	REAR BUMPER UPPER RUBBER PAD (SN)	DEFORMED	300.00	150.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	20.00	10.00
1	SET REAR FENDER ARTWORK STICKER (SN)	NOT NECESSARY	150.00	-

Report Ref No. CS/FCI19018729/Att3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	SET REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R @\$30.00 (SN)	NECESSARY	60.00	60.00
1	SET REAR TAILGATE INNER REFLECTIVE STICKER (SN)	NOT NECESSARY	100.00	-
1	SET REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS (SN)	REPEATED	50.00	-
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
2	SET REAR TAILLAMP CLIPS L/R @\$30.00 (SN)	NECESSARY	60.00	20.00
			1,675.00	845.00
	LABOUR			
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,RESETTING HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR.		100.00	100.00
	TO REMOVE,REINSTALL TAILGATE WINDSCREEN.		150.00	120.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR).		140.00	80.00
	TO RE-SPRAY PAINTING ON THE REAR BOOTLID,REAR END PANEL,REAR FENDER (L/R),SPARE TYRE PANEL AND REAR BUMPER.		1,400.00	800.00
	TO RE-SPRAY PAINTING ON THE FRONT BONNET,FRONT SUPPORT PANEL,FRONT FENDER (L/R) AND FRONT BUMPER.		1,000.00	250.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		120.00	80.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		1,600.00	1,100.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	80.00
	TO REMOVE,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION.		80.00	80.00
	-		-	-
	-		-	-
	-		-	-
			4,710.00	2,690.00
	GRAND TOTAL		22,846.84	18,130.43



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			14,500.00
---	--	--	-----------

Report Ref No. CS/FCI19018729/Atf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.