

TRIPLE-T AUTOMOBILE

BLK 5 DEFU LANE 10 #01-574 SINGAPORE 539186

TEL: 6280 8927 FAX: 6280 4205

Vehicle No: GBG5699R

Model No. Toyota Dyna

Chassis no. *

Accident Date : 18/10/2019

Owner : Guan Lee Vegetables & Fruits Pte Ltd

Date of Estimate : 22/10/2019

Estimate for Accident Vehicle No. GBG5699R

<u>List Items:</u>	Qty	Unit Price	Total Amount
1 Front windscreen glass <i>CR</i> ✓	1	\$678.50	\$678.50
2 Front windscreen glass rubber <i>ne</i> ✓	1	\$144.50	\$144.50
3 Front panel <i>bt</i> ✓	1	\$515.00	\$515.00
4 Front panel emblem 'DYNA' <i>ne</i> ✓	1	\$38.00	\$38.00
5 Front wiper panel (white) <i>bt</i> ✓	1	\$149.80	\$149.80
6 Front corner panel rh <i>SC</i> ✓	1	\$101.65	\$101.65
7 Front radiator grille <i>CR</i> ✓	1	\$221.00	\$221.00
8 Headlamp assy <i>lh/rh</i> <i>bro</i> ✓	<i>1pc</i> 2	\$344.50 ✓	\$689.00 ×
9 Front bumper <i>turn</i> ✓	1	\$269.00	\$269.00
10 Front bumper cross member - repair	1	\$0.00	\$0.00
11 Front bumper bracket <i>lh/rh</i> <i>bt</i> ✓	<i>1pc</i> 2	\$107.00 ✓	\$214.00 ×
12 Front bumper fog lamp garnish <i>lh/rh</i> <i>SC</i> ✓	<i>1pc</i> 2	\$55.00 ✓	\$110.00
13 Steering box <i>bro</i> ✓	1	\$545.50	\$545.50
14 Steering shaft ?	1	\$221.00	\$221.00
		Bal c/d	\$3,896.95
		Add 15%	\$584.54
		Sub-Total	\$4,481.49

<u>Special Nett Items</u>	Qty	Unit Price	Total Amount
1 Front panel logo <i>ne</i> ✓	1	\$25.00	\$25.00
2 Front panel company advertisement <i>ne</i> ✓	1	\$550.00	\$550.00 200
3 Front wiper garnish clips ×	1set	\$20.00	\$20.00
4 Front grille clips <i>ne</i> ✓	1set	\$10.00	\$10.00
5 Front bumper clips <i>ne</i> ✓	1set	\$20.00	\$20.00
6 Front number plate <i>bt</i> ✓	1	\$40.00	\$40.00
7 ERP sticker ×	1	\$10.00	\$10.00
8 ERP brakcet <i>ne</i> ✓	1	\$40.00	\$40.00
		Sub-Total =	\$715.00
		Total cost for parts =	\$5,196.49

Labour charges

- 1 Panel beating for replace and repair affected parts
- 2 Spray painting
- 3 Apply putty and anti-corrosion to affected parts.
- 4 Wiring / bulb checking
- 5 Remove and replace front windscreen glass

800	\$1,200.00
700	\$1,000.00
	\$50.00
30	\$40.00
120	\$150.00
	<u>\$2,440.00</u>

Total parts	=	\$5,196.49
Total labour	=	<u>\$2,440.00</u>
Total Amount	=	<u>\$7,636.49</u>

Paul
Hp 900/100 68

7 days

W/S

23/10/19 @ 1120

Excess: 3,000

Revert

Resin after paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: