

ASS. REC. BY:

REF: CS/SMD19618754/U9f3 n2 Special Instruction:

SUPERVISOR: Marcus

ASSIGNMENT (Office)

From (Person): Agnes Chan Shu Hui of SMD Date/Time: 23.10.19 10.34 a.m.

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLM 8982C Insured: SDD 86J

at Workshop m/s Zoom Auto works Tel: 94507920

of 130 Bedok Reservoir Road #08-1369

Policy No: D19MPV01000915 Claim No: CMTD1904933

Sum Insured: Excess:

Make of Veh: D.O.A. 19.10.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 23.10.19 11.19 a.m. Person Contacted: Elin H.O.P. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate	Inspector: BIK 15 Kaki Bukit road 4, 701-53
	SLM 8982C - NA/AG 19013596/24	D. CA - 19/10/2019
	SDD 86J - NA/AG 19013596/24	D. CA - 19/10/2019
29/10/19 @ 12.30pm	Informed Agnes Chan, we are pending estimate from repairer.	
08/11/19 @ 4.49pm	revised to Agnes Chan via alexander.	

ASS. REC. BY:

MARCUS

REP:

Said

ASSIGNMENT

Front:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLM8982C

at Workshop m/s

ZOOM

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

87/k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

20

days

Res.: Yes or No

Lum Sum:

2

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

339k

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLM8982C

Yr Regn:

4, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CAI

Make:

Honda vete / Hybrid

1496

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

209173

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Ru 3 1226845

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 215 / 60 216

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

maximum

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

19/10/19

D.O.I.

24/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & L.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27A44428 745 6mth nett 26571

8/11/19 4/5 @ 19.000 conf. and with Elin. (RD # 14052.08, 43%)

RECEIVED 12 NOV 2019

Date/Time, File Pass to?

☐

Prel. Report

1) (X)u Inpsr

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

20

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

450
11
461

Report Forms:

MER-TP

Lump Sum / LEA:

19000

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 08 Nov 2019

Preliminary Advice

Insured Vehicle No	: SDD86J	Accident Date	: 19/10/2019
TP Vehicle No	: SLM8982C	Assignment Date	: 23/10/2019
Make	:	Est. Duration of Repair	: 20.00
Date of Inspection	: 24/10/2019		
Inspection At	: ZOOM AUTOWERKS PTE LTD (HQ) 130 BEDOK RESERVOIR ROAD, EUNOS SPRING, #08-1339 SINGAPORE 470130		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear & front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	33,052.08
Revised Amount	:S\$	23,774.64
Check Items (Estimated)	:S\$	0.00
Total	:S\$	23,774.64
Lump Sum Repair	:S\$	19,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Oct 2019		23 Oct 2019 10:34 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YAP FUI LIN, ID: S2594245J								
Main Claimant:	JIN & WEI ENTERPRISES								
Vehicle Reg. No.:	SLM8982C	Date of Loss:	19/10/2019 16:00 - :59						
Claim Type:	TP / CMTD1904933	Policy/Cover Note No.:	D19MTPV01000915 (Comprehensive)						
Vehicle Reg. No. (Insured):	SDD86J	Policy No. (Claimant):							
		Excess:							
Repairer:	Zoom Autowerks Pte Ltd (HQ) 130 Bedok Reservoir Road, Eunos Spring, #08-1339, 470130 Bedok - Tel: 94507920								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/11/2019]								
Adj Asg. Remarks:	Please assign case to Marcus								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Friday, 25 October 2019 12:20 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SLM 8982C (YOUR REF: CMTD1904933)

This mail is associated with :

***SLM8982C (CMTD1904933)**
[SDD86J]

TP

JIN & WEI ENTERPRISES

Oct 19 2019 4:00PM

[YAP FUI LIN]

Zoom Autowerks Pte Ltd

Dear Agnes,

Please be informed that we have inspected the vehicle SLM 8982C on 24/10/2019.

We are pending estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Bidded Car Plate Number for sale

Looking for auspicious numbers?

Browse our list of hottest bidded car plate numbers for sale.

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

2016 Audi A3 Sedan 1.4A TFSI Ambiente At Only \$72,777.



Guarantee Super Cheapest,
Upgraded Original SSR3 18"
Rims/Tyre Only 2 Month Old.
HTS Motor StarAd



Browse by Category ▼

Sort by Date Posted ▼

20 vehicles

Vezel Hybrid 1.5A X

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	Vezel Hybrid 1.5A X		Any	Any	2017	Any	Any	Any



Honda Vezel Hybrid 1.5A X
Honda Sensing

Fuel Type: Petrol-Electric

Auction Closing Time: 4th Nov 2019 at 05:00 PM

Keys Available, Mileage Done 13,479, Road Tax Expiry 28/Dec/2019.

Posted: 24-Oct-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel Hybrid 1.5A X****\$70,800****\$9,460 /yr****12-Jan-2017****1,496 cc****33,700 km****SUV**

Fuel Type: Petrol-Electric

1 Year Warranty. Accident Free, Loan Available, Trade In Welcome.

Posted: 23-Oct-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Honda Vezel Hybrid 1.5A X
Honda Sensing

\$77,800**\$9,790 /yr****04-Jul-2017****1,496 cc****23,000 km****SUV**

Fuel Type: Petrol-Electric

Attractive Loan Packages, Enquirer To Know More! Very Beautiful Purplish Black Vezel Hybrid! Powerful Yet Low Petrol Consumption! Safety Honda Sensing Functions With Auto Lane Departure Warning! Well Taken Care By Previous Owner! STA Evaluation Highly Recom...

Posted: 19-Oct-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

**Honda Vezel Hybrid 1.5A X****\$75,500****\$9,650 /yr****17-May-2017****1,496 cc****-****SUV**

Fuel Type: Petrol-Electric

Elegant Silver SUV, Powerful Drive With 150 Bhp, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available.

Prime Motor & Leasing

Posted: 19-Oct-2019 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



Stamford Tyres - Paint Protection

Stamford Tyres has built a reputation on steadfast commitment to service and product excellence over the years.

More info about this shop

Honda Vezel Hybrid 1.5A X**\$78,500****\$10,300 /yr****10-Mar-2017****1,496 cc****4,900 km****SUV**

e: Petrol-Electric

n 100000Km Warranty. High Trade In.

Compare

Das WeltAuto.

Used cars you can trust. Guaranteed.

Some decisions don't have to weigh heavily on you

Vezel Hybrid 1.5A X

Price Range ▼

Depreciation ▼

2017 ▼

Vehicle Type ▼



Home » Used Cars » Prime Car Traders Pte Ltd » Honda Vezel Hybrid 1.5A X

Honda Vezel Hybrid 1.5A X

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price	\$74,800	Fuel Type	Petrol-Electric
Depreciation ⓘ	\$9,660 /yr View models with similar depre	Reg Date	20-Apr-2017 (7yrs 5mths 25days COE left)
Mileage	N.A.	Manufactured ⓘ	2016
Road Tax ⓘ	N.A.	Transmission	Auto
Dereg Value ⓘ	\$41,937 as of today (change)	OMV ⓘ	\$29,052
COE ⓘ	\$51,000	ARF ⓘ	\$5,000
Engine Cap	1,496 cc	No. of Owners ⓘ	1
Curb Weight ⓘ	1,280 kg		
Type of Vehicle	SUV		

Features

Hybrid 4 Cylinder Inline DOHC I-VTEC Engine 150Bhp. 7 Speed Automatic. 8 SRS Airbags. ABS. Electric Parking Brake. Fuel Consumption At 25 Km/L. View specs of the Honda Vezel Hybrid (2014)

Accessories

Eco Assist. Cruise Control. Auto Brake Hold. Smart Key System. Paddle Shift. Eco/Sport Mode. Retractable Side Mirrors.

Description

Low Mileage, 1 Owner, Immaculate Condition, In House Loan Available And High Trade In Available Too. Contact Our Sales Team For More Information.

Category

PARF Car, Hybrid Cars

Status

Available


Resourc

Compare

https://www.sgcarmart.com/used_cars/info.php?ID=845521&DL=3518



Price Chart



Click on the point to view the vehicle

Shortlist

Compare

Report Error

More Action

Seller Information

Company

Prime Car Tr

1/3

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	339K
Vehicle Details	
Vehicle No.:	SLM8982C
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5 HYBRID AT ABS D
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	LEB5926851
Chassis No.:	RU31226845
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$22,034.00
Original Registration Date:	17 Apr 2017
First Registration Date:	17 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00 2500
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Apr 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	16 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,405.00
COE Rebate Amount:	\$40,679.00
Total Rebate Amount:	\$44,429.00

The information contained herein is correct as at 25 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/10/2019 20:03
Date Of Accident	19/10/2019 16:30
Exact Location Of Accident	PIE (CHANGI) BESIDE KIM KEAT LINK EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM8982C
Insured/Policyholder	
Name Of Registered Owner	JIN & WEI ENTERPRISES
Co Reg No	52998339K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5 HYBRID AT ABS D
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999994251
Cover Note Number	

Driver

Name of Driver	CHUA HOCK CHUAN
NRIC No	S2586812I
Date Of Birth	06/07/1962
Occupation	OUTDOOR
Date Of Driving Pass	05/10/1982
Driving Experience	37 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81217815
Fax Number	
Contact Number	OFFICE-81217815
EMail Address	NOEMAIL

Address	BLK 815 TAMPINES AVENUE 4 #05-241
Postcode	520815
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20191019/7016.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDD86J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJU7850M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SKS2500E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

CHUA HOCK CHUAN

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SLM8982C

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- to comply with requirements under any regulations, laws or court orders.

JIN & WEI ENTERPRISES
Co. Reg. No: S2998339K
210 Turf Club Road, Lot No. (03/04/06/07)
CARMART @ The Grand Stand S287995
Tel: +65 6466 1009 Fax: +65 6466 0109

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NINC/FIN No.:

Scanned by CamScanner

Accident Sketch Plan

SKETCH PLAN



Vehicle A' SLM8982C
 'B' SDD 86J-
 'C' SJU 7850M
 'D' SKS 2500E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle A' was travelling along the stated venue. As I was travelling along lane 1, front vehicle came to a stop, and I stopped as well. About 2 to 3 seconds later, I felt an impact on the rear, causing my vehicle to propel forward and hit onto the front car. I then realised as I was caught in a chain collision of 4 cars.

DECLARATION

JIN & WEI ENTERPRISES

Co. Reg. No: S2968336K
 210 Turt Club Road, Lot No. (03/04/06/07)
 CARMART @ The Grand Stand S287995
 Tel: +65 8466 1009 Fax: +65 8466 0109

Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Scanned by CamScanner

Police Report



**SINGAPORE
POLICE FORCE**



T/20191019/7016

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20191019/7016

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/10/2019 19:37		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: CHUA HOCK CHUAN			Address: APT BLK 815 TAMPINES AVENUE 4 #05-241 SINGAPORE 520815		
ID Type / ID No.: NRIC NO / S2586812I			Contact No.: Home/Office: Mobile: 81217815		
Nationality: SINGAPORE CITIZEN			Email: elin.cqw@gmail.com		
Sex: Male	Age: 57	Date of Birth: 06/07/1962	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation:			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Government Property	Drink Drive: No	Date/Time of Accident: 19/10/2019 16:30	Type of Location: PIE CHANGI OUTSIDE KIM KEAT EXIT
Location: PAN ISLAND EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 90 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Chain collision			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SDD86J	Car	MERCEDES BENZ				0
SJU7850M	Car	MITSUBISHI	lancer			0
SKS2500E	Car	TOYOTA	harrier			0
SLM8982C	Car					0

Police Report



**SINGAPORE
POLICE FORCE**



T/20191019/7016

2 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191019/7016

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHUA HOCK CHUAN	ID No.	S25868121
Related Vehicle	SLM8982C (Car)	Contact No.	81217815
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	19/10/2019	Date Discharge	19/10/2019
No. of Days granted Medical Leave	05	Degree of Injury	Serious
Passenger			
Name	OLIVER	ID No.	NIL
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the stated date and time, I was travelling along PIE towards CHANGI, car plate bearing SLM8982C. As I was travelling on lane one slightly after Kim Keat Exit. My Front vehicle stopped, i Stopped. Few seconds later i felt and impact from my rear. Causing me to propelled forward colliding into the front vehicle. I then realized that i was caught in a Chain collision of 4 cars.

I was the 2nd Vehicle involved in the chain collision.

First vehicle - SKS2500E
second vehicle - SLM8982C
Third vehicle - SDD86J
Fourth vehicle - SJU7850M

After the accident i seek medical attention at Mount Alvernia Hospital. Was given 5 days of Medical Certificate.

Police Report



**SINGAPORE
POLICE FORCE**



T/20191019/7016

3 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20191019/7016

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
SHARIFAH NOR FARIZAN BINTE SYED MOHD
SAID
Contact No.: 65476172

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
19/10/2019 19:37

Classification Of Case:



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

SMO

Not Authorized

25 October 2019

2/5 #19,000/
24/10/19

REG NO.: SLM 8982 C
MAKE/MODEL: HONDA VEZEL

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

20 day Take photo After repair

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Front bonnet 820	\$ Buc 1,151.70
2	Front bonnet hinges	\$ Buc 143.40
1	Front bonnet lock	\$ Buc 145.00
1	Front bonnet rubber	\$ Buc 78.30
2	Front headlamps 1759.10 x 2 = 3518.20	\$ Cne 3,569.00
2	Front headlamp lower brackets	\$ 11 150.60
1	Front grille	\$ Cne 285.00
1	Front grille top outer garnish	\$ Cne 195.30
1	Front grille logo 38.80	\$ Buc 45.70
1	Front grille chrome moulding	\$ 11 285.00 X
1	Front bumper 801.70	\$ 7.5 1,085.40
2	Front bumper fog lamp covers 45.20	\$ 0/5 Sw 90.40 1PC
1	Front bumper lower grille	\$ 11 185.00 X
1	Front bumper reinforcement 321.00	\$ 7.5 321.40
2	Front bumper side retainers 60.30	\$ 0/5 Buc 120.60 1PC
1	Front bumper tow hook cover 15.00	\$ 11 48.00
1	Front bumper undercover	\$ 11 225.00 X
2	Front fenders 580.40	W/SR \$ 0/5 Buc 160.80 1PC
2	Front fender "HYBRID" emblem 65.00	W/S \$ Buc 130.00 1PC
2	Front fender inner shields	\$ 11 311.00 X
2	Front fender wheel arch garnishes 295.00	\$ 0/5 Sw 976.60 1PC
1	Front support panel	\$ Buc 576.00
1	Horn	\$ 11 80.00 X
1	Air con condenser	Buc/S \$ Buc 748.00
1	Radiator	Buc/S \$ Buc 1,150.00
1	Radiator fan blade	\$ Buc 117.00
1	Radiator fan cowling	\$ Cne 105.00
1	Radiator fan motor	\$ Sw 298.00
2	Radiator side garnishes 60.00	\$ 0/5 Sw 131.40 1PC
1	Front door -R/H	\$ 11 1,085.70 X
1	Front door rubber - R/H	\$ 11 122.70 X
2	Front door hinges	\$ 11 179.40 X
1	Rear door -R/H	\$ 11 1,085.50 X
1	Rear door rubber	\$ 11 130.80 X
1	Rear windscreen moulding	\$ Buc 121.80
1	Rear tailgate 953.00	\$ Buc 1,287.60
2	Rear tailgate dampers	\$ 11 331.60 X
1	Rear tailgate inner trim board	\$ De/Cne 225.00
1	Rear tailgate inner pull pocket	\$ 11 32.00 X
2	Rear tailgate lamps	Scr/S \$ Cne 570.00
		\$ 19,080.70

12331.40

LIST ITEMS

1	Rear tailgate lock	198.50
1	Rear tailgate lock catch	
1	Rear tailgate logo	
1	Rear tailgate rubber	188.20
1	Rear tailgate "VEZEL" emblem	
1	Rear tailgate "HYBRID" emblem	
2	Rear tailgate number plate lamps	
1	Rear tailgate number plate garnish	
2	Rear taillamps	485.20 x2 = 970.40
2	Rear taillamp panels	255.00
1	Rear end panel	514.00
1	Rear end panel inner garnish	
1	Rear keyless sensor (1 set)	
1	Rear bumper	762.70
2	Rear bumper - side	225.30
2	Rear bumper brackets side holder	
1	Rear bumper lower COVER	
2	Rear bumper reflectors	151.90
2	Rear bumper side retainers	50.90
1	Rear floor board top tray	
1	Rear floor panel	1120.00
1	Rear exhaust silencer	545.50
1	Rear exhaust heat shield	
1	Rear fender -R/H	885.10
1	Rear fender air gate	
1	Rear fender inner shield o/s	
2	Rear fender inner trim boards	265.00
1	Rear fender wheel arch garnish	184.20

intake manifold

front support panel top garnish

aircon fan assy

Bonnet insulator

cra

twi

cra/gm

7orn

1255.00 Less 20%

221.30

425.50

189.50

\$	twi	269.50	/
\$	17	55.00	X
\$	nu	40.30	/
\$	twi	227.00	/
\$	nu	56.20	/
\$	nu	62.50	/
\$	17	97.00	X
\$	cm	185.50	/
\$	cra	1,390.00	/
\$	o/s sh	510.00	IPC
\$	body	585.80	/
\$	dis	160.50	/
\$	17	189.50	X
\$	dis	950.60	/
\$	o/s dis	450.60	IPC
\$	17	97.00	X
\$	dis	325.00	/
\$	o/s cra	303.80	IPC
\$	o/s sh	101.80	IPC
\$	cra	187.60	/
\$	cra/gm / sh	1,145.70	/
\$	sh / twi	840.30	/
\$	sh	949.00	/
\$	body / sh	1,500.70	/
\$	17	48.00	X
\$	dis	149.80	/
\$	o/s dis	530.00	IPC
\$	17	300.70	/
\$		29,890.10	
\$		5,978.02	
\$		23,912.08	

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	
1	Front bumper lower spoiler	
1	Front number plate with holder	
2	Front fender inner shield clips (2 set)	
1	Rear windscreen sealant	
1	Rear bumper clip (1 set)	
1	Rear reverse sensor (1 set)	
1	Rear reverse camera	

\$	nu	45.00	30
\$	re	750.00	400
\$	cra	50.00	40
\$	17	100.00	X
\$	re	80.00	40
\$	re	45.00	30
\$	sh / sh	350.00	200
\$	sh / sh	480.00	300
\$		1,900.00	

1040

P-22055.80
202
1764464

S/N	LABOUR CHARGES		
1	To check wiring and reset headlamps focusing.	\$	80.00
2	To remove, refit, replaced damaged lamps and check up rear wiring.	\$	80.00
3	To remove and refit inner garnishes, inner trim to assist repair.	\$	150.00
4	To remove and refit rear reverse sensor and camera.	\$	150.00
5	To transfer rear tailgate mechanism and wiring assembly.	\$	120.00
6	To remove, replace air-con condenser, refill gas and conduct leakage test.	\$	180.00
7	To remove and refit rear windscreen glass.	\$	180.00
8	To remove, refit door fittings and replace damaged parts, transfer all fittings to new door.	\$	300.00
9	To apply undercoating.	\$	200.00
10	Panel beating.	\$	3,000.00
11	To re-spray painting on the affected areas.	\$	2,800.00
		\$	7,240.00

5090

GRAND TOTAL :

\$ 33,052.08

34805.12

P- 1764464
S.N- 1040.00
L- 5090.00
23774.64
202
19019

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No ill modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19018754/UQF3N2

Date: 19/11/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D19MTPV01000915
Claimant Vehicle No :	SLM8982C	Insured Vehicle No :	SDD86J
Date of Loss:	19/10/2019	Nature of Claim:	TP
		Claim No:	CMTD1904933

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM8982C	Engine No:	LEB5926851
Make & Model:	HONDA VEZEL, 1.5 HYBRID (A)	Chassis No:	RU31226845
Reg. Date:	17/04/2017 (Man. Year: 2016)	Odometer:	209173 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	MAXIMUM 6 mm	Rear Left Side:	MAXIMUM 6 mm
Front Right Side:	MAXIMUM 6 mm	Rear Right Side:	MAXIMUM 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	27,565.12	18,684.64	8,880.48	32.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,240.00	5,090.00	2,150.00	29.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	34,805.12	23,774.64	11,030.48	31.69
Approved Total (Overridden) (\$\$)		19,000.00		
Nett Amount (\$\$)	34,805.12	19,000.00	15,805.12	45.41

INSPECTION

Date of Assignment:	23/10/2019	
Date Inspected:	24/10/2019 Inspected At:	BLK 15 KAKI BUKIT BROAD 4 , BARTLEY BIZ #01-53 REPAIRER: ZOOM AUTOWERKS PTE LTD
Estimated Period of Repair:	20.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM8982C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	1,151.70 FL	*820.00 FL
2	2		*FRONT BONNET HINGES	Bent	143.40 FL	*143.40 FL
3	1		*FRONT BONNET LOCK	Twisted	145.00 FL	*145.00 FL
4	1		*FRONT BONNET RUBBER	Necessary	78.30 FL	*78.30 FL
5	2		*FRONT HEADLAMPS	Cracked	3,569.00 FL	*3,518.20 FL
6	2		*FRONT HEADLAMP LOWER BRACKETS	Not Necessary	150.60 FL	*- FL
7	1		*FRONT GRILLE	Cracked	285.00 FL	*285.00 FL
8	1		*FRONT GRILLE TOP OUTER GARNISH	Cracked	195.30 FL	*195.30 FL
9	1		*FRONT GRILLE LOGO	Necessary	45.70 FL	*38.80 FL
10	1		*FRONT GRILLE CHROME MOULDING	Not Necessary	285.00 FL	*- FL
11	1		*FRONT BUMPER	Distorted	1,085.40 FL	*801.70 FL
12	1		*FRONT BUMPER FOG LAMP COVERS	O/s Twisted	90.40 FL	*45.20 FL
13	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	185.00 FL	*- FL
14	1		*FRONT BUMPER REINFORCEMENT	Distorted	321.40 FL	*321.00 FL
15	1		*FRONT BUMPER SIDE RETAINERS	O/s Bent	120.60 FL	*60.30 FL
16	1		*FRONT BUMPER TOW HOOK COVER	Missing	48.00 FL	*15.00 FL
17	1		*FRONT BUMPER UNDERCOVER	Not Necessary	225.00 FL	*- FL
18	1		*FRONT FENDERS	O/s Buckled/N/s Repair	1,160.80 FL	*580.40 FL
19	1		*FRONT FENDER HYBRID EMBLEM	N/s Necessary	130.00 FL	*65.00 FL
20	2		*FRONT FENDER INNER SHIELDS	Not Necessary	311.00 FL	*- FL
21	1		*FRONT FENDER WHEEL ARCH GARNISHES	O/s Torn	976.60 FL	*295.00 FL
22	1		*FRONT SUPPORT PANEL	Bent	576.00 FL	*576.00 FL
23	1		*HORN	Not Necessary	80.00 FL	*- FL
24	1		*AIR CON CONDENSER	Bent/Punctured	748.00 FL	*748.00 FL
25	1		*RADIATOR	Bent/Punctured	1,150.00 FL	*1,150.00 FL
26	1		*RADIATOR FAN BLADE	Bent	117.00 FL	*117.00 FL
27	1		*RADIATOR FAN COWLING	Cracked	105.00 FL	*105.00 FL
28	1		*RADIATOR FAN MOTOR	Jammed	298.00 FL	*298.00 FL
29	1		*RADIATOR SIDE GARNISHES	O/s Torn	131.40 FL	*60.00 FL
30	1		*FRONT DOOR-R/H	Repair	1,085.70 FL	*- FL
31	1		*FRONT DOOR RUBBER-R/H	Not Necessary	122.70 FL	*- FL
32	2		*FRONT DOOR HINGES	Repair	179.40 FL	*- FL
33	1		*REAR DOOR-R/H	Repair	1,085.50 FL	*- FL
34	1		*REAR DOOR RUBBER	Not Necessary	130.80 FL	*- FL
35	1		*REAR WINDSCREEN MOULDING	Necessary	121.80 FL	*121.80 FL
36	1		*REAR TAILGATE	Badly Dented	1,287.60 FL	*953.00 FL
37	2		*REAR TAILGATE DAMPERS	Not Necessary	331.60 FL	*- FL
38	1		*REAR TAILGATE INNER TRIM BOARD	Deformed/Cracked	225.00 FL	*225.00 FL
39	1		*REAR TAILGATE INNER PULL POCKET	Not Necessary	32.00 FL	*- FL
40	2		*REAR TAILGATE LAMPS	Scratched/Cracked	570.00 FL	*570.00 FL
41	1		*REAR TAILGATE LOCK	Twisted	269.50 FL	*198.50 FL
42	1		*REAR TAILGATE LOCK CATCH	Not Necessary	55.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR TAILGATE LOGO	Necessary	40.30 FL	*40.30 FL
44	1		*REAR TAILGATE RUBBER	Twisted	227.00 FL	*188.20 FL
45	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	56.20 FL	*56.20 FL
46	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	62.50 FL	*62.50 FL
47	2		*REAR TAILGATE NUMBER PLATE LAMPS	Not Necessary	97.00 FL	*- FL
48	1		*REAR TAILGATE NUMBER PLATE GARNISH	Cracked	185.50 FL	*185.50 FL
49	2		*REAR TAILLAMPS	Cracked	1,390.00 FL	*970.40 FL
50	1		*REAR TAILLAMP PANELS	O/s Bent	510.00 FL	*255.00 FL
51	1		*REAR END PANEL	Badly Dented	585.80 FL	*514.00 FL
52	1		*REAR END PANEL INNER GARNISH	Distorted	160.50 FL	*160.50 FL
53	1		*SET REAR KEYLESS SENSOR	Not Necessary	189.50 FL	*- FL
54	1		*REAR BUMPER	Distorted	950.60 FL	*762.70 FL
55	1		*REAR BUMPER-SIDE	O/s Distorted	450.60 FL	*225.30 FL
56	2		*REAR BUMPER SIDE HOLDER	Not Necessary	97.00 FL	*- FL
57	1		*REAR BUMPER LOWER COVER	Distorted	325.00 FL	*325.00 FL
58	1		*REAR BUMPER REFLECTORS	O/s Cracked	303.80 FL	*151.90 FL
59	1		*REAR BUMPER SIDE RETAINERS	O/s Bent	101.80 FL	*50.90 FL
60	1		*REAR FLOOR BOARD TOP TRAY	Cracked	187.60 FL	*187.60 FL
61	1		*REAR FLOOR PANEL	Crumpled/Buckled	1,145.70 FL	*1,120.00 FL
62	1		*REAR EXHAUST SILENCER	Bent/Twisted	840.30 FL	*545.50 FL
63	1		*REAR EXHAUST HEAT SHIELD	Bent	149.00 FL	*149.00 FL
64	1		*REAR FENDER-R/H	Badly Dented/Buckled	1,500.70 FL	*885.10 FL
65	1		*REAR FENDER AIR GATE	Not Necessary	48.00 FL	*- FL
66	1		*REAR FENDER INNER SHIELD O/S	Distorted	149.80 FL	*149.80 FL
67	1		*REAR FENDER INNER TRIM BOARDS	O/s Distorted	530.00 FL	*265.00 FL
68	1		*REAR FENDER WHEEL ARCH GARNISH	Torn	300.70 FL	*184.20 FL
69	1		*INTAKE MANIFOLD	Cracked	1,255.00 FL	*1,255.00 FL
70	1		*FRONT SUPPORT PANEL TOP GARNISH	Twisted	221.30 FL	*221.30 FL
71	1		*AIRCON FAN ASSY	Cracked/Jammed	425.50 FL	*425.50 FL
72	1		*BONNET INSULATOR	Torn	189.50 FL	*189.50 FL
73	1		*SET FRONT BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
74	1		*FRONT BUMPER LOWER SPOILER	Deformed	750.00 FS	*400.00 FS
75	1		*FRONT NUMBER PLATE WITH HOLDER	Cracked	50.00 FS	*40.00 FS
76	2		*SET FRONT FENDER INNER SHIELD CLIPS	Not Necessary	100.00 FS	*- FS
77	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
78	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
79	1		*SET REAR REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS
80	1		*REAR REVERSE CAMERA	Shorted	480.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **33,981.40** **23,095.80**
 - List Item Discount on L Items 20.00/20.00% (S\$) 6,416.28 4,411.16

Total Parts (S\$) 27,565.12 18,684.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING }	New	80.00	30.00
2	TO REMOVE,REFIT,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING }	New	80.00	0.00
3	TO REMOVE AND REFIT INNER GARNISHES,INNER TRIM TO ASSIST REPAIR	New	150.00	80.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA	New	150.00	50.00
5	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
6	TO REMOVE,REPLACE AIR-CON CONDENSER,REFILL GAS AND CONDUCT LEAKAGE TEST	New	180.00	100.00
7	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
8	TO REMOVE,REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS,TRANSFER ALL FITTINGS TO NEW DOOR	New	300.00	0.00
9	TO APPLY UNDERCOATING	New	200.00	150.00
10	PANEL BEATING	New	3,000.00	2,500.00
11	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	2,800.00	2,000.00
Gross Labour Cost (S\$)			7,240.00	5,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >