

KIANG MOTOR

Block 25 Kaki Bukit Road 4 #08-26 Synergy@KB Singapore 417800
HP: 92712214 Fax: (65) 69664526

23RD Oct 2019

YEO YONG WAH
25 KAKI BUKIT ROAD4
08-26 SYNERGY @KB
Singapore 417800

Accident date: 21st OCT 2019
Estimated repair cost for vehicle no: SMM4138M MAZDA 6 S 2.0A '2019

S/n	Qty	Items	U/price	Amount
				\$1,150.30
1	1	Front bonnet		\$165.20
2	1	Front bonnet lock		\$221.30
3	1	Front bonnet centre moulding		\$985.30
4	1	Front bumper	\$113.60	\$227.20
5	2	Front bumper side bracket	\$6.50	\$52.00
6	8	Front bumper clips		\$85.30
7	1	Front bumper LH lower side garnish		\$0.00
8	1	Front bumper fog lamp cover		\$412.50
9	1	Front bumper reinforcement		\$50.00
10	1	Front bumper number plate		\$58.90
11	1	Front bumper number plate garnish		\$255.30
12	1	Front bumper center lower garnish		\$221.30
13	1	Front bumper lower garnish		\$258.30
14	1	front bumper lower grille		\$752.30
15	1	Front support panel		\$920.30
16	1	front head lamp-LH		\$49.70
17	1	front head lamp lower bracket		\$425.30
18	1	Front grille		\$50.00
19	1	front grille clips		\$85.00
20	1	Front grille emble logo		\$1,213.20
21	1	Rear Boot Lid	\$212.30	\$424.60
22	2	Rear Boot Lid Hinges	\$259.50	\$519.00
23	2	Rear Boot Lid shock absorber		\$80.00
24	1	Rear boot lid emble logo	\$385.20	\$770.40
25	2	Rear Boot Lid side reflector		\$35.00
26	1	Rear boot lid Mazda logo		\$25.00
27	1	Rear boot lid 6 logo		\$165.30
28	1	Rear boot lid inner rubber		\$223.20
29	1	Rear Boot Lid Inner Lock	\$4.20	\$42.00
30	10	Rear Boot Lid Inner Trim board clips		\$385.60
31	1	Rear Boot Lid Inner Trim board	\$952.30	\$1,904.60
32	2	Rear tail lamp	\$149.50	\$299.00
33	2	Rear tail lamp panel	\$5.00	\$20.00
34	4	Rear tail lamp clips		\$425.10
35	1	Rear end panel		\$223.35
36	1	Rear End Panel Top Garnish		\$1,625.30
37	1	Rear fender RH		\$285.30
38	1	Rear fender inner trim board-RH	\$5.00	\$50.00
39	10	Rear fender inner trim board clips		\$1,150.30
40	1	Rear Bumper	\$95.20	\$190.40
41	2	Rear Bumper Side Bracket	\$58.80	\$117.60
42	2	Rear Bumper side reflector		\$350.00
43	1	Rear Bumper reverse sensor		\$50.00
44	1	Rear Bumper number plate		\$245.90
45	1	Rear Bumper number plate lamp		

46	8	Rear bumper clips	\$4.50	\$36.00
47	2	Rear Bumper mud shield	\$68.50	\$137.00
48	4	Rear Bumper mud shield clips	\$4.50	\$18.00
49	1	Rear Bumper reinforcement		\$423.10
50	2	Rear bumper clips	\$55.30	\$110.60
51	1	Rear Exhaust		\$985.30
52	2	Rear Exhaust chome pipe	\$220.00	\$440.00
53	1	Rear windscreen seal		\$112.10
54	1	Rear spare tire panel		\$1,050.30
55	1	Rear spare tire panel sealant		\$200.00
56	1	Rear spare tire panel top cover		\$420.00

Subtotal :- \$21,178.05

<u>Labour charges</u>	\$150.00
To Remove & refix cushion	
	\$280.00
To Remove & refix rear exhaust	
	\$150.00
To Remove & refix rear windscreen	
	\$50.00
Gum	
	\$100.00
To Remove & refix reverse Sensor	
	\$120.00
Tuff kote	
	\$80.00
To Check Wiring System	
	\$100.00
Towing charges	
	\$1,400.00
Panel beating	
	\$1,400.00
Spray painting	

Subtotal :- \$3,830.00

Total:- \$25,008.05

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	565H

Vehicle Details

Vehicle No.:	SMM4138M
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 Oct 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 SEDAN 2.0 AT EXECUTIVE 2WD
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	PE21258430
Chassis No.:	JM6GL1072K0312225
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$21,935.00
Original Registration Date:	27 Jun 2019
First Registration Date:	27 Jun 2019
Transfer Count:	0
Actual ARF Paid:	\$22,709.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2029
PARF Rebate Amount:	\$17,031.00

Intended COE Rebate Details

COE Expiry Date:	26 Jun 2029
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$39,400.00
COE Rebate Amount:	\$28,724.00
Total Rebate Amount:	\$45,755.00

The information contained herein is correct as at 23 Oct 2019

OK