

ASS. REC. BY:

REF:

CS/AGI1901879/Avd372

Special Instruction:

Surayer: Adrian

ASSIGNMENT (Office)

From (Person): Ivy Ratilim

of

AGI

Date/Time: 23/10/2019 @ 9.41am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMM 4138M

Insured:

SLF 7593K

at Workshop m/s

Kiang Motor

Tel:

92712214

of

25 kaki Bukit Rd 4 # 08-26 Synergy

Policy No:

Claim No:

C10004374 / JM

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10am @ 23/10/2019

Person Contacted:

Chms

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

Schedule 1

SMM 4138M - X

SLF 7593K - X

14/1/2020

Adrian confirmed LS \$7000 (Ref 18.008-05, 72/0)

ASS. REC. BY:

REF: AGI

## ASSIGNMENT

From: \_\_\_\_\_ Date: 23/10/2019

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SMM4138M

at Workshop m/s: Kiang Motor

of B1K 25 kaki Bukit Road 4 #08-26

Insured: synergy

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: Smm4138m - Yr Regn: 2019 June

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 6 c.c. 1998

Colour: Bronze A/C: Insured / Std / NI / NA

Sp. Reading: 7859 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM66L1072K0312225

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17.

R: 225/55 R17.

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A. \_\_\_\_\_

D.O.I. 23/10/19.

Survey held at: Kiang motor.

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Budget Direct.

RECEIVED 15 JAN 2020

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 15/1 typist

Report Format:

TP

Lump Sum / T.E.J.:

Took up

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + PS: \$

Parking:

Others:

TOTAL

450

## Nivitha (LKK Auto)

---

**From:** Ivy Ratilla <ivy.r@budgetdirect.com.sg>  
**Sent:** Wednesday, 23 October 2019 9:41 AM  
**To:** Admin-D (LKKAuto)  
**Cc:** SUR; Julie Mangubat  
**Subject:** TPPD Survey: Claim ref:C10004374/JM || OI- SLF7593K (Red) TP- SMM4138M || Est:0.00 || Kiang Motor  
**Attachments:** PHOTO-2019-10-21-22-48-53.jpg; PHOTO-2019-10-21-22-48-52.jpg; PHOTO-2019-10-21-22-48-53.jpg

Hi Team,

Good morning.

We would like to arrange TP Survey for SMM4138M.

Workshop information:

Kiang Motor

Blk 25 Kaki Bukit road 4

# 08-26 Synergy

Singapore

Hp:92712214

Please confirm. Thank you.

Regards,

**Ivy Ratilla**

**Executive, Claims Admin**

T +65 6540 2185

F +65 6725 0853

E [ivy.r@budgetdirect.com.sg](mailto:ivy.r@budgetdirect.com.sg)



**Customer Care** +65 6221 2111

**Claims** +65 6221 2199

**Claims (Int.)** +65 6540 2199

190 Clemenceau Avenue, #03-01

Singapore Shopping Centre

Singapore

239924

[budgetdirect.com.sg](http://budgetdirect.com.sg)

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

---

**From:** chan pick yuen <chris\_chanbebe@hotmail.com>  
**Sent:** Tuesday, 22 October 2019 6:43 PM  
**To:** Ivy Ratilla <ivy.r@budgetdirect.com.sg>; Claims <claims@budgetdirect.com.sg>  
**Cc:** Julie Mangubat <julie.m@budgetdirect.com.sg>  
**Subject:** Re: SMM4138M & SLF7593K doa 21/10/19 || C10004374

Dear Sir / Mdm ,

LKK Auto Consultant Pte Ltd.  
please let us have your confirmation soon . Thanks

Best Regards  
Chris Chan

---

**From:** chan pick yuen <chris\_chanbebe@hotmail.com>  
**Sent:** Tuesday, 22 October 2019 1:21 PM  
**To:** Claims <claims@budgetdirect.com.sg>  
**Subject:** SMM4138M & SLF7593K doa 21/10/19

Dear Sir / Mdm ,

Our refer : SLF7593K ( Auto & General insurance )

Enclosed is the scene photos .  
Please let us have your 10 name list of surveyor to survey our clients vehicle: SMM4138M . Thank

Best Regards  
Chris Chan  
Kiang Motor  
Blk 25 Kaki Bukit road 4  
# 08-26 Synergy  
Singapore  
Hp:927122147

Get Outlook for iOS

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

[Back to CarMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
 Owner ID: S65H

#### Vehicle Details

Vehicle No.: SMM4138M  
 Vehicle to be Exported: Yes  
 Intended Deregistration Date: 23 Oct 2019  
 Vehicle Make: MAZDA  
 Vehicle Model: MAZDA6 SEDAN 2.0 AT EXECUTIVE 2WD  
 Primary Colour: Grey  
 Manufacturing Year: 2018  
 Engine No.: PE21258430  
 Chassis No.: JM6GL1072K0312225  
 Maximum Power Output: 121.0 kW (162 bhp)  
 Open Market Value: \$21,935.00  
 Original Registration Date: 27 Jun 2019  
 First Registration Date: 27 Jun 2019  
 Transfer Count: 0  
 Actual ARF Paid: \$22,709.00

#### Intended PARF Rebate Details

PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 26 Jun 2029  
 PARF Rebate Amount: \$17,031.00

#### Intended COE Rebate Details

COE Expiry Date: 26 Jun 2029  
 COE Category: E - Open - all except motorcycle  
 COE Period(Years): 10  
 QP Paid: \$39,400.00  
 COE Rebate Amount: \$28,724.00  
**Total Rebate Amount: \$45,755.00**

The information contained herein is correct as at 23 Oct 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	22/10/2019 15:54
Date Of Accident	21/10/2019 11:50
Exact Location Of Accident	EXITING TO TAMPINES EXPRESSWAY TOWARDS PUNGGOL
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMM4138M
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YEO YONG WAH
NRIC No	S1602565H
Email Address	YYW88@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-94556897
Alternative Phone No	OFFICE-94556897

### Vehicle Particulars

Manufacturer	MAZDA
Model	-
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900114328
Cover Note Number	

### Driver

Name of Driver	YEO YONG WAH
NRIC No	S1602565H
Date Of Birth	01/04/1963
Occupation	INDOOR
Date Of Driving Pass	14/06/1986
Driving Experience	33 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94556897
Fax Number	
Contact Number	OFFICE-94556897
EMail Address	YYW88@YAHOO.COM.SG

Address	BLK 893 TAMPINES AVE 8 #03-46
Postcode	520893
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES N.P.C
Police Station Address	ROAD: TAMPINES N.P.C , POSTCODE: 529682 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE SEE POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF7593K
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HO BOON WEI
NRIC/Passport Number	S8135345Z
Contact Number	92373100
Address	NA
	NA
Postcode	NA
Insurance Company Name	



Nature Of Damage NA

No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SGC9163E  
Vehicle Make/Model/Colour TOYOTA  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver FAN FU LEI  
NRIC/Passport Number S2660473G  
Contact Number 90180409  
Address NA  
Postcode NA  
Insurance Company Name  
Nature Of Damage NA  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number GR7655L  
Vehicle Make/Model/Colour TOYOTA HIACE  
Details Of Properties  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver UNKNOWN  
NRIC/Passport Number  
Contact Number 96368272  
Address NA  
Postcode NA  
Insurance Company Name  
Nature Of Damage NA  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SMC8666G  
Vehicle Make/Model/Colour BMW  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver JERRY  
NRIC/Passport Number  
Contact Number 90266983  
Address NA  
Postcode NA  
Insurance Company Name  
Nature Of Damage NA  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name YEO YONG WAH  
Approximate Age  
Injuries Sustain  
Injured person in which vehicle? SMM4138M  
Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance?

NO

Address

BLK 893 TAMPINES AVE 8 #03-46

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature  
Date & Time: 22/10/2019  
3.55pm

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 22/10/2019  
3.55pm

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Individual Statement Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please see police report -

Reporting Only  
Own Damage Claim  
☒ Third Party Claim

@ Chiang Motu

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 22/10/2019 3:55pm

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 22/10/2019 7:55pm

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No:



**SINGAPORE  
POLICE FORCE**



T/20191021/2170

1 of 3

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

Report No. T/20191021/2170

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 21/10/2019 19:21		Vide Report No.:		Station Diary No.: 116	
<b>Informant's Particulars</b>					
Name of Informant: YEO YONG WAH			Address: APT BLK 893 TAMPINES AVENUE 8 #03-46 SINGAPORE 520893		
ID Type / ID No.: NRIC NO / S1602565H			Contact No.: Home/Office: Mobile: 94556897		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 56	Date of Birth: 01/04/1963	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: PROJECT DIRECTOR			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 21/10/2019 11:50	Type of Location: Straight Road
Location: Along Road 1 SELETAR EXPRESSWAY  EXITING TO TAMPINES EXPRESSWAY, TOWARDS PUNGGOL				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GR7655L	Van	TOYOTA	HIACE DIESEL	Green	Seriously Damaged	0
SGC9163E	Car	TOYOTA	WISH 1.8 A	Silver	Slightly Damaged	1
SLF7593K	Car	HONDA	STREAM 1.8X A	Red	Seriously Damaged	0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE  
POLICE FORCE**



T/20191021/2170

2 of 3

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

Report No. T/20191021/2170

## CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SMC8666G	Car	BMW	X3 XDRIVE28i A/T 4WD S/R LED NAV HUD	White	Seriously Damaged	2
SMM4138M	Car	MAZDA	MAZDA6 SEDAN 2.0 AT EXECUTIVE 2WD	Grey	Seriously Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMM4138M	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1900114328	27/06/2019	26/06/2021

**Brief Details.**

On the 21st of October 2019 at about 1150hrs, I was travelling from Seletar Expressway exiting to Tampines Expressway towards Punggol. I was driving car bearing plate number SMM4138M when the car in front of me (SGC9163E) suddenly stopped. I then applied emergency break about 2m behind the said vehicle however, the vehicle behind me (SLF7593K) could not stop in time and collided into my vehicle, causing a chain collision. The forth vehicle is a van bearing plate number GR7655L and the fifth vehicle is a car bearing plate number SMC8666G.

No one was injured at that point of time.

The first vehicle driver informed that there was a lorry in front of his car who had his tyre came off and the tyre was underneath the first vehicle hence he had to stop.

I have an in-car camera installed in my vehicle.

The first driver is namely Fan Fu Lei, S2660473G, hp no: 90180409. The third driver is namely Ho Boonwei, S8135345Z, hp no: 92373100. The forth driver can be contacted at 96368272. The fifth driver is namely Jerry, hp no: 90266983.

The traffic police was at scene to manage the accident.

Subsequently, I went to see the doctor due to neck pain/numbness down to the shoulder blade. I was given 5 days MC (1000044823) from 21/10/2019 to 25/10/2019.



**SINGAPORE  
POLICE FORCE**



T/20191021/2170

3 of 3

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

Report No. T/20191021/2170

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
G /  
Sgt 3 SITI NUR SYAFIAH BINTE AZMAN

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
21/10/2019 19:21

Officer In Charge Of Case:  
TP / GIT /  
SI THABAGESH JEYATHESH  
Contact No.: 65476232

Classification Of Case:

Authentication Stamp  
NP158

SIGNATURE:



**Name of Policyholder** : Yeo Yong Wah  
**Period of Insurance** : 27 Jun 2019 To 26 Jun 2021  
**Engine No.** : PE21258430  
**Chassis No.** : JM6GL1072K0312225

Vehicle No. : SMM4138M  
Policy No. : 1900114328  
Endorsement No. :  
Issued Date : 10 Jul 2019

Make/Model : MAZDA 6 2.0 SKYACTIV

Engine Capacity/Tonnage : 1,998.00 CC

Sum Insured : Market Value

First Year of Registration : 2019

Driver Restriction : NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive\*:

a) The Polyether

b) Any other person who is driving on the Policyholder's order is with halftje permission.  
This Policy will indemnify the Policyholder or any authorised driver only if halftje meets the specified age condition

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorized Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 188), Section 35 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

Section 1  
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2  
Property Damage - \$0

Wireframes: \$100

Named Driver and Excess (where applicable)

Yeo Yong Wah - \$600 (Own Damage)

## APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Trade Eumears Pte Ltd, Add: 27A Telokong Peranti, Singapore 600042 61310808

For other Approved Reporting Centres/AIG Authorised Repairs, please contact our 24-hour accident emergency helpline at +65 8338 8200. Alternatively, you may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: HONG LEONG FINANCE LTD

I/We hereby certify that this policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 185), Part IV of the Road Transport Act, 1967 (Malaysia), Road Transport (Amendment) Act 2018 and Motor Vehicles (Third Party Risks) Rules, 1969 (Malaysia).

0503570190

ARF (API) PTE LTD - MAZDA

7 MAXWELL ROAD #01-100 ANNEX B MND COMPLEX  
SINGAPORE 069111

Underwritten by AIG Asia Pacific Insurance Plc. Ltd.

**AIG Asia Pacific Insurance Pte. Ltd.**  
AUTHORISED REPRESENTATIVE

**德意志银行**



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



# KIANG MOTOR

Block 25 Kaki Bukit Road 4 #08-26 Synergy@KB Singapore 417800  
HP: 92712214 Fax: (65) 69664526

YEO YONG WAH  
25 KAKI BUKIT ROAD4  
# 08-26 SYNERGY @KB  
Singapore 417800

TP Budget Direct  
Veron.

23<sup>rd</sup> Oct 2019

Jm6641072K0312225

Accident date: 21<sup>st</sup> OCT 2019

Estimated repair cost for vehicle no: SMM4138M MAZDA 6 S 2.0A '2019

S/n	Qty	Items	U/price	Amount
1	1	Front bonnet		\$1,150.30 x
2	1	Front bonnet lock		\$165.20 x
3	1	Front bonnet centre moulding		\$221.30 x
4	1	Front bumper Deformed		\$985.30 x
5	2	Front bumper side bracket	\$113.60	\$227.20 x 92
6	8	Front bumper clips	\$6.50	\$52.00 30
7	1	Front bumper LH lower side garnish		\$85.30 x
8	1	Front bumper fog lamp cover		\$0.00 x
9	1	Front bumper reinforcement		\$412.50 x
10	1	Front bumper number plate		\$50.00 x
11	1	Front bumper number plate garnish		\$58.90 x
12	1	Front bumper center lower garnish		\$255.30 x
13	1	Front bumper lower garnish		\$221.30 x
14	1	front bumper lower grille		\$258.30 x
15	1	Front support panel		\$752.30 x
16	1	front head lamp-LH		\$920.30 x
17	1	front head lamp lower bracket		\$49.70 x
18	1	Front grille		\$425.30 x
19	1	front grille clips		\$50.00 20
20	1	Front grille emble logo		\$85.00 x
21	1	Rear Boot Lid		\$1,213.20 x
22	2	Rear Boot Lid Hinges	\$212.30	\$424.60 x
23	2	Rear Boot Lid shock absorber	\$259.50	\$519.00 x
24	1	Rear boot lid emble logo		\$80.00 x
25	2	Rear Boot Lid side reflector	\$385.20	\$770.40 x
26	1	Rear boot lid Mazda logo		\$35.00 x
27	1	Rear boot lid 6 logo		\$25.00 x
28	1	Rear boot lid inner rubber		\$165.30 x
29	1	Rear Boot Lid Inner Lock		\$223.20 x
30	10	Rear Boot Lid Inner Trim board clips	\$4.20	\$42.00 x
31	1	Rear Boot Lid Inner Trim board		\$385.60 x
32	2	Rear tail lamp	\$952.30	\$1,904.60 952.30
33	2	Rear tail lamp panel	\$149.50	\$299.00 x
34	4	Rear tail lamp clips	\$5.00	\$20.00 10
35	1	Rear end panel		\$425.10 x
36	1	Rear End Panel Top Garnish		\$223.35 x
37	1	Rear fender RH		\$1,625.30 x
38	1	Rear fender inner trim board-RH		\$285.30 x
39	10	Rear fender inner trim board clips	\$5.00	\$50.00 x
40	1	Rear Bumper		\$1,150.30 x
41	2	Rear Bumper Side Bracket	\$95.20	\$190.40 84
42	2	Rear Bumper side reflector	\$58.80	\$117.60 52
43	1	Rear Bumper reverse sensor		\$350.00 x
44	1	Rear Bumper number plate		\$50.00 x
45	1	Rear Bumper number plate lamp		\$245.90 x

46	8	Rear bumper clips	HP	\$4.50	\$36.00 ✓
47	2	Rear Bumper mud shield	HP	\$68.50	\$137.00 +
48	4	Rear Bumper mud shield clips	HP	\$4.50	\$18.00 +
49	1	Rear Bumper reinforcement	Sent		\$423.10 ✓
50	2	Rear bumper clips	Repaired	\$55.30	\$110.60 +
51	1	Rear Exhaust			\$985.30 +
52	2	Rear Exhaust chrome pipe		\$220.00	\$440.00 +
53	1	Rear windscreen seal	HP		\$112.10 +
54	1	Rear spare tire panel	HP		\$1,050.30 +
55	1	Rear spare tire panel sealant			\$200.00 +
56	1	Rear spare tire panel top cover			\$420.00 +

8011-55  
6409-24

Subtotal :- \$21,178.05

#### Labour charges

To Remove & refix cushion

\$150.00 80

To Remove & refix rear exhaust

\$280.00 +

To Remove & refix rear windscreen

\$150.00 ✓

Gum

\$50.00 (SN)

To Remove & refix reverse Sensor

\$100.00 60

Tuff kote

\$120.00 80

To Check Wiring System

\$80.00 30

Towing charges

2350

\$100.00 +

Panel beating

\$1,400.00 1100

Spray painting

\$1,400.00 1000

Subtotal :- \$3,830.00

Total :- \$25,008.05

total 375924

4/s 7k  
07 Days

7k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI19018779/Avd3n2		
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 16-01-2020		
		Code : AGI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLF 7593K	Veh. Inspected	SMM 4138M	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10004374/JM	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	23/10/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MAZDA 6	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JM6GL1072K0312225	Colour	BRONZE	
Odometer	7859	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm	
L/H Front Tyre	225/55 R17	BRIDGESTONE	6 mm	
R/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/55 R17	BRIDGESTONE	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	21/10/2019	Inspection Date	23/10/2019	
Survey held at	KIANG MOTOR BLK 25 KAKI BUKIT ROAD 4 #08-26 SYNERGY @ KB SINGAPORE 417800			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 4138M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BONNET	NOT NECESSARY	1,150.30	-
1	FRONT BONNET LOCK	NOT NECESSARY	165.20	-
1	FRONT BONNET CENTRE MOULDING	NOT NECESSARY	221.30	-
1	FRONT BUMPER	DEFORMED	985.30	985.30
2	FRONT BUMPER SIDE BRACKET @\$113.60	NECESSARY	227.20	92.00
8	FRONT BUMPER CLIPS @\$6.50	NECESSARY	52.00	30.00
1	FRONT BUMPER LH LOWER SIDE GARNISH	NOT NECESSARY	85.30	-
1	FRONT BUMPER FOG LAMP COVER (NPA)	NOT NECESSARY	-	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	412.50	-
1	FRONT BUMPER NUMBER PLATE	NOT NECESSARY	50.00	-
1	FRONT BUMPER NUMBER PLATE GARNISH	NOT NECESSARY	58.90	-
1	FRONT BUMPER CENTER LOWER GARNISH	NOT NECESSARY	255.30	-
1	FRONT BUMPER LOWER GARNISH	NOT NECESSARY	221.30	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	258.30	-
1	FRONT SUPPORT PANEL	NOT NECESSARY	752.30	-
1	FRONT HEAD LAMP-LH	CRACKED	920.30	920.30
1	FRONT HEAD LAMP LOWER BRACKET	NOT NECESSARY	49.70	-
1	FRONT GRILLE	CRACKED	425.30	425.30
1	FRONT GRILLE CLIPS	NECESSARY	50.00	20.00
1	FRONT GRILLE EMBLEM LOGO	NECESSARY	85.00	85.00
1	REAR BOOT LID	DENTED	1,213.20	1,213.20
2	REAR BOOT LID HINGES @\$212.30	NOT NECESSARY	424.60	-
2	REAR BOOT LID SHOCK ABSORBER @\$259.50	NOT NECESSARY	519.00	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	80.00	80.00
2	REAR BOOT LID SIDE REFLECTOR @\$385.20	NOT NECESSARY	770.40	-
1	REAR BOOT LID MAZDA LOGO	NECESSARY	35.00	35.00
1	REAR BOOT LID 6 LOGO	NECESSARY	25.00	25.00
1	REAR BOOT LID INNER RUBBER	CUT	165.30	165.30
1	REAR BOOT LID INNER LOCK	DAMAGED	223.20	223.20
10	REAR BOOT LID INNER TRIM BOARD CLIPS @\$4.20	NOT NECESSARY	42.00	-
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	385.60	-
2	REAR TAIL LAMP @\$952.30	O/S CRACKED	1,904.60	952.30
2	REAR TAIL LAMP PANEL @\$149.50	TO REPAIR SEE LABOUR	299.00	-

Report Ref No. CS/AGI19018779/Avd3n2





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	REAR TAIL LAMP CLIPS @\$5.00	NECESSARY	20.00	10.00
1	REAR END PANEL	DENTED	425.10	425.10
1	REAR END PANEL TOP GARNISH	DEFORMED	223.35	223.35
1	REAR FENDER RH	NOT NECESSARY	1,625.30	-
1	REAR FENDER INNER TRIM BOARD-RH	NOT NECESSARY	285.30	-
10	REAR FENDER INNER TRIM BOARD CLIPS @\$5.00	NOT NECESSARY	50.00	-
1	REAR BUMPER	DISTORTED	1,150.30	1,150.30
2	REAR BUMPER SIDE BRACKET @\$95.20	NECESSARY	190.40	84.00
2	REAR BUMPER SIDE REFLECTOR @\$58.80	O/S CRACKED	117.60	58.00
1	REAR BUMPER REVERSE SENSOR	DAMAGED	350.00	350.00
1	REAR BUMPER NUMBER PLATE	NOT NECESSARY	50.00	-
1	REAR BUMPER NUMBER PLATE LAMP	NOT NECESSARY	245.90	-
8	REAR BUMPER CLIPS @\$4.50	NECESSARY	36.00	36.00
2	REAR BUMPER MUD SHIELD @\$68.50	NOT NECESSARY	137.00	-
4	REAR BUMPER MUD SHIELD CLIPS @\$4.50	NOT NECESSARY	18.00	-
1	REAR BUMPER REINFORCEMENT	BENT	423.10	423.10
2	REAR BUMPER CLIPS @\$55.30	REPEATED	110.60	-
1	REAR EXHAUST	NOT NECESSARY	985.30	-
2	REAR EXHAUST CHROME PIPE @\$220.00	NOT NECESSARY	440.00	-
1	REAR WINDSCREEN SEAL	NOT NECESSARY	112.10	-
1	REAR SPARE TIRE PANEL	NOT NECESSARY	1,050.30	-
1	REAR SPARE TIRE PANEL SEALANT	NOT NECESSARY	200.00	-
1	REAR SPARE TIRE PANEL TOP COVER	NOT NECESSARY	420.00	-
	LESS 20% DISCOUNT		-	-1,602.35
			21,178.05	6,409.40
	<b>SPECIAL NETT ITEMS</b>			
1	GUM (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<b>LABOUR</b>			
	TO REMOVE & REFIX CUSHION.		150.00	80.00
	TO REMOVE & REFIX REAR EXHAUST.	NOT NECESSARY	280.00	-
	TO REMOVE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIX REVERSE SENSOR.		100.00	60.00
	TUFF KOTE.		120.00	80.00
	TO CHECK WIRING SYSTEM.		80.00	30.00

Report Ref No. CS/AGI19018779/Avd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING CHARGES.	NOT NECESSARY	100.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP PANEL.		1,400.00	1,100.00
	SPRAY PAINTING.		1,400.00	1,000.00
			3,780.00	2,350.00
<b>GRAND TOTAL</b>			<b>25,008.05</b>	<b>8,759.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>7,000.00</b>

Report Ref No. CS/AGI19018779/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.