## CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO: SHC 8564B (Supplementary)

MAKE

MODEL

: HYUNDAI i40

DATE: 1.11.2019

TEL: 6542 5119

FAX: 6542 6039

| Qty | Parts Description/ Labour                 | Type | Unit Price | Amount   |
|-----|---|------|------------|----------|
|     | Radiator Hose Upper Support Bracket Mokey |      |            | \$ 128.0 |
|     | Idle Pulley boken                         |      |            | \$ 189.5 |
|     | vio Ken                                   |      |            | 107.5    |
|     | OVER MEAN . V                             |      |            | 6 212 -  |
|     | SUB TOTAL                                 |      |            | \$ 317.5 |
|     | LESS 20%                                  |      |            | \$ 63.5  |
|     | DISCOUNTED TOTAL                          |      |            | \$ 254.0 |
|     |   |      |            |          |
|     | CILLIA                                    |      | 9          |          |
|     | 01/11/2019                                |      |            |          |
|     | 2   |      |            |          |
|     |   |      |            |          |
|     | orlingang  Z  y                           |      |            |          |
|     |   |      |            |          |
|     | 1 / 4 .                                   |      |            |          |
|     | of the thirds                             |      |            |          |
|     |   | L .  |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      | 9          |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     | 9   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            |          |
|     |   |      |            | 3        |
|     |   |      |            | 3.       |

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.