
Kindly advise if there is any evidence(ie: PIR) from your client.
Kindly advise if there is any evidence (c. 1 m) from year electric
Thank you.
"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole
intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability,
whatsoever, should be deemed / inferred from this negotiation of terms/settlement.
In the event of new evidence being discovered or subsequently produced by either party that will materially
affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation
terms/settlement."
Best Regards,
best Regards,
Hsiao Tong, Chew (Ms) Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 email: chewht@lkkauto.com fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 S(408933)
From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 12 November 2019 4:56 PM To: Sg Motor <sgmotor2000@yahoo.com.sg></sgmotor2000@yahoo.com.sg>
Cc: Sg Motor <sg_motor_enterprise@yahoo.com.sg></sg_motor_enterprise@yahoo.com.sg>
Subject: RE: Accident involving VCQ 3937 & SH 9134X along Upper Pickering Street on 11/10/2019 Your Ref:
CC4/III19018789/pb3
Without Praindice
Without Prejudice
Dear Sire Midm
Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that liability is unclear. Attached is a copy of our insured accident report for your easy reference.

As per III instruction, we would like to request for evidences (ie: video footage/ scene photos / PIR) for our necessary action.



Brief Details.

Reference to A/20191011/0139, i am here to lodge a traffic accident report.

On 11/10/19 at about 2055hrs, while driving a vehicle bearing registrsion plate number SH9134X, travelling on lane 1 of Upper Pickering Street and wanting to turn right to Parkroyal on pickering, lobby area. I checked my blindspot and making sure and no vehicle and turn right. However, while turning right toward the hotel lobby, a foreign motorcycle bearing registration plate number VCQ3937, drive straight and the head of the motorcycle collide into my front right of my vehicle. The accident happened inside the junction of yellow box. I wished to state that I have checked for blind spot and turn right.

I came down and make a checked on the motorycle rider. Ambulance and Traffic Police came shortly. Ambulance checked on both me and the motocycle guy and no injuries. Both parties exchange particulars and with the advice of police officer, to lodge a traffic accident report. Before i left, traffic police SS Syahid took my in car camera memory card (one samsung 64GB Micro SD card) and issue me a acknowledgment slip.

I did not suffer any injuries and lodging this report to inform Comfort Delgro with regard to the accident

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.
In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."
Best Regards,
Hsiao Tong, Chew (Ms) Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 email: <u>chewht@lkkauto.com</u> fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 S(408933)
From: Sg Motor <sgmotor2000@yahoo.com.sg></sgmotor2000@yahoo.com.sg>
Sent: Tuesday, 12 November 2019 4:25 PM To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com></chewht@lkkauto.com>
Cc: Sg Motor <sg enterprise@yahoo.com.sg="" motor=""> Subject: Accident involving VCQ 3937 & SH 9134X along Upper Pickering Street on 11/10/2019 Your Ref:</sg>
CC4/III19018789/pb3
Describers Tons
Dear Hsiao Tong
May I know the liability for this case.
Thank You
Regards
Linda

SG 98 Motor Pte Ltd

× S
Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898
On Thursday, 31 October 2019, 05:22:10 pm GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:</sgmotor2000@yahoo.com.sg>
Dear Shu Pei
Attached is the Police report & Log card for your reference.
Thank You
Describe
Regards
Linda
SG 98 Motor Pte Ltd
Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898
On Thursday, 31 October 2019, 08:41:34 am GMT+8, Shu Pei (LKKAuto) <shupei@lkkauto.com> wrote:</shupei@lkkauto.com>

Dear Sir / Madam, Kindly lets us have a copy of GIA report & police report.

Thank you

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAuto)

Sent: Tuesday, 29 October 2019 9:33 AM
To: Sg Motor <sgmotor2000@yahoo.com.sg>

Cc: Sg Motor <sg motor enterprise@yahoo.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com> Subject: RE: Accident involving VCQ 3937 & SH 9134X along Upper Pickering Street on 11/10/2019

Dear Sir / Madam,

Thank you for your email.

Kindly lets us have a copy of GIA report & police report.

Please note that: -

LKK ref	Officer in charge	
CC4/III19018789/pb3	Hsiao Tong	

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei| Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sg Motor <sgmotor2000@yahoo.com.sg>

Sent: Friday, 25 October 2019 1:28 PM

To: Shu Pei (LKKAuto) < shupei@lkkauto.com>

Cc: Sg Motor <sg motor enterprise@yahoo.com.sg>

Subject: Accident involving VCQ 3937 & SH 9134X along Upper Pickering Street on 11/10/2019

Dear Shu Pei

May I know who is the case handler for this claim.

May I know the liability.

Thank You

Regards

Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

Claim Audit

	UDIT.		Domarks	Ву
No.		Audit	Remarks	
1	23 Oct 2019 15:05	Clm Dtl Modified	Claimant's Name: ->	[A] Lau Shu Pei
	23 Oct	Clm Veh		[A] Lau Shu Pei
	2019 15:05	Model Changed	(200080) ADIVA ADI 200 19000 3M	[11] 200 3110 1 0
3	23 Oct 2019 15:05	Clm Created	Reg No: VCQ3937. Acct Date: 2019/10/11. Claim Type: TP. Insurer: India International Insurance Pte Ltd (HQ). Workshop: Sg 98 Motor Pte Ltd (HQ)	[A] Lau Shu Pei
4	23 Oct 2019 15:05	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei
		Adj Next		[A] Lau Shu Pe
	2019 15:05	Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/11/04	[A] 200 5110 7 0
6	23 Oct 2019 15:05	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] Lau Shu Pe
7	23 Oct 2019 15:05	Label Added	(30653):Direct Settlement.	[A] Lau Shu Pe
8	23 Oct 2019 15:05	Adj Adjuster Assigned	[None] -> BRYAN TANI	[A] Lau Shu Pe
9	01 Nov 2019 10:18	Clm Dtl Modified	Claimant's Name:> MOHD AMIRUL BIN MOHAMAD FAJERI. Claimant's ID: -> G6818772P.	[A] Lau Shu Pe
10	01 Nov 2019 10:18	Clm Veh Model Changed	(206086) -> (202721) YAMAHA 135LC 135cc ES.	[A] Lau Shu Pe
11	01 Nov 2019 10:19	Clm Dtl Modified	Insured Name: -> COMFORT TRANSPORTATION PTE LTD.	[A] Lau Shu Pe
12	06 Nov 2019 15:02	Adj Mandate Request	Cur.Req:0.00:PODS Liability: TBA Remark: Pls provide insured video.	[A] CHEW HSIAO TONG
13		Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/11/04. Mandate Remarks: Insured SD card is with Traffic Police.	[I] Pooi Chin Han Daniel
14	07 Nov 2019 09:42	50 978	Maintained:Insured SD card is with Traffic Police.	[I] Pooi Chin Han Daniel
15	18 Nov 2019 08:14	Adj Mandate Request	Cur.Req:0.00:PODS Liability: TBA Remark: Pls provide insured video.	[A] CHEW HSIAO TONG
16	19 Nov 2019	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date: $2019/11/04$. Mandate Remarks: Have asked Comfort, Insured SD card is still with the Traffic Police.	[1] Pooi Chin Han Daniel
17	19 Nov 2019 09:44	3	Maintained: Have asked Comfort, Insured SD card is still with the Traffic Police.	[I] Pooi Chin Han Daniel
18	30 Nov 2019 09:51	Adj Mandate Request	Cur.Req:0.00:PODS Liability: TBA Remark: Pls provide insured video. Currently pending for evidence from 3rd party.	[A] CHEW HSIAO TONG
19		Adj Mandate Request Cancelled		[A] CHEW HSIAO TONG
20	04 Dec 2019 09:07		Cur.Req:0.00:PODS Liability: 100% Remark: 3rd party submitted a copy of PIR to show that traffic p olice taken action against our driver on Inconsiderate Driving.	[A] CHEW HSIAO TONG
21	06 Dec 2019	Adj Next Rpt	Cur Rpt:Final Rpt. Cur Due Date:2019/11/04. Mandate Remarks: Agreed to do direct settlement. Revert with your quantum advice	[I] Sundari Nagarajan
22	14:36 06 Dec 2019	Changed Adj Mandate Set	Approved:0.00:Agreed to do direct settlement. Revert with your quantum advice	[I] Sundari Nagarajan
23	14:36 19 Feb 2020 17:31			[A] NUR SHAQILAH BTE ABDOL WAHAE
24	19 Feb 2020 17:31	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] NUR SHAQILAH BTE ABDOL WAHAE
25	19 Feb 2020 17:31	Clm Dtl Modified	JPJ Reg. Date: -> 2019/01/15.	[A] NUR SHAQILAH BTE ABDOL WAHAE
26	19 Feb 2020 17:31	Clm Details Notified		[A] NUR SHAQILAH BTE ABDOL WAHAE

AUDIT TRAIL No. On Audit 20 Feb 27 2020 Request Page 13 Adj Mandate 80:00: PODS Liability: 100% *Quantum: (a)COR: \$2,050.00 + (b)LOU(4days x \$20.00): \$80.00 + (c)Towing Fee: \$40.00 = Total: \$2,170.00 *Vehicle Model:Yamaha 135 (134cc) *4 recommendation repair days *For your approval please. [A] CHEW HSIAO TONG

◀ 🖺 ▶ Audit Type None ▼ Go ◀ 🖺 ▶ Date To **Date From**

ACTIVITY No record

Bill Ref No	ng for this cas	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2323371	24 Oct 2019 09:23:18	TP Case (Insurer)	Motor	LKK Auto Consultants Pte Ltd	India International Insurance Pte Ltd (HQ)	VCQ3937	SH9134X	11.77
2444025	19 Feb 2020 17:31:39	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	VCQ3937	SH9134X	11.77

Print Received Message

This mail is associated with:

*VCQ3937 (MCT19100280) [SH9134X] TP

MOHD AMIRUL BIN MOHAMAD FAJERI Oct 11 2019 8:00PM [COMFORT TRANSPORTATION PTE LTD] Sg 98 Motor Pte Ltd

From

India International Insurance Pte Ltd (HQ) (III_SG), sent on 20/02/2020 09:13 AM.

To

LKK_HQ

Subject Alert - Adj Mandate Approved (S\$2170.00) - VCQ3937 - Claim Handler: Pool Chin Han Daniel

Approved:2170.00.	

Hsiao Tong (LKKAuto)

From:

Hsiao Tong (LKKAuto)

Sent:

Friday, 21 February 2020 4:31 PM

To:

Sq Motor

Cc:

Sq Motor, Admin A

Subject:

RE: Accident involving VCQ 3937 & SH 9134X along Upper Pickering Street on

11/10/2019 Your Ref: CC4/III19018789/pb3

Attachments:

DV_VCQ3937.pdf; III GIRO FORM.pdf

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair	\$ 2,050.00	
2. Loss of Use (4days x \$20.00)	\$ 80.00	
3. LTA/GIA Search Fee	\$ 40.00	
Total	\$ 2,170.00	

If our offer is acceptable by your client, please duly sign the DV enclosed and return together with the following document to us (LKK) for our necessary action: -

- Original LOD.
- Original Repair Tax Invoice, addressed to M/s India International Insurance Pte Ltd.
- Original Towing Receipt.
- Original Authorisation to Act signed by your client.
- GIRO FORM (if not provided to III before)

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sg Motor <sgmotor2000@yahoo.com.sg>

Sent: Tuesday, 4 February 2020 4:04 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Sg Motor <sg_motor_enterprise@yahoo.com.sg>; Admin A <admin-a@lkkauto.com>

Subject: Re: Accident involving VCQ 3937 & SH 9134X along Upper Pickering Street on 11/10/2019 Your Ref:

CC4/III19018789/pb3

Dear Hsiao Tong

Attached is the Letter of Demand for your kind action.

Thank You

Regards Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21 Ang Mo Kio Industrial Park 1 Singapore 569622

Tel: 64524898 Fax: 64526898

On Tuesday, 3 December 2019, 01:23:39 pm GMT+8, Sg Motor <sgmotor2000@yahoo.com.sg> wrote:

Dear Hsiao Tong

Attached is the police investigation result for your perusal.

Thank You

Regards Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21 Ang Mo Kio Industrial Park 1 Singapore 569622

Tel: 64524898 Fax: 64526898

On Saturday, 30 November 2019, 09:51:12 am GMT+8, Hsiao Tong (LKKAuto) < chewht@lkkauto.com > wrote:

#D
Without Prejudice
Dear Sirs/Mdm,
We refer to our below email.
Kindly advise if there is any evidence(ie: PIR) from your client.
Thank you.
"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.
In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."
Best Regards,
Hsiao Tong, Chew (Ms) Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 email: chewht@lkkauto.com fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 S(408933)

From: Hsiao Tong (LKKAuto)
Sent: Tuesday, 12 November 2019 4:56 PM To: Sg Motor <sgmotor2000@yahoo.com.sg>
Cc: Sg Motor <sg_motor_enterprise@yahoo.com.sg>
Subject: RE: Accident involving VCQ 3937 & SH 9134X along Upper Pickering Street on 11/10/2019 Your Ref:

CC4/III19018789/pb3


Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

Please be informed that liability is unclear. Attached is a copy of our insured accident report for your easy reference.

As per III instruction, we would like to request for evidences (ie: video footage/ scene photos / PIR) for our necessary action.



Brief Details.

Reference to A/20191011/0139, i am here to lodge a traffic accident report.

On 11/10/19 at about 2055hrs, while driving a vehicle bearing registrsion plate number SH9134X, travelling on lane 1 of Upper Pickering Street and wanting to turn right to Parkroyal on pickering, lobby area. I checked my blindspot and making sure and no vehicle and turn right. However, while turning right toward the hotel lobby, a foreign motorcycle bearing registration plate number VCQ3937, drive straight and the head of the motorcycle collide into my front right of my vehicle. The accident happened inside the junction of yellow box. I wished to state that I have checked for blind spot and turn right.

I came down and make a checked on the motorycle rider. Ambulance and Traffic Police came shortly. Ambulance checked on both me and the motocycle guy and no injuries. Both parties exchange particulars and with the advice of police officer, to lodge a traffic accident report. Before i left, traffic police SS Syahid took my in car camera memory card (one samsung 64GB Micro SD card) and issue me a acknowledgment slip.

I did not suffer any injuries and lodging this report to inform Comfort Delgro with regard to the accident

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sg Motor <sgmotor2000@yahoo.com.sg> Sent: Tuesday, 12 November 2019 4:25 PM To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Sg Motor <sg motor enterprise@yahoo.com.sg>

Subject: Accident involving VCQ 3937 & SH 9134X along Upper Pickering Street on 11/10/2019 Your Ref:

CC4/III19018789/pb3

Dear Hsiao Tong
May I know the liability for this case.
Thank You
Regards
Linda
SG 98 Motor Pte Ltd
Blk 4001 #01-21
Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898
On Thursday, 31 October 2019, 05:22:10 pm GMT+8, Sg Motor < sgmotor2000@yahoo.com.sg> wrote:
Dear Shu Pei
Attached is the Police report & Log card for your reference.
Thank You
Thank You
Thank You Regards

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1
Singapore 569622
Tel: 64524898 Fax: 64526898
On Thursday, 31 October 2019, 08:41:34 am GMT+8, Shu Pei (LKKAuto) <shupei@lkkauto.com> wrote:</shupei@lkkauto.com>
Dear Sir / Madam,
Kindly lets us have a copy of GIA report & police report.
Thank you
To check availability of the case handler, you may contact the undersigned
Best Regards,
Shu Pei Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 email: shupei@lkkauto.com fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 S(408933)
From: Shu Pei (LKKAuto)
Sent: Tuesday, 29 October 2019 9:33 AM To: Sa Meter < sameter 2000@yahoo.com.sa>
Cc: Sg Motor <sg enterprise@yahoo.com.sg="" motor="">; Hsiao Tong (LKKAuto) <chewht@lkkauto.com> Subject: RE: Accident involving VCQ 3937 & SH 9134X along Upper Pickering Street on 11/10/2019</chewht@lkkauto.com></sg>

Dear Sir / Madam, Thank you for your email. Kindly lets us have a copy of GIA report & police report.

Please note that: -

LKK ref	Officer in charge		
CC4/III19018789/pb3	Hsiao Tong		

To check availability of the case handler, you may contact the undersigned

Best	Regards,
------	----------

Shu Pei| Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupei@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sg Motor <sgmotor2000@yahoo.com.sg>

Sent: Friday, 25 October 2019 1:28 PM

To: Shu Pei (LKKAuto) < shupei@lkkauto.com>

Cc: Sg Motor <sg motor enterprise@yahoo.com.sg>

Subject: Accident involving VCQ 3937 & SH 9134X along Upper Pickering Street on 11/10/2019

Dear Shu Pei

May I know who is the case handler for this claim.

May I know the liability.

Thank You

Regards

Linda

SG 98 Motor Pte Ltd

Blk 4001 #01-21

Ang Mo Kio Industrial Park 1

Singapore 569622

Tel: 64524898 Fax: 64526898

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adi Sub	mitted	Ins Auth'ed	Status	
Main	07 Nov 2019 Edit Reg		22 Oct 2019 00:00 Edit Adj Rpt	S\$2,050.00 Edit Estimates	S\$2,05	0.00			for Survey
	Main	Re	ference	Cla	im Details		Documen	nts	Show All
CLAIM SU	JBFOLDER DE	TAILS	almi disenti seral metali			[Create	ed by adjuster]		
Insured:	COMFORT	TRANSPORTAT	ION PTE LTD,	Co. Reg. No.: 19	99303821R				
Main Claimant:	моно ам	IRUL BIN MOHA	MAD FAJERI,	ID: G6818772	•				
Vehicle Reg No.:	Data of Local Lat to Lat to Local Lat to L					Date (Man Yr)]			
Claim Type	TP / MCT	19100280			olicy/Cover lote No.:	Dan market	015 (TP, Fire & The	A 100 TO	
Vehicle Reg No. (Insured):	SH9134X				olicy No. Claimant):				
		7			xcess:				
Repairer:	S9 Motor	Trading Pte Ltd	(HQ) 4001 ANG	MO KIO INDUST	RIAL PARK	1 #01-21,	569622 Ang Mo K	io - Tel:	
Handling Insurer:	India Inte	ernational Insur	ance Pte Ltd (H	Q) - Tel: 63476	100 [Han	dled by Po	ooi Chin Han Dan	iel]	
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561 [Handled by I	BRYAN TA	NI] [Final R	pt due 04/	11/2019]
ASSOCIA	TED MAIL RE	CEIVED						View All C	Compose Case Ma
III_SG (III_SG (III_SG (06/12/2019): A 19/11/2019): A 07/11/2019): A	Alert - Adj Mand Alert - Adj Mand Alert - Adj Mand KS	ate Approved (S ate Maintained	5\$0.00) - VCQ: - VCQ3937 - C - VCQ3937 - C	3937 - Clair Iaim Handl Iaim Handl	m Handle er: Pooi (er: Pooi (View Al	Chin Han Daniel	D Create New	

Claim Documents

*VCQ3937 (MCT19100280) [SH9134X]

MOHD AMIRUL BIN MOHAMAD FAJERI Oct 11 2019 8:00PM [COMFORT TRANSPORTATION PTE LTD] S9 Motor Trading Pte Ltd

_		ad Photos Compose New Letter		View in Brow	1
Pho	tos/Images		3 per p		•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	29/01/20 16:17	Front View	0	Load JPG	S
2	29/01/20 16:18	General View	0	Load JPG	₹
3	29/01/20 16:18	General View	0	Load JPG	•
4	29/01/20 16:18	General View	0	Load JPG	•
5	29/01/20 16:18	General View	0	Load JPG	•
6	29/01/20 16:18	General View	0	Load JPG	Ø
7	29/01/20 16:18	General View	0	Load JPG	•
8	29/01/20 16:18	General View	0	Load JPG	•
9	29/01/20 16:18	General View	0	Load JPG	•
10	29/01/20 16:18	General View	0	Load JPG	Ø
11	29/01/20 16:18	General View	0	Load JPG	•
12	29/01/20 16:18	General View	0	Load JPG	•
13	29/01/20 16:18	General View	0	Load JPG	•
14	29/01/20 16:18	General View	0	Load JPG	•
15	29/01/20 16:18	General View	0	Load JPG	•
16	29/01/20 16:18	General View	0	Load JPG	•
17	29/01/20 16:18	General View	0	Load JPG	•
18	29/01/20 16:18	General View	0	Load JPG	•
19	29/01/20 16:18	General View	0	Load JPG	•
20	29/01/20 16:19	General View	0	Load JPG	•
21	29/01/20 16:19	General View	0	Load JPG	•
22	29/01/20 16:19	General View	0	Load JPG	•
23	29/01/20 16:19	General View	0	Load JPG	•
24	29/01/20 16:19	General View	0	Load JPG	•
25	29/01/20 16:19	General View	0	Load JPG	•
26	29/01/20 16:19	General View	0	Load JPG	•
27	29/01/20 16:19	General View	0	Load JPG	•
28	29/01/20 16:19	General View	0	Load JPG	•
29	29/01/20 16:19	General View	0	Load JPG	•
30	29/01/20 16:19	General View	0	Load JPG	9
31	29/01/20 16:19	General View	0	Load JPG	•
32	29/01/20 16:19	General View	0	Load JPG	•
33	29/01/20 16:19	General View	0	Load JPG	•
34	29/01/20 16:19	General View	0	Load JPG	•
35	29/01/20 16:19	General View	0	Load JPG	•

Phot	tos/Images		3 per	-	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	_
36	29/01/20 16:19	General View	0	Load JPG	•
37	29/01/20 16:19	General View	0	Load JPG	
38	29/01/20 16:19	General View	0	Load JPG	€
39	29/01/20 16:19	General View	0	Load JPG	•
40	29/01/20 16:19	Odometer Reading	0	Load JPG	
41	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
42	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
43	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
44	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
45	29/01/20 16:20	Reinspection Photo	0	Load JPG	
46	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
47	29/01/20 16:20	Reinspection Photo	0	Load JPG	
48	29/01/20 16:20	Reinspection Photo	0	Load JPG	
49	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
50	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
51	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
52	29/01/20 16:20	Reinspection Photo	0	Load JPG	
53	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
54	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
55	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
56	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
57	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
58	29/01/20 16:20	Reinspection Photo	0	Load JPG	2
59	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
60	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
61	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
62	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
63	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
64	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
65	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
66	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
67	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
68	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
69	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
70	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
71	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
72	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
73	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
74	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
75	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
	100000000000000000000000000000000000000	Reinspection Photo	0	Load JPG	•
76	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
77	29/01/20 16:20	Reinspection Photo	ō	Load JPG	•
78	29/01/20 16:20	- Control Cont	0	Load JPG	2
79	29/01/20 16:20	Reinspection Photo	0		2
80	29/01/20 16:20	Reinspection Photo	0		•
81	29/01/20 16:20	Reinspection Photo	0		•
82	29/01/20 16:20	Reinspection Photo Reinspection Photo	0		Z

Pho	otos/Images		3 per pa	ige ▼	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1	humbnail	Print
84	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
85	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
86	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
87	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
88	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
89	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
90	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
91	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
92	29/01/20 16:20	Reinspection Photo	o	Load JPG	•
93	29/01/20 16:20	Reinspection Photo	o	Load JPG	•
94	29/01/20 16:20	Reinspection Photo	0	Load JPG	•
95	29/01/20 16:20	Reinspection Photo	0	Load JPG	3
96	29/01/20 16:20	Reinspection Photo	0	Load JPG	2
97				100000000000000000000000000000000000000	
	29/01/20 16:20	Reinspection Photo		Load JPG	€
98	29/01/20 16:20	Reinspection Photo	0	Load JPG	€
99	29/01/20 16:20	After Repair Photo	0	Load JPG	•
100	29/01/20 16:20	After Repair Photo	0	Load JPG	•
Doc	umentation		1 per pa	ge v	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		humbnail	-
1	23/10/19 15:06	EMAIL FROM III DD 22102019		Load PDF	Fine
2	23/10/19 15:06	WKSP NOTICE		Load PDF	
3	01/11/19 10:17	Police Report & LOG CARD		Load PDF	
4	01/11/19 17:05	INSURANCE CERT		Load PDF	
5	01/11/19 17:05	TP ESTIMATE- MARKED		Load PDF	
6	04/12/19 09:05	PIR FROM TP.		Load PDF	
7	20/02/20 09:01	LOD	-	Load PDF	
8	20/02/20 09:01	Towing Receipt	0	Load PDF	
9	05/03/20 16:36	Authorisation to Act	0	Load PDF	
10	05/03/20 16:36	DISCHARGE VOUCHER		Load PDF	
11	05/03/20 16:36	WORKSHOP INVOICE		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Т	humbnail	Print
1	24/10/19 09:23	Singapore Accident Statement	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer	
snow Remarks 10: — nandling Insurer	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/III19018789/DPS3S2

Date:

05/03/2020

REFERENCE

Handling Insurer:

India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle

Date of Loss:

VCQ3937

Insured Vehicle No:

SH9134X

No:

11/10/2019

Nature of Claim:

TP

Claim No:

MCT19100280

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

VCQ3937

Make & Model:

YAMAHA 135LC, 135cc ES 15/01/2019 (Man. Year: 2019)

Engine No: Chassis No: G3G5E077410

Reg. Date: Colour:

Black

Odometer:

PMYUG0810K0077390 26987 km

Engine Capacity:

134 cc

Market Value/New Car Price: Sum Insured (S\$):

N/A

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good Yes

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

70/90 R17

Rear Tyre Size:

80/90 R17

Front Left Side:

Maxxis 2 mm

Rear Left Side:

Maxxis 2 mm

Front Right Side:

0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,845.00	2,268.00	1,577.00	41.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	310.00	290.00	48.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,445.00	2,578.00	1,867.00	42.00
Approved Total (Overridden) (S\$)		2,050.00		
Nett Amount (S\$)	4,445.00	2,050.00	2,395.00	53.88
+ Loss of Use (4.0 x S	\$20.00/day) (S\$)	80.00		
	Other Costs (S\$)	40.00		
N	ett Liability (S\$)	2,170.00		

INSPECTION

Date of Assignment:

22/10/2019

S9 Motor Trading Pte Ltd

Date Inspected:

23/10/2019 Inspected At:

BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21

Singapore 569622

Estimated Period of Repair:

4.0 days

Adjuster:

BRYAN TANI

Manager:

CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

(Last Synchronised: 05 Mar 2020)

Parts:

N/A

YAMAHA 135LC 135cc ES (Model not available in database)

Labour:

Part Source:

(Price-denominated Standard List) Repairer's

Print Code: (Unsubmitted, no print-code for VCQ3937)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Re	con	nm	е	nc	led	Par	ts	
	0.000		0.0	00	100	1000		

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*HEAD LAMP	Not Necessary	320.00 F	*-FL
2	1	*HANDLE BAR	Bent	115.00 F	*115.00 FL
3	1	*HANDLE BAR BRACKET	Not Necessary	95.00 F	*-FL
4	2	*HANDLE GRIP	Not Necessary	160.00 F	*-FL
5	1	*SET BALANCER	N/s Cut / O/s Not Necessary	160.00 F	*80.00 FL
6	1	*FORK UNDER BRACKET	Damaged	180.00 F	*180.00 FL
7	1	*SET FORK TUBE (2PCS)	Bent / Distorted	480.00 F	*480.00 FL
8	1	*SET CONE BEARING	Damaged	120.00 F	*120.00 FL
9	1	*FRONT RIM	Repair	320.00 F	*-FL
10	1	*BRAKE LEVER	Not Necessary	65.00 F	*-FL
11	1	*GEAR PEDAL	Bent	65.00 F	*65.00 FL
12	1	*LEG SHIELD - LH	Not Necessary	125.00 F	*-FL
13	1	*FRONT MUDGUARD	Broken	250.00 F	*250.00 FL
14	1	*FRONT PANEL	Cut	185.00 F	*185.00 FL
15	1	*FRONT LH FAIRING	Cut	195.00 F	*195.00 FL
16	1	*CENTRE LEG SHIELD	Mtg Deformed	150.00 F	*150.00 FL
17	1	*REAR LH FAIRING	Cut / Mtg Broken	165.00 F	*165.00 FL
18	1	*FRONT BOX	Broken	135.00 F	*135.00 FL
19	1	*FOOTREST	Bent	65.00 F	*65.00 FL
20	1	*FOOTREST BRACKET	Bent	135.00 F	*135.00 FL
21	1	*SET FOOTREST - RUBBER	Not Necessary	80.00 F	*-FL
22	1	*REAR-BOX	Cut	280.00 FS	*180.00 FS
F=Fr	anchise part. S=Spcf	Nett, L=ListItemDisc.	277277422		2 502 25
			Sub Total (S\$)	3,845.00	2,500.00

Sub Total (S\$)	3,845.00	2,500.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	232.00
	is Malayetta secure	The state of the s

Total Parts (S\$)

Report was unsubmitted during this print-out.

2,268.00

3,845.00

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended	Lahour
Recommended	Laboui

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOWING FEE.	New	40.00	0.00
2	REMOVE & REPLACE NECESSARY PARTS ALIGN & ETC.	New	250.00	180.00
3	REMOVE & REPLACE FORK, ASSY, TO TOP UP FORK OIL.	New	120.00	80.00
4	RE-ALIGN BODY ALIGNMENT.	New	190.00	50.00
		Gross Labour Cost (S\$)	600.00	310.00
	Report was unsubmitte	ed during this print-out.		

< END OF ESTIMATES >