

6 Temasek

REF: CS/PWD/19018792/Kqd3^{SR}

Special Instruction:

REC. BY:

Operator: Menmen

ASSIGNMENT (Office)

AWD

Date/Time: 23/10/19 @ 9:35am

Estimated Cost:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

Insured: SKB 51512

To Inspect Vehicle No:

SLS 7876B

Tel: 64833353

at Workshop m/s

Lyle Design

of

10 Amk Ind. Park 2A #04-04

Claim No:

1201900031803

Policy No:

PNPV2018-00005666-01

Excess:

D.O.A. 22/10/2019

Sum Insured:

Make of Veh:
(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time: 11am @ 23/10/19

Person Contacted:

Siew Hoon

Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>SLS 7876B -X</u>
	<u>SKB 51512 -X</u>

24/10/19 @ 2.11pm Siew Hoon informed conduct this case as 'WP'.
24/10/19 @ 2.20pm informed Vanessa Chan, we are pending estimate from repairer.
24/10/19 @ 11.57pm revised to Vanessa Chan via Menmen.

ASS. REC. BY:

REF:

FWD/

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.:

at Workshop nvs

of:

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh.:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Est. or Market Value:

IDAC Accident Report:

Consistent? Yes or No

GIA / PR. Seen:

Consistent? Yes or No

Est. Repairs:

07

days

Res.

Yes

or No

Lump Sum:

1.8.1

%

3. Va.

Yes

or No

CA / REV / REP. / 24 HRS

Owner:

Person Contacts:

Vehicle IN / OUT

Date / Time:

Action / Instruction:

Veh No:

SL5 7876B

Yr Regn:

10. 17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai

Elantra

cc

1591

Colour:

M. Black

A/C

Insured / Std / NI / NA

St Reading:

40639

T-Radio

Insured / Std / NI / NA

Eng No:

Ch No:

KMI1D841CMJU 550138

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / R/Rim / STD A/Rim or

Tyre Size

F:

225/40 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Dayton

Front

R-Bar

8

mm

Rear

R-Bar

8

mm

L-Bar

8

mm

L-Bar

8

mm

D.O.A.

22/10/19

D.O.A.

23/10/19

Survey held at:

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

8/F

The UIC / Chassis frame / Body Structure affected due to collision

14/4 @ 6286.00 email

18/1 @ 6416.00 email

RECEIVED 19 FEB 2020

18/2/20 @ 7.10pm confirmed with Siew Hoon final fig 86531.04, 7 days.
(Red 8547.28, 57%)

Draft/Type File/Pass to:



Preli. Report

18/2 10/19



Final Report

Auto/Type File Return to:

Days Of Repair:

7

Resurvey No. of Trip:

2

Add Fee:



Site Insp. IS



Interview IS



Travel IS



V. check IS

Report Format:

MER-TP

Lump Sum / L.B. / IS

6531.04

Survey Fee

Transportation

D.O.A. IS

V. check IS

250

50

50

11

Nivitha (LKK Auto)

From: venessa.chan@fwd.com
Sent: Wednesday, 23 October 2019 9:35 AM
To: admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: eileen.bay@fwd.com; motorclaims.sg@fwd.com
Subject: PRE-REPAIR SURVEY --- YOUR REF: SKB5151Z --- ACCIDENT INVOLVING SLS 7876 B (#2) AND SKB 5151 Z (#3) AND SHA 7594 G (#1) ON 22 OCTOBER 2019 ALONG BARTLEY ROAD EAST AT ABOUT 0800 HOURS

Dear Nivitha,

Please refer to the email below and liaise with TP repairer for PRS.

Please create the case in Merimen.


Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com
W www.fwd.com.sg



From: Motor Claims SG - SG Common
Sent: Wednesday, October 23, 2019 9:32 AM
To: 'Elaine Toh'; Eileen Bay - SGUser
Cc: Motor Claims SG - SG Common
Subject: PRE-REPAIR SURVEY --- YOUR REF: SKB5151Z --- ACCIDENT INVOLVING SLS 7876 B (#2) AND SKB 5151 Z (#3) AND SHA 7594 G (#1) ON 22 OCTOBER 2019 ALONG BARTLEY ROAD EAST AT ABOUT 0800 HOURS

Hi Elaine,

Thank you for your selection of LKK Auto Consultants Pte Ltd.
We will proceed to assign survey.


Thank you.

Best Regards,

Venessa Chan
Administrative Assistant, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
E venessa.chan@fwd.com
W www.fwd.com.sg



From: Elaine Toh [<mailto:Elainetoh@visionlawllc.com>]
Sent: Wednesday, October 23, 2019 8:52 AM
To: Eileen Bay - SGUser
Cc: Motor Claims SG - SG Common
Subject: RE: PRE-REPAIR SURVEY --- YOUR REF: SKB5151Z --- ACCIDENT INVOLVING SLS 7876 B (#2) AND SKB 5151 Z (#3) AND SHA 7594 G (#1) ON 22 OCTOBER 2019 ALONG BARTLEY ROAD EAST AT ABOUT 0800 HOURS
Importance: High

Our Ref: SLS 7876 B (et)
WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to your email of 22 October 2019 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **LKK AUTO CONSULTANTS PTE LTD** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue : Lye Designs
10 Ang Mo Kio Industrial Park 2A
#04-04 AMK Autopoint
Singapore 568047
Contact: Siew Hoon @ 64833353 (Please call before going)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.



FOR SURVEYOR

Please initial here after completion of pre-repair inspection.
Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

Regards,
Elaine Toh (Secretary)
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802

cc: SLS 7876 B – By fax: 64842457 only

From: eileen.bay@fwd.com [mailto:eileen.bay@fwd.com]

Sent: Tuesday, 22 October, 2019 5:06 PM

To: ElaineToh@visionlawllc.com

Cc: motorclaims.sg@fwd.com

Subject: RE: PRE-REPAIR SURVEY --- YOUR REF: SKB5151Z --- ACCIDENT INVOLVING SLS 7876 B (#2) AND SKB 5151 Z (#3) AND SHA 7594 G (#1) ON 22 OCTOBER 2019 ALONG BARTLEY ROAD EAST AT ABOUT 0800 HOURS

WITHOUT PREJUDICE

Dear Sir / Madam,

Please find our panel surveyors as follows: -

1. LKK Auto Consultants Pte Ltd
2. Infiniti Appraisal Service
3. AJAX Inspection Services Pte Ltd
4. RT Appraisal Pte Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receive your reply.

**Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.*

**Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.*

Kind regards,

Eileen Bay

Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 69217411

E eileen.bay@fwd.com

W www.fwd.com.sg



PNPV2018-00005666-01

From: Elaine Toh [mailto:ElaineToh@visionlawllc.com]

Sent: Tuesday, 22 October, 2019 2:58 PM

To: Motor Claims SG - SG Common <motorclaims.sg@fwd.com>

Subject: PRE-REPAIR SURVEY --- YOUR REF: SKB 5151 Z --- ACCIDENT INVOLVING SLS 7876 B

(#2) AND SKB 5151 Z (#3) AND SHA 7594 G (#1) ON 22 OCTOBER 2019 ALONG BARTLEY ROAD EAST AT ABOUT 0800 HOURS

Importance: High

Our Ref: SLS 7876 B (et)
WITHOUT PREJUDICE

Dear Sir/Madam,

We are instructed by **KOH YEE HONG** to notify you of a road traffic accident on 22 October 2019 at about 0800 hours along Bartley Road East involving our client's motor vehicle registration number SLS 7876 B and motor vehicle registration number SKB 5151 Z driven by you/your insured at the material time.

As a result of the accident, our client's motor vehicle has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the motor vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor vehicle without further reference to you.

Thank you.

Regards,
Elaine Toh (Secretary)
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802

cc: SLS 7876 B – By fax: 64842457 only

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Shiau Chan (LKKAuto)

From: Siew Hoon <siewhoon@lyedesigns.com.sg>
Sent: Tuesday, 18 February 2020 3:29 PM
To: Shiau Chan (LKKAuto)
Subject: RE: SLS7876B MARKED ESTIMATE > Confirm \$6,531.04 part-by-part, 7 repair days

Importance: High

Hi Shiau Chan

Confirm \$6,531.04 part-by-part, 7 repair days

Thank you.

Warm Regards

Siew Hoon

Lye Designs

10 Ang Mo Kio Industrial Park 2A

#04-04 AMK Autopoint

Singapore 568047

T : 6483 3353

F : 6484 2457

E : siewhoon@lyedesigns.com.sg

W : www.lyedesigns.com.sg

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]

Sent: Tuesday, 18 February 2020 3:13 PM

To: Siew Hoon

Subject: RE: SLS7876B MARKED ESTIMATE > Additional item for marking- Plastic Dip Grille, Front Number Plate, R/Bumper Lip - invoice

Dear Siew Hooi,

WITHOUT PREJUDICE

As spoken with you.

Confirm final fig \$6,531.04 and 7 repair days.

Kindly send the relevant documents to FWD Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eileen Bay

Date: 25 Oct 2019

Preliminary Advice

Insured Vehicle No	: SKB5151Z	Accident Date	: 22/10/2019
TP Vehicle No	: SLS7876B	Assignment Date	: 23/10/2019
Make	: HYUNDAI ELANTRA	Est. Duration of Repair	: 7.00
Date of Inspection	: 23/10/2019		
Inspection At	: LYE DESIGNS (HQ) 10 AMK AUTOPOINT #04-04, ANG MO KIO INDUSTRIAL PARK 2A SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear & front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,254.48
Revised Amount	:S\$	6,743.84
Check Items (Estimated)	:S\$	2,924.00
Total	:S\$	9,667.84

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Thursday, 24 October 2019 2:20 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SLS 7876B (YOUR REF: 1201900031803)

This mail is associated with :
***SLS7876B (1201900031803)**
[SKB5151Z]
TP
KOH YEE HONG
Oct 22 2019 12:00AM
[NG WEI YANG]
Lye Designs

Dear Venessa,

Please be informed that we have inspected the vehicle SLS 7876B on 23/10/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 22/10/2019 11:25
Date Of Accident 22/10/2019 08:00
Exact Location Of Accident BARTLEY ROAD EAST
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLS7876B
Insured/Policyholder
Name Of Registered Owner KOH YEE HONG
NRIC No S9233800B
Email Address KOHYEEHONG.D@GMAIL.COM
Mobile Phone No (LOCAL) +65-91874320
Alternative Phone No OTHERS-91874320

Vehicle Particulars

Manufacturer HYUNDAI
Model ELANTRA AD 1.6 GLS AT
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number P10094007R01
Cover Note Number 05/10/2019 - 04/10/2020

Driver

Name of Driver KOH YEE HONG
NRIC No S9233800B
Date Of Birth 18/09/1992
Occupation INDOOR
Date Of Driving Pass 27/05/2013
Driving Experience 6 YEARS AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-91874320
Fax Number
Contact Number OTHERS-91874320
Email Address KOHYEEHONG.D@GMAIL.COM

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

22/10/19

11:05 AM

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Enquire Vehicle Registration Details

Owner Particulars

NRIC/Passport/Company Cert No.: S9233800B
 Owner ID Type: Singapore NRIC
 Owner Name: KOH YEE HONG
 Registered Address: 1 SIN MING AVENUE #03-02 SINGAPORE 575728
 Mailing Address: -
 Birth Date: 18 Sep 1992

Vehicle Particulars

Vehicle No.: SL57876B
 Previous Vehicle No.: -
 Effective Date of Ownership: 05 Oct 2017
 Original Regn Date: 05 Oct 2017
 Registration Date: 05 Oct 2017
 Year of Manufacture: 2017
 Vehicle Type: Passenger Motor Car
 Vehicle Scheme: -
 Vehicle Attachment 1: No Attachment
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: ELANTRA AD 1.6 GLS AT
 Primary Colour: Black
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: KMHD841CMJU550138
 Engine No.: G4FGHU630885
 Engine Capacity / Power Rating: 1591 cc / -
 Maximum Power Output: 93.8 kW (125 bhp)
 Propellant: Petrol
 Max Unladen Weight: 1345 kg
 Maximum Laden Weight: 1800 kg
 Open Market Value: \$12,577.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 04 Oct 2027
 Minimum PARF Benefit: \$6,288.00
 No. of Transfers: 0
 IQ Label No.: 1127945616
 COE No.: 2017100101002800K
 COE Expiry Date: 04 Oct 2027
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
 Quota Premium (QP) / Prevailing Quota Premium: \$42,902.00 / -

Actual QP Paid: \$42,902.00
 QP (Regn Cat): \$42,902.00
 OPC Cash Rebate Eligibility: No
 QP during COE Bidding Exercise: \$42,902.00
 Additional Registration Fee Rate: First \$12,577.00 (100%)
 Actual ARF Paid: \$12,577.00
 Vehicle Lifespan Expiry Date: No Lifespan
 CO2 Emission: 161.00 (g/km)
 CEV/VES Rebate Utilised Amount: -
 CO Emission: -
 HC Emission: -
 NOx Emission: -
 PM Emission: -
 Message: To renew the COE, the Prevailing Quota Premium payable is that of Category A.

Print

OK

Save as PDF

**HYUNDAI****KOMOCO MOTORS PTE. LTD.****BUYER'S ORDER**

GST Reg. No. MR - 8500364 - 4

RCB No. 199609283R

253 Alexandra Road #01-01 Singapore 159936 Tel. 6475
8888 Facsimile: 6472 0018Sales Contract No:
Car Type: Standard
Model: ELANTRA 1.6 4DR AUTO "S"

Vin No:

Buyer's Order No: 0007281
COE Type: Bidding
Date: 10/09/2017 05:44:19 PM
Colour: NKA - PHANTOM BLACK**Particulars Of Buyer:**Name: KOH YEE HONG
Address: 1, Sin Ming Avenue #03-02
Singapore 575728
NRIC / Passport No: S9233800B
Date Of Birth: 18/09/1992
Home No: Mobile No: 91874320
Email: kohyeehong.d@gmail.com
Occupation: CIVIL SERVANT
Sales Consultant's Name: ANDREW TEO**Selling Price Includes The Following Options:**

1) Six(6) Bids Guaranteed

Buyer's Account (Inclusive of GST):

1) Elantra Bodykit \$2000.00

Sales Consultant's Account:
NIL**For Buyer's Account:****Vehicle**

Price (Inclusive of Free Options & GST)	\$85,999.00
Road Tax: (6 months)	Inclusive
COE Rebate Level @ \$28,000.00	Inclusive
CEVS Surcharge	\$0.00
Off Peak Car Rebate	(\$0.00)
Selling Price	\$85,999.00
Luxury Package	\$0.00
COE Top Up	\$0.00
Less COE Rebate	(\$0.00)
Less CEVS Rebate	(\$0.00)
Less Cash Discount	(\$2,000.00)
Less Loyalty Discount	(\$0.00)
Nett Selling Price	\$83,999.00
Buyer's Account (Inclusive of GST)	\$2,000.00
Balance Due	\$85,999.00

Details Of Hire Purchase:

Finance Company: ORCHARD CREDIT PTE LTD

Loan: \$50,000.00 for 60 months at 1.98 %

Monthly Installment: \$917.00

Details Of Deposit:


Payment Type	Amount
DEPOSIT	\$12,000.00


Expected Delivery Date: SEP17/NOV17

Important Notice:

- a) Any amendments to the buyer's order, handwritten or photocopy will not be accepted.
 b) Accessories not installed by Komoco Motors Pte Ltd will void the new car warranty.
 c) Full payment must be made before registration. All cheques must be crossed and made payable to KOMOCO MOTORS PTE LTD.
 d) Deposit amounts are not refundable and not transferable.
 e) Documents either original or photocopied that have not been stamped, attested and endorsed by Komoco Motors Pte Ltd will be considered void.
 f) The Company takes no responsibility for any loss or damage to the customer in the sale of the customers' second-hand car to any dealer for obtaining finance.
 g) 1) SIX(6) BIDS GUARANTEED: Refunds will only be made after the Sixth (6) failed bid.

I/We hereby agree to purchase from you the abovementioned vehicle at the prices shown above and on the terms and conditions printed on the back hereof,
 and I/We confirm that I/We have read and understood I/We have also signed an irrevocable letter of authority for my COE bid with KOMOCO MOTORS PTE LTD.


 Buyer's Signature:
 Date: 10/09/2017 05:44:19 PM


 Witness's Signature:
 Name: ANDREW TEO
 NRIC: S18781667
 Date: 10/09/2017 05:44:19 PM

 Komoco Authorised Signature:
 Date:
BUYER'S COPY



(Panel Beating , Repair, Servicing & General Claim)
 10, AMK Assetpoint, #04-04 Ang Mo Kio, Ind. Park 2A, Singapore 568047
 TEL : 6483 3353 FAX : 6484 2457 Email: kdevrali@singnet.com.sg
 Reg No: 52806901D

ESTIMATE

Not Authorized
Running Repair
Today
8 6416.00

Date 23 Oct 2019
 To
 Owner Koh Yee Hong
 Vehicle Reg. No. SLS7876B
 Make/Model Hyundai Elantra
 Chasis No. KMHD841CMJU550138
 Year Mfg 2017
 Date of Accident 22 October 2019

ESTIMATE COST OF REPAIR TO "HYUNDAI ELANTRA" " REG. NO. SLS7876B "

ITEM	DESCRIPTION	UNIT PRICE	AMOUNT
1pc	Front Bumper <i>589.50</i>		<i>Br</i> 605.40
2pc	Front Bumper Side Retainer : LHR and RHR	50.00	<i>Sm</i> 100.00
10 pcs	Front Bumper Clips	6.50	<i>nc</i> 65.00
1pc	Front Grille <i>495.80</i>		<i>nc</i> 611.50
1pc	LHF Headlamp Assy HID Ballast		<i>Sm</i> 1,345.90
1pc	LHF Headlamp Bracket		<i>Sm</i> 56.30
1pc	LHF Foglamp		<i>Sm</i> 329.90
1pc	LHF Foglamp Garnish		<i>Sm</i> 53.50
1pc	Rear Boot Cover(Boot Lid) <i>1048.00</i>		<i>Br</i> 2,385.00
1pc	Rear Boot Cover Lock		<i>nc</i> 155.50
2 pcs	Rear Boot Lamp <i>155.00</i>	388.00	<i>Sm</i> 776.00
1 pc	Rear Boot Weatherstrip <i>186.70</i>		<i>nc</i> 191.20
2 pcs	Rear Boot Hinge	160.50	<i>R</i> 321.00
1pc	Rear Boot Number Plate Light		<i>Sm</i> 70.00
1pc	Rear Boot Logo "Elantra"		<i>nc</i> 57.00
1pc	Rear Boot Emblem 'H'		<i>nc</i> 52.50
1pc	Reinforcement <i>328.20</i>		<i>Br</i> 395.00
1pc	Rear End Panel		<i>R</i> <i>Br</i> 522.00
1pc	Rear End Panel Top Garnish		<i>nc</i> 153.80
1pc	Rear Bumper <i>489.20</i>		<i>Br</i> <i>nc</i> 560.00
10 pcs	Rear Bumper Clips	6.00	<i>nc</i> 60.00
2 pcs	Rear Bumper Side Retainer : LHR and RHR	58.50	<i>nc</i> 117.00
2 pcs	Rear Bumper Reflector : LHR and RHR	63.50	<i>nc</i> 127.00
2 pcs	Taillamp : LHR and RHR <i>015.00 x</i>	514.90	<i>nc</i> 1,029.80
4 pcs	Taillamp Clips : LHR and RHR	8.00	<i>nc</i> 32.00
2 pcs	Rear Exhaust Mounting	42.90	<i>Sm</i> 85.80
2 pcs	Rear Sport Exhaust Mufflers	830.00	<i>R</i> 1,660.00
Sub-total			11,918.10
Less 20%			(2,383.62)
Total List Items			9,534.48
Balance B/F			9,534.48

@ 520.30

LD Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed & is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Date 23 Oct 2019
To
Owner Koh Yee Hong
Vehicle Reg. No. SLS7876B
Make/Model Hyundai Elantra
Chasis No. KMHD841CMJU550138
Year Mfg 2017
Date of Accident 22 October 2019

ESTIMATE COST OF REPAIR TO "HYUNDAI ELANTRA" " REG. NO. SLS7876B"			
ITEM	DESCRIPTION	UNIT PRICE	AMOUNT
	Balance C/F		9,534.48
Special Nett Items			
1 set	Reverse Sensor		380.00
	Total Special Nett Items		380.00
Labour Charges			
	To remove, refix interior upholstery to facilitate repair works		30.00
	To remove, refix rear reverse sensor		50.00
	To refocus, re-wire & check wiring; check computer		80.00
	To re-spray undercoating for Rear End Panel		80.00
	To putty and re-spray paint of the affected areas		1,600.00
	To remove and replace the above damaged, panel beat and knock out rear panel, adjust and realign the same		1,500.00
	Total Labour Charges		3,340.00
GRAND TOTAL : PARTS AND LABOUR			13,254.48

ESTIMATE(SUPPLEMENTARY)

Date 24 Oct 2019
To

Owner Koh Yee Hong
Vehicle Reg. No. SLS7876B
Make/Model Hyundai Elantra
Chasis No. KMHD841CMJU550138
Year Mfg 2017
Date of Accident 22 October 2019

ESTIMATE COST OF REPAIR TO "HYUNDAI ELANTRA"			
" REG. NO. SLS7876B"			
ITEM	DESCRIPTION	UNIT PRICE	AMOUNT
1pc	Antenna Smart Key CM		82.90 ✓
1pc	Front Bumper Lip X 2pc		805.00 X
1pc	Rear Boot Spoiler BT X		
20pcs	Rear Reinforcement Bracket BT	36.90	73.80 ✓
1pc	Rear Bumper Guard		66.80 X
1pc	Rear Bumper Lip CM ✓ 496.30 - 520 (SN) (cost \$513.60)		1,051.30 ✓
	Sub-total		2,079.80
	Less 20%		(415.96)
	Total List Items		1,663.84



(Paint Beating, Repair, Servicing & General Claim)
11, AMK Autoport, #04-04 Ang Mo Kio, Ind. Park 2A, Singapore 568047
TEL: 6483 3353 FAX: 6484 2457 Email: ldenail@singnet.com.sg
Reg No: 52806993D

ESTIMATE(SUPPLEMENTARY)

Date 14 Nov 2019

To

Owner Koh Yee Hong

Vehicle Reg. No. SLS7876B

Make/Model Hyundai Elantra

Chasis No. KMHD841CMJU550138

Year Mfg 2017

Date of Accident 22 October 2019

ESTIMATE COST OF REPAIR TO "HYUNDAI ELANTRA"			
" REG. NO. SLS7876B"			
ITEM	DESCRIPTION	UNIT PRICE	AMOUNT
	<u>Special Nett Items</u>		
1	Front Number Plate		Net 40.00 ✓
	Total Special Nett Items		40.00
	<u>Labour Charges</u>		
	To plastic dip Front Grille		80/ 120.00
	ESTIMATE PARTS AND LABOUR GRAND TOTAL \$		160.00

Shiau Chan (LKKAUTO)

From: Siew Hoon <siewhoon@lyedesigns.com.sg>
Sent: Thursday, 24 October 2019 2:40 PM
To: Admin-D (LKKAUTO); SUR
Cc: Kenneth Kong (LKKAUTO)
Subject: SLS7876B MARKED ESTIMATE
Attachments: SLS7876B_Marked Estimate_23.10.19-24.10.19.pdf

Importance: High

Hi

I've received a phone call from Xiao Chan on this case.

Kenneth came at 1:30pm to conduct re-survey after we have dismantled the vehicle.

As he is rushing to next appointment he just passed me his markings without taking a copy with him.

Pls find the soft copy of the Estimate marked yesterday and today.

Would like to highlight that the Rear Boot Lamp LHR.

Thank you.

Warm Regards

Siew Hoon

Lye Designs

10 Ang Mo Kio Industrial Park 2A

#04-04 AMK Autopoint

Singapore 568047

T : 6483 3353

F : 6484 2457

E : siewhoon@lyedesigns.com.sg

W : www.lyedesigns.com.sg

ESTIMATE

Not Authorized
Returning B4pain
Today

Date: 23 Oct 2019
To: [blank]
Owner: Koh Yee Hong
Vehicle Reg. No: SLS7876B
Make/Model: Hyundai Elantra
Chassis No: KMHD841CMJU550138
Year Mfg: 2017
Date of Accident: 22 October 2019

ESTIMATE COST OF REPAIR TO "HYUNDAI ELANTRA" "REG. NO. SLS7876B"

ITEM	DESCRIPTION	UNIT PRICE	AMOUNT	
1pc	Front Bumper		605.40	✓
1pc	Front Bumper Side Retainer LHR and RHR	50.00	100.00	X
10 pcs	Front Bumper Clips	6.50	65.00	✓
1pc	Front Grille		611.50	✓
1pc	LHF Headlamp Assy HID Ballast		1,345.90	X
1pc	LHF Headlamp Bracket		56.30	X
1pc	LHF Foglamp		329.90	X
1pc	LHF Foglamp Garnish		53.50	X
1pc	Rear Boot Cover(Boot Lid)		2,385.00	✓
1pc	Rear Boot Cover Lock		155.50	✓
2 pcs	Rear Boot Lamp LHR Damaged	MSR 388.00	776.00	✓
1 pc	Rear Boot Weatherstrip		191.20	✓
2 pcs	Rear Boot Hinge	160.50	321.00	X
1pc	Rear Boot Number Plate Light		70.00	X
1pc	Rear Boot Logo "Elantra"		57.00	✓
1pc	Rear Boot Emblem "H"		52.50	✓
1pc	Reinforcement		395.00	✓
1pc	Rear End Panel		522.00	✓
1pc	Rear End Panel Top Garnish		153.80	✓
1pc	Rear Bumper		580.00	✓
10 pcs	Rear Bumper Clips	6.00	60.00	✓
2 pcs	Rear Bumper Side Retainer LHR and RHR	58.50	117.00	✓
2 pcs	Rear Bumper Reflector LHR and RHR	63.50	127.00	✓
2 pcs	Taillamp LHR and RHR	514.90	1,029.80	✓
4 pcs	Taillamp Clips LHR and RHR	8.00	32.00	X
2 pcs	Rear Exhaust Mounting	42.90	85.80	X
2 pcs	Rear Sport Exhaust Mufflers	830.00	1,660.00	X
Sub-total			11,918.10	
Less 20%			(2,383.62)	
Total List Items			9,534.48	
Balance B/F			9,534.48	

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2019 Edit Reg		23 Oct 2019 00:00 Edit Adj Rpt	S\$6,531.04 Edit Estimates	S\$6,531.04 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	NG WEI YANG, ID: S7914449E	
Main Claimant:	KOH YEE HONG, ID: S9233800B	
Vehicle Reg. No.:	SLS7876B	Date of Loss: 22/10/2019 00:00 - :59 [24 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201900031803	Policy/Cover Note No.: PNPV2018-00005666-01 (Comprehensive) Coverage: 30/05/2019 - 29/05/2020
Vehicle Reg. No. (Insured):	SKB5151Z	Policy No. (Claimant):
		Excess:
Repairer:	Lye Designs (HQ) 10 Amk Autopoint #04-04, Ang Mo Kio Industrial Park 2A, 568047 Ang Mo Kio - Tel: 64833353	
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Eileen Bay]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 04/11/2019]	

ASSOCIATED MAIL RECEIVED	View All Compose Case Mail
There are no mail for this case.	

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLS7876B (1201900031803)**

[SKB5151Z]


































TP

KOH YEE HONG

Oct 22 2019 12:00AM

[NG WEI YANG]

Lye Designs

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/10/19 11:57	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
20	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
21	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
22	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
23	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
24	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
25	18/02/20 16:12	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
26	18/02/20 16:12	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
27	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
28	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
29	18/02/20 16:12	General View	 Load JPG	<input checked="" type="checkbox"/>
30	18/02/20 16:13	DISMANTLE PHOTO	 Load JPG	<input checked="" type="checkbox"/>
31	18/02/20 16:13	DISMANTLE PHOTO	 Load JPG	<input checked="" type="checkbox"/>
32	18/02/20 16:13	DISMANTLE PHOTO	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRdoc&fuseaction=dsp_docview&domainid=1&corole=4&objid=880182&extid=320933&... 2/2

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/FWD19018792/KQD3S2
Date: 19/02/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00005666-01
Claimant Vehicle No : SLS7876B **Insured Vehicle No :** SKB5151Z
 Date of Loss: 22/10/2019 Nature of Claim: TP Claim No: 1201900031803

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLS7876B**
 Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGHU630885
 Reg. Date: 05/10/2017 (Man. Year: 2017) Chassis No: KMHD841CMJU550138
 Colour: Metallic Black Odometer: 40639 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
 Front Left Side: Dayton 8 mm Rear Left Side: Dayton 8 mm
 Front Right Side: Dayton 8 mm Rear Right Side: Dayton 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,618.32	4,501.04	7,117.28	61.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,460.00	2,030.00	1,430.00	41.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	15,078.32	6,531.04	8,547.28	56.69

INSPECTION

Date of Assignment: 23/10/2019
 Date Inspected: 23/10/2019 Inspected At: Lye Designs (HQ)
 10 Amk Autopoint #04-04, Ang Mo Kio Industrial Park
 2A
 Singapore 568047
 Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Feb 2020)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS7876B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	605.40 FL	*589.50 FL
2	2		*FRONT BUMPER SIDE RETAINER: LHR AND RHR	Serviceable	100.00 FL	*- FL
3	10		*FRONT BUMPER CLIPS	Necessary	65.00 FL	*65.00 FL
4	1		*FRONT GRILLE	Dented	611.50 FL	*495.80 FL
5	1		*LHF HEADLAMP ASSY HID BALLAST	Serviceable	1,345.90 FL	*- FL
6	1		*LHF HEADLAMP BRACKET	Serviceable	56.30 FL	*- FL
7	1		*LHF FOGLAMP	Serviceable	329.90 FL	*- FL
8	1		*LHF FOGLAMP GARNISH	Serviceable	53.50 FL	*- FL
9	1		*REAR BOOT COVER (BOOT LID)	Bent	2,385.00 FL	*1,048.00 FL
10	1		*REAR BOOT COVER LOCK	Dented	155.50 FL	*155.50 FL
11	1		*REAR BOOT LAMP	N/s Cut / O/s Serviceable	776.00 FL	*388.00 FL
12	1		*REAR BOOT WEATHERSTRIP	Dented / Distorted	191.20 FL	*186.70 FL
13	2		*REAR BOOT HINGE	Repair	321.00 FL	*- FL
14	1		*REAR BOOT NUMBER PLATE LIGHT	Serviceable	70.00 FL	*- FL
15	1		*REAR BOOT LOGO ELANTRA	Necessary	57.00 FL	*57.00 FL
16	1		*REAR BOOT EMBLEM H	Necessary	52.50 FL	*52.50 FL
17	1		*REINFORCEMENT	Bent	395.00 FL	*328.20 FL
18	1		*REAR END PANEL	Repair	522.00 FL	*- FL
19	1		*REAR END PANEL TOP GARNISH	Distorted	153.80 FL	*153.80 FL
20	1		*REAR BUMPER	Buckled / Cracked	560.00 FL	*489.20 FL
21	10		*REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
22	1		*REAR BUMPER SIDE RETAINER: LHR AND RHR	N/s Distorted	117.00 FL	*58.50 FL
23	2		*REAR BUMPER REFLECTOR: LHR AND RHR	Mtg Distorted	127.00 FL	*127.00 FL
24	1		*TAILLAMP: LHR AND RHR	O/s Serviceable/N/s MtgCracked	1,029.80 FL	*514.90 FL
25	4		*TAILLAMP CLIPS: LHR AND RHR	Not Necessary	32.00 FL	*- FL
26	2		*REAR EXHAUST MOUNTING	Serviceable	85.80 FL	*- FL
27	2		*REAR SPORT EXHAUST MUFFLERS	Repair	1,660.00 FL	*- FL
28	1		*SET REVERSE SENSOR	Serviceable	380.00 FS	*- FS
29	1		*ANTENNA SMART KEY	Cracked	82.90 FL	*82.90 FL
30	1		*FRONT BUMPER LIP	Serviceable	805.00 FL	*- FL
31	1		*REAR BOOT SPOILER (NPA)	Serviceable	0.00 FL	*- FL
32	2		*REAR REINFORCEMENT BRACKET	Bent	73.80 FL	*73.80 FL
33	1		*REAR BUMPER GUARD	Serviceable	66.80 FL	*- FL
34	1		*REAR BUMPER LIP	Cracked	841.04 FS	*520.00 FS
35	1		*FRONT NUMBER PLATE	Dented	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,207.64	5,486.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,589.32	985.26
Total Parts (\$\$)	11,618.32	4,501.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REFIX INTERIOR UPHOLSTERY TO FACILITATE REPAIR WORKS.	New	30.00	30.00
2	TO REMOVE, REFIX REAR REVERSE SENSOR.	New	50.00	50.00
3	TO REFOCUS, RE-WIRE & CHECK WIRING; CHECK COMPUTER.	New	80.00	40.00
4	TO RE-SPRAY UNDERCOATING FOR REAR END PANEL.	New	80.00	30.00
5	TO PUTTY AND RE-SPRAY PAINT OF THE AFFECTED AREAS.	New	1,600.00	1,000.00
6	TO REMOVE AND REPLACE THE ABOVE DAMAGED, PANEL BEAT AND KNOCK OUT REAR PANEL, ADJUST AND REALIGN THE SAME.	New	1,500.00	800.00
7	TO PLASTIC DIP FRONT GRILLE.	New	120.00	80.00
Gross Labour Cost (S\$)			3,460.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >