

INS. CASE OWNER:

MingYao.Lee

CC3/AIG19018797/Kea3

LKK:

IDAC:

ASSIGNMENT

Surveyor:

KENNETH

DOI: 22/10/2019

Date / Time : 22/10/2019

Registered in Merimen: 23/10/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SLV 7990M

Claim No. : 6910141479SG

Name of Insured : MS SIM MUI MUI

Policy No. : 1800010591

Insured Tel No. : HP: +65-94572966

Make / Model : MAZDA 3-1.5 (A)

Excess Sec II : \$\$ D.O.A : 19/10/2019 21:00

Place of Accident : MANILA STREET

Is driver the owner? (YES / NO) Nature of Accident :


If NO, Driver Name / Age : LIEW ZHENG YAN JOE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO


Driver Tel No. : +65-94572966 (V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SHF 604G

INSRS:
WSP: TRANS-CABTel :
Liability :

RMKS:

INSRS:
WSP:Tel :
Liability :

RMKS:

INSRS:
WSP:Tel :
Liability :

RMKS:

INSRS:
WSP:Tel :
Liability :

RMKS:

Date/ Time	SHF 604G - X	SLV 7990M - X	STAGE	DATE / PIC
			Non-Reporting ltr (1st):	
			Non-Reporting ltr (2nd):	
			Non-Reporting ltr (Final):	
			Notification ltr (if non-pickup):	
			Call OI:	ASHER 31.10.19
			After call ltr to OI:	
			Documentation Check List:	Handler Typist
			Notification ltr (if non-pickup)	☐ ☐
			After call ltr to OI:	☒ ☐
			Authorisation To Act:	☒ ☐
			Release Voucher:	☒ ☐
			Final Repair Bill:	☒ ☐
			Car Rental Invoice:	☒ ☐
			Towing Invoice	☐ ☐
			LTA / GIA :	☒ ☐
			Medical Bill:	☐ ☐
			PIR:	☐ ☐
			Mandate/Reject Instruction:	☒ ☐
			LOD	☒ ☐
			Payment Breakdown Form:	☐ ☐
			Post-Repair Photos:	☐ ☐
			Others:	☐ ☐

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by: KSC
FINALIZATION	Date/Time:	Confirm with:	Confirm by: KSC
Repair Cost:	45 SS 3,550.00	(5 days) Reduction:	81 %
FINAL SETTLEMENT	Date/Time: 31.03.20	Confirm with: OPA YIN	Email ☒ Call ☐
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No. :	9
Repair Cost:	21/51 SS 3,198.50	OVD MAKE A LEFT	TURN INTO MAIN ROAD HIT TP.
Loss of Rental (LOR):	SS 665.38	(1 days) x + 95.04	
Loss of Use (LOU):	SS -	(\$ x days)	
Loss of Income (LOI):	SS 350.00	(\$ 50 x 7 days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☒		[Tick only one]	
GIA/LTA Search	SS 1.44		
Medical:	SS -		
Disbursement:	SS -	(e.g. Tow/ Independent)	
Legal Cost	SS -		
Total:	SS 4,831.37	Global Sum \$:	
FINAL PAYMENT	Date/Time: 31.03.20	Confirm with: OPA YIN	Email ☒ Call ☐
Payee 1:	SS 4,831.37	Name 1:	TRANS-CAB AUTO SERVICES PTE LTD
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPY SENT
31/10/2019

- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: TP
- 3) Survey fee: 4320

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 604G

AAD1910-152

Not Authorized
21 Sep & 35501

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

22 OCT 2019

SHF 604G

VF1ABL15AUC278443

RENAULT

LATITUDE

19.10.19

Ally

27/6/2014

PART		LIST	
1	DOOR PANEL REAR RH	\$	<i>B</i> 758.70
1	DOOR LOCK REAR RH	\$	<i>R</i> 467.30
1	DOOR BLIND REAR RH	\$	<i>SL</i> 506.90
1	DOOR WEATHESTRIIP REAR RH	\$	<i>SL</i> 311.60
1	DOOR SEAL REAR RH	\$	<i>SL</i> 119.80
1	ROCKER PANEL INNER GARNISH RH	\$	<i>SL</i> 466.51
1	ROCKER PANEL INNER RH	\$	<i>R</i> 1,024.79
1	ROCKER PANEL OUTER RH	\$	<i>R</i> 1,184.99
1	ROCKER PANEL CENTER RH	\$	<i>R</i> 990.25
1	FENDER PANEL REAR RH	\$	<i>B</i> 1,933.20
1	FENDER PANEL INNER TRIM REAR RH	\$	<i>SL</i> 671.45
1	WHEELARCH REAR RH	\$	<i>SL</i> 275.40
1	BUMPER COVER REAR	\$	<i>SL</i> 561.70
1	BUMPER LOWER REAR	\$	<i>SL</i> 411.90
1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 98.10
1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 82.10
1	BUMPER RETAINER RH REAR	\$	<i>SL</i> 59.80
1	BUMPER REFLECTOR RH	\$	<i>SL</i> 16.60
1	BUMPER BEAM REAR	\$	<i>R</i> 547.80
1	BUMPER BEAM BRACKET RH REAR	\$	<i>SL</i> 100.90
1	TAILLAMP RH	\$	<i>SL</i> 313.10
TOTAL		\$	10,902.89
10%		\$	1,090.29
		\$	9,812.60

Trans-cab Auto Services Pte Ltd

AAD1910-152

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 604G**Special Nett**

1	REAR DOOR STICKER '6555-3333'	\$	nn	80.00	60sn
1	FENDER INNER TRIM CLIP RH	\$	nn	28.00	X
1	TAILLAMP CLIP RH	\$	nn	5.00	X
1SET	FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
2	REAR WINDSCREEN SEALANT	\$	nn	80.00	40sn
1	WINDSCREEN MOULDING	\$	nn	100.00	✓
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	30sn
1	REAR RIGHT TYRE	\$	sn	300.00	} X
1	REAR RIGHT TYRE RIM	\$	sn	380.00	
1	REAR WHEEL RIM COVER	\$	sn	50.00	
1SET	PARKING AID	\$	sn	700.00	
1SET	REAR BUMPER CLIP	\$	nn	66.00	
1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	} X
1SET	BUMPER RETAINER CLIP RH RR	\$	nn	20.00	
1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	
1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	
TOTAL		\$		2,075.00	

TOTAL PARTS \$ 11,887.60**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 *7000*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *1000*

To check steering geometry and computer wheel alignment

\$ 220.00 *600*

Trans-cab Auto Services Pte Ltd

AAD1910-152

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 604G

To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	120/
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	60/
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To rust-proofing of the affected areas.	\$	170.00	60/
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20/
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	660/
Towing Fees	\$	nn 170.00	X
TOTAL	\$	15,140.00	
Over All Total	\$	27,027.60	

LUMP SUM (REPAIR DAY)~~20~~ DAYS

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: