

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 604G**AAD1910-152***Not Authored
21 Sep & 3550h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

22 OCT 2019

SHF 604G

VF1ABL15AUC278443

RENAULT

LATITUDE

19.10.19

Ally

27/6/2014

PART		LIST	
1	DOOR PANEL REAR RH	\$	<i>As</i> 758.70
1	DOOR LOCK REAR RH	\$	<i>R</i> 467.30
1	DOOR BLIND REAR RH	\$	<i>SL</i> 506.90
1	DOOR WEATHESTRIIP REAR RH	\$	<i>SL</i> 311.60
1	DOOR SEAL REAR RH	\$	<i>SL</i> 119.80
1	ROCKER PANEL INNER GARNISH RH	\$	<i>SL</i> 466.51
1	ROCKER PANEL INNER RH	\$	<i>R</i> 1,024.79
1	ROCKER PANEL OUTER RH	\$	<i>R</i> 1,184.99
1	ROCKER PANEL CENTER RH	\$	<i>R</i> 990.25
1	FENDER PANEL REAR RH	\$	<i>As</i> 1,933.20
1	FENDER PANEL INNER TRIM REAR RH	\$	<i>SL</i> 671.45
1	WHEELARCH REAR RH	\$	<i>SL</i> 275.40
1	BUMPER COVER REAR	\$	<i>SL</i> 561.70
1	BUMPER LOWER REAR	\$	<i>SL</i> 411.90
1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 98.10
1	BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 82.10
1	BUMPER RETAINER RH REAR	\$	<i>SL</i> 59.80
1	BUMPER REFLECTOR RH	\$	<i>SL</i> 16.60
1	BUMPER BEAM REAR	\$	<i>R</i> 547.80
1	BUMPER BEAM BRACKET RH REAR	\$	<i>SL</i> 100.90
1	TAILLAMP RH	\$	<i>SL</i> 313.10
TOTAL		\$	10,902.89
10%		\$	1,090.29
		\$	9,812.60

Trans-cab Auto Services Pte Ltd

AAD1910-152

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 604G

Special Nett

1	REAR DOOR STICKER '6555-3333'	\$	nn	80.00	60sn
1	FENDER INNER TRIM CLIP RH	\$	nn	28.00	X
1	TAILLAMP CLIP RH	\$	nn	5.00	X
1SET	FENDER WHEELARCH REAR RH CLIP	\$	nn	35.00	X
2	REAR WINDSCREEN SEALANT	\$	nn	80.00	40sn
1	WINDSCREEN MOULDING	\$	nn	100.00	✓
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	30sn
1	REAR RIGHT TYRE	\$	sn	300.00	} X
1	REAR RIGHT TYRE RIM	\$	sn	380.00	
1	REAR WHEEL RIM COVER	\$	sn	50.00	
1SET	PARKING AID	\$	sn	700.00	
1SET	REAR BUMPER CLIP	\$	nn	66.00	
1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	
1SET	BUMPER RETAINER CLIP RH RR	\$	nn	20.00	}
1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	
1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	
TOTAL		\$		2,075.00	

TOTAL PARTS \$ 11,887.60**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 6,000.00 *7000*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *nn* 380.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 *1000*

To check steering geometry and computer wheel alignment

\$ 220.00 *600*

Trans-cab Auto Services Pte Ltd**AAD1910-152**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 604G

To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	120/
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	60/
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To rust-proofing of the affected areas.	\$	170.00	60/
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20/
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	660/
Towing Fees	\$	nn 170.00	X
TOTAL	\$	15,140.00	
Over All Total	\$	27,027.60	

LUMP SUM (REPAIR DAY)**20 DAYS****3 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: